

22/03/2018

ASS. F.C. BY:

REF: CS/EGU8004708/UTbnz

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Yee Pui Li

of

ECI

Date/Time: 13032018 1:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 9330E

Insured:

SLF 9840J

at Workshop m/s

Fastech Auto

Tel:

6746 5405

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

Claim No:

SLF-9840J / RH / pi

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12032018

CA / REV / REP. / REV 24 HRS Wp.

H.O.D. Endorsement:

Date/Time: 13-03-2018 2:21pm

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLC 9330E - x

SLF 9840J - x

8/3-

Revert preli advice

lump sum \$5200/- (Red: 8826.73 : 62%)

08/11/13 wof

ASS. REC. PY: 140105

REF:

ER11

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC9330Eat Workshop n/s RP.

of \_\_\_\_\_

Insured: SLF9840J

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 5200

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

3888A  
Vehicle: IN / OUTVeh No: SLC9330E Yr Regn: 6, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: BMW 523i c.c. 2497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 15-2708 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAFP32070C25-7835

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Continental

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 13/3/18

Date / Time Action / Instruction

LTA 32/96 Rep 15 2 yrs. 3m.20/2/18 1/5 \$5200 confirmed with Alcan (Red 882683 162%)

RECEIVED 20 MAR 2018

Date/Time, File Pass to?

1) 28/3 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

Report Format: TPLump Sum / I.B.I: (\$ 5200)

350



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18004708/Utb

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 13-03-2018



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 9840J	Veh. Inspected	SLC 9330E
Policy No.		Coverage (\$)	0.00
Claim No.	SLF9840J/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	13/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	12/03/2018	Inspection Date	13/03/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SLF9840J/RH/pl  
Our Ref: CS/EGI18004708/Utb

Date: 28/3/2018

The Motor Claims Department  
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SLC 9330E .**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 13/3/2018 at the premises of M/s Fastech and have the following to report: -

Workshop Estimate Amount	: S\$ 14,026.83
Revised Estimate Amount	: S\$ 5,200.00
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

**Description of Damage:**

The vehicle sustained damages  
At front portion.



Repair days: 3 Days

**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

## Catherine Chong (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 13 March, 2018 1:46 PM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SLF9840J / TP : SLC9330E/LKK / DOA : 12/03/2018  
**Attachments:** SLF9840J - SAS.pdf; SLC9330E - SAS.pdf; SLC9330E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6  
#01-46/48/50 AUTOBAY  
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

### Yee Pei Li

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 13.03.2018  
Our Reference: SLF 9840J/RH/pl  
Your Reference: SLC 9330E  
  
To: FASTECH AUTO PTE LTD

Sent via Fax ☐  
or ☐  
Email ☐ nancy.lam@fastechauto.com.sg

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLC 9330E  
Insured's Vehicle: SLF 9840J  
Date Of Accident: 12.03.2018

We acknowledge receipt of your request for PRS on: 13.03.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☐ Our Insured's driver has not reported the accident to us todate.  
☒ Others: OFFICER-IN-CHARGE - ROHAINI

Prepared by: Pei Li 6829 9194 claims@ergo.com.sg  
Signature: [Signature] FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

[Signature]  
Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Wednesday, 28 March 2018 1:08 PM  
**To:** Admin-D (LKKAUTO); 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR; assignments  
**Subject:** RE: SLF9840J / TP : SLC9330E/LKK / DOA : 12/03/2018  
**Attachments:** PRELI ADVISED SLC 9330E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLC 9330E**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 13 March 2018 2:03 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: SLF9840J / TP : SLC9330E/LKK / DOA : 12/03/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Tuesday, 13 March, 2018 1:46 PM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Subject:** OI : SLF9840J / TP : SLC9330E/LKK / DOA : 12/03/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6



## Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3888A
Vehicle Details	
Vehicle No.:	SLC9330E
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	05787379N52B25AF
Chassis No.:	WBAFP32070C257835
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$38,510.00
Original Registration Date:	24 Jun 2010
First Registration Date:	24 Jun 2010
Transfer Count:	2
Actual ARF Paid:	\$38,510.00 1925-k
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2020
PARF Rebate Amount:	\$23,106.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jun 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$9,090.00
<b>Total Rebate Amount:</b>	<b>\$32,196.00</b>

The information contained herein is correct as at 13 Mar 2018

OK



Your perfect companion for a great getaway  
**Receive a Samsonite  
 Orfeo Luggage**  
 Maybank Credit Cards and CreditAble


[FIND OUT MORE](#)

Terms and Conditions apply.


**Maybank**

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
**2016 Audi A3 Sportback Attraction @ \$101,800 Only.**


Best Price In Market. White, 1.  
 Owner, Full Records, Breyton  
 Rims, Drop By Now.  
 TradeIt.Com Pte Ltd StarAd

**HIN LUNG AUTO**  
 Ho Bee Group

**30 years**  
 of car sale

**One Stop Car Hub**  
 Finance, Insurance, Workshop  
 New and Used Cars

 Browse by Category 







« Back ( 1 2 3 ) Next »

 Sort by Date Posted 

 20 results/page 
**44 vehicles**

BMW 523

 Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	BMW 523		Any	Any	2010	Any	Any	Any	Available
	BMW 5 Series	523i Highline	\$51,800	\$14,680 /yr	20-May-2010	2,497 cc	90,000 km	Luxury	Available
Highline Model, 100% Accident Free. Low Down Payment And In House Loan Are Available. Trade In Are Welcomed Too. Peace Of Mind With An Optional 1 Or 2 Years Warranty, Available In Showroom For Viewing ...									
Posted: 13-Mar-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$61,800	\$15,410 /yr	01-Dec-2010	2,497 cc	123,000 km	Luxury	Available
Buy With A Peace Of Mind. Pml Unit. 100% Quality Buy! Sta And Vicom Evaluation Welcome. Vehicle In Showroom Condition By Professional Groomer. Elegant Silver With Cream Leather Interior. Lowest Intere...									
Shuang Hup Credit									
Posted: 13-Mar-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$52,800	\$15,280 /yr	30-Apr-2010	2,497 cc	108,843 km	Luxury	Available
Just Arrived. Nice New SLW Plate! Luxury Black On Beige Interior With Immaculate Conditions. High OMV \$40475 High PARF \$20238. Genuine Low Mileage Done 108843 Km. Well Maintained By Owner. 100% Accide...									
Posted: 13-Mar-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$59,800	\$14,680 /yr	01-Dec-2010	2,497 cc	122,000 km	Luxury	Available
New Road Tax, PML Unit, Excellent Condition, Well Maintained By Previous Owners, STA And VICOM Evaluation Welcome. Vehicle In Showroom Condition, Elegant Blue With Clean Leather Interior. 100% Major A...									
Posted: 13-Mar-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
<div> <div>Car Buying</div> <div>Car Ownership</div> </div> <div> <div>Car Selling</div> <div>On The Move</div> </div> <div> <div>Car Aftermarket</div> <div>Lifestyle</div> </div> <div> <div>Buying a pre-owned car, but Unsure of its Condition?</div> <div>Get, STA Car Evaluation</div> </div>									
	BMW 5 Series	523i	\$58,800	\$14,040 /yr	29-Dec-2010	2,497 cc	108,000 km	Luxury	Available
Extremely Popular Luxury Executive Sedan That Blends Perfectly For Business And Leisure. Executive Sedan Owned. Immaculate Condition. Owned By 1 Extremely Careful Lady! Cheapest In Town, Peace Of Mind...									
Posted: 13-Mar-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i	\$58,800	\$14,950 /yr	16-Sep-2010	2,497 cc	87,000 km	Luxury	Available
F10 Model! Superb Drive And Handling With No Repairs Needed. Buy With No Regrets! High/Flexible Loan! Excellent Condition. Lowest Depreciation. Call To View In Air-Conditioned Showroom Now!									
GS Automobiles Pte Ltd									
Posted: 13-Mar-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW									
	BMW 5 Series	523i Highline	\$64,800	\$15,560 /yr	15-Dec-2010	2,497 cc	138,000 km	Luxury	Available
1 Owner! Agent Maintained, Low Downpayment, Flexi Bank/In House Loan Available, Up To 90% Loan! 100% Loan Approve With Our In House Loan With Low Interest, 100% Accident Free, Welcome Trade In, Please...									

[Compare](#)

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

VEH: SLC 9330E

28/3  
+

1,506.32+

645.++

68.++

145.++

60.++

296.++

235.++

356.25+

98.3+

2,456.5+

118.++

=

6,064.37\*

6,064.37x

90.%

5,457.933\*

0.0

40.45.++

20.++

520.++

600.++

=

1,180.\*

0.0

5,457.933+

1,180.++

=

6,637.933\*

6,637.933x

80.%

5,310.3464\*

QTY	PARTICULAR
1PCS	BONNET
1PCS	FRONT BUMPER 1566.32
1PCS	FRONT BUMPER REINFORCEMENT 645.00
1PCS	FRONT BUMPER LOGO
1PCS	FRONT BUMPER SPONGE
2PCS	FRONT BUMPER SIDE HOLDERS @\$45.00
1SET	FRONT BUMPER CLIPS
2PCS	FRONT BUMPER REINFORCEMENT STAYS @
2PCS	FRONT BUMPER GRILLES @\$148.00
2PCS	FRONT BUMPER PDC SENSOR @\$235.00
1PCS	FRONT BUMPER CENTRE LOWER GRILLE
1PCS	FRONT BUMPER INNER AIR SURROUND
1PCS	FRONT BUMPER INNER AIR DUCT
1PCS	HEADLAMP O/S 2466.50
1PCS	FRONT SUPPORT PANEL
1PCS	AIR CON CONDENSER
2PCS	FRONT FOG LAMPS @\$285.00
1PCS	FRONT LICENSE PLATE
1PCS	FRONT BUMPER TOP RUBBER

(10)

TO CHECK WIRING  
TO SPRAY RUST PROOFING  
TO REFILL AIR CON GAS  
LABOUR FOR PANEL BEATING & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

\$680.00 520

\$880.00 600

TOTAL

\$14,026.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18004708/Utbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 02-04-2018		
		Code : EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLF 9840J	Veh. Inspected	SLC 9330E	
Policy No.		Coverage (\$)	0.00	
Claim No.	SLF9840J/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W 523I (A)	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAFP32070C257835	Colour	BLACK	
Odometer	152708	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/03/2018	Inspection Date	13/03/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 9330E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	TO REPAIR SEE LABOUR	2,168.62	-
1	FRONT BUMPER	DENTED / DEFORMED	1,950.00	1,566.32
1	FRONT BUMPER REINFORCEMENT	DENTED / BENT	899.23	645.00
1	FRONT BUMPER LOGO	NECESSARY	68.00	68.00
1	FRONT BUMPER SPONGE	TORN	145.00	145.00
2	FRONT BUMPER SIDE HOLDERS	NOT NECESSARY	230.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	60.00
2	FRONT BUMPER REINFORCEMENT STAYS @\$78.00	NOT NECESSARY	156.00	-
2	FRONT BUMPER GRILLES @\$148.00	SCRATCHED	296.00	296.00
2	FRONT BUMPER PDC SENSOR @\$235.00	SHORTED (1 PC ONLY)	470.00	235.00
1	FRONT BUMPER CENTRE LOWER GRILLE	NOT NECESSARY	82.00	-
1	FRONT BUMPER INNER AIR SURROUND	TORN	366.25	366.25
1	FRONT BUMPER INNER AIR DUCT	CRACKED	98.30	98.30
1	HEADLAMP O/S	CRACKED	2,865.12	2,466.50
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	666.30	-
1	AIR CON CONDENSER	NOT NECESSARY	988.01	-
2	FRONT FOG LAMPS @\$285.00	NOT NECESSARY	570.00	-
1	FRONT BUMPER TOP RUBBER	NECESSARY	118.00	118.00
	LESS 10% DISCOUNT		-	-606.44
			12,196.83	5,457.93
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT LICENSE PLATE (SN)	SCRATCHED	50.00	40.00
			50.00	40.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-

Report Ref No. CS/EGI18004708/Utn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT SUPPORT PANEL. TO PUTTY & SPRAY PAINTING.		680.00	520.00
			880.00	600.00
			1,780.00	1,140.00
GRAND TOTAL			14,026.83	6,637.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS/EGI18004708/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.