

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no : 6631 1188

Account Detail		Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
		Document No	
		Document Date	
		0	
		12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	04/09/2017	SLS0475X	0	29912	60D/SLS0475X/090311
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A29016406QMY ACC DATE:08/03/18 TOW IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP				169.50
3	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
4	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS				339.00
5	B	BP-MECH REPL DASHBOARD ASSY				1356.00
6	B	BP-MECH REPL SEAT BELT ASSY				678.00
7	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				678.00
8	B	BP-MECH REPL AIRBAG SENSOR AND ECU				169.50
9	B	BP-MECH R/I ABS UMP AND FUSE TO TO FAC REPAIR ON LH AND RH WHEEL HOUSE				508.50
10	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				160.00
11	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				5424.00
12	B	BP-RES RESRPAY ACC AFF AREA				4448.00
13	1	T16410-37201 RADIATOR ASSY, L/CAP	1.00	1800.20	15.00	1530.17

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
LINK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company	Parts	Labour	Tarikh 97495749 EX \$500 Revert Not Authorised sur@linkauto.com * Resurvey before paint 10 days.
	Materials	Lubrication/Fluid	
	Others		
			Amount Due 13/3/18 @ 1630

3621405

3621405

TO SECURITY GUARD

Acknowledged by Repairer

Signature:

Date:

DATE 12/03/2018

TIME 08:19

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No	
	Document Date	
	0	
	12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	0	29912 60D/SLS0475X/090311
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	2	T16572-37130 RADIATOR HOSE NO 2,	1.00	43.20	15.00	? 36.72
15	3	T16573-21090 HOSE, RADIATOR, NO.3	1.00	43.30	15.00	? 36.80
16	4	T16261-21160 HOSE, WATER BY-PASS	1.00	37.90	15.00	? 32.21
17	5	T16533-21040 UPP RADIATOR SUPPORT,	2.00	39.00	15.00	bt 66.30
18	6	T16523-21050 CUSHION, RADIATOR	2.00	11.50	15.00	? 19.54
19	7	T16712-37040 RADIATOR SHROUD FAN 2,	2.00	78.60	15.00	? 133.62
20	8	T16711-37070 RADIATOR SHROUD FAN,	1.00	221.40	15.00	? 188.19
21	9	T16361-28360 RADIATOR FAN BLADE 2,	1.00	234.20	15.00	? 199.07
22	0	T16361-28350 RADIATOR FAN BLADE,	1.00	183.10	15.00	? 155.63
23	1	T16535-37010 SUPPORT, RADIATOR,	1.00	21.50	15.00	? 18.27
24	2	T16363-37031 MOTOR, COOLING FAN	1.00	548.90	15.00	? 466.56
25	3	T16363-37090 MOTOR, COOLING FAN	1.00	548.90	15.00	? 466.56
26	4	T17751-37080 INLET AIR-CLEANER,	1.00	57.10	15.00	? 48.53
27	5	T17752-37090 F/INLET AIR CLEANER 2,	1.00	137.00	15.00	? 116.45
28	6	T17700-37211 AIR CLEANER ASSY,	1.00	950.30	15.00	? 807.75
29	7	T52119-68909 FRONT BUMPER COVER,	1.00	574.90	15.00	de 488.66
30	8	T52115-68031 R/FRT BUMPER SUPPORT,	1.00	60.90	15.00	rel 51.76
31	9	T52116-68031 L/FRT BUMPER SUPPORT,	1.00	60.90	15.00	rel 51.76
32	0	T52611-68030 FRT BUMPER ABSORBER,	1.00	89.20	15.00	one 75.82
33	1	T52021-68020 F/BPR REINFORCEMENT,	1.00	295.70	15.00	bt 251.34
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3621406

TO SECURITY GUARD

3621406PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 12/03/2018
TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingsapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jiancha 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP S6	ZGE20R	04/09/2017	SLS0475X	0	29912	60D/SLS0475X/09031
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	2	T52030-68010 R/F BUMPER HOLE COVER,	1.00	83.30	15.00	70.80
35	3	T52040-68010 L/F BUMPER HOLE COVER,	1.00	83.30	15.00	70.80
36	4	T52618-68010 F/LOWER BPR ABSORBER,	1.00	125.80	15.00	106.93
37	5	T53149-68010 PROTECTOR RADIATOR	1.00	31.30	15.00	26.60
38	6	T53113-68010 L/F LWR RADIATOR GRILLE,	1.00	55.20	15.00	46.92
39	7	T53112-68030 F/LOW RADIATOR GRILLE,	1.00	55.20	15.00	46.92
40	8	T53101-68010 GRILLE SUB-ASSY,	1.00	401.80	15.00	341.53
41	9	S52161-OK040 PIECE,RR BUMPER	10.00	3.90	15.00	33.10
42	0	T53811-68060 FENDER SUB-ASSY,RH	1.00	955.90	15.00	812.51
43	1	T53875-68020 R/FRT FENDER LINER,	1.00	167.10	15.00	142.03
44	2	T53812-68060 FENDER SUB-ASSY,LH	1.00	955.90	15.00	812.51
45	3	T53876-68020 L/FRT FENDER LINER,	1.00	167.10	15.00	142.03
46	4	T53301-68020 FRONT BONNET ASSY,	1.00	945.30	15.00	803.50
47	5	T90467-09050 CLIP	6.00	2.30	15.00	11.70
48	6	T53341-68020 FRT BONNET INSULATOR,	1.00	398.40	15.00	338.64
49	7	T53866-68021 R/F FENDER SEAL COWL,	1.00	33.00	15.00	28.05
50	8	T53867-68021 SEAL, FR FENDER TO	1.00	33.00	15.00	28.05
51	9	T53510-68050 FRONT BONNET LOCK,	1.00	89.80	15.00	76.33
52	0	T53452-68010 HOLDER, HOOD STAY	1.00	28.30	15.00	24.05
53	1	T53410-68030 R/FRT BONNET HINGE,	1.00	57.10	15.00	48.53
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3621407

3621407

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
 TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482	
		Document No		
		Document Date		
		0		
		12/03/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	0	29912 :60D/SLS0475X/09031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
54	2	T53420-68030 L/FRT BONNET HINGE,	1.00	57.10	15.00	bt 48.53
55	3	T53292-68020 F/UPPER RADIATOR SEAL,	1.00	89.80	15.00	? 76.33
56	4	T53208-68020 F/BRACE LOCK SUPPORT,	1.00	89.80	15.00	bt 76.33
57	5	T53201-68021 FRT RADIATOR SUPPORT,	1.00	1441.10	15.00	bt 1224.93
58	6	T53289-68020 F/RADIATOR SEAL COVER,	1.00	62.60	15.00	? 53.21
59	7	T53299-68010 L/F RADIATOR SEAL COVER,	1.00	78.60	15.00	? 66.81
60	8	T57142-68010 L/FRONT BUMPER ARM,	1.00	49.90	15.00	? 42.41
61	9	T57141-68010 R/FRONT BUMPER ARM,	1.00	49.10	15.00	? 41.73
62	0	T57117-68010 R/F SIDE MEMBER PLATE,	1.00	99.20	15.00	? 84.32
63	1	T57118-68010 L/F SIDE MEMBER PLATE,	1.00	102.20	15.00	? 86.87
64	2	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20	15.00	rec 61.37
65	3	TSUNCY-MOULD SIDE MOULDING	1.00	211.50	15.00	rec 179.77
66	4	T88450-12280 A/C CONDENSER ASSY,	1.00	1507.40	15.00	bt 1281.29
67	5	T88710-68051 A/C TUBE & ACCESSORY,	1.00	678.80	15.00	? 576.98
68	6	T88703-68060 A/C DISCHARGE HOSE,	1.00	407.90	15.00	? 346.71
69	7	T85315-68020 FRONT WASHER JAR,	1.00	57.90	15.00	x 49.21
70	8	T45130-68041 B0 PAD ASSY, STEERING	1.00	2402.20	15.00	act 2041.87
71	9	T73960-68010 F/INSTRUMENT AIR-BAG,	1.00	3240.20	15.00	act 2754.17
72	0	T55302-68901 B0 UPP INSTRUMENT PANEL,	1.00	920.80	15.00	act 782.68
73	1	T55550-68020 B0 DOOR ASSY, GLOVE	1.00	419.70	15.00	x 356.74
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3621408

TO SECURITY GUARD

3621408

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
 TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATEJoin Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No S1000004 / ICCUA1		Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Document No 0		Mr Tan Kian Cheong (Chen Jianche 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482	
Document Date 12/03/2018					

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	0	29912 60D/SLS0475X/09031:

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
74	2	T73210-68040 C0 BELT, ASSY FR SEAT,	1.00	838.20	15.00	act 712.47
75	3	T73220-68040 C0 BELT ASSY, FR SEAT	1.00	838.20	15.00	act 712.47
76	4	T73360-68030 C0 BELT ASSY, NO.1	1.00	526.00	15.00	? 447.10
77	5	T73370-68030 C0 BELT ASSY, NO.1	1.00	526.00	15.00	? 447.10
78	6	T81185-68100 UNIT, HEADLAMP LH	1.00	1222.20	15.00	cm 1038.87
79	7	T81145-68100 UNIT, HEADLAMP	1.00	1222.20	15.00	cm 1038.87
80	8	T81210-47010 R/FRONT FOG LAMP ASSY	1.00	300.90	15.00	? 255.76
81	9	T81220-47010 LAMP ASSY, FOG, LH	1.00	286.00	15.00	? 243.10
82	0	T89173-59275 SENSOR, AIR BAG, FR	2.00	314.00	15.00	act 533.80
83	1	T89170-68060 SENSOR ASSY, AIR BAG	1.00	741.00	15.00	act 629.85
84	2	T84307-74020 CABLE SUB-ASSY	1.00	953.30	15.00	? 810.30
85	3	T82140-68020 AIR-BAG WIRE ASSY,	1.00	24.10	15.00	act 20.48

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 26,375.67	40,486.17
		Labour 14,030.50	GST 7.00% 2,834.03
		Materials 80.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 43,320.20

3621409

PLEASE TEAR ALONG PERFORATED LINE

3621409

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
 TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors