

ASS. REC. BY:

REF: CS/MSG18004710 / Tlvb

Special Instruction:

Survivor:
Merimen

Thurifan

ASSIGNMENT (Office)

From (Person): Joslin Lim

of

MSL/H

Date/Time: 12032018 4:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 475 X

Insured:

at Workshop m/s

Borneo Motor

Tel:

of

2 Pandan Crescent

Policy No:

M290164068MY

Claim No:

551966

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 08/3/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 13-03-2018 1:38pm

Person Contacted:

Shushi

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLS 475 X

14/3/18

Revert by merimen

16/3/18

Rece approved from Ai Ngoh by merimen

16/3/18

Informed Shushi c/A EA \$500 by email

19/4/18

Final fig \$33,952.41 confirmed by email (Recd 678637, 17/4)

21/4/18

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: 4500
 (Client's Record)
 Make of Veh: _____

X	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bel. or Market Value: 9103K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SLS475X Yr Regn: 2017 Sep.
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Wish. C/C: 1798
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 9516 T. Radio: Insured / Std / NI / NA
 Eng. No: _____
 C/No: STD 6620W40J007490
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: NII / S/Rim STD A/Rim or
 Tyre Size: 195/65R15
 R: 1 1

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: 6 mm Rear: 4 mm
 R/Bal: _____ mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 13/5/18 @ 1650
 Survey held at: Borneo Parden
 Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction

RECEIVED 20 APR 2018.

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

19/4 - typist

Report Format: merimen
 Lump Sum / I.B.I: 33,952.41

Days Of Repair: 10
 Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Insp \$
☐ Rearend \$

Survey Fee _____
 Transporter _____
 Photo _____
 Other _____

Survey Department Check List (Case Handler)

Reference No.: CS MSG 18004710 Tivb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 19/4/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004710/T1vb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-03-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLS 475X
Policy No.	A29016406QMY	Coverage (\$)	0.00
Claim No.	551966	Excess (\$)	500.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/03/2018	Inspection Date	13/03/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Mar 2018		12 Mar 2018 16:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

TAN KIAN CHEONG, ID: S7520553H, Tel: +6591822482

Vehicle Reg. No.:

SLS475X

Date of Loss:

08/03/2018 21:00 - :59

Claim Type:

OD / 551966

Policy/Cover Note No.:

A29016406QMY (Comprehensive)
Coverage: 04/09/2017 - 03/09/2018

Excess:

S\$500.00

Repairer:

Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/03/2018]

Driver/Custodian:

NG YI TING, PATRICIA (39 / Female), NRIC: S7834861E, Tel: +6597940887

Adj Asg. Remarks:

Please revert.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLS475X (551966)**

OD

Mar 8 2018 9:00PM

[TAN KIAN CHEONG]

Borneo Motors (singapore) Pte Ltd - (pandan)

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/04/2018 14:16 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$33952.41) - SLS475X - Claim Handler: Joslin Lim

Approved:33952.41:subject to confirmation of check items

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 19 Apr 2018

Preliminary Advice

Vehicle No	: SLS475X	Accident Date	: 08/03/2018
Make	: TOYOTA WISH	Policy No.	: A29016406QMY
Assignment Date	: 12/03/2018	Excess	: S\$500.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 10.00
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD - (PANDAN) (HQ) TOYOTA BODYCARE CENTRE, NO. 2 PANDAN CRESENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,738.78	(incl.supplementary \$252.61)
Revised Amount	:S\$	33,952.41	(incl.supplementary \$252.61)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	33,952.41	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$	103,000.00	
COE / PARF Rebate	:S\$	62,131.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	40,869.00	

Remarks

(X)

The vehicle is economical for repair.

()

The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 16 March 2018 5:16 PM
To: SUR; Shashitharan
Subject: SLS 475X-DOA: 8/3/2018 (MSIG OD)

Dear ShaShi,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SLS 475X (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLS475X (551966)**

OD

Mar 8 2018 9:00PM

[TAN KIAN CHEONG]

Borneo Motors (singapore) Pte Ltd - (pandan)

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 16/03/2018 16:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$37538.17) - SLS475X - Claim Handler: Joslin Lim

Approved:37538.17:subject to confirmation of check items

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joslin Lim	Date: 14 Mar 2018
<u>Preliminary Advice</u>	

Vehicle No	: SLS475X	Accident Date	: 08/03/2018
Make	: TOYOTA WISH	Policy No.	: A29016406QMY
Assignment Date	: 12/03/2018	Excess	: S\$500.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 10.00
Inspection At	: BORNEO MOTORS (SINGAPORE) PTE LTD - (PANDAN) (HQ) TOYOTA BODYCARE CENTRE, NO. 2 PANDAN CRESENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,486.17
Revised Amount	:S\$	28,217.90
Check Items (Estimated)	:S\$	9,320.27
Total	:S\$	37,538.17

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	62,131.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,869.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0553H
Vehicle Details	
Vehicle No.:	SLS475X
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR1981506
Chassis No.:	JTDGG20W40J007490
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	04 Sep 2017
First Registration Date:	04 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2027
PARF Rebate Amount:	\$14,966.00
Intended COE Rebate Details	
COE Expiry Date:	03 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,802.00
COE Rebate Amount:	\$47,165.00
Total Rebate Amount:	\$62,131.00

The information contained herein is correct as at 14 Mar 2018

OK



Toyota Wish Min Price to No Max Depreciation Vehicle Type Category Search

Home » New Cars » Toyota Wish Search Results

Resources

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Tyres



Toyota Wish Search Results (2 vehicles)

Sort by Model (Ascending) 15 re

Car Model	Price	Dealer	Built in	Use
Toyota Wish		Borneo Motors	Japan	
1.8 Standard CVT (A)	\$112,988 A \$10,300 /yr 2	14.7km/l 141bhp 7-speed (A) CVT		33 U
1.8 Elegance CVT (A)	\$119,988 A \$11,000 /yr 2	14.7km/l 141bhp 7-speed (A) CVT		60
Toyota Wish		Parallel Importers	Japan	
1.8 X (A)	\$104,000 \$9,900 /yr 2	16km/l 144bhp 7-speed (A) CVT		33 U
1.8 X (A)	FACELIFT \$105,000	15.9km/l 141bhp 7-speed (A) Super CVT-i		60

Car Model	Price	Dealer	Built in	Use
			15	re

1 result(s) for Toyota Wish models no longer being sold by local distributors
View all past Toyota cars



Toyota Wish
(2008-2009)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car price lists, new car launches, new car promotions, new car reviews, latest car news & car a join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and i properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be give information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

-
-
-
-

- Terms of Service
- Privacy Policy
- Personal Data Protection

Compare

TYPE OF CLAIM: ☒ OD ☐ OD/UL ☐ DSMCA: Shah

MOTOR ACCIDENT REPORT

Date Of Report: 9/8/2018 Time: 9am Date Of Accident: 8/3/2018 Time: 9pmExact Location Of Accident: Buangtik Drive towards Hougang Ave 10 (Lamp Post 466)Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLS 475X Co. Reg. No.(for Co. Vehicle)/NRIC/PP/FIN No: 575205534Name Of Registered Owner: TAN KIAN CHEONGMobile Number: 91822482 Alternative No: 97940887 Email Address: tennytan@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model:Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: MSIAType Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☐ Policy / Cover Note No:

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: NG YI TINH PATRICIA NRIC/ Passport / FIN No: 57834861EDate Of Birth: 14/11/1978 Occupation: Indoor ☒ Outdoor ☐Date Of Driving Pass: 16 DEC 2002 Gender: Male ☐ Female ☒Mobile Number: 97940887 Fax No: Alternative No:Address: 572, HOUGANG ST. 51, #09-37 Postal Code: 530572Email Address: patngyt@gmail.comWas driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Car AccidentNumber of Passengers in the above vehicle (Including Driver): 3 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: TAN LE XUAN Charmaine Gender: Male ☐ Female ☒Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☐ Yes ☒Was any injured conveyed to hospital by ambulance? No ☐ Yes ☒Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:Number of vehicles involved in the accident: 3Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below

Witness Name: Contact No: Email:

Was there any other vehicle or property damaged? No ☒ Yes ☐ with traffic police SD cardWas there any video captured by Car Camera? No ☐ Yes ☒ Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: 5JZ 57674 Vehicle Make/Model/Colour: Volvo / S60 / BLACKDetails Of Properties Damage in Accident: RearVehicle Category: SedanName of Driver: LAW KIM HENGNRIC/Passport/FIN Number: 5250 4532 6 Contact Number: 96283400Address: 320C Anchorvale Drive #08-122 Postal Code: 540220Insurance Company Name: NTUCNature Of Damage: Rear No. Of Passenger (Including Driver): 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number: SJJ9504H	Vehicle Make/Model/Colour:
Details Of Properties Damage in Accident:	
Name of Driver:	
NRIC/Passport/FIN Number:	Contact Number:
Address:	Postal Code:
Insurance Company Name:	
Nature Of Damage:	No. Of Passenger (Including Driver):

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number:	Vehicle Make/Model/Colour:
Details Of Properties Damage in Accident:	
Name of Driver:	
NRIC/Passport/FIN Number:	Contact Number:
Address:	Postal Code:
Insurance Company Name:	
Nature Of Damage:	No. Of Passenger (Including Driver):

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number:	Vehicle Make/Model/Colour:
Details Of Properties Damage in Accident:	
Name of Driver:	
NRIC/Passport/FIN Number:	Contact Number:
Address:	Postal Code:
Insurance Company Name:	
Nature Of Damage:	No. Of Passenger (Including Driver):

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number:	Vehicle Make/Model/Colour:
Details Of Properties Damage in Accident:	
Name of Driver:	
NRIC/Passport/FIN Number:	Contact Number:
Address:	Postal Code:
Insurance Company Name:	
Nature Of Damage:	No. Of Passenger (Including Driver):

DETAILS OF INJURED PERSON 1

Name: TAN LEXIN SHERISE	Approximate Age: 5+
Address:	Postal Code:
Injuries Sustained:	Injured person in which vehicle:
Were seat belt worn? Yes ☐ No ☐	Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

DETAILS OF INJURED PERSON 2

Name:	Approximate Age:
Address:	Postal Code:
Injuries Sustained:	Injured person in which vehicle:
Were seat belt worn? Yes ☐ No ☐	Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

DETAILS OF INJURED PERSON 3

Name:	Approximate Age:
Address:	Postal Code:
Injuries Sustained:	Injured person in which vehicle:
Were seat belt worn? Yes ☐ No ☐	Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

DETAILS OF INJURED PERSON 4

Name:	Approximate Age:
Address:	Postal Code:
Injuries Sustained:	Injured person in which vehicle:
Were seat belt worn? Yes ☐ No ☐	Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

9/3/2018
9:15am


Policyholder's Signature / Date & Time

9/3/2018
9:10am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



- Refer to Police Report T/2018 0309/2001

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20180309/2001

1 of 4

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

Report No. T/20180309/2001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/03/2018 00:21	Vide Report No.: F/20180308/0242	Station Diary No.: 1
--	-------------------------------------	-------------------------

Informant's Particulars

Name of Informant: NG YI TING, PATRICIA			Address: APT BLK 572 HOUGANG STREET 51 #09-37 SINGAPORE 530572		
ID Type / ID No.: NRIC NO / S7834861E			Contact No.: Home/Office: Mobile: 97940887		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 39	Date of Birth: 14/11/1978	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Sales and marketing manager			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/03/2018 21:00	Type of Location: Straight Road
Location: BUANGKOK DRIVE				
Lamp Post Number: 66				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJJ9504H	Car	CITROEN		White	Slightly Damaged	2
SJZ5767H	Car	VOLVO		Black	Slightly Damaged	1
SLS475X	Car	TOYOTA		Silver	Seriously Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS475X	MSIG INSURANCE (SINGAPORE) PTE. LTD.	A29016406	04/09/2017	03/09/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Passenger				
Name	Tan Le Xuan, Shermaine		ID No.	T1008297D
Related Vehicle	SLS475X (Car)		Contact No.	97940887
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	NG YI TING, PATRICIA		ID No.	S7834861E
Related Vehicle	SLS475X (Car)		Contact No.	97940887
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Passenger				
Name	Tan Le Xin, Sherise		ID No.	T1223824F
Related Vehicle	SLS475X (Car)		Contact No.	97940887
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	Slight



**SINGAPORE
POLICE FORCE**



T/20180309/2001

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

3 of 4

Report No. T/20180309/2001

CONTINUATION OF REPORT

Brief Details.

On the 08/03/18 at about 2100hrs, while I was driving my car (SLS475X) along Buangkok Drive towards Buangkok Green, near to L/P 66, I could not stop my car in time and knocked onto the rear side of the car (SJZ5767H) in front of me when the traffic light turns red. My daughter, Tan Le Xin Sherise, was conveyed to KK Hospital as she was feeling dizzy. My other daughter, Tan Le Xuan Shermaine was fine. We were attended by police and was given a case card by TP, IC: Zayid, Ctt: 65476394, report no: F/2018/0308/0242.

20180309	SINGAPORE POLICE FORCE	
SIGNATURE		



**SINGAPORE
POLICE FORCE**



T/20180309/2001

Police Station Of Origin:
Kampong Java N.P.C
21 Kampong Java Road SINGAPORE
228892
Tel No: 1800-2959999

4 of 4

Report No. T/20180309/2001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt NURSYAZRINA BINTE MOHAMMED
FEROZAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt RAZIZ BIN TAHAR

Contact No.: 65476200

Authentication Stamp
NP168

SINGAPORE
POLICE FORCE

SN 167

SIGNATURE

Signature Of Informant:

Date/Time:

09/03/2018 00:21

Classification Of Case:



Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: +6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCU1 Document No 0 Document Date 12/03/2018	Mr Tan Kian Cheong (Chen Jianche 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	2GE20R	04/09/2017	SLS0475X	0	29912 -60D/SLS0475X/09031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES <i>N/A</i> POLICY NO.:A29016406QMY ACC DATE:08/03/18 TOW IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 50 100.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP				✓ 169.50 ✓
3	L	BP-LPO SUPPLY REGN PLATE (PO#)				✓ 80.00 ✓
4	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS				✓ 339.00 ✓
5	B	BP-MECH REPL DASHBOARD ASSY				✓ 1356.00 ✓
6	B	BP-MECH REPL SEAT BELT ASSY				✓ 678.00 ✓
7	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				✓ 678.00 ✓
8	B	BP-MECH REPL AIRBAG SENSOR AND ECU				✓ 169.50 ✓
9	B	BP-MECH R/I ABS UMP AND FUSE TO TO FAC REPAIR ON LH AND RH WHEEL HOUSE				photo. ? 508.50 ✓
10	2	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				✓ 160.00 ✓
11	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				✓ 408 5424.00
12	B	BP-RES RESRPAY ACC AFF AREA				✓ 33% 4448.00
13	1	T16410-37201 RADIATOR ASSY, L/CAP	1.00	1800.20	15.00	? 1530.17 ✓ biv

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
LINK Auto Consultants hence notify the Repairer of the following: • To survey before/after spray painting • To display damaged part(s) during survey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis	Parts		Tariff 97493749
	Labour		EX \$500
	Materials		Revert Not Authorise
	Lubrication/Fluid		sur@linkauto.com
	Others		* Re survey before print
			10 days.
			Amount Due 13/3/18 @ 1630

Tan Kian 97493749
EX \$500
Revert Not Authorised
sure linkauto.com
Re survey before print
10 days.

3621405

3621405

TO SECURITY GUARD

Acknowledged by Repairer

Signature:

DATE 12/03/2018

PLEASE ALLOW THE UNDERMENTIONED

TIME 08:19

VEHICLE TO LEAVE THE COMPANY PREMISES

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATEJoin Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCU1	Mr Tan Kian Cheong (Chen Jianche 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No	
	Document Date	
	0	
	12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	2GE20R	04/09/2017	SLS0475X	0	29912 (60D/SLS0475X/09031)
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	2	T16572-37130 RADIATOR HOSE NO 2,	1.00	43.20	15.00	36.72
15	3	T16573-21090 HOSE, RADIATOR, NO.3	1.00	43.30	15.00	36.80
16	4	T16261-21160 HOSE, WATER BY-PASS	1.00	37.90	15.00	32.21
17	5	T16533-21040 UPP RADIATOR SUPPORT,	2.00	39.00	15.00	66.30
18	6	T16523-21050 CUSHION, RADIATOR	2.00	11.50	15.00	19.54
19	7	T16712-37040 RADIATOR SHROUD FAN 2,	2.00	78.60	15.00	133.62
20	8	T16711-37070 RADIATOR SHROUD FAN,	1.00	221.40	15.00	188.19
21	9	T16361-28360 RADIATOR FAN BLADE 2,	1.00	234.20	15.00	199.07
22	0	T16361-28350 RADIATOR FAN BLADE,	1.00	183.10	15.00	155.63
23	1	T16535-37010 SUPPORT, RADIATOR,	1.00	21.50	15.00	18.27
24	2	T16363-37031 MOTOR, COOLING FAN	1.00	548.90	15.00	466.56
25	3	T16363-37090 MOTOR, COOLING FAN	1.00	548.90	15.00	466.56
26	4	T17751-37080 INLET AIR-CLEANER,	1.00	57.10	15.00	48.53
27	5	T17752-37090 F/INLET AIR CLEANER 2,	1.00	137.00	15.00	116.45
28	6	T17700-37211 AIR CLEANER ASSY,	1.00	950.30	15.00	807.75
29	7	T52119-68909 FRONT BUMPER COVER,	1.00	574.90	15.00	488.66
30	8	T52115-68031 R/FRT BUMPER SUPPORT,	1.00	60.90	15.00	51.76
31	9	T52116-68031 L/FRT BUMPER SUPPORT,	1.00	60.90	15.00	51.76
32	0	T52611-68030 FRT BUMPER ABSORBER,	1.00	89.20	15.00	75.82
33	1	T52021-68020 F/BPR REINFORCEMENT,	1.00	295.70	15.00	251.34

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3621406

TO SECURITY GUARD

3621406

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

Co. Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004/ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HP/MP	S6	ZGE20R	04/09/2017	SLS0475X	0	29912 60D/SLS0475X/090311
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	2	T52030-68010 R/F BUMPER HOLE COVER,	1.00	83.30	15.00	de 70.80 ✓
35	3	T52040-68010 L/F BUMPER HOLE COVER,	1.00	83.30	15.00	2 70.80 ✓
36	4	T52618-68010 F/LOWER BPR ABSORBER,	1.00	125.80	15.00	2 106.93 ✓
37	5	T53149-68010 PROTECTOR RADIATOR	1.00	31.30	15.00	3 26.60 ✓
38	6	T53113-68010 L/F LWR RADIATOR GRILLE,	1.00	55.20	15.00	de 46.92 ✓
39	7	T53112-68030 F/LOW RADIATOR GRILLE,	1.00	55.20	15.00	4 46.92 ✓
40	8	T53101-68010 GRILLE SUB-ASSY,	1.00	401.80	15.00	cr 341.53 ✓
41	9	S52161-0K040 PIECE, RR BUMPER	10.00	3.90	15.00	re 33.10 ✓
42	0	T53811-68060 FENDER SUB-ASSY, RH	1.00	955.90	15.00	bt 812.51 ✓
43	1	T53875-68020 R/FRT FENDER LINER,	1.00	167.10	15.00	up 142.03 ✓
44	2	T53812-68060 FENDER SUB-ASSY, LH	1.00	955.90	15.00	bt 812.51 ✓
45	3	T53876-68020 L/FRT FENDER LINER,	1.00	167.10	15.00	re 142.03 ✓
46	4	T53301-68020 FRONT BONNET ASSY,	1.00	945.30	15.00	bt 803.50 ✓
47	5	T90467-09050 CLIP	6.00	2.30	15.00	rec 11.70 ✓
48	6	T53341-68020 FRT BONNET INSULATOR,	1.00	398.40	15.00	2 338.64 ✓
49	7	T53866-68021 R/F FENDER SEAL COWL,	1.00	33.00	15.00	me 28.05 ✓
50	8	T53867-68021 SEAL, FR FENDER TO	1.00	33.00	15.00	me 28.05 ✓
51	9	T53510-68050 FRONT BONNET LOCK,	1.00	89.80	15.00	bt 76.33 ✓
52	0	T53452-68010 HOLDER, HOOD STAY	1.00	28.30	15.00	x 24.05 ✓
53	1	T53410-68030 R/FRT BONNET HINGE,	1.00	57.10	15.00	bt 48.53 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3621407

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

3621407

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068907 Attn: Motor Claims Dept	S1000004/ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No	
	Document Date	
	0	
	12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	04/09/2017	SLS0475X	0	29912	60D/SLS0475X/090311
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
54	2	T53420-68030 L/FRT BONNET HINGE,	1.00	57.10	15.00	bt 48.53 ✓
55	3	T53292-68020 F/UPPER RADIATOR SEAL,	1.00	89.80	15.00	bt 76.33 ✓
56	4	T53208-68020 F/BRACE LOCK SUPPORT,	1.00	89.80	15.00	bt 76.33 ✓
57	5	T53201-68021 FRT RADIATOR SUPPORT,	1.00	1441.10	15.00	bt 1224.93 ✓
58	6	T53289-68020 F/RADIATOR SEAL COVER,	1.00	62.60	15.00	bt 53.21 ✓
59	7	T53299-68010 L/F RADIATOR SEAL COVER,	1.00	78.60	15.00	bt 66.81 ✓
60	8	T57142-68010 L/FRONT BUMPER ARM,	1.00	49.90	15.00	bt 42.41 ✓
61	9	T57141-68010 R/FRONT BUMPER ARM,	1.00	49.10	15.00	bt 41.73 ✓
62	0	T57117-68010 R/F SIDE MEMBER PLATE,	1.00	99.20	15.00	bt 84.32 ✓
63	1	T57118-68010 L/F SIDE MEMBER PLATE,	1.00	102.20	15.00	bt 86.87 ✓
64	2	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20	15.00	bt 61.37 ✓
65	3	TSUNCY-MOULD SIDE MOULDING	1.00	211.50	15.00	bt 179.77 ✓
66	4	T88450-12280 A/C CONDENSER ASSY,	1.00	1507.40	15.00	bt 1281.29 ✓
67	5	T88710-68051 A/C TUBE & ACCESSORY,	1.00	678.80	15.00	bt 576.98 ✓
68	6	T88703-68060 A/C DISCHARGE HOSE,	1.00	407.90	15.00	bt 346.71 ✓
69	7	T85315-68020 FRONT WASHER JAR,	1.00	57.90	15.00	bt 49.21 ✓
70	8	T45130-68041 B0 PAD ASSY, STEERING	1.00	2402.20	15.00	bt 2041.87 ✓
71	9	T73960-68010 F/INSTRUMENT AIR-BAG,	1.00	3240.20	15.00	bt 2754.17 ✓
72	0	T55302-68901 B0 UPP INSTRUMENT PANEL,	1.00	920.80	15.00	bt 782.68 ✓
73	1	T55550-68020 B0 DOOR ASSY, GLOVE	1.00	419.70	15.00	bt 356.74 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3621408

3621408

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Borneo Motors



Co. Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCU1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 12/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNF	S6	04/09/2017	SLS0475X	0	29912	60D/SLS0475X/09031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	23R1981506	60	Shashitharan		--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
74	2	T73210-68040 C0 BELT, ASSY FR SEAT,	1.00	838.20	15.00	act 712.47 ✓
75	3	T73220-68040 C0 BELT ASSY, FR SEAT	1.00	838.20	15.00	act 712.47 ✓
76	4	T73360-68030 C0 BELT ASSY, NO.1	1.00	526.00	15.00	act 447.10 ✓
77	5	T73370-68030 C0 BELT ASSY, NO.1	1.00	526.00	15.00	act 447.10 ✓
78	6	T81185-68100 UNIT, HEADLAMP LH	1.00	1222.20	15.00	act 1038.87 ✓
79	7	T81145-68100 UNIT, HEADLAMP	1.00	1222.20	15.00	act 1038.87 ✓
80	8	T81210-47010 R/FRONT FOG LAMP ASSY	1.00	300.90	15.00	act 255.76 ✓
81	9	T81220-47010 LAMP ASSY, FOG, LH	1.00	286.00	15.00	act 243.10 ✓
82	0	T89173-59275 SENSOR, AIR BAG, FR	2.00	314.00	15.00	act 533.80 ✓
83	1	T89170-68060 SENSOR ASSY, AIR BAG	1.00	741.00	15.00	act 629.85 ✓
84	2	T84307-74020 CABLE SUB-ASSY <i>spiral cable at steering wheel.</i>	1.00	953.30	15.00	act 810.30 ✓
85	3	T82140-68020 AIR-BAG WIRE ASSY,	1.00	24.10	15.00	act 20.48 ✓

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

(5) 52.61

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 26,375.67	40,486.17
		Labour 14,030.50	GST: 7.00%
		Materials 80.00	2,834.03
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 43,320.20

3621409

PLEASE TEAR ALONG PERFORATED LINE

3621409

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/03/2018
TIME 08:39

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 19 April 2018 3:14 PM
To: 'Shashi PTCBC'; SUR; Taufikh (LKKAUTO)
Subject: RE: SLS475X FINAL BILL

Dear Shashi,

Confirmed final amount \$33,952.41 before excess \$500 and GST

No of days: 10 days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shashi PTCBC [mailto:Shashitharan@borneomotors.com.sg]
Sent: Thursday, 12 April 2018 4:33 PM
To: SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: FW: SLS475X FINAL BILL

Hi gentral reminder to finalize

-----Original Message-----

From: Shashi PTCBC
Sent: Wednesday, April 4, 2018 2:23 PM
To: SUR; 'taufikh@lkkauto.com'
Subject: FW: SLS475X FINAL BILL

-----Original Message-----

From: Shashitharan@borneomotors.com.sg [mailto:Shashitharan@borneomotors.com.sg]
Sent: Wednesday, April 4, 2018 2:21 PM
To: Shashi PTCBC
Subject: SLS475X FINAL BILL

Sent by: B051776 [Shashitharan@borneomotors.com.sg]
Number of Images: 4
Attachment File Type: PDF

Device Name: ApeosPort-V C2276
Device Location:



Co Reg No : 195700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631-1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 04/04/2018	Mr Tan Kian Cheong (Chen Jiancha) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	9440	29912 :60D/SLS0475X/09031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	22R1981506	60	Shashitharan	19/03/2018	8.00	04/04/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES POLICY NO.:A29016406QMY ACC DATE:08/03/18 TOW IN:08/03/18 EXCESS:\$500 DATE-IN:19/03/18 DATE SURVEY:19/03/18 NO OF REPAIR DAYS:10 BY:taufikh AUTHORIZED ON:19/03/18	*			50.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP	*			169.50
3	L	BP-LPO SUPPLY REGN PLATE (PO#)	E33			80.00
4	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS				339.00
5	B	BP-MECH REPL DASHBOARD ASSY				1356.00
6	B	BP-MECH REPL SEAT BELT ASSY				678.00
7	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				678.00
8	B	BP-MECH REPL AIRBAG SENSOR AND ECU				169.50
9	B	BP-MECH R/I ABS UMP AND FUSE TO TO FAC REPAIR ON LH AND RH WHEEL HOUSE				508.50
10	2	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL	*			160.00
11	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	*			4068.00
12	B	BP-RES RESRPAY ACC AFF AREA	*			3336.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623274

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

3623274

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 120462
Tel no.: 6531 1188

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482	
		Document No		
		0		
		Document Date		
		04/04/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP S6	ZGE20R	04/09/2017	SLS0475X	9440	29912	60D/SLS0475X/09031

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W40J007490	22R1981506	60	Shashitharan	19/03/2018 8.00	04/04/2018 18.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	V	EXC Excess element of insurance repair to be paidby the insured party	88			-500.00
14	1	T52119-68909 COVER, FR BUMPER	1.00	574.90	15.00	488.66
15	2	T52115-68031 SUPPORT, FR BUMPER RH	1.00	60.90	15.00	51.76
16	3	T52116-68031 SUPPORT, FR BUMPER LH	1.00	60.90	15.00	51.76
17	4	T52611-68030 ABSORBER FR BUMPER	1.00	89.20	15.00	75.82
18	5	T52021-68020 REINFORCEMENT, FR	1.00	295.70	15.00	251.34
19	6	T52030-68010 COVER, BUMPER HOLE RH	1.00	83.30	15.00	70.80
20	7	T53101-68010 GRILLE, RADIATOR	1.00	401.80	15.00	341.53
21	8	S52161-0K040 PIECE, RR BUMPER	10.00	3.90	15.00	33.10
22	9	T53811-68060 FENDER SUB-ASSY, RH	1.00	955.90	15.00	812.51
23	0	T53812-68060 FENDER SUB-ASSY, LH	1.00	955.90	15.00	812.51
24	1	T53301-68020 HOOD SUB ASSY	1.00	945.30	15.00	803.50
25	2	T90467-09050 CLIP	6.00	2.30	15.00	11.70
26	3	T53510-68050 LOCK ASSY HOOD	1.00	89.80	15.00	76.33
27	4	T53410-68030 HINGE ASSY HOOD RH	1.00	57.10	15.00	48.53
28	5	T53420-68030 HINGE ASSY HOOD LH	1.00	57.10	15.00	48.53
29	6	T53208-68020 SUPPORT HOOD LOCK	1.00	89.80	15.00	76.33
30	7	T53201-68021 SUPPORT SUB ASSY	1.00	1441.10	15.00	1224.93
31	8	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	15.00	61.37

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623275

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

3623275

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: +6631-1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP S6	ZGE20R	04/09/2017	SLS0475X	9440	29912	60D/SLS0475X/090311
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	19/03/2018 8.00	04/04/2018 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	9	TSUNCY-MOULD	1.00	211.50	15.00	179.77
33	0	S88450-02350	1.00	1507.40	15.00	1281.29
34	1	T55302-68901 BO	1.00	920.80	15.00	782.68
35	2	T81185-68100	1.00	1222.20	15.00	1038.87
36	3	T81145-68100	1.00	1222.20	15.00	1038.87
37	4	T89173-59275	2.00	314.00	15.00	533.80
38	5	T16533-21040	2.00	39.00	15.00	66.30
39	6	T16711-37070	1.00	221.40	15.00	188.19
40	7	T16361-28350	1.00	183.10	15.00	155.63
41	8	T16361-28360	1.00	234.20	15.00	199.07
42	9	T16363-37030	1.00	548.90	15.00	466.56
43	0	T16363-37090	1.00	548.90	15.00	466.56
44	1	T17700-37211	1.00	950.30	15.00	807.75
45	2	T53299-68010	1.00	78.60	15.00	66.81
46	3	T84307-74020	1.00	953.30	15.00	810.30
47	4	T16470-37030	1.00	158.80	15.00	134.98 (A)
48	5	T45130-68041 BO	1.00	2402.20	15.00	2041.87
49	6	T73960-68010	1.00	3240.20	15.00	2754.17
50	7	T73210-68040 CO	1.00	838.20	15.00	712.47
51	8	T73220-68040 CO	1.00	838.20	15.00	712.47

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623276

TO SECURITY GUARD

3623276

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 195700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6531 1166

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No	
	Document Date	
	0	
	04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	9440	29912 160D/SLS0475X/09031

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	19/03/2018	8.00	04/04/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	9	T89170-68060 SENSOR ASSY, AIR BAG	1.00	741.00	15.00	629.85
53	0	T82140-68020 WIRE ASSY	1.00	24.10	15.00	20.48
54	1	T53113-68010 GRILLE RADIATOR LWR	1.00	55.20	15.00	46.92
55	2	T53112-68030 GRILLE RADIATOR LWR	1.00	55.20	15.00	46.92
56	3	T53119-68010 PROTECTOR GRILLE	1.00	28.50	15.00	24.22 (A)
57	4	T53149-68010 PROTECTOR RADIATOR	1.00	31.30	15.00	26.60 (B)
58	5	T57141-68010 SUPPORT, FR BUMPER	1.00	49.10	15.00	41.73
59	6	T57142-68010 SUPPORT, FR BUMPER	1.00	49.90	15.00	42.41
60	7	T57117-68010 RETAINER FR BUMPER	1.00	99.20	15.00	84.32
61	8	T57118-68010 RETAINER, FR BUMPER	1.00	102.20	15.00	86.87
62	9	T16410-37201 RADIATOR ASSY, L/CAP	1.00	1800.20	15.00	1530.17

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	33,452.41
		Labour 22,359.91	GST 7.00%
		Materials 11,512.50	2,341.67
		Lubrication/Fluid 80.00	Less
		Others 0.00	0.00
		0.00	Amount Due
			35,794.08

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Mar 2018		12 Mar 2018 16:06 Edit Adj Rpt	S\$33,952.41 Edit Estimates	S\$33,952.41 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAN KIAN CHEONG, ID: 57520553H, Tel: +6591822482								
Vehicle Reg. No.:	SLS475X	Date of Loss:	08/03/2018 21:00 - :59 [6 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 551966	Policy/Cover Note No.:	A29016406QMY (Comprehensive) Coverage: 04/09/2017 - 03/09/2018						
		Excess:	S\$500.00						
Repairer:	Borneo Motors (singapore) Pte Ltd - (pandan) (HQ) Toyota Bodycare Centre, No. 2 Pandan Crescent, 128462 West Coast - Tel: 66311188								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/04/2018]								
Driver/Custodian:	NG YI TING, PATRICIA (39 / Female), NRIC: S7834861E, Tel: +6597940887								
Adj Asg. Remarks:	Please revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (19/04/2018): Alert - Adj Mandate Approved (S\$33952.41) - SLS475X - Claim Handler: Joslin Lim - MSIG_SG (16/03/2018): Alert - Adj Mandate Approved (S\$37538.17) - SLS475X - Claim Handler: Joslin Lim									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS475X (551966)
OD
Mar 8 2018 9:00PM
[TAN KIAN CHEONG]
Borneo Motors (singapore) Pte Ltd - (pandan)

Upload Documents Upload Photos Compose New Letter			View View in Browser v	
Assessment Reports			1 per page v	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	09/03/18 15:44	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 15:56	Adjuster Immediate Advice	 Load HTM	
2	19/04/18 09:21	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 14:27	General View	 Load JPG ☒	
2	14/03/18 14:27	General View	 Load JPG ☒	
3	14/03/18 14:27	General View	 Load JPG ☒	
4	14/03/18 14:27	General View	 Load JPG ☒	
5	14/03/18 14:27	General View	 Load JPG ☒	
6	14/03/18 14:27	General View	 Load JPG ☒	
7	14/03/18 14:27	General View	 Load JPG ☒	
8	14/03/18 14:27	General View	 Load JPG ☒	
9	14/03/18 14:27	General View	 Load JPG ☒	
10	14/03/18 14:27	General View	 Load JPG ☒	
11	14/03/18 14:27	General View	 Load JPG ☒	
12	14/03/18 14:27	General View	 Load JPG ☒	
13	14/03/18 14:27	General View	 Load JPG ☒	
14	14/03/18 14:27	General View	 Load JPG ☒	
15	14/03/18 14:27	General View	 Load JPG ☒	
16	14/03/18 14:27	General View	 Load JPG ☒	
17	14/03/18 14:27	General View	 Load JPG ☒	
18	14/03/18 14:27	General View	 Load JPG ☒	
19	14/03/18 14:27	General View	 Load JPG ☒	
20	14/03/18 14:27	General View	 Load JPG ☒	
21	14/03/18 14:27	General View	 Load JPG ☒	
22	14/03/18 14:27	General View	 Load JPG ☒	
23	14/03/18 14:27	General View	 Load JPG ☒	
24	14/03/18 14:27	General View	 Load JPG ☒	
25	14/03/18 14:27	General View	 Load JPG ☒	
26	14/03/18 14:27	General View	 Load JPG ☒	
27	14/03/18 14:27	General View	 Load JPG ☒	
28	14/03/18 14:27	General View	 Load JPG ☒	
29	14/03/18 14:27	General View	 Load JPG ☒	
30	14/03/18 14:27	General View	 Load JPG ☒	
31	14/03/18 14:27	General View	 Load JPG ☒	
32	14/03/18 14:27	General View	 Load JPG ☒	
33	14/03/18 14:27	General View	 Load JPG ☒	

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
				☒
34	14/03/18 14:27	General View	 Load JPG	☒
35	14/03/18 14:27	General View	 Load JPG	☒
36	14/03/18 14:27	General View	 Load JPG	☒
37	14/03/18 14:27	General View	 Load JPG	☒
38	14/03/18 14:27	General View	 Load JPG	☒
39	14/03/18 14:27	General View	 Load JPG	☒
40	14/03/18 14:27	General View	 Load JPG	☒
41	14/03/18 14:27	General View	 Load JPG	☒
42	14/03/18 14:27	General View	 Load JPG	☒
43	14/03/18 14:27	General View	 Load JPG	☒
44	14/03/18 14:27	General View	 Load JPG	☒
45	14/03/18 14:27	General View	 Load JPG	☒
46	14/03/18 14:27	General View	 Load JPG	☒
47	14/03/18 14:27	General View	 Load JPG	☒
48	14/03/18 14:27	General View	 Load JPG	☒
49	14/03/18 14:27	General View	 Load JPG	☒
50	14/03/18 14:27	General View	 Load JPG	☒
51	14/03/18 14:27	General View	 Load JPG	☒
52	14/03/18 14:27	General View	 Load JPG	☒
53	14/03/18 14:27	General View	 Load JPG	☒
54	14/03/18 14:27	General View	 Load JPG	☒
55	14/03/18 14:27	General View	 Load JPG	☒
56	14/03/18 14:27	General View	 Load JPG	☒
57	14/03/18 14:27	General View	 Load JPG	☒
58	14/03/18 14:27	General View	 Load JPG	☒
59	14/03/18 14:27	General View	 Load JPG	☒
60	14/03/18 14:27	General View	 Load JPG	☒
61	14/03/18 14:27	General View	 Load JPG	☒
62	14/03/18 14:27	General View	 Load JPG	☒
63	14/03/18 14:27	General View	 Load JPG	☒
64	14/03/18 14:27	General View	 Load JPG	☒
65	14/03/18 14:27	General View	 Load JPG	☒
66	14/03/18 14:27	General View	 Load JPG	☒
67	14/03/18 14:27	General View	 Load JPG	☒
68	14/03/18 14:27	General View	 Load JPG	☒
69	14/03/18 14:27	General View	 Load JPG	☒
70	14/03/18 14:27	General View	 Load JPG	☒
71	14/03/18 14:27	General View	 Load JPG	☒
72	14/03/18 14:27	General View	 Load JPG	☒
73	14/03/18 14:27	General View	 Load JPG	☒
74	14/03/18 14:27	General View	 Load JPG	☒
75	14/03/18 14:27	General View	 Load JPG	☒
76	14/03/18 14:27	General View	 Load JPG	☒
77	14/03/18 14:27	General View	 Load JPG	☒
78	14/03/18 14:27	General View	 Load JPG	☒
79	14/03/18 14:27	General View	 Load JPG	☒
80	14/03/18 14:27	General View	 Load JPG	☒
81	14/03/18 14:27	General View	 Load JPG	☒
82	14/03/18 14:27	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
83	14/03/18 14:27	General View		☒
84	14/03/18 14:27	General View		☒
85	14/03/18 14:27	General View		☒
86	14/03/18 14:27	General View		☒
87	14/03/18 14:27	General View		☒
88	14/03/18 14:27	General View		☒
89	14/03/18 14:27	General View		☒
90	14/03/18 14:27	General View		☒
91	14/03/18 14:27	General View		☒
92	14/03/18 14:27	General View		☒
93	14/03/18 14:27	General View		☒
94	14/03/18 14:27	General View		☒
95	14/03/18 14:27	General View		☒
96	14/03/18 14:27	General View		☒
97	14/03/18 14:27	General View		☒
98	14/03/18 14:27	General View		☒
99	14/03/18 14:27	General View		☒
100	14/03/18 14:27	General View		☒
101	14/03/18 14:27	General View		☒
102	14/03/18 14:27	General View		☒
103	14/03/18 14:27	General View		☒
104	14/03/18 14:27	General View		☒
105	14/03/18 14:27	General View		☒
106	14/03/18 14:27	General View		☒
107	14/03/18 14:27	General View		☒
108	14/03/18 14:27	General View		☒
109	14/03/18 14:27	General View		☒
110	14/03/18 14:27	General View		☒
111	14/03/18 14:27	General View		☒
112	14/03/18 14:27	General View		☒
113	14/03/18 14:27	General View		☒
114	14/03/18 14:27	General View		☒
115	14/03/18 14:27	General View		☒
116	14/03/18 14:27	General View		☒
117	14/03/18 14:27	General View		☒
118	14/03/18 14:27	General View		☒
119	14/03/18 14:27	General View		☒
120	14/03/18 14:27	General View		☒
121	14/03/18 14:27	General View		☒
122	14/03/18 14:27	General View		☒
123	14/03/18 14:27	General View		☒
124	14/03/18 14:27	General View		☒
125	14/03/18 14:27	General View		☒
126	14/03/18 14:27	General View		☒
127	04/04/18 17:27	Reinspection Photo		☒
128	04/04/18 17:27	Reinspection Photo		☒
129	04/04/18 17:27	Reinspection Photo		☒
130	04/04/18 17:27	Reinspection Photo		☒
131	04/04/18 17:27	Reinspection Photo		☒
132	04/04/18 17:27	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
133	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
134	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
135	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
136	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
137	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
138	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
139	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
140	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
141	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
142	04/04/18 17:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/03/18 13:39	Borneo email + Estimate	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 14:28	MARK ESTIMATE	 Load PDF	
2	19/04/18 09:17	1ST MARK ESTIMATE	 Load PDF	
3	19/04/18 09:17	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	09/03/18 15:44	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	09/03/18 15:41	Accident Photo	 Load JPG	☒
2	09/03/18 15:41	Accident Photo	 Load JPG	☒
3	09/03/18 15:41	Accident Photo	 Load JPG	☒
4	09/03/18 15:41	Accident Photo	 Load JPG	☒
5	09/03/18 15:41	Accident Photo	 Load JPG	☒
6	09/03/18 15:41	Accident Photo	 Load JPG	☒
7	09/03/18 15:41	Accident Photo	 Load JPG	☒
8	09/03/18 15:41	Accident Photo	 Load JPG	☒
9	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
10	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
11	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
12	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
13	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
14	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
15	09/03/18 15:41	Accident Scene Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Borneo Motors (S) Pte Ltd (Pandan)	Thumbnail	Print
1	09/03/18 15:42	Accident Sketch Plan	 Load JPG	☒
2	09/03/18 15:42	Common Statement	 Load JPG	☒
3	09/03/18 15:42	Police Report	 Load JPG	☒
4	09/03/18 15:42	Police Report	 Load JPG	☒
5	09/03/18 15:42	Police Report	 Load JPG	☒
6	09/03/18 15:42	Police Report	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
7	09/03/18 15:42	Borneo Motors (S) Pte Ltd (Pandan)	 Load JPG	☒
8	09/03/18 15:42	Nric And Driving Licence	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18004710/T1VBQ2

Date: 25/04/2018

REFERENCE

Insured/Claimant:	TAN KIAN CHEONG	Policy No:	A29016406QMY	
Date of Loss:	08/03/2018	Nature of Claim:	OD	Claim No: 551966

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS475X	Engine No:	2ZR1981506
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W40J007490
Reg. Date:	04/09/2017 (Man. Year: 2017)	Odometer:	9516 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$103,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,741.47	22,489.91	4,251.56	15.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,930.50	11,462.50	2,468.00	17.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,671.97	33,952.41	6,719.56	16.52
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	40,171.97	33,452.41	6,719.56	16.73
+ GST 7.00/7.00% (S\$)	2,812.04	2,341.67	470.37	16.73
Nett Amount (S\$)	42,984.01	35,794.08	7,189.93	16.73

INSPECTION

Date of Assignment: 12/03/2018

Date Inspected: 13/03/2018 Inspected At:

Borneo Motors (singapore) Pte Ltd -
(pandan) (HQ)
Toyota Bodycare Centre, No. 2 Pandan
Crescent
Singapore 128462

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLS475X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*REGN PLATE	Bent	80.00 FS	*80.00 FS
3	1		*RADIATOR ASSY,L/CAP	Bent	1,530.17 FS	*1,530.17 FS
4	1		*RADIATOR HOSE NO 2,	Not Necessary	36.72 FS	*- FS
5	1		*HOSE ,RADIATOR ,NO.3	Not Necessary	36.80 FS	*- FS
6	1		*HOSE ,WATER BY-PASS	Not Necessary	32.21 FS	*- FS
7	2		*UPP RADIATOR SUPPORT,	Bent	66.30 FS	*66.30 FS
8	2		*CUSHION ,RADIATOR	Not Necessary	19.54 FS	*- FS
9	2		*RADIATOR SHROUD FAN 2 ,	Serviceable	133.62 FS	*- FS
10	1		*RADIATOR SHROUD FAN,	Deformed	188.19 FS	*188.19 FS
11	1		*RADIATOR FAN BLADE 2,	Cut	199.07 FS	*199.07 FS
12	1		*RADIATOR FAN BLADE,	Cut	155.63 FS	*155.63 FS
13	1		*SUPPORT ,RADIATOR,	Not Necessary	18.27 FS	*- FS
14	1		*MOTOR,COOLING FAN	Distorted	466.56 FS	*466.56 FS
15	1		*MOTOR,COOLING FAN	Distorted	466.56 FS	*466.56 FS
16	1		*INLET AIR-CLEANER	Not Necessary	48.53 FS	*- FS
17	1		*F/INLET AIR CLEANER 2,	Not Necessary	116.45 FS	*- FS
18	1		*AIR CLEANER ASSY ,	Cracked	807.75 FS	*807.75 FS
19	1		*FRONT BUMPER COVER,	Deformed	488.66 FS	*488.66 FS
20	1		*R/FRT BUMPER SUPPORT,	Necessary	51.76 FS	*51.76 FS
21	1		*L/FRT BUMPER SUPPORT,	Necessary	51.76 FS	*51.76 FS
22	1		*FRT BUMPER ABSORBER ,	Cracked	75.82 FS	*75.82 FS
23	1		*F/BPR REINFORCEMENT ,	Bent	251.34 FS	*251.34 FS
24	1		*R/F BUMPER HOLE COVER,	Deformed	70.80 FS	*70.80 FS
25	1		*L/F BUMPER HOLE COVER,	Not Necessary	70.80 FS	*- FS
26	1		*F/LOWER BPR ABSORBER ,	Not Necessary	106.93 FS	*- FS
27	1		*PROTECTOR RADIATOR	Not Necessary	26.60 FS	*- FS
28	1		*L/F LWR RADIATOR GRILLE ,	Deformed	46.92 FS	*46.92 FS
29	1		*F/LOW RADIATOR GRILLE,	Deformed	46.92 FS	*46.92 FS
30	1		*GRILLE SUB-ASSY,	Cracked	341.53 FS	*341.53 FS
31	10		*PIECE ,RR BUMPER	Necessary	33.10 FS	*33.10 FS
32	1		*FENDER SUB-ASSY ,RH	Bent	812.51 FS	*812.51 FS
33	1		*R/FRT FENDER LINER ,	Not Necessary	142.03 FS	*- FS
34	1		*FENDER SUB-ASSY ,LH	Bent	812.51 FS	*812.51 FS
35	1		*L/FRT FENDER LINER ,	Not Necessary	142.03 FS	*- FS
36	1		*FRONT BONNET ASSY ,	Bent	803.50 FS	*803.50 FS
37	6		*CLIP	Necessary	11.70 FS	*11.70 FS
38	1		*FRT BONNET INSULATOR ,	Not Necessary	338.64 FS	*- FS
39	1		*R/F FENDER SEAL COWL ,	Not Necessary	28.05 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SEAL ,FR FENDER TO	Not Necessary	28.05 FS	*- FS
41	1		*FRONT BONNET LOCK ,	Bent	76.33 FS	*76.33 FS
42	1		*HOLDER ,HOOD STAY	Not Necessary	24.05 FS	*- FS
43	1		*R/FRT BONNET HINGE,	Bent	48.53 FS	*48.53 FS
44	1		*L/FRT BONNET HINGE,	Bent	48.53 FS	*48.53 FS
45	1		*F/UPPER RADIATOR SEAL,	Not Necessary	76.33 FS	*- FS
46	1		*F/BRACE LOCK SUPPORT,	Bent	76.33 FS	*76.33 FS
47	1		*FRT RADIATOR SUPPORT,	Bent	1,224.93 FS	*1,224.93 FS
48	1		*F/RADIATOR SEAL COVER,	Not Necessary	53.21 FS	*- FS
49	1		*L/F RADIATOR SEAL COVER,	Deformed	66.81 FS	*66.81 FS
50	1		*L/FRONT BUMPER ARM ,	Bent	42.41 FS	*42.41 FS
51	1		*R/FRONT BUMPER ARM,	Bent	41.73 FS	*41.73 FS
52	1		*R/F SIDE MEMBER PLATE,	Bent	84.32 FS	*84.32 FS
53	1		*L/F SIDE MEMBER PLATE,	Bent	86.87 FS	*86.87 FS
54	1		*TOYOTA SYMBOL EMBLEM ,	Necessary	61.37 FS	*61.37 FS
55	1		*SIDE MOULDING	Necessary	179.77 FS	*179.77 FS
56	1		*A/C CONDENSER ASSY ,	Bent	1,281.29 FS	*1,281.29 FS
57	1		*A/C TUBE & ACCESSORY,	Not Necessary	576.98 FS	*- FS
58	1		*A/C DISCHARGE HOSE,	Not Necessary	346.71 FS	*- FS
59	1		*FRONT WASHER JAR ,	Not Necessary	49.21 FS	*- FS
60	1		*PAD ASSY ,STEERING	Activated	2,041.87 FS	*2,041.87 FS
61	1		*F/INSTRUMENT AIR-BAG,	Activated	2,754.17 FS	*2,754.17 FS
62	1		*UPP INSTRUMENT PANEL,	Activated	782.68 FS	*782.68 FS
63	1		*DOOR ASSY ,GLOVE	Not Necessary	356.74 FS	*- FS
64	1		*BELT ,ASSY FR SEAT,	Activated	712.47 FS	*712.47 FS
65	1		*BELT ,ASSY FR SEAT,	Activated	712.47 FS	*712.47 FS
66	1		*BELT ASSY,NO.1	Not Necessary	447.10 FS	*- FS
67	1		*BELT ASSY,NO.1	Not Necessary	447.10 FS	*- FS
68	1		*UNIT ,HEADLAMP LH	Cracked	1,038.87 FS	*1,038.87 FS
69	1		*UNIT ,HEADLAMP	Cracked	1,038.87 FS	*1,038.87 FS
70	1		*R/FRONT FOG LAMP ASSY	Not Necessary	255.76 FS	*- FS
71	1		*LAMP ASSY ,FOG,LH	Not Necessary	243.10 FS	*- FS
72	2		*SENSOR,AIR BAG,FR	Activated	533.80 FS	*533.80 FS
73	1		*SENSOR ASSY,AIR BAG	Activated	629.85 FS	*629.85 FS
74	1		*CABLE SUB-ASSY	Activated	810.30 FS	*810.30 FS
75	1		*AIR-BAG WIRE ASSY ,	Activated	20.48 FS	*20.48 FS
76	1		*TANK ASSY ,RESERVE	Deformed	134.98 FS	*134.98 FS
77	1		*PROTECTOR GRILLE	Deformed	24.22 FS	*24.22 FS
78	1		*PROTECTOR RADIATOR	Deformed	26.60 FS	*26.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	26,741.47	22,489.91
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP	New	169.50	169.50
2	R/I AIRCOND PIPE VACCUM AND REGAS	New	339.00	339.00
3	REPL DASHBOARD ASSY	New	1,356.00	1,356.00
4	REPL SEAT BELT ASSY	New	678.00	678.00
5	RESET ECU UPON COMPLETION OF REPAIR	New	678.00	678.00
6	REPL AIRBAG SENSOR AND ECU	New	169.50	169.50
7	R/I ABS UMP AND FUSE TO FAC REPAIR ON LH AND RH WHEEL HOUSE	New	508.50	508.50
8	SUPPLY SEALANT (NETT) 2 PANEL	New	160.00	160.00
9	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	5,424.00	4,068.00
10	RESPRAY ACC AFF AREA	New	4,448.00	3,336.00
Gross Labour Cost (S\$)			13,930.50	11,462.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >