

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3057G

DATE 3/10/2018 10:30

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Retainer ?		\$ 9.20	\$ 18.40
	SUB TOTAL			\$ 1,783.70
	LESS 20%			\$ 356.74
	DISCOUNTED TOTAL			\$ 1,426.96
	Labour Charge			220
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00 180
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 1,976.96
<p>Kahin 1/1/16</p> <p>12/3/18 1025h</p> <p>2 Aug</p> <p>4/5</p> <p>After Repair p LH</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.</p>				

Date: