

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 3267S

DATE 3/10/2018 10:13

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Reinforcement ?			\$ 504.10
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Protector (LH) x 4			\$ 29.20
	Headlamp (LH) ✓			\$ 797.90
	Front Fender (LH) ✓			\$ 593.00
	Front Fender Shield (LH) x			\$ 86.00
	Front Fender Retainer (LH) x			\$ 9.20
	Front Wheel Hub Cap (LH) x			\$ 145.00
	<b>SUB TOTAL</b>			<b>\$ 2,861.90</b>
	<b>LESS 20%</b>			<b>\$ 572.38</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,289.52</b>
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00 <b>Nett</b>
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			<b>440</b>
	Panel Beating			\$ <del>560.00</del>
	Spray Painting Charge			\$ <del>400.00</del> 360
	Wiring Charge			\$ <del>30.00</del> 20
	Tuff Kote			\$ <del>50.00</del> 20
	FRT Wheel Alignment			\$ <del>80.00</del> x
	<b>TOTAL LABOUR</b>			<b>\$ 1,120.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,509.52</b>
<p>Kalari 11/11/14</p> <p>12/3/18 1045h.</p> <p>3 Pys</p> <p>4/5</p> <p>After Repair phh</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: _____ Date: _____</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				