

22/03/2018

ASS. REC. BY:

REF: CS/MSG18004724/T11d301 Special Instruction:

Surveyor: Taufik
Meningin

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSIG

Date/Time: 12/3/18 @ 4:50pm

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7 CS

Insured:

SKQ 1810C

To Inspect Vehicle No:

EC 800H

Tel:

97 68 4247

at Workshop m/s

Auto Wheels Motorworks

of

No. 1, Bkt Batok Crescent #02-40

Policy No:

A80417468AVW

Claim No:

551967

Sum Insured:

Excess:

D.O.A. 9/3/2018

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

10:10am 13/3/18

Person Contacted:

Louis

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	EC 800H-X
	SKQ 1810C-X
	Part by Part \$7,686.27 (red: 3281.18 : 30%)

Tanpin

MSIG

Date 13/3/2018

EC 800H

2011 Aug 12

Estimated Cost:

OD (TP) NS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No

EC 800H

at Workshop this

Auto wheels

of No. 1, Bkt Batok Crescent #02-40

Insured

Policy No

Claims No

Sum Insured

Excess

Client's Record

Make of Van

Louis

91928963

(Policy Condition

Remark: The van had commenced its repair at the time of inspection.

NS	CIS

Sal. or Market Value

OD Accident Report Consistent? : Yes or No

OD PR Seen Consistent? : Yes or No

Est. Repairs days Res: Yes or No

Sum Sum % 3 Year: Yes or No

CA / REV / REP. / 24 HRS w/p

Vehicle IN / OUT

Date Person Contacted

Date Time Action Instruction

RECEIVED 23 MAY 2018

Date Time File Possibility

☐ Prelim. Report
☐ Final Report

Days Of Repair

7

Resurvey No. of Trip

2

Add Fee:

☐ Step 1
☐ Step 2
☐ Step 3
☐ Step 4

Step 1

Step 2

Step 3

Step 4

Surve Fee

300

Inspection Fee

10

10

10

10

10

300

Report Format

Sum Sum

7686.27

Type of Van: Major Business Van, Taxi, Private Motor

Truck Trailer:

Make

BMW X8I

2996

Colour

Gold

Insured: Std. N/A

So Reading

77752

Insured: Std. N/A

Eng No

WBAFR12030C945006

C No

Gen Cond: Good Fair Poor Burnt

Steering: Good Jammed Leaked Burnt

Brake: Good Jammed Leaked Burnt

Mod No: STD A/R

Tyre Size

285/30R20

BS/DUN/EKNOVA/GY/PS/LIZA/MC/OHTSU/PR/SUM/TOYO/YOKO

Front

Rear

R.Ba

6

--

R.Ba

6

--

L.Ba

6

--

L.Ba

6

--

D.O.A

D.O

13/3/18 @ 2pm

Survey Method

Auto wheels

Des of Damages: Fr. Rear CS NS UC Roofed

Rear N/S

The UO: Chassis frame Body Structure affected due to CS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Mar 2018		12 Mar 2018 16:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIM KIAN LIN, ID: S1286792A, Tel: +6592763081, Email: skianlin@gmail.com		
Main Claimant:	PHANG HAN CHUEN, ID: S7211132Z		
Vehicle Reg. No.:	EC800H	Date of Loss:	09/03/2018 08:00 - :59
Claim Type:	TP / 551967	Policy/Cover Note No.:	A80417468AVW (Comprehensive) Coverage: 10/11/2017 - 09/11/2018
Vehicle Reg. No. (Insured):	SKQ1810C	Policy No. (Claimant):	
		Excess:	\$500.00
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 13/03/2018]		
Driver/Custodian (Insured):	SIM KIAN LIN (59 / Male), NRIC: S1286792A, Tel: +6592763081		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Hasrianah Binte Hassan

From: Woon Choo Kwok
Sent: Monday, 12 March, 2018 10:37 AM
To: Elaine Ngu; Hasrianah Binte Hassan
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: Accident involved with vehicle EC800H and SKQ1810C(TP) on 9/3/2018 along AYE towards ECP
Attachments: GIA.pdf; LTA SEARCH.jpg

Dear EN & HAS

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msigg-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Monday, March 12, 2018 9:43 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msigg-asia.com>
Subject: FW: Accident involved with vehicle EC800H and SKQ1810C(TP) on 9/3/2018 along AYE towards ECP

From: Louis Ong [<mailto:louisongautowheels@yahoo.com>]
Sent: 09 March 2018 20:28
To: Claims <claims@sg.msigg-asia.com>
Cc: Tan Jin Hao <jinhao_tan@sg.msigg-asia.com>
Subject: Accident involved with vehicle EC800H and SKQ1810C(TP) on 9/3/2018 along AYE towards ECP

Hi,

We would like to do a Direct Settlement with you if our liability is 100%.

Can advise us on the liability and arrange for survey.

We would like LKK to survey the vehicle.

Thanks

Auto Wheels Motorworks
Louis Ong
91928963



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004724/T1td3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 1810C	Veh. Inspected	EC 800H
Policy No.	A80417468AVW	Coverage (\$)	0.00
Claim No.	551967	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/03/2018	Inspection Date	13/03/2018
Survey held at	AUTO WHEELS MOTORWORKS PTE LTD NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/03/2018 15:18
Date Of Accident 09/03/2018 08:00
Exact Location Of Accident AYE TWD ECP
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number EC800H
Insured/Policyholder
Name Of Registered Owner PHANG HAN CHUEN
NRIC No S7211132Z
Email Address CELEST.CHOO@LION.COM
Mobile Phone No (LOCAL) +65-91099104
Alternative Phone No OFFICE-91099104

Vehicle Particulars

Manufacturer BMW
Model 528I-3.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 2018-V800184
Cover Note Number

Driver

Name of Driver CHOO CHUI YUEN
NRIC No S7215935G
Date Of Birth 09/05/1972
Occupation INDOOR
Date Of Driving Pass 17/01/2001
Driving Experience 17 YEARS AND 1 MONTH
Gender FEMALE
Mobile Number
Fax Number
Contact Number
Email Address NOEMAIL

Address

BLK 129 PENDING RD #09-336

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKQ1810C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident along AYE Towards ECP (near lamp pole 464).

Time of collision at about 8am on 9 March 2018

Vehicle B collided onto Vehicle A on filter lane ~~for~~ on AYE toward ECP

Vehicle A camera recorded incident took place

Vehicle A (EC500H) claim against ~~Vehicle B~~ Vehicle B (SKQ 1810C)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

STJ/11322
Phang Han Chuen

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: S. K. N.
NRIC/FIN No.: 020445H

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Phang Han Chuen
S78 11132 Z

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: S. H. N.
NRIC/FIN No.: 020694911



AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: MSIG INSURANCE

DATE: 12/3/2018
VEHICLE NO: EC800H
MODEL: BMW 528i
YEAR: 2011
ACCIDENT DATE: 9/3/2018
TYPE OF CLAIM: TP SKQ1810C
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	
REAR BUMPER	1	\$ 1,645.80 <i>de ✓</i>
REAR BUMPER CLIPS	10	\$ 50.00 <i>ae ✓</i>
LH REAR BUMPER RETAINER	1	\$ 255.70 <i>ae ✓</i>
REAR BUMPER CENTRE BRACKET	1	\$ 294.70 <i>? ch ✓</i>
LH REAR BUMPER REFLECTOR	1	\$ 168.40 <i>out ✓</i>
REVERSE SENSOR	4	\$ 1,020.40 <i>Runt ✓</i>
LH REAR FENDER	1	RESTORE
REAR REINFORCEMENT	1	782.40 <i>Runt ✓</i>
END PANEL	1	\$ 1,120.10 <i>Ro x</i>
LH REAR ABS SENSOR	1	\$ 345.20 <i>Runt ✓</i>
REAR EXHAUST PIPE	1	\$ 1,972.40 <i>bt ✓</i>
REAR EXHAUST PIPE FINISHER	2	\$ 664.40 <i>dd ✓</i>
REAR EXHAUST PIPE MOUNTING	2	\$ 88.60 <i>th ✓</i>
REAR EXHAUST PIPE HEATER SHIELD	1	\$ 345.80 <i>R ✓</i>
REAR EXHAUST PIPE BRACKET	2	\$ 112.80 <i>R } an x</i>
FRONT DRIVER SEAT BELT	1	\$ 715.60 <i>R ✓</i>
FRONT DRIVER SEAT BELT BUCKLE	1	\$ 456.10 <i>R ✓</i>
FRONT DRIVER HEADREST SENSOR	1	\$ 345.50 <i>? aut ✓</i>
PASSENGER SEAT BELT	1	\$ 715.60 <i>R ✓</i>
PASSENGER SEAT BELT BUCKLE	1	\$ 456.10 <i>R ✓</i>
PASSENGER HEADREST SENSOR	1	\$ 345.50 <i>? aut ✓</i>

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

TOTAL:	\$	5,337.50	11901.10
DISCOUNT 5%:	\$	266.88	
	\$	5,070.63	11306.04

S/NET
LH REAR TYRE

1

	\$	500.00	X nn
TOTAL:		\$500.00	

LABOUR

LABOUR FOR FACILITATE REPAIR
TO RESPRAY BOOTLID
TO RESRAY LH REAR FENDER
TO RESPRAY REAR BUMPER
TO RESPRAY END PANEL
TO CHECK AND RECONNECT ALL NECESSARY WIRING
FACILITATE REPAIR
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
TO REMOVE AND RESET LH ABS SENSOR
TO REMOVE AND REFIT AND RESET SEAT BELT WARNING LIGHT
TO REMOVE AND REFIT AND RESET AIRBAG WARNING LIGHT
TO REMOVE AND REFIT REAR EXHAUST PIPE
SUNDARIES
RUST PROOFING

PRICE

\$	2,000.00	800
\$	300.00	200
\$	300.00	X nn
\$	300.00	200
\$	300.00	200
\$	50.00	30
\$	200.00	80
\$	100.00	30
\$	250.00	100
\$	250.00	200
\$	500.00	
\$	500.00	80
\$	80.00	30
\$	100.00	30

TOTAL: \$ 5,230.00

TOTAL:	\$	10,800.63
7% GST:	\$	756.04
	\$	11,556.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

- WP

13/3/18 @ 2pm

7 days

* Resurvey before paint

sur@lkkauto.com

* Bring check items

17202.86

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: MSIG INSURANCE

DATE: 12/3/2018
VEHICLE NO: EC800H
MODEL: BMW 528i
YEAR: 2011
ACCIDENT DATE: 9/3/2018
TYPE OF CLAIM: TP SKQ1810C
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

SUPPLEMENTARY

DESCRIPTION	QTY	LIST PRICE
PARTS		
REAR EXHAUST PIPE CLAMP KIT	1	\$ 175.60 <i>bt✓</i>

TOTAL:	\$	175.60
DISCOUNT 5%	\$	8.78
	\$	<u>166.82</u>

PARTS - \$166.82 + \$5,539.45 = \$5,706.27

S/NET - \$0

LABOUR - \$1,980

TOTAL - \$7,686.27 (7 DAYS) PART BY PART

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT DATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: MSIG INSURANCE

DATE: 12/3/2018
VEHICLE NO: EC800H
MODEL: BMW 528I
YEAR: 2011
ACCIDENT DATE: 9/3/2018
TYPE OF CLAIM: TP SKQ1810C
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisngautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS	1	
BOOTLID	1	\$ - 1,645.80 <i>de</i>
REAR BUMPER	10	\$ - 50.00 <i>ae</i>
REAR BUMPER CLIPS	1	\$ - 255.70 <i>ae</i>
LH REAR BUMPER RETAINER	1	\$ ✓ 294.70 ? <i>crack</i>
REAR BUMPER CENTRE BRACKET	1	\$ - 168.40 <i>mt</i>
LH REAR BUMPER REFLECTOR	4	\$ x 1,020.40 ?
REVERSE SENSOR	1	
LH REAR FENDER	1	\$ x 782.40 ? <i>R x</i>
REAR REINFORCEMENT	1	\$ x 1,120.10 <i>R</i>
END PANEL	1	\$ x 345.20 ?
LH REAR ABS SENSOR	1	\$ - 1,972.40 <i>bt</i>
REAR EXHAUST PIPE	2	\$ - 664.40 <i>dt</i>
REAR EXHAUST PIPE FINISHER	2	\$ - 88.60 ?
REAR EXHAUST PIPE MOUNTING	2	\$ x 345.80 ?
REAR EXHAUST PIPE HEATER SHIELD	1	\$ x 112.80 ?
REAR EXHAUST PIPE BRACKET	2	\$ x 715.60 ?
FRONT DRIVER SEAT BELT	1	\$ x 456.10 ?
FRONT DRIVER SEAT BELT BUCKLE	1	\$ ✓ 345.50 ? ✓
FRONT DRIVER HEADREST SENSOR	1	\$ x 715.60 ?
PASSENGER SEAT BELT	1	\$ x 456.10 ?
PASSENGER SEAT BELT BUCKLE	1	\$ ✓ 345.50 ?
PASSENGER HEADREST SENSOR	1	

AUTO WHEELS

MOTORWORKS PTE LTD

NO. 1 BUKIT BATOK CRESCENT #01-00

WHEEL PLAZA SINGAPORE 658064

TOTAL: \$ 5,337.50
DISCOUNT 5%: \$ 266.88
\$ 5,070.63

\$5,831

\$ 291.55

\$ 5,539.45

S/NET
LH REAR TYRE

1

TOTAL: \$ 500.00X
\$500.00

LABOUR

LABOUR FOR FACILITATE REPAIR

TO RESPRAY BOOTLID

TO RESRAY LH REAR FENDER

TO RESPRAY REAR BUMPER

TO RESPRAY END PANEL

TO CHECK AND RECONNECT ALL NECESSARY WIRING

FACILITATE REPAIR

TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR

TO REMOVE AND REFIT REVERSE SENSOR

TO REMOVE AND RESET LH ABS SENSOR

TO REMOVE AND REFIT AND RESET SEAT BELT WARNING LIGHT

TO REMOVE AND REFIT AND RESET AIRBAG WARNING LIGHT

SUNDARIES

RUST PROOFING

PRICE

\$ 2,000.00 800

\$ 300.00 200

\$ X 300.00 X

\$ 300.00 200

\$ 300.00 200

\$ 50.00 30

\$ 200.00 80

\$ 100.00 30

\$ 250.00 100

\$ 250.00 200

\$ 500.00 200

\$ 500.00 80

\$ 80.00 30

\$ 100.00 30

TOTAL: \$ 5,230.00

1980

TOTAL: \$ 10,800.63

7% GST: \$ 756.04

\$ 11,556.67

Tanfilm 97495749
WP

13/5/18 @ 2pm

7 days

* Respray before paint

sur@lkkauto.com

* Respray check items

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: MSIG INSURANCE

DATE: 12/3/2018
VEHICLE NO: EC800H
MODEL: BMW 528I
YEAR: 2011
ACCIDENT DATE: 9/3/2018
TYPE OF CLAIM: TP SKQ1810C
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

SUPPLEMENTARY

DESCRIPTION	QTY	LIST PRICE
PARTS	1	\$ 175.60 ✓ Bt
REAR EXHAUST PIPE CLAMP KIT		

TOTAL:	\$	175.60
DISCOUNT 5%	\$	8.78
	\$	<u>166.82</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Pending for Survey Report
Main	09 Mar 2018		12 Mar 2018 16:50 Edit Adj Rpt	S\$7,686.27 Edit Estimates	S\$7,686.27 View Rpt		Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SIM KIAN LIN , ID: S1286792A, Tel: +6592763081, Email: skianlin@gmail.com									
Main Claimant: PHANG HAN CHUEN , ID: S72111322									
Vehicle Reg. No.: EC800H		Date of Loss: 09/03/2018 08:00 - :59 [78 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 551967		Policy/Cover Note No.: A80417468AVW (Comprehensive) Coverage: 10/11/2017 - 09/11/2018							
Vehicle Reg. No. (Insured): SKQ1810C		Policy No. (Claimant): Excess: S\$500.00							
Repairer: Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 13/03/2018]									
Driver/Custodian (Insured): SIM KIAN LIN (59 / Male) , NRIC: S1286792A, Tel: +6592763081									
ASSOCIATED MAIL RECEIVED				View All					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All									
Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EC800H (551967)
[SKQ1810C]
TP
PHANG HAN CHUEN
Mar 9 2018 8:00AM
[SIM KIAN LIN]
Auto Wheels Motorworks Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

1 per page

Assessment Reports			Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
1	12/03/18 16:39	Accident Statement From: OD - Reg. No: SKQ1810C, Claimant: SIM KIAN LIN	1 Load HTM	

3 per page

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	22/05/18 15:33	General View	1 Load JPG	
2	22/05/18 15:33	General View	1 Load JPG	
3	22/05/18 15:33	General View	1 Load JPG	
4	22/05/18 15:33	General View	1 Load JPG	
5	22/05/18 15:33	General View	1 Load JPG	
6	22/05/18 15:33	General View	1 Load JPG	
7	22/05/18 15:33	General View	1 Load JPG	
8	22/05/18 15:33	General View	1 Load JPG	
9	22/05/18 15:33	General View	1 Load JPG	
10	22/05/18 15:33	General View	1 Load JPG	
11	22/05/18 15:33	General View	1 Load JPG	
12	22/05/18 15:33	General View	1 Load JPG	
13	22/05/18 15:33	General View	1 Load JPG	
14	22/05/18 15:33	General View	1 Load JPG	
15	22/05/18 15:33	General View	1 Load JPG	
16	22/05/18 15:33	General View	1 Load JPG	
17	22/05/18 15:33	General View	1 Load JPG	
18	22/05/18 15:34	General View	1 Load JPG	
19	22/05/18 15:34	General View	1 Load JPG	
20	22/05/18 15:34	General View	1 Load JPG	
21	22/05/18 15:34	General View	1 Load JPG	
22	22/05/18 15:34	General View	1 Load JPG	
23	22/05/18 15:34	General View	1 Load JPG	
24	22/05/18 15:34	General View	1 Load JPG	
25	22/05/18 15:34	General View	1 Load JPG	
26	22/05/18 15:34	General View	1 Load JPG	
27	22/05/18 15:34	General View	1 Load JPG	
28	22/05/18 15:34	General View	1 Load JPG	
29	22/05/18 15:34	General View	1 Load JPG	
30	22/05/18 15:34	General View	1 Load JPG	
31	22/05/18 15:34	General View	1 Load JPG	
32	22/05/18 15:34	General View	1 Load JPG	
33	22/05/18 15:34	General View	1 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	22/05/18 15:34	General View	 Load JPG	☒
35	22/05/18 15:34	General View	 Load JPG	☒
36	22/05/18 15:34	General View	 Load JPG	☒
37	22/05/18 15:34	General View	 Load JPG	☒
38	22/05/18 15:34	General View	 Load JPG	☒
39	22/05/18 15:34	General View	 Load JPG	☒
40	22/05/18 15:34	General View	 Load JPG	☒
41	22/05/18 15:34	General View	 Load JPG	☒
42	22/05/18 15:34	General View	 Load JPG	☒
43	22/05/18 15:34	General View	 Load JPG	☒
44	22/05/18 15:34	General View	 Load JPG	☒
45	22/05/18 15:34	General View	 Load JPG	☒
46	22/05/18 15:34	General View	 Load JPG	☒
47	22/05/18 15:34	General View	 Load JPG	☒
48	22/05/18 15:34	General View	 Load JPG	☒
49	22/05/18 15:34	General View	 Load JPG	☒
50	22/05/18 15:34	General View	 Load JPG	☒
51	22/05/18 15:34	General View	 Load JPG	☒
52	22/05/18 15:34	General View	 Load JPG	☒
53	22/05/18 15:34	General View	 Load JPG	☒
54	22/05/18 15:34	General View	 Load JPG	☒
55	22/05/18 15:34	General View	 Load JPG	☒
56	22/05/18 15:34	General View	 Load JPG	☒
57	22/05/18 15:34	General View	 Load JPG	☒
58	22/05/18 15:34	General View	 Load JPG	☒
59	22/05/18 15:34	General View	 Load JPG	☒
60	22/05/18 15:34	General View	 Load JPG	☒
61	22/05/18 15:34	General View	 Load JPG	☒
62	22/05/18 15:34	General View	 Load JPG	☒
63	22/05/18 15:34	General View	 Load JPG	☒
64	22/05/18 15:34	General View	 Load JPG	☒
65	22/05/18 15:34	General View	 Load JPG	☒
66	22/05/18 15:34	General View	 Load JPG	☒
67	22/05/18 15:34	General View	 Load JPG	☒
68	22/05/18 15:34	General View	 Load JPG	☒
69	22/05/18 15:34	General View	 Load JPG	☒
70	22/05/18 15:34	General View	 Load JPG	☒
71	22/05/18 15:34	General View	 Load JPG	☒
72	22/05/18 15:34	General View	 Load JPG	☒
73	22/05/18 15:34	General View	 Load JPG	☒
74	22/05/18 15:34	General View	 Load JPG	☒
75	22/05/18 15:34	General View	 Load JPG	☒
76	22/05/18 15:34	General View	 Load JPG	☒
77	22/05/18 15:34	General View	 Load JPG	☒
78	22/05/18 15:34	General View	 Load JPG	☒
79	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
80	22/05/18 15:36	Reinspection Photo	Load JPG	☒
81	22/05/18 15:36	Reinspection Photo	Load JPG	☒
82	22/05/18 15:36	Reinspection Photo	Load JPG	☒
83	22/05/18 15:36	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
85	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
86	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
87	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
88	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
89	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
90	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
91	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
92	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
93	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
94	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
95	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
96	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
97	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
98	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
99	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
100	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
101	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
102	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
103	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
104	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
105	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
106	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
107	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
108	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
109	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
110	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
111	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
112	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
113	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
114	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
115	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
116	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
117	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
118	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
119	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
120	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
121	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
122	22/05/18 15:36	Reinspection Photo	 Load JPG	☒
123	22/05/18 15:37	Photo Before Spray	 Load JPG	☒
124	22/05/18 15:37	Photo Before Spray	 Load JPG	☒
125	22/05/18 15:37	Photo Before Spray	 Load JPG	☒
126	22/05/18 15:38	Photo After Spray	 Load JPG	☒
127	22/05/18 15:38	Photo After Spray	 Load JPG	☒
128	22/05/18 15:38	Photo After Spray	 Load JPG	☒
129	22/05/18 15:38	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/03/18 16:39	EC800H GIA Rpt	 Load PDF	
2	12/03/18 16:39	TP EC800H GIA report	 Load PDF	

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ) From: OD - Reg. No: SKQ1810C, Claimant: SIM KIAN LIN		Load PDF
3	12/03/18 16:48	Email frm TP - PRI		
			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Load PDF
1	28/05/18 14:09	Supplementary		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004724/T1TD3E2
Date: 28/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80417468AVW

Claimant Vehicle No: EC800H

Insured Vehicle No: SKQ1810C

Date of Loss: 09/03/2018

Nature of Claim: TP

Claim No: 551967

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EC800H**
Make & Model: BMW 528i, 3.0 (A)
Reg. Date: 12/08/2011 (Man. Year: 2011)
Colour: Gold
Engine Capacity: 2996 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HIDDEN
Chassis No: WBAFR12030C945006
Odometer: 77752 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):
Handbrake (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Yes
No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/30 R20
Front Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm

Rear Tyre Size: 285/30 R20
Rear Left Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,052.86	5,736.27	6,316.59	52.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	1,950.00	3,200.00	62.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,202.86	7,686.27	9,516.59	55.32
+ GST 7.00/7.00% (S\$)	1,204.20	538.04	666.16	55.32
Nett Amount (S\$)	18,407.06	8,224.31	10,182.75	55.32

INSPECTION

Date of Assignment: 12/03/2018
Date Inspected: 13/03/2018 Inspected At:

Auto Wheels Motorworks Pte Ltd (HQ)
No.1 Bukit Batok Crescent, #02-40
WCEGA PLAZA
Singapore 658064

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2018)
 Parts: 143 BMW 528I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for EC800H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID (NPA)	Repair	0.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	1,645.80 FL	*1,645.80 FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*LH REAR BUMPER RETAINER	Necessary	255.70 FL	*255.70 FL
5	1		*LH REAR BUMPER REFLECTOR	Cut	168.40 FL	*168.40 FL
6	4		*REVERSE SENSOR	Not Necessary	1,020.40 FL	*- FL
7	1		*LH REAR FENDER (NPA)	Repair	0.00 FL	*- FL
8	1		*REAR REINFORCEMENT	Not Necessary	782.40 FL	*- FL
9	1		*END PANEL	Repair	1,120.10 FL	*- FL
10	1		*LH REAR ABS SENSOR	Not Necessary	345.20 FL	*- FL
11	1		*REAR EXHAUST PIPE	Bent	1,972.40 FL	*1,972.40 FL
12	2		*REAR EXHAUST PIPE FINISHER	Dented	664.40 FL	*664.40 FL
13	2		*REAR EXHAUST PIPE MOUNTING	Bent	88.60 FL	*88.60 FL
14	1		*REAR EXHAUST PIPE HEATER SHIELD	Not Necessary	345.80 FL	*- FL
15	2		*REAR EXHAUST PIPE BRACKET	Not Necessary	112.80 FL	*- FL
16	1		*FRONT DRIVER SEAT BELT	Not Necessary	715.60 FL	*- FL
17	1		*FRONT DRIVER SEAT BELT BUCKLE	Not Necessary	456.10 FL	*- FL
18	1		*FRONT DRIVER HEADREST SENSOR	Activated	345.50 FL	*345.50 FL
19	1		*PASSENGER SEAT BELT	Not Necessary	715.60 FL	*- FL
20	1		*PASSENGER SEAT BELT BUCKLE	Not Necessary	456.10 FL	*- FL
21	1		*PASSENGER HEADREST SENSOR	Activated	345.50 FL	*345.50 FL
22	1		*LH REAR TYRE	Not Necessary	500.00 FS	*- FS
23	1		*SUNDRIES	Necessary	80.00 FS	*30.00 FS
24	1		*REAR EXHAUST PIPE CLAMP KIT	Bent	175.60 FL	*175.60 FL
25	1		*REAR BUMPER CENTRE BRACKET	Cracked	294.70 FL	*294.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,656.70 6,036.60

- List Item Discount on L Items 5.00/5.00% (\$\$) 603.84 300.33

Total Parts (\$\$) 12,052.86 5,736.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR FACILITATE REPAIR	New	2,000.00	800.00
2	TO RESPRAY BOOTLID	New	300.00	200.00
3	TO RESPRAY LH REAR FENDER	New	300.00	0.00
4	TO RESPRAY REAR BUMPER	New	300.00	200.00
5	TO RESPRAY END PANEL	New	300.00	200.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRING FACILITATE REPAIR	New	50.00	30.00
7	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	New	200.00	80.00
8	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	30.00
9	TO REMOVE AND RESET LH ABS SENSOR	New	250.00	100.00
10	TO REMOVE AND REFIT AND RESET SEAT BELT WARNING LIGHT }	New	250.00	200.00
11	TO REMOVE AND REFIT AND RESET AIRBAG WARNING LIGHT}	New	500.00	0.00
12	TO REMOVE AND REFIT REAR EXHAUST PIPE	New	500.00	80.00
13	RUST PROOFING	New	100.00	30.00
Gross Labour Cost (S\$)			5,150.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >