

ONE SINGAPORE 038987

R/H Rear Tyre

L/H Rear Tyre

SKG 8766D

1.

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R Page No.:1 of 1

ECICS LTD	Ref:	CS3/ICS18004726/Wbe2	
7 TEMASEK BOULEVARD#10-01 SUNTEC TOWER	Date:	08-05-2018	

Veh. Inspected

Code. 100
Policy Particulars :- (THIRD PARTY CLAIM)


			Tom mopositus			
	Policy No.		Coverage (\$)	0.00		
	Claim No.	DMPC1800091H	Excess (\$)	0.00		
	Assign From	JANICE GOH	Assign Date	13/03/2018		
2.		Vehicle Parti	iculars & Condition			
	Make & Model	TOYOTA LEXUS RX270	c.c	2672		
	Engine No.	HIDDEN	Year of Reg.	2013		
	Chassis No.	JTJZA11A602019333	Colour	DARK GREY		
	Odometer	118434 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	235/60 R18	NEXEN	4 mm		
	L/H Front Tyre	235/60 R18	NEXEN	4 mm		

4. **Description of Damages**

235/60 R18

235/60 R18

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.



4 mm

SKH 8870E

	5.	General Information					
Acciden		Accident Date	10/03/2018	Inspect Date / Time	13/03/2018 (12:00 PM)		
		Survey held at	160 SIN MING DRIVE #05-17				
		Repairer	HIAP LEK AUTOMOBILE TRADING				

NEXEN

NEXEN

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000-\$17,000

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: 11 Working Days

Report Ref No. CS3/ICS18004726/Wbe2

Inspected By

WILSON TEO CHENG MING

Automotive Assessor

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.