

22/03/2002

ASS. REC. BY:

REF: CS/CTI 18004727/Uqd313

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Jowyn Tay

of

CTI

Date/Time: 13/03/2018 @ 11:01am

Estimated Cost:

Bill to:

☒ TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JL 7353D

Insured:

at Workshop m/s

Car City Auto

Tel:

6781 0300

of Blk 9006, Tampines St. 93 # 01-198

Policy No:

DMPCSN 3087881700

Claim No:

SNMIRD01261C01

Sum Insured:

Excess:

waived

Make of Veh:

(Client's Record)

D.O.A. 07/03/2018CA ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:48am @ 13/3/18

Person Contacted:

Mr. Ng

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

8JL 7353D - X

14/3/18 @ 2:08pm revert to Jowyn Tay via Messenger.

14/3/18 @ 3:48pm Alfred Toh informed C/A not more than US\$6300 via Messenger.

14/3/18 @ 5:21pm Informed Mr Ho C/A not more than US\$6300 & ex: of by one

(08/11/13) wef

ASS. REG. BY: Marius

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SJL 7353dat Workshop m/s Car city

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: none

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 20K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

0744X

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJL 7353D Regn: 1208

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Volkswagen Touran c.c. 1390Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 118642 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVG2221T29W058946

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 13/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

RP.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 13602rep 63003/5/18 Conf'd d/p @ \$400 with MR HO
(Rcd @ 732482, 58%)

RECEIVED 17 MAR 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

MR-TPLump Sum / J.B.I. (\$) \$400Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

220

Transportation:

S + RS, SI

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004727/Uqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-03-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJL 7353D
Policy No.	DMPCSN3087881700	Coverage (\$)	0.00
Claim No.	SNM18D01261C01	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/03/2018	Inspection Date	13/03/2018
Survey held at	CAR CITY AUTO CENTRE PTE LTD BLK 9006 TAMPINES ST 93 #01-198 SINGAPORE 528840		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 14 March 2018 5:21 PM
To: ccacpl@singnet.com.sg
Cc: SUR
Subject: VEHICLE SJL 7353D (DOA: 07/03/2018)

Dear Mr Ho,

As instructed by our client China Taiping Insurance , please proceed to repair the insured vehicle **SJL 7353D** at repair cost not more than Lump Sum \$6,300.00 (Excess \$0/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Mar 2018 17:55	Clim Veh Model Changed	(201186) VOLKSWAGEN TOURAN 1.4 TSI (A).	[R] Ho Too Boon
2	09 Mar 2018 17:55	Clim Created	Reg No: SJL7353D. Policy No: DMPCSN3087881700. Acct Date: 2018/03/07. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Car City Auto Centre Pte Ltd (HQ). Created from SAS:MCCA18032712	[R] Ho Too Boon
3	09 Mar 2018 18:01	Clim Submitted	12727.82.	[R] Ho Too Boon
4	13 Mar 2018 11:01	Clim Registration Modified	Excess: -> 0.00.	[I] Jowyn Tay
5	13 Mar 2018 11:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE PROCEED TO SURVEY & REVERT. EXCESS WAIVED FOR THIS ACCIDENT.	[I] Jowyn Tay
6	13 Mar 2018 11:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/22	[I] Jowyn Tay
7	13 Mar 2018 11:01	Adj Mandate Set	Approved:0.00.	[I] Jowyn Tay
8	13 Mar 2018 11:42	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	13 Mar 2018 14:57	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	14 Mar 2018 14:02	Adj Rpt Initiated		[A] SHIAU CHAN
11	14 Mar 2018 14:07	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/22	[A] SHIAU CHAN
12	14 Mar 2018 14:08	Adj Mandate Request	Cur.Reg:10626.22:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	14 Mar 2018 15:08	Adj Mandate Request Cancelled		[A] SHIAU CHAN
14	14 Mar 2018 15:11	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/22	[A] SHIAU CHAN
15	14 Mar 2018 15:12	Adj Mandate Request	Cur.Reg:6300.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER AGREED REPAIR COST NOT MORE THAN LUMP SUM \$6,300.00. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	14 Mar 2018 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/22. Mandate Remarks: Please proceed to authorize repairs NO MORE THAN \$6,300.00. RE-INSPECTION OF VEHICLE REQUIRED.	[I] Alfred Toh
17	14 Mar 2018 15:48	Adj Mandate Set	Approved:6300.00:Please proceed to authorize repairs NO MORE THAN \$6,300.00. RE-INSPECTION OF VEHICLE REQUIRED.Reinsp:Adj decides.	[I] Alfred Toh

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1744594	09/03/2018 17:55	Motor	Car City Auto Centre Pte Ltd (HQ)	Car City Auto Centre Pte Ltd (HQ)	SJL7353D		xx.xx
1748057	14/03/2018 14:02	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJL7353D		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 14 Mar 2018

Preliminary Advice

Vehicle No	: SJL7353D	Accident Date	: 07/03/2018
Make	: VOLKSWAGEN TOURAN	Policy No.	: DMPCSN3087881700
Assignment Date	: 13/03/2018	Excess	: S\$0.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,727.82
Revised Amount	:S\$	6,555.28
Check Items (Estimated)	:S\$	4,070.94
Total	:S\$	10,626.22

Lump Sum Repair	:S\$	6,300.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	13,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,398.00

Braking System	:	In Order
Steering System	:	In Order
Tyre Condition (Front)	:	6/6mm
Tyre Condition (Rear)	:	6/6mm

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER AGREED REPAIR COST NOT MORE THAN LUMP SUM \$6,300.00.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 14 Mar 2018

Preliminary Advice

Vehicle No	: SJL7353D	Accident Date	: 07/03/2018
Make	: VOLKSWAGEN TOURAN	Policy No.	: DMPCSN3087881700
Assignment Date	: 13/03/2018	Excess	: S\$0.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 6.00
Inspection At	: CAR CITY AUTO CENTRE PTE LTD (HQ) BLK 9006 #01-198, TAMPINES STREET 93 SINGAPORE 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,727.82
Revised Amount	:S\$	6,555.28
Check Items (Estimated)	:S\$	4,070.94
Total	:S\$	10,626.22

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	13,602.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,398.00

Braking System	:	In Order
Steering System	:	In Order
Tyre Condition (Front)	:	6/6mm
Tyre Condition (Rear)	:	6/6mm

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0744Z
Vehicle Details	
Vehicle No.:	SJL7353D
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4 TSI 170HP
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	BLG056024
Chassis No.:	WVGZZZ1TZ9W058946
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$25,583.00
Original Registration Date:	10 Dec 2008
First Registration Date:	10 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$25,583.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Dec 2018
PARF Rebate Amount:	\$12,791.00
Intended COE Rebate Details	
COE Expiry Date:	09 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,989.00
COE Rebate Amount:	\$811.00
Total Rebate Amount:	\$13,602.00

The information contained herein is correct as at 13 Mar 2018

OK



Choice of
\$0 excess



Option of any
workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2008 Mercedes Benz S300L At \$7.5K For 6 Months.



Best For Renewal. Low Depre.
Best Value For Money. Interior
Beautiful Condition.
Direct Owner StarAd



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

Volkswagen Touran

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen Touran		Any	Any	2009	Any	Any	Any	Available
	Volkswagen	Touran 1.4A TSI	\$20,800	\$9,180 /yr	21-Jan-2009	1,390 cc	135,000 km	MPV	Available
Posted: 04-Mar-2018 Tags: 2009 Volkswagen Touran, Volkswagen Touran, Volkswagen, Touran, Used Volkswagen									
	Volkswagen	Touran 1.4A TSI	\$21,688	\$9,280 /yr	27-Feb-2009	1,390 cc	168,000 km	MPV	Available
Low Depreciation. Well Maintained And Accident Free. Original Genuine Mileage Serviced With Volkswagon Specialist Workshop Agent. Please Call For Enquire.									
Posted: 01-Mar-2018 Tags: 2009 Volkswagen Touran, Volkswagen Touran, Volkswagen, Touran, Used Volkswagen									
	Volkswagen	Touran Sport 1.4A TSI	\$23,800	\$8,110 /yr	16-Jul-2009	1,390 cc	143,000 km	MPV	Available
New Rims Just Bought In September, View To Believe Worry Free Drive, 140K Km Full Car Check, New Battery And Servicing In Dec 2017.									
Posted: 03-Feb-2018 Tags: 2009 Volkswagen Touran, Volkswagen Touran, Volkswagen, Touran, Used Volkswagen									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Volkswagen Touran, Volkswagen Touran Singapore, used Volkswagen Touran Singapore, used Volkswagen Touran, used vehicles Singapore or even buy used Volkswagen Touran Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/03/2018 16:30
Date Of Accident	07/03/2018 17:05
Exact Location Of Accident	ALONG BEDOK ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL7353D
Insured/Policyholder	
Name Of Registered Owner	FOO CHUEN CHONG
NRIC No	S7630744Z
Email Address	FOOCHUENCHONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91465655
Alternative Phone No	OTHERS-91465655

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOURAN-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3087881700
Cover Note Number	

Driver

Name of Driver	FOO CHUEN CHONG
NRIC No	S7630744Z
Date Of Birth	29/09/1976
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1995
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91465655
Fax Number	
Contact Number	OTHERS-91465655
Email Address	FOOCHUENCHONG@GMAIL.COM

Address	47 BEDOK ROAD #01-17
Postcode	469566
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE4185D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANNIE NEO
NRIC/Passport Number	S7076349D
Contact Number	90609937
Address	821B UPPER EST COAST ROAD
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 8/3/18 @ 1228hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/3/2018 at about 1705hrs along Bedok Road towards Simpang Bedok, I had collided onto the rear of another car Registration number: SJE 4185D near to Lampost: 77. I then came down to check whether is there any injury on the other driver who informed that she is fine. I then exchanged particulars, insurance company and handphone.

I wish to state that there is no other car or people involved in this incident nor any government property.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time: 8/3/18 @ 1225hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**CAR CITY AUTO CENTRE
PTE LTD
BLK 9006 TAMPINES
STREE 93**

**#01-198
SINGAPORE 528840**

**Claim Reference: CCA00359
Assessment Number: CCA00359
Version: CAR CITY/1
Date Calculated: 09/03/2018 08:26**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by the Insurance Company

Acknowledged by Repairer:
Signature:
Date:

**Full Report - V1
Registration: SJL7353D
Printed: 09/03/2018 16:26**

Summary Information

Claim

Location: Singapore (SG)
Printed by: HO TOO BOON
Authorisation Status: Interim
Work Provider: China Taiping Insurance (S) Pt
Claim Reference: CCA00359
Policy Number: DMPCSN3087881700
Other Reference:
Third Party:
Insured Amount:
Under Warranty:
Warranty Expired:

Currency: SGD
Date of Incident: 07/03/2018
Able to Authorise Repairs: TBA
Repairs Authorised: TBA

Estimated Repair Time:
Quote Due Date:
Actual Repair Days:
Parts Ordered Date:
Hire Car Start:
Hire Car End:
Vehicle Collected:

*13/3/18
6 days
Express name
Not Authorised
alter
2/53
Completed Repair
No 10300*

Vehicle Details

Vehicle

Manufacturer: VOLKSWAGEN
Model: Touran
Sub Model: BASE MODEL
Model Sheet Number: 655 01
Registration: SJL7353D
Registration Month: December
Registration Year: 2008
VIN Number: WVGZZZ1T29W058946
Manufacture Year: 2008
Odometer: 118642
Colour: Other
Engine Number: BLG056024
Fuel Level: %

Model Specs

ROOF RAILS FROM 05/2008
CLIMATRONIC
RADIO RCD 310
SIDE WINDOW/RR SCRIN
SCREEN AERIAL
PARKING HELP SYSTEM
FRT FOLDING BACKREST
SPORT COMFORT SEATS
HEIGHT ADJ PASS SEAT
CHECK PACKAGE
LUMBAR SUPPORT
FRONT CENTRE ARMREST
HD COOLING
UPHILL TRACTION CONT
TYRES 205/55 VR 16
SPACE SAVER SP-WHEEL
SMOKER EQUIPMENT
1.4 LTR 125 KW
TWO COAT METALLIC
VISIBLE VIN WINDOW
ELECTRIC WINDOWS
8 SPEAKER
FOG LAMPS
WIPER SYNCHRONIZER
LEATHER TRIM
HEATED FRONT SEATS
REAR FOLDING SEATS
STRG WHEEL LEATHER
OIL LEVEL GAUGE
ALTERNATOR 140A
6 SPEED DSG
CRUISE CONTROL
WHEELS 6.5J X 16 ALU
ALUMINIUM DECAL
STABILITY PROGRAM
TRIM HIGHLINE
FRONT BRAKE 312 X 25

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Fair
Steering: Satisfactory
Brakes Pedal Travel: Satisfactory
Place of Inspection: Repairer
Pre-Accident Damage:

Severity of Impact: Heavy Panel
Vehicle Status on Inspection: Unroadworthy
Date of Inspection: 08/03/2018

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00359

Assessment Number: CCA00359

Version: CAR CITY/1

Date Calculated: 09/03/2018 08:26

Full Report - V1

Registration: SJL7353D


Printed: 09/03/2018 16:26

Tyres Condition: Fair


Tyres - Tread Depth (MM):

	Axles	Left Tyre Depth	Right Tyre Depth	
LHF	0	7.0	7.0	RHF
LHR	1	6.0	6.0	RHR

Damage Areas:



Direction of Impact:



Addresses

Cost Summary

Total Labour	\$1,373.40
Total Paint/Material	\$242.48
Total Parts	\$10,864.94
Total of Additional Costs	\$247.00
Excess:	TBA
Grand Total Exc GST:	\$12,727.82
7 % GST:	\$890.95
Grand Total Inc GST:	\$13,618.77

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
10 83 19 00	R + R ENGINE COVER	2.0	8.40
87 03 17 00	DRAIN + REFILL REFRIGERANT	5.0	21.00
63 29 55 63	RENEW FRONT BUMPER COVER (REMOVED)	7.0	29.40
	INCLUDES: R + R MOULDING, FRONT FOG LAMPS, FRONT SPOILER AND NUMBER PLATE SUPPORT		
94 15 55 50	RENEW L/HEADLAMP (REMOVED)	1.0	4.20
94 15 55 50	RENEW R/HEADLAMP (REMOVED)	1.0	4.20
50 55 55 50	RENEW LEFT FRONT WING (REMOVED)	2.0	8.40
50 55 51 50	L/F WING SEAL (COMPOSITE WORK)	2.0	8.40
50 55 19 50	R + R R/F WING (BUMPER COVER AND SIDE WINDOW REMOVED)	9.0	37.80
	INCLUDES: R + R WHEELHOUSE LINER		
50 55 55 50	RENEW RIGHT FRONT WING (REMOVED)	2.0	8.40
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)	2.0	8.40
NO NUMBER	R + R L/F WING STRUT	2.0	8.40
NO NUMBER	R + R R/F WING STRUT	2.0	8.40

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00359

Assessment Number: CCA00359

Version: CAR CITY/1

Date Calculated: 09/03/2018 08:26

Full Report - V1

Registration: SJL7353D

Printed: 09/03/2018 16:26

24 25 19 23	R + R AIR CLEANER		
87 44 19 50)	R + R CONDENSER/EVAPORATOR PIPE	4.0	16.80
	(BUMPER COVER REMOVED)	4.0	16.80
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT		
87 45 19 50)	R + R COMPRESSOR/EVAPORATOR PIPE	5.0	21.00
	(SOUND PROTECTION PAN REMOVED)		
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT		
87 43 19 50	R + R COMPRESSOR/CONDENSER PIPE	4.0	16.80
	(SOUND PROTECTION PAN REMOVED)		
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT		
87 50 19 50	R + R CONDENSER	1.0	4.20
	(LOCK CARRIER REMOVED)		
	DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT		
21 41 19 25)	R + R CHARGE AIR COOLER PRESSURE PIPE	4.0	16.80
21 41 19 24)	R + R CHARGE AIR COOLER PRESSURE PIPE	2.0	8.40
21 43 19 90)	R + R CHARGE AIR COOLER	4.0	16.80
	(BUMPER REMOVED)		
19 20 19 23)	R + R COOLING BLOWER HOUSING	2.0	8.40
19 20 55 73	RENEW COOLING BLOWER HOUSING	2.0	8.40
	INCLUDES: R + R ELECTRIC FAN		
19 70 19 00)	R + R RADIATOR	6.0	25.20
	(BUMPER COVER REMOVED)		
	INCLUDES: DETACH + REFIT LOCK CARRIER, DRAIN + REFILL COOLANT		
19 70 55 50	RENEW RADIATOR (REMOVED)	3.0	12.60
	INCLUDES: CONVERT ATTACHED PARTS		
90 50 20 00)	R + R HORN	2.0	8.40
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED)	5.0	21.00
	INCLUDES: CONVERT ATTACHED PARTS		
55 22 19 00	REMOVE/REFIT BONNET PANEL	7.0	29.40
	INCLUDES: ADJUST BONNET CLEARANCES		
55 18 19 00	R + R BONNET LOCK UPPER PART	2.0	8.40
55 22 55 50	RENEW BONNET	4.0	16.80
	(BONNET REMOVED)		
	INCLUDES: R + R ALL PARTS		
55 25 56 50	RENEW BOTH FRONT BONNET HINGES	3.0	12.60
	(BONNET REMOVED)		
96 91 19 ZAX	R + R ALARM SYSTEM HORN	2.0	8.40
64 10 55 00	RENEW FRONT SCREEN	22.0	92.40
	INCLUDES: R + R A-PILLAR TRIMS, INTERIOR MIRROR, SUN VISORS AND INTERIOR LAMP		
64 29 19 00)	R + R L/F SIDE WINDOW	2.0	8.40
	(A-PILLAR TRIM REMOVED)		
64 29 19 00)	R + R R/F SIDE WINDOW	2.0	8.40
	(A-PILLAR TRIM REMOVED)		
50 65 53 ZAX	REMOVE PARTS L/F BUMPER BRACKET	9.0	37.80
	INCLUDES: R + R LOCK CARRIER, CROSSMEMBER AND WING		
50 65 55 ZAX	RENEW L/F BUMPER BRACKET	7.0	29.40
50 43 55 50	RENEW L/F ASSEMBLIES CARRIER CONSOLE	5.0	21.00

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00359

Assessment Number: CCA00359

Version: CAR CITY/1

Date Calculated: 09/03/2018 08:26

Full Report - V1

Registration: SJL7353D

Printed: 09/03/2018 16:26

NO NUMBER	RENEW L/F SIDEMEMBER CLOSING PANEL	9.0	37.80
50 65 55 ZAX	RENEW R/F BUMPER BRACKET (COMP WORK)	5.0	21.00
50 43 55 50	RENEW R/F ASSEMBLIES CARRIER CONSOLE	5.0	21.00
NO NUMBER	RENEW R/F SIDEMEMBER CLOSING PANEL	9.0	37.80
50 65 59 ZAX	FIT PARTS L/F BUMPER BRACKET	13.0	54.60
	INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY		
19 62 19 23)	R + R LOWER COOLANT HOSE	3.0	12.60
21 35 19 73)	R + R COOLANT PIPE	3.0	12.60
94 15 16 00	ADJUST HEADLAMPS	2.0	8.40
0245	PANEL WORK FRONT	18.0*	75.60
0500	CHECK FRONT BONNET CABLE		
0637	CHECK L/F FOG LAMP		
4455	CHECK COMPRESSOR		
LABOUR COST			
	Total Work Units	217.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	21.7HRS	\$911.40
	Paint Labour	11.0HRS	\$462.00
	Total Labour	32.7HRS	\$1,373.40

PAINT WORK

Guide Number	Description	Time Basis 10 WU = 1 HR. Price = \$42.00/HR	WU	Cost Price (\$)
	- TWO COAT METALLIC			
471	BONNET NEW PART PAINTING		20.0	
741	L/F WING NEW PART PAINTING		10.0	
742	R/F WING NEW PART PAINTING		10.0	
1275	L/S-MEMB COVER PANELSURFACE PAINT		4.0	
1276	R/S-MEMB COVER PANELSURFACE PAINT		4.0	
1285	L/ABSORBER SUPPORT SURFACE PAINT		4.0	
1286	R/ABSORBER SUPPORT SURFACE PAINT		4.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R		10.0	
296	TOWING EYE COVER NEW PART PAINT K1R		3.0	
391	FRONT SPOILER NEW PART PAINT K1R		5.0	
411	GRILLE NEW PART PAINT K1R		4.0	
1481	LEFT FRONT DOOR SURFACE PAINT		8.0	
1482	RIGHT FRONT DOOR SURFACE PAINT		8.0	
LABOUR COST - PAINT				
	TIME(PAINT)			
	Preparation Main Work Metal		94.0	
	Preparation Comp. Work Plastic		11.0	
	Preparation Work Multi Layer Paint		5.0	
	Total Work Units (10WU/HR)		0.0	
	Total Paintwork Labour		110.0	
	MATERIAL COST - PAINT		11.0HRS	\$462.00
	New Part Painting			Cost Price
	New Part Painting - Plastic K1R			\$101.13
	Surface-/Blend Paint			\$64.45
	Material-Const Main Work Metal			\$49.80
	Material-Const Comp. Work Plastic			\$18.10
	Total Excluding Pearlescent Uplift			\$9.00
				\$242.48

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00359

Assessment Number: CCA00359

Version: CAR CITY/1

Date Calculated: 09/03/2018 08:26

Full Report - V1

Registration: SJL7353D

Printed: 09/03/2018 16:26

Pearlescent Uplift @ 0.0%
Total Paint Material Cost

\$0.00
\$242.48

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
283	1	FRONT BUMPER	1T0 807 221 D GRU		0%	2.5	590.00*
296	1	TOWING EYE COVER	1T0 807 241 B GRU		0%	1.1	40.00*
297	1	L/F AIR GUIDE GRILLE	1T0 853 665 K 9B9		0%	1.1	75.00*
298	1	R/F AIR GUIDE GRILLE	1T0 853 666 P 9B9		0%	1.1	75.00*
299	1	FRT CTR COWL GRILLE	1T0 853 677 9B9		0%	1.1	120.00*
301	1	L/F PROTECT MOULDING	1T0 807 717 9B9		0%	1.1	35.00*
302	1	R/F PROTECT MOULDING	1T0 807 718 9B9		0%	1.1	35.00*
307	1	L/CHROME MLDG-BUMPER	1T0 807 243 ZZZ		0%	1.1	50.00*
308	1	R/CHROME MLDG-BUMPER	1T0 807 244 ZZZ		0%	1.1	50.00*
319	1	L/F OUT BUMPER BRKT	1T0 807 183 A		0%	1.1	35.00*
320	1	R/F OUT BUMPER BRKT	1T0 807 184 A		0%	1.1	35.00*
329	1	L/F BUMPER GUIDE	1T0 807 889 C		0%	1.1	18.00*
330	1	R/F BUMPER GUIDE	1T0 807 890 C		0%	1.1	18.00*
339	1	FRT BUMPER C-MEMBER	1T0 807 093 E		0%	1.1	200.00*
340	1	FRT BUMPER SUPPORT	1T0 807 109 B		0%	1.1	270.00*
341	1	CTR FILLER PIECE	1T0 807 248 F		0%	1.1	18.00*
391	1	FRONT BUMPER SPOILER	1T0 805 903 B 9B9		0%	1.1	250.00*
411	1	RAD GRILLE CHROME	1T0 853 651 AG PWF		0%	1.1	400.00*
471	1	BONNET	1T0 823 031 L		0%	1.1	600.00*
475	1	LEFT BONNET HINGE	1T0 823 301 F		0%	1.1	60.00*
476	1	RIGHT BONNET HINGE	1T0 823 302 F		0%	1.1	60.00*
481	1	BONNET INSULATION	1T0 863 831 D		0%	1.1	185.00*
493	1	LOWER LOCK	1T1 823 509		0%	1.1	110.00*
494	1	SAFETY LATCH	1T0 823 480 B		0%	1.1	40.00*
523	1	L/BONNET SEAL	1T0 823 707 B		0%	1.1	20.00*
524	1	R/BONNET SEAL	1T0 823 708 B		0%	1.1	20.00*
561	1	LEFT HEADLAMP ASSY	1T2 941 005 B		0%	1.1	345.00*
562	1	RIGHT HEADLAMP ASSY	1T2 941 006 B		0%	1.1	345.00*
638	1	R/F FOG LAMP	5K0 941 700 A		0%	1.1	125.00*
741	1	L/F WING	1T0 821 021 B		0%	1.1	310.00*
742	1	R/F WING	1T0 821 022 B		0%	1.1	310.00*
761	1	L/WING STRUT	1T0 821 135 B		0%	1.1	25.00*
762	1	R/WING STRUT	1T0 821 136 B		0%	1.1	25.00*
841	1	L/F WHEELHOUSE COVER	1T0 805 911 N		0%	1.1	55.00*
842	1	R/F WHEELHOUSE COVER	1T0 805 912 G		0%	1.1	55.00*
930	1	FRT LOCK CARRIER	1T0 805 588 AD 9B9		0%	1.1	585.00*
1275	1	L/S-MEMB COVER PANEL	1K0 804 105 D		0%	1.1	190.00*
1276	1	R/S-MEMB COVER PANEL	1K0 804 106 D		0%	1.1	190.00*
1279	1	L/S-MEMBER SUPPORT	1K0 803 127		0%	1.1	100.00*
1280	1	R/S-MEMBER SUPPORT	1K0 803 128		0%	1.1	100.00*
1285	1	L/ABSORBER SUPPORT	1K0 804 181 B		0%	1.1	30.00*
1286	1	R/ABSORBER SUPPORT	1K0 804 182 B		0%	1.1	30.00*
1301	1	L/S-MEMBER SUPPORT	1K0 804 055 A		0%	1.1	40.00*
1302	1	R/S-MEMBER MOUNTING	1K0 804 056		0%	1.1	40.00*
1401	1	WINDSCREEN	1T0 845 011 DH		0%	1.1	450.00*

CAR CITY AUTO CENTRE PTE LTD

Claim Reference: CCA00359

Assessment Number: CCA00359

Version: CAR CITY/1

Date Calculated: 09/03/2018 08:26

Full Report - V1

Registration: SJL7353D

Printed: 09/03/2018 16:26

1405	1	APPLICATOR	D 009 500 25	0%	11	2.70U	X
1409	1	CUTTING FILAMENT	357 853 999 B	0%	11	14.00U	X
1410	1	CLEANING SOLUTION	D 009 401 04	0%	11	6.36U	X
1411	1	WINDSCREEN BOND KIT	D 004 660 M2	0%	21	41.45U	X
1414	1	WINDSCREEN PRIMER	D 009 200 02	0%	11	7.55U	X
1417	8	BUFFER STOP	1T0 845 237	0%	11	6.96U	X
1418	2	SPACER	443 845 631 A	0%	11	1.92U	X
4456	1	COMPR/CONDENSER HOSE	1K0 820 721 BQ	0%	11	260.00*	X
4465	1	CONDENSER	1K0 820 411 AK	0%	21/11	290.00*	X
4469	1	PROTECTION GRILLE	1K0 820 746	0%	11	20.00*	X
4481	1	EVAP/CONDENSER HOSE	1T0 820 741 AM	0%	11	350.00*	X
4483	1	EVAP/COMPRESSOR HOSE	1T0 820 743 AQ	0%	21	430.00*	X
7751	1	UPPER AIR DUCT	1T0 121 341 D	0%	11	20.00*	X
7753	1	L/AIR GUIDE PANEL	1T0 121 283 C	0%	11	35.00*	X
7754	1	R/AIR GUIDE PANEL	1T0 121 284 C	0%	11	35.00*	X
7761	1	RADIATOR	5K0 121 251 AA	0%	21/11	300.00*	X
7766	1	THERMOSWITCH	06A 919 501 A	0%	11	50.00*	X
7767	1	FAN SHROUD	1K0 121 205 AJ	0%	one	100.00*	X
			9B9				
7773	1	LOWER WATER HOSE	1K0 121 156 CN	0%	11	130.00*	X
7776	1	UPPER WATER HOSE	SEE GUIDE NO.	0%	11	130.00*	X
			7773				
7790	1	L/ELECTRIC FAN	1K0 959 455 EA	0%	11	380.00*	X
7791	1	R/ELECTRIC FAN	1K0 959 455 ET	0%	11	260.00*	X
7889	1	INLET WATER HOSE	1K0 122 109 BC	0%	11	15.00*	X
8723	1	TURBO PRESSURE TUBE	1K0 145 770 AK	0%	11	160.00*	X
8745	1	INTERCOOLER	1K0 145 803 CD	0%	11	330.00*	X
8747	1	R/LOWER CAC HOSE	1K0 145 834 BD	0%	11	130.00*	X
8751	1	LOAD AIR TUBE	1T0 145 840	0%	21	210.00*	X
8755	1	L/LOWER CAC HOSE	1K0 145 832 F	0%	11	120.00*	X
9647	1	L/HORN BRACKET	1T0 951 182 C	0%	11	25.00*	X
9648	1	R/HORN BRACKET	1K0 951 182 H	0%	11	25.00*	X
9649	1	LOW TON HORN	5C0 951 221 B	0%	11	60.00*	X
9650	1	HIGH TON HORN	5C0 951 223 C	0%	11	60.00*	X
f: OEM Parts			Sub Total			\$10,764.94	
g: Original			Mark Up From Cost	(0 %)		\$0.00	
h: Secondhand			Sundry Parts	(Fixed)		\$100.00	
p: Parallel			Total Parts			\$10,864.94	
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
AUDATEX FEES	SPECIALIST	0%	\$42.00 ✓
NUM PLATE & HOLDER	SPECIALIST		320 \$55.00 40
ANTI-FREEZE COOLANT	SPECIALIST	0%	11 \$60.00 20
AIR-CON GAS	SPECIALIST		\$50.00 ✓
SEALANT	SPECIALIST	0%	11 \$30.00 ✓
ERP BRKT	SPECIALIST		11 \$10.00 ✓
Total Extras			\$247.00

Final Calculation

CAR CITY AUTO CENTRE PTE LTD**Claim Reference: CCA00359****Assessment Number: CCA00359****Version: CAR CITY/1****Date Calculated: 09/03/2018 08:26****Full Report - V1****Registration: SJL7353D****Printed: 09/03/2018 16:26**

Total Parts		
Labour		\$10,864.94
Total Panel/Mechanical	\$911.40	
Total Paintwork	\$462.00	
Total Labour		\$1,373.40
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$247.00	
Total of Additional Costs		\$247.00
Total Paint/Material Costs		\$242.48
Grand Total Excludes GST		\$12,727.82
GST @ 7 %		\$890.95
Grand Total Includes GST		\$13,618.77

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM18D01261C01
Assessment Number: CCA00359
Version: LKKAUTOC/3
Date Calculated: 03/05/2018 08:49

Full Report - V1
Registration: SJL7353D
Printed: 03/05/2018 15:49

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	07/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D01261C01	Estimated Repair Time:	
Policy Number:	DMPCSN3087881700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	VOLKSWAGEN
Model:	Touran
Sub Model:	BASE MODEL
Model Sheet Number:	655 01
Registration:	SJL7353D
Registration Month:	December
Registration Year:	2008
VIN Number:	WVGZZZ1TZ9W058946
Manufacture Year:	2008
Odometer:	118642
Colour:	Other
Engine Number:	BLG056024
Fuel Level:	%

Model Specs

ROOF RAILS	FROM 05/2008
CLIMATRONIC	VISIBLE VIN WINDOW
RADIO RCD 310	ELECTRIC WINDOWS
SIDE WINDOW/RR SCRNR	8 SPEAKER
SCREEN AERIAL	FOG LAMPS
PARKING HELP SYSTEM	WIPER SYNCHRONIZER
FRT FOLDING BACKREST	LEATHER TRIM
SPORT COMFORT SEATS	HEATED FRONT SEATS
HEIGHT ADJ PASS SEAT	REAR FOLDING SEATS
CHECK PACKAGE	STRG WHEEL LEATHER
LUMBAR SUPPORT	OIL LEVEL GAUGE
FRONT CENTRE ARMREST	ALTERNATOR 140A
HD COOLING	6 SPEED DSG
UPHILL TRACTION CONT	CRUISE CONTROL
TYRES 205/55 VR 16	WHEELS 6.5J X 16 ALU
SPACE SAVER SP-WHEEL	ALUMINIUM DECAL
SMOKER EQUIPMENT	STABILITY PROGRAM
1.4 LTR 125 KW	TRIM HIGHLINE
TWO COAT METALLIC	FRONT BRAKE 312 X 25


Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Fair	Severity of Impact:	Heavy Panel
Steering:	Satisfactory	Vehicle Status on Inspection:	Unroadworthy
Brakes Pedal Travel:	Satisfactory	Date of Inspection:	08/03/2018
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tyres - Tread Depth (MM):			

Left Tyre

Right Tyre



Addresses

Cost Summary

Total Labour	\$785.40
Total Paint/Material	\$218.27
Total Parts	\$5,589.00
Total of Additional Costs	\$192.00
Excess:	- \$0.00
Grand Total Exc GST:	\$6,784.67
7 % GST:	\$474.93
Grand Total Inc GST:	\$7,259.60

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
10 83 19 00	R + R ENGINE COVER	2.0	8.40
87 03 17 00	DRAIN + REFILL REFRIGERANT	5.0	21.00
63 29 19 00	R + R FRONT BUMPER COVER INCLUDES: R + R RADIATOR GRILLE	9.0	37.80
63 29 55 63	RENEW FRONT BUMPER COVER (REMOVED) INCLUDES: R + R MOULDING, FRONT FOG LAMPS, FRONT SPOILER AND NUMBER PLATE SUPPORT	7.0	29.40
94 15 55 50	RENEW R/HEADLAMP (REMOVED)	1.0	4.20
87 45 19 50)	R + R COMPRESSOR/EVAPORATOR PIPE (SOUND PROTECTION PAN REMOVED) DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	5.0	21.00
87 50 19 50	R + R CONDENSER (LOCK CARRIER REMOVED) DOES NOT INCLUDE: DRAIN + REFILL REFRIGERANT	1.0	4.20
21 41 19 24)	R + R CHARGE AIR COOLER PRESSURE PIPE	2.0	8.40
19 20 19 23)	R + R COOLING BLOWER HOUSING	2.0	8.40
19 20 55 73	RENEW COOLING BLOWER HOUSING INCLUDES: R + R ELECTRIC FAN	2.0	8.40
19 70 19 00)	R + R RADIATOR (BUMPER COVER REMOVED)	6.0	25.20

	INCLUDES: DETACH + REFIT LOCK CARRIER, DRAIN + REFILL COOLANT		
19 70 55 50	RENEW RADIATOR (REMOVED)	3.0	12.60
	INCLUDES: CONVERT ATTACHED PARTS		
50 38 19 50	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)	13.0	54.60
	DOES NOT INCLUDE: ADJUST HEADLAMPS		
50 38 55 50	RENEW FRONT LOCK CARRIER (REMOVED)	5.0	21.00
	INCLUDES: CONVERT ATTACHED PARTS		
55 22 19 00	REMOVE/REFIT BONNET PANEL	7.0	29.40
	INCLUDES: ADJUST BONNET CLEARANCES		
55 22 55 50	RENEW BONNET (BONNET REMOVED)	4.0	16.80
	INCLUDES: R + R ALL PARTS		
64 10 55 00	RENEW FRONT SCREEN	22.0	92.40
	INCLUDES: R + R A-PILLAR TRIMS, INTERIOR MIRROR, SUN VISORS AND INTERIOR LAMP		
94 15 16 00	ADJUST HEADLAMPS	2.0	8.40
LABOUR COST			
	Total Work Units	98.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	9.8HRS	\$411.60
	Paint Labour	8.9HRS	\$373.80
	Total Labour	18.7HRS	\$785.40

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
471	BONNET NEW PART PAINTING	20.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	10.0	
296	TOWING EYE COVER NEW PART PAINT K1R	3.0	
411	GRILLE NEW PART PAINT K1R	4.0	
1481	LEFT FRONT DOOR SURFACE PAINT	8.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
LABOUR COST - PAINT			
	TIME(PAINT)	73.0	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	89.0	
	Total Paintwork Labour	8.9HRS	\$373.80
MATERIAL COST - PAINT			
	New Part Painting		\$101.13
	New Part Painting - Plastic K1R		\$49.20
	Surface-/Blend Paint		\$40.84
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$218.27

Pearlescent Uplift @ 0.0%
Total Paint Material Cost

\$0.00
\$218.27

PARTS

Guide No.Qty		Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
283	1	FRONT BUMPER	1T0 807 221 D			0%	590.00*
			GRU				
298	1	R/F AIR GUIDE GRILLE	1T0 853 666 P 9B9			0%	75.00*
299	1	FRT CTR COWL GRILLE	1T0 853 677 9B9			0%	120.00*
301	1	L/F PROTECT MOULDING	1T0 807 717 9B9			0%	35.00*
302	1	R/F PROTECT MOULDING	1T0 807 718 9B9			0%	35.00*
307	1	L/CHROME MLDG-BUMPER	1T0 807 243 ZZZ			0%	50.00*
308	1	R/CHROME MLDG-BUMPER	1T0 807 244 ZZZ			0%	50.00*
319	1	L/F OUT BUMPER BRKT	1T0 807 183 A			0%	35.00*
320	1	R/F OUT BUMPER BRKT	1T0 807 184 A			0%	35.00*
339	1	FRT BUMPER C-MEMBER	1T0 807 093 E			0%	200.00*
340	1	FRT BUMPER SUPPORT	1T0 807 109 B			0%	270.00*
411	1	RAD GRILLE CHROME	1T0 853 651 AG			0%	400.00*
			PWF				
471	1	BONNET	1T0 823 031 L			0%	600.00*
493	1	LOWER LOCK	1T1 823 509			0%	110.00*
562	1	RIGHT HEADLAMP ASSY	1T2 941 006 B			0%	345.00*
638	1	R/F FOG LAMP	5K0 941 700 A			0%	125.00*
930	1	FRT LOCK CARRIER	1T0 805 588 AD			0%	585.00*
			9B9				
1401	1	WINDSCREEN	1T0 845 011 DH			0%	450.00*
1405	1	APPLICATOR	D 009 500 25			0%	0.00F
1409	1	CUTTING FILAMENT	357 853 999 B			0%	0.00F
1410	1	CLEANING SOLUTION	D 009 401 04			0%	0.00F
1411	1	WINDSCREEN BOND KIT	D 004 660 M2			0%	41.45U
1414	1	WINDSCREEN PRIMER	D 009 200 02			0%	7.55U
1417	8	BUFFER STOP	1T0 845 237			0%	0.00F
1418	2	SPACER	443 845 631 A			0%	0.00F
4465	1	CONDENSER	1K0 820 411 AK			0%	290.00*
4483	1	EVAP/COMPRESSOR HOSE	1T0 820 743 AQ			0%	430.00*
7761	1	RADIATOR	5K0 121 251 AA			0%	300.00*
7767	1	FAN SHROUD	1K0 121 205 AJ			0%	100.00*
			9B9				
8751	1	LOAD AIR TUBE	1T0 145 840			0%	210.00*
f: OEM Parts			Saving				\$31.94
g: Original			Sub Total				\$5,489.00
h: Secondhand			Mark Up From Cost	(0 %)			\$0.00
p: Parallel			Sundry Parts	(Fixed)			\$100.00
x: Exchange			Total Parts				\$5,589.00

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
AUDATEX FEES	SPECIALIST	0%	\$42.00
NUM PLATE & HOLDER	SPECIALIST		\$40.00
ANTI-FREEZE	SPECIALIST	0%	\$20.00

COOLANT			
AIR-CON GAS	SPECIALIST		\$50.00
SEALANT	SPECIALIST	0%	\$30.00
ERP BRKT	SPECIALIST		\$10.00
Total Extras			\$192.00

Final Calculation

Total Parts			\$5,589.00
Labour			
Total Panel/Mechanical		\$411.60	
Total Paintwork		\$373.80	
Total Labour			\$785.40
Additional Costs			
Corr Prot Materials External		\$0.00	
Corr Prot Materials Internal		\$0.00	
Cost of Specialist		\$192.00	
Total of Additional Costs			\$192.00
Total Paint/Material Costs			\$218.27
Grand Total Excludes GST			\$6,784.67
GST @ 7 %			\$474.93
Grand Total Includes GST			\$7,259.60

Assessment Notes

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/18063
Policy No:	DMPCSN3087881700	Date of Loss:	07/03/2018
Vehicle Reg. No.:	SJL7353D	Driveable?	
Driver Age/Info:	41 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FOO CHUEN CHONG	Contact No:	+6591465655
Driver:	FOO CHUEN CHONG		

Make/Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Vehicle Reg. Date:	10/12/2008
Vehicle Colour:	GREY		
Engine No:	BLG056024	Chassis No:	WVGZZZ1TZ9W058946
Odometer:	118642 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Description of Accident/Loss	AS PER ATTACHED SKETCH PLAN
Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	10,764.94
Miscellaneous Items	347.00
Labour	1,615.88
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,727.82
+ GST 7.00% (S\$)	890.95
Nett Amount (S\$)	13,618.77

This claim is handled by: HO TOO BOONGenerated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2018)

Parts: M1-MPV VOLKSWAGEN TOURAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Car City Auto Centre Pte Ltd/SJL7353D/09/03/2018 18:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*APPLICATOR	0.00	0.00	*2.70 F ^{XXN}
2	1	NA	*BONNET	0.00	0.00	<i>PUL</i> *600.00 F
3	1	NA	*BONNET INSULATION	0.00	0.00	*185.00 F ^{XXN}
4	1	NA	*BUFFER STOP	0.00	0.00	*6.96 F ^{XXN}
5	1	NA	*CLEANING SOLUTION	0.00	0.00	*6.36 F ^{XXN}
6	1	NA	*COMPR/CONDENSER HOSE	0.00	0.00	*260.00 F ^{XXN}
7	1	NA	*CONDENSER	0.00	0.00	<i>BT/PAC</i> *290.00 F
8	1	NA	*CTR FILLER PIECE	0.00	0.00	*18.00 F ^{XXN}
9	1	NA	*CUTTING FILAMENT	0.00	0.00	*14.00 F ^{XXN}
10	1	NA	*EVAP/COMPRESSOR HOSE	0.00	0.00	<i>BT</i> *430.00 F
11	1	NA	*EVAP/CONDENSER HOSE	0.00	0.00	*350.00 F ^{XXN}
12	1	NA	*FAN SHROUD	0.00	0.00	<i>CRA</i> *100.00 F
13	1	NA	*FRONT BUMPER	0.00	0.00	<i>DIS</i> *590.00 F
14	1	NA	*FRONT BUMPER SPOILER	0.00	0.00	*250.00 F ^{XR}
15	1	NA	*FRT BUMPER C-MEMBER	0.00	0.00	<i>BL</i> *200.00 F
16	1	NA	*FRT BUMPER SUPPORT	0.00	0.00	<i>BT</i> *270.00 F
17	1	NA	*FRT CTR COWL GRILLE	0.00	0.00	<i>TW</i> *120.00 F
18	1	NA	*FRT LOCK CARRIER	0.00	0.00	<i>TW</i> *585.00 F
19	1	NA	*HIGH TONE HORN	0.00	0.00	*60.00 F ^{XXN}
20	1	NA	*INLET WATER HOSE	0.00	0.00	*15.00 F ^{XXN}
21	1	NA	*INTERCOOLER	0.00	0.00	*330.00 F ^{XXN}
22	1	NA	*L/ABSORBER SUPPORT	0.00	0.00	*30.00 F ^{XXN}
23	1	NA	*L/AIR GUIDE PANEL	0.00	0.00	*35.00 F ^{XXN}
24	1	NA	*L/BONNET SEAL	0.00	0.00	*20.00 F ^{XXN}
25	1	NA	*L/CHROME MLDG-BUMPER	0.00	0.00	<i>CRA</i> *50.00 F
26	1	NA	*L/ELECTRIC FAN	0.00	0.00	*380.00 F ^{XXN}
27	1	NA	*L/F AIR GUIDE GRILLE	0.00	0.00	*75.00 F ^{XXN}
28	1	NA	*L/F BUMPER GUIDE	0.00	0.00	*18.00 F ^{XXN}
29	1	NA	*L/F OUT BUMPER BRKT	0.00	0.00	<i>BT</i> *35.00 F
30	1	NA	*L/F PROTECT MOULDING	0.00	0.00	<i>CRA</i> *35.00 F
31	1	NA	*L/F WHEELHOUSE COVER	0.00	0.00	*55.00 F ^{XXN}
32	1	NA	*L/F WING	0.00	0.00	*310.00 F ^{XR}
33	1	NA	*L/HORN BRACKET	0.00	0.00	*25.00 F ^{XXN}
34	1	NA	*L/LOWER CAC HOSE	0.00	0.00	*120.00 F ^{XXN}
35	1	NA	*L/S/MEMBER SUPPORT	0.00	0.00	*100.00 F ^{XXN}
36	1	NA	*L/S-MEMB COVER PANEL	0.00	0.00	*190.00 F ^{XXN}
37	1	NA	*L/S-MEMBER SUPPORT	0.00	0.00	*40.00 F ^{XXN}
38	1	NA	*L/WING STRUT	0.00	0.00	*25.00 F ^{XXN}
39	1	NA	*LEFT BONNET HINGE	0.00	0.00	*60.00 F ^{XR}
40	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	*345.00 F ^{XXN}
41	1	NA	*LOAD AIR TUBE	0.00	0.00	<i>TN</i> *210.00 F
42	1	NA	*LOW TONE HORN	0.00	0.00	*60.00 F ^{XXN}
43	1	NA	*LOWER LOCK	0.00	0.00	<i>TW</i> *110.00 F
44	1	NA	*LOWER WATER HOSE	0.00	0.00	*130.00 F ^{XXN}

Car City Auto Centre Pte Ltd/SJL7353D/09/03/2018 18:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1	NA	*PROTECTION GRILLE	0.00	0.00	*20.00 F <i>Am</i>
46	1	NA	*R/ABSORBER SUPPORT	0.00	0.00	*30.00 F <i>XAV</i>
47	1	NA	*R/AIR GUIDE PANEL	0.00	0.00	*35.00 F <i>XAV</i>
48	1	NA	*R/BONNET SEAL	0.00	0.00	*20.00 F <i>XAV</i>
49	1	NA	*R/CHROME MLDG-BUMPER	0.00	0.00	<i>CRA</i> *50.00 F
50	1	NA	*R/ELECTRIC FAN	0.00	0.00	*260.00 F <i>XAV</i>
51	1	NA	*R/F AIR GUIDE GRILLE	0.00	0.00	<i>MIS</i> *75.00 F
52	1	NA	*R/F BUMPER GUIDE	0.00	0.00	*18.00 F <i>XAV</i>
53	1	NA	*R/F FOG LAMP	0.00	0.00	<i>BRO</i> *125.00 F
54	1	NA	*R/F OUT BUMPER BRKT	0.00	0.00	<i>BA</i> *35.00 F
55	1	NA	*R/F PROTECT MOULDING	0.00	0.00	<i>CRA</i> *35.00 F
56	1	NA	*R/F WHEELHOUSE COVER	0.00	0.00	*55.00 F <i>Am</i>
57	1	NA	*R/F WING	0.00	0.00	*310.00 F <i>XIS</i>
58	1	NA	*R/HORN BRACKET	0.00	0.00	*25.00 F <i>XAV</i>
59	1	NA	*R/LOWER CAC HOSE	0.00	0.00	*130.00 F <i>XAV</i>
60	1	NA	*R/S/MEMBER SUPPORT	0.00	0.00	*100.00 F <i>XAV</i>
61	1	NA	*R/S-MEMB COVER PANEL	0.00	0.00	*190.00 F <i>XAV</i>
62	1	NA	*R/S-MEMBER MOUNTING	0.00	0.00	*40.00 F <i>XAV</i>
63	1	NA	*R/WING STRUT	0.00	0.00	*25.00 F <i>XAV</i>
64	1	NA	*RAD GRILLE CHROME	0.00	0.00	<i>CRA</i> *400.00 F
65	1	NA	*RADIATOR	0.00	0.00	<i>BA/Am</i> *300.00 F
66	1	NA	*RIGHT BONNET HINGE	0.00	0.00	*60.00 F <i>ARR</i>
67	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	<i>CRA</i> *345.00 F
68	1	NA	*SAFETY LATCH	0.00	0.00	*40.00 F <i>XAV</i>
69	1	NA	*SPACER	0.00	0.00	*1.92 F <i>Am</i>
70	1	NA	*THERMOSWITCH	0.00	0.00	*50.00 F <i>Am</i>
71	1	NA	*TOWING EYE COVER	0.00	0.00	*40.00 F <i>XAV</i>
72	1	NA	*TURBO PRESSURE TUBE	0.00	0.00	*160.00 F <i>XAV</i>
73	1	NA	*UPPER AIR DUCT	0.00	0.00	*20.00 F <i>XAV</i>
74	1	NA	*UPPER WATER HOSE	0.00	0.00	*130.00 F <i>Am</i>
75	1	NA	*WINDSCREEN	0.00	0.00	<i>CRA</i> *450.00 F
76	1	NA	*WINDSCREEN BOND KIT	0.00	0.00	<i>MC</i> *41.45 F
77	1	NA	*WINDSCREEN PRIMER	0.00	0.00	<i>MZC</i> *7.55 F

F=Franchise part.

Total Parts (S\$)

10,764.94

Car City Auto Centre Pte Ltd/SJL7353D/09/03/2018 18:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	AIR-CON GAS	New 50.00 ✓
2	1	ANTI-FREEZE	Rec 60.00 20
3	1	AUDATEX FEES	42.00 ✓
4	1	ERP BRACKET	Rec 10.00 ✓
5	1	NUM PLATE & HOLDER	Bro 55.00 40
6	1	SEALANT	Rec 30.00 ✓
7	1	SUNDRY PARTS	Rec 100.00 ✓
Sub Total (S\$)			347.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	372.80 462.00
2	Total Paint Materials	New	218.27 242.48
3	Total Panel/Mechanical Labour	New	44.60 911.40
Gross Labour Cost (S\$)			1,615.88

Car City Auto Centre Pte Ltd/SJL7353D/09/03/2018 18:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Mar 2018 Sendback Est	09 Mar 2018 18:01 S\$12,727.82	13 Mar 2018 11:01 Edit Adj Rpt	S\$5,400.00 Edit Estimates	S\$5,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: FOO CHUEN CHONG , ID: S7630744Z, Tel: +6591465655, Email: FOOCHUENCHONG@GMAIL.COM									
Vehicle Reg. No.: SJL7353D		Date of Loss: 07/03/2018 17:00 - :59 [110 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D01261C01		Policy/Cover Note No.: DMPCSN3087881700 (Comprehensive)							
		Excess: S\$0.00							
Repairer: Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/03/2018]									
Driver/Custodian: FOO CHUEN CHONG (41 / Male), NRIC: S7630744Z, Tel: +6591465655									
Adj Asg. Remarks: PLEASE PROCEED TO SURVEY & REVERT. EXCESS WAIVED FOR THIS ACCIDENT.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA TAIPING (14/03/2018): Alert - Adj Mandate Approved (S\$6300.00) - SJL7353D - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJL7353D (SNM18D01261C01)

OD

Mar 7 2018 5:00PM

[FOO CHUEN CHONG]

Car City Auto Centre Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v	
Assessment Reports				1 per page v	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	09/03/18 18:01	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/03/18 14:07	Adjuster Immediate Advice		Load HTM	
2	14/03/18 15:11	Adjuster Immediate Advice		Load HTM	
Photos/ Images				3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/03/18 19:59	Chassis Number		Load JPG	☒
2	13/03/18 19:59	Odometer Reading		Load JPG	☒
3	13/03/18 19:59	General View		Load JPG	☒
4	13/03/18 19:59	General View		Load JPG	☒
5	13/03/18 19:59	General View		Load JPG	☒
6	13/03/18 19:59	General View		Load JPG	☒
7	13/03/18 19:59	General View		Load JPG	☒
8	13/03/18 19:59	General View		Load JPG	☒
9	13/03/18 19:59	General View		Load JPG	☒
10	13/03/18 19:59	General View		Load JPG	☒
11	13/03/18 19:59	General View		Load JPG	☒
12	13/03/18 19:59	General View		Load JPG	☒
13	13/03/18 19:59	General View		Load JPG	☒
14	13/03/18 19:59	General View		Load JPG	☒
15	13/03/18 19:59	General View		Load JPG	☒
16	13/03/18 19:59	General View		Load JPG	☒
17	13/03/18 19:59	General View		Load JPG	☒
18	13/03/18 19:59	General View		Load JPG	☒
19	13/03/18 19:59	General View		Load JPG	☒
20	13/03/18 19:59	General View		Load JPG	☒
21	13/03/18 19:59	General View		Load JPG	☒
22	13/03/18 19:59	General View		Load JPG	☒
23	13/03/18 19:59	General View		Load JPG	☒
24	13/03/18 19:59	General View		Load JPG	☒
25	13/03/18 19:59	General View		Load JPG	☒
26	13/03/18 19:59	General View		Load JPG	☒
27	13/03/18 19:59	General View		Load JPG	☒
28	13/03/18 19:59	General View		Load JPG	☒
29	13/03/18 19:59	General View		Load JPG	☒
30	13/03/18 19:59	General View		Load JPG	☒
31	13/03/18 19:59	General View		Load JPG	☒
32	13/03/18 19:59	General View		Load JPG	☒
33	13/03/18 19:59	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
				☒
34	13/03/18 19:59	General View	 Load JPG	☒
35	13/03/18 19:59	General View	 Load JPG	☒
36	13/03/18 19:59	General View	 Load JPG	☒
37	13/03/18 19:59	General View	 Load JPG	☒
38	13/03/18 19:59	General View	 Load JPG	☒
39	13/03/18 19:59	General View	 Load JPG	☒
40	13/03/18 19:59	General View	 Load JPG	☒
41	13/03/18 19:59	General View	 Load JPG	☒
42	13/03/18 19:59	General View	 Load JPG	☒
43	13/03/18 19:59	General View	 Load JPG	☒
44	13/03/18 19:59	General View	 Load JPG	☒
45	13/03/18 19:59	General View	 Load JPG	☒
46	13/03/18 19:59	General View	 Load JPG	☒
47	13/03/18 19:59	General View	 Load JPG	☒
48	13/03/18 19:59	General View	 Load JPG	☒
49	13/03/18 19:59	General View	 Load JPG	☒
50	13/03/18 19:59	General View	 Load JPG	☒
51	13/03/18 19:59	General View	 Load JPG	☒
52	13/03/18 19:59	General View	 Load JPG	☒
53	13/03/18 19:59	General View	 Load JPG	☒
54	13/03/18 19:59	General View	 Load JPG	☒
55	13/03/18 19:59	General View	 Load JPG	☒
56	13/03/18 19:59	General View	 Load JPG	☒
57	13/03/18 19:59	General View	 Load JPG	☒
58	13/03/18 19:59	General View	 Load JPG	☒
59	13/03/18 19:59	General View	 Load JPG	☒
60	13/03/18 19:59	General View	 Load JPG	☒
61	13/03/18 19:59	General View	 Load JPG	☒
62	13/03/18 19:59	General View	 Load JPG	☒
63	13/03/18 19:59	General View	 Load JPG	☒
64	13/03/18 19:59	General View	 Load JPG	☒
65	13/03/18 19:59	General View	 Load JPG	☒
66	13/03/18 19:59	General View	 Load JPG	☒
67	13/03/18 19:59	General View	 Load JPG	☒
68	13/03/18 19:59	General View	 Load JPG	☒
69	13/03/18 19:59	General View	 Load JPG	☒
70	13/03/18 19:59	General View	 Load JPG	☒
71	13/03/18 19:59	General View	 Load JPG	☒
72	13/03/18 19:59	General View	 Load JPG	☒
73	13/03/18 19:59	General View	 Load JPG	☒
74	13/03/18 19:59	General View	 Load JPG	☒
75	13/03/18 19:59	General View	 Load JPG	☒
76	13/03/18 19:59	General View	 Load JPG	☒
77	13/03/18 19:59	General View	 Load JPG	☒
78	13/03/18 19:59	General View	 Load JPG	☒
79	03/05/18 16:29	Reinspection Photo	Load JPG	☒
80	03/05/18 16:29	Reinspection Photo	Load JPG	☒
81	03/05/18 16:29	Reinspection Photo	Load JPG	☒
82	03/05/18 16:29	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
83	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
84	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
85	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
86	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
87	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
88	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
89	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
90	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
91	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
92	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
93	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
94	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
95	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
96	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
97	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
98	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
99	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
100	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
101	03/05/18 16:29	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 13:59	ESTIMATE	 Load PDF	
2	14/03/18 13:59	REVISED AUDATEX	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 16:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 16:40	Accident Photo	 Load JPG	☒
2	08/03/18 16:40	Accident Photo	 Load JPG	☒
3	08/03/18 16:40	Accident Photo	 Load JPG	☒
4	08/03/18 16:40	INSURED CAR	 Load JPG	☒
5	08/03/18 16:40	INSURED CAR	 Load JPG	☒
6	08/03/18 16:40	INSURED CAR	 Load JPG	☒
7	08/03/18 16:40	INSURED CAR	 Load JPG	☒
8	08/03/18 16:40	INSURED CAR	 Load JPG	☒
9	08/03/18 16:40	INSURED CAR	 Load JPG	☒
10	08/03/18 16:40	INSURED CAR	 Load JPG	☒
11	08/03/18 16:40	INSURED CAR	 Load JPG	☒
12	08/03/18 16:40	INSURED CAR	 Load JPG	☒
13	08/03/18 16:40	INSURED CAR	 Load JPG	☒
14	08/03/18 16:40	INSURED CAR	 Load JPG	☒
15	08/03/18 16:40	INSURED CAR	 Load JPG	☒
16	08/03/18 16:40	INSURED CAR	 Load JPG	☒
Documentation				

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 16:36	Sketch Plan		Load TIF
2	08/03/18 16:36	Sketch Plan #2		Load TIF
3	08/03/18 16:36	CI		Load TIF
4	08/03/18 16:36	OWNER / DRIVER IC N DL		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
 
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118004727/UQD3E2

Date: 11/05/2018

REFERENCE

Insured/Claimant: FOO CHUEN CHONG Policy No: DMPCSN3087881700
Date of Loss: 07/03/2018 Nature of Claim: OD Claim No: SNM18D01261C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL7353D**
Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A) Engine No: BLG056024
Reg. Date: 10/12/2008 (Man. Year: 2008) Chassis No: WVGZZZ1TZ9W058946
Colour: Brown Odometer: 118642 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$20,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,764.94	5,489.00	5,275.94	49.01
Miscellaneous Items	347.00	292.00	55.00	15.85
Labour	1,615.88	1,003.67	612.21	37.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,727.82	6,784.67	5,943.15	46.69
Approved Total (Overridden) (\$\$)		5,400.00		
(\$\$)	12,727.82	5,400.00	7,327.82	57.57
+ GST 7.00/7.00% (\$\$)	890.95	378.00	512.95	57.57
Nett Amount (\$\$)	13,618.77	5,778.00	7,840.77	57.57

INSPECTION

Date of Assignment: 13/03/2018 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 13/03/2018 Inspected At: Blk 9006 #01-198, Tampines Street 93
Singapore 528840
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 May 2018)
Parts: M1-MPV VOLKSWAGEN TOURAN 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJL7353D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*APPLICATOR	Not Necessary	2.70 F	*- F
2	1	NA	*BONNET	Buckled	600.00 F	*600.00 F
3	1	NA	*BONNET INSULATION	Serviceable	185.00 F	*- F
4	1	NA	*BUFFER STOP	Not Necessary	6.96 F	*- F
5	1	NA	*CLEANING SOLUTION	Not Necessary	6.36 F	*- F
6	1	NA	*COMPR/CONDENSER HOSE	Not Necessary	260.00 F	*- F
7	1	NA	*CONDENSER	Bent / Punctured	290.00 F	*290.00 F
8	1	NA	*CTR FILLER PIECE	Not Necessary	18.00 F	*- F
9	1	NA	*CUTTING FILAMENT	Not Necessary	14.00 F	*- F
10	1	NA	*EVAP/COMPRESSOR HOSE	Bent	430.00 F	*430.00 F
11	1	NA	*EVAP/CONDENSER HOSE	Not Necessary	350.00 F	*- F
12	1	NA	*FAN SHROUD	Cracked	100.00 F	*100.00 F
13	1	NA	*FRONT BUMPER	Distorted	590.00 F	*590.00 F
14	1	NA	*FRONT BUMPER SPOILER	Repair	250.00 F	*- F
15	1	NA	*FRT BUMPER C-MEMBER	Bent	200.00 F	*200.00 F
16	1	NA	*FRT BUMPER SUPPORT	Bent	270.00 F	*270.00 F
17	1	NA	*FRT CTR COWL GRILLE	Twisted	120.00 F	*120.00 F
18	1	NA	*FRT LOCK CARRIER	Twisted	585.00 F	*585.00 F
19	1	NA	*HIGH TONE HORN	Not Necessary	60.00 F	*- F
20	1	NA	*INLET WATER HOSE	Not Necessary	15.00 F	*- F
21	1	NA	*INTERCOOLER	Not Necessary	330.00 F	*- F
22	1	NA	*LABSORBER SUPPORT	Not Necessary	30.00 F	*- F
23	1	NA	*L/AIR GUIDE PANEL	Not Necessary	35.00 F	*- F
24	1	NA	*L/BONNET SEAL	Not Necessary	20.00 F	*- F
25	1	NA	*L/CHROME MLDG-BUMPER	Cracked	50.00 F	*50.00 F
26	1	NA	*L/ELECTRIC FAN	Not Necessary	380.00 F	*- F
27	1	NA	*L/F AIR GUIDE GRILLE	Not Necessary	75.00 F	*- F
28	1	NA	*L/F BUMPER GUIDE	Not Necessary	18.00 F	*- F
29	1	NA	*L/F OUT BUMPER BRKT	Bent	35.00 F	*35.00 F
30	1	NA	*L/F PROTECT MOULDING	Cracked	35.00 F	*35.00 F
31	1	NA	*L/F WHEELHOUSE COVER	Not Necessary	55.00 F	*- F
32	1	NA	*L/F WING	Repair	310.00 F	*- F
33	1	NA	*L/HORN BRACKET	Not Necessary	25.00 F	*- F
34	1	NA	*L/LOWER CAC HOSE	Not Necessary	120.00 F	*- F
35	1	NA	*L/S/MEMBER SUPPORT	Not Necessary	100.00 F	*- F
36	1	NA	*L/S-MEMB COVER PANEL	Not Necessary	190.00 F	*- F
37	1	NA	*L/S-MEMBER SUPPORT	Not Necessary	40.00 F	*- F
38	1	NA	*L/WING STRUT	Not Necessary	25.00 F	*- F
39	1	NA	*LEFT BONNET HINGE	Repair	60.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1	NA	*LEFT HEADLAMP ASSY	Not Necessary	345.00 F	*- F
41	1	NA	*LOAD AIR TUBE	Torn	210.00 F	*210.00 F
42	1	NA	*LOW TONE HORN	Not Necessary	60.00 F	*- F
43	1	NA	*LOWER LOCK	Twisted	110.00 F	*110.00 F
44	1	NA	*LOWER WATER HOSE	Not Necessary	130.00 F	*- F
45	1	NA	*PROTECTION GRILLE	Not Necessary	20.00 F	*- F
46	1	NA	*R/ABSORBER SUPPORT	Not Necessary	30.00 F	*- F
47	1	NA	*R/AIR GUIDE PANEL	Not Necessary	35.00 F	*- F
48	1	NA	*R/BONNET SEAL	Not Necessary	20.00 F	*- F
49	1	NA	*R/CHROME MLDG-BUMPER	Cracked	50.00 F	*50.00 F
50	1	NA	*R/ELECTRIC FAN	Not Necessary	260.00 F	*- F
51	1	NA	*R/F AIR GUIDE GRILLE	Missing	75.00 F	*75.00 F
52	1	NA	*R/F BUMPER GUIDE	Not Necessary	18.00 F	*- F
53	1	NA	*R/F FOG LAMP	Broken	125.00 F	*125.00 F
54	1	NA	*R/F OUT BUMPER BRKT	Bent	35.00 F	*35.00 F
55	1	NA	*R/F PROTECT MOULDING	Cracked	35.00 F	*35.00 F
56	1	NA	*R/F WHEELHOUSE COVER	Not Necessary	55.00 F	*- F
57	1	NA	*R/F WING	Repair	310.00 F	*- F
58	1	NA	*R/HORN BRACKET	Not Necessary	25.00 F	*- F
59	1	NA	*R/LOWER CAC HOSE	Not Necessary	130.00 F	*- F
60	1	NA	*R/S/MEMBER SUPPORT	Not Necessary	100.00 F	*- F
61	1	NA	*R/S-MEMB COVER PANEL	Not Necessary	190.00 F	*- F
62	1	NA	*R/S-MEMBER MOUNTING	Not Necessary	40.00 F	*- F
63	1	NA	*R/WING STRUT	Not Necessary	25.00 F	*- F
64	1	NA	*RAD GRILLE CHROME	Cracked	400.00 F	*400.00 F
65	1	NA	*RADIATOR	Bent / Twisted	300.00 F	*300.00 F
66	1	NA	*RIGHT BONNET HINGE	Repair	60.00 F	*- F
67	1	NA	*RIGHT HEADLAMP ASSY	Cracked	345.00 F	*345.00 F
68	1	NA	*SAFETY LATCH	Not Necessary	40.00 F	*- F
69	1	NA	*SPACER	Not Necessary	1.92 F	*- F
70	1	NA	*THERMOSWITCH	Not Necessary	50.00 F	*- F
71	1	NA	*TOWING EYE COVER	Not Necessary	40.00 F	*- F
72	1	NA	*TURBO PRESSURE TUBE	Not Necessary	160.00 F	*- F
73	1	NA	*UPPER AIR DUCT	Not Necessary	20.00 F	*- F
74	1	NA	*UPPER WATER HOSE	Not Necessary	130.00 F	*- F
75	1	NA	*WINDSCREEN	Cracked	450.00 F	*450.00 F
76	1	NA	*WINDSCREEN BOND KIT	Necessary	41.45 F	*41.45 F
77	1	NA	*WINDSCREEN PRIMER	Necessary	7.55 F	*7.55 F

F=Franchise part.

Total Parts (S\$)	10,764.94	5,489.00
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR-CON GAS (NECESSARY)	50.00	50.00
2	1	ANTI-FREEZE (NECESSARY)	60.00	20.00
3	1	AUDATEX FEES	42.00	42.00
4	1	ERP BRACKET (NECESSARY)	10.00	10.00
5	1	NUM PLATE & HOLDER (BROKEN)	55.00	40.00
6	1	SEALANT (NECESSARY)	30.00	30.00
7	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			347.00	292.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	462.00	373.80
2	Total Paint Materials	New	242.48	218.27
3	Total Panel/Mechanical Labour	New	911.40	411.60
Gross Labour Cost (S\$)			1,615.88	1,003.67

Report was unsubmitted during this print-out.

< END OF ESTIMATES >