



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer :	MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No. :	SQT18001069	Page	1
Registration No :	SLK9179J	Date	: 12. Mar 2018	Customer No.	: WM003
Chassis No :	JHMGK5850HX201158	Svc Advisor	: NG SIN HAI	Engine No	: L15B31190830
Model :	JAZZ 1.5VTIR CVT 17YM	Date Time	: 12. Mar 2018 7:17:36 PM	Surveyor Name	:
Owner's Name :	NG CHYE MING	Survey Date	:	Authorisation Date	:
Ins Policy No. :					
Date of Accident :	10/3/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:A29070982QMY OWNER:NG CHYE MING ACC DATE:10/03/2018 SURVEYED BY: DATE:13/03/2018 AUTHORIZED ON : REF NO :						
BOSUN	SUNDRIES	1	100.00	30 ✓	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓ 171	180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	80.00	✓ ✓	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓ 171	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL RR SEATS	1	560.00	✓ 532	560.00	39.20	599.20
BG52R	REPLACE RR. R QTR GLASS.(N)	1	280.00	✓ 266	280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	✓ ✓	80.00	5.60	85.60
BOMISC1	REMOVE AND REPLACE RHR WHEEL/RIM	1	50.00	✓ ✓	50.00	3.50	53.50
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. (N)	1	1900.00	1120? X	1900.00	133.00	2033.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00	✓ 532	560.00	39.20	599.20
BKFE22R	CUT OFF & RENEW RR R FENDER AND ALL DAMAGED PARTS	1	5000.00	3360-3192	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	2250-2137.50	3000.00	210.00	3210.00
BOMISC1	REMOVE AND REPLACED RHS SPOILER	1	180.00	✓ 171	180.00	12.60	192.60
BOMISC1	RESET AND CALIBRATE SMART ENTRY SYSTEM	1	280.00	✓ 266	280.00	19.60	299.60
			Sum Labor		12430.00	870.10	13,300.10
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓ ✓	180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SLK9179J
Chassis No : JHMGK5850HX201158
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : NG CHYE MING
Ins Policy No. :
Date of Accident : 10/3/2018

Document No. : SQT18001069 **Page** 2
Date : 12. Mar 2018
Customer No. : WM003
Svc Advisor : NG SIN HAI
Engine No : L15B31190830
Date | Time : 12. Mar 2018 7:17:36 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04715-T5B-000ZZ	FACERR.BUMPER	1 RP	492.60	35	320.19	22.41	342.60
71593-T5A-000	SPACERR.RR.BUMPER	1 net	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	5 net	2.00	35	6.50	0.46	6.96
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J	1 cut	819.60	35	532.74	37.29	570.03
42200-T5B-N52	BEARING ASSYRR.HUB	1 cut	281.80	35	183.17	12.82	195.99
42100-T5A-J75	BEAM ASSYRR.AXLE	1 cut	893.20	35	580.58	40.64	621.22
52611-T5A-J12	DAMPER UNITRR.	1 cut	212.90	35	138.38	9.69	148.07
04631-TAS-300ZZ	PANEL SET,R.SIDE	1 bt	223.30	35	145.14	10.16	155.30
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE 363.54	1 bt	537.60	35	349.44	24.46	373.90
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR	1 bt	703.40	35	457.21	32.00	489.21
67825-T5A-003	TAPER.RR.DOOR SASH	1 net	15.40	35	10.01	0.70	10.71
72824-T5A-J01	SUB SEALR.RR.DOOR	1 cut	6.30	35	4.09	0.29	4.38
72825-T5A-013	SUB SEALR.RR.DOOR CENTER	1 cut	18.30	35	11.89	0.83	12.72
72826-T5A-003	SEALRR.DOOR LOWER	2 cut	3.20	35	4.16	0.29	4.45
71800-T5B-003ZF	GARNISH ASSYR.SIDE SILL	1 cut	363.60	35	236.34	16.54	252.88
72721-T5A-003	GARNISHR.RR.DOOR	1 cut	27.90	35	18.13	1.27	19.40
74551-T5B-000	COVERR.RR.FENDER	1 cut	21.10	35	13.71	0.96	14.67
74552-T5B-003	FENDER,R.RR.INNER	1 cut	77.50	35	50.37	3.53	53.90
91514-TF0-003	CLIPSIDE SILL GARNISH 3.31	4 net	5.10	35	13.26	0.93	14.19
Sum Item					3082.78	215.79	3,298.57

15,712.99

Survey By: Tan Jia Min 97195749
 Date & Time: 13/3/18 @ 1220
 Excess: \$500
 Status: Revent.
 Signature: [Signature]

Handwritten signature and date: 15/3/18

Total Amount 15,692.78 1,098.49 16,791.27
Total (Inclusive of GST) 16,791.27

Handwritten notes:
 9 days Resurvey before paint.
 Sure@lukaup.com.
 Not Authorised.

LUK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 12/3/2018 7:50:46 PM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages.
 GST Amount is calculated from individual line(s)