



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No. : SQT18001069 Date : 12. Mar 2018 Customer No. : WM003 Svc Advisor : NG SIN HAI Engine No : L15B31190830 Date Time : 12. Mar 2018 7:17:36 PM Surveyor Name : Survey Date : Authorisation Date :	Page 1
Registration No : SLK9179J Chassis No : JHMGK5850HX201158 Model : JAZZ 1.5VTIR CVT 17YM Owner's Name : NG CHYE MING Ins Policy No. : Date of Accident : 10/3/2018		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:A29070982QMY OWNER:NG CHYE MING ACC DATE:10/03/2018 SURVEYED BY: DATE:13/03/2018 AUTHORIZED ON : REF NO :						
BOSUN	SUNDRIES	1	100.00	30 ✓	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	80.00	✓	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL RR SEATS	1	560.00	✓	560.00	39.20	599.20
BG52R	REPLACE RR. R QTR GLASS.(N)	1	280.00	✓	280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	✓	80.00	5.60	85.60
BOMISC1	REMOVE AND REPLACE RHR WHEEL/RIM	1	50.00	✓	50.00	3.50	53.50
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. (N)	1	1900.00	1120? ✓	1900.00	133.00	2033.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00	6 days ✓	560.00	39.20	599.20
BKFE22R	CUT OFF & RENEW RR R FENDER AND ALL DAMAGED PARTS	1	5000.00	3360. ✓	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	2250 ✓	3000.00	210.00	3210.00
BOMISC1	REMOVE AND REPLACED RHS SPOILER	1	180.00	✓	180.00	12.60	192.60
BOMISC1	RESET AND CALIBRATE SMART ENTRY SYSTEM	1	280.00	✓	280.00	19.60	299.60
			Sum Labor		12430.00	870.10	13,300.10
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer	: MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT18001069	Page	2
Registration No	: SLK9179J	Date	: 12. Mar 2018	Customer No.	: WM003
Chassis No	: JHMGK5850HX201158	Svc Advisor	: NG SIN HAI	Engine No	: L15B31190830
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 12. Mar 2018 7:17:36 PM	Surveyor Name	:
Owner's Name	: NG CHYE MING	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 10/3/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04715-T5B-000ZZ	FACERR.BUMPER	1 <i>Rx</i>	492.60	35	320.19	22.41	342.60
71593-T5A-000	SPACERR.RR.BUMPER	1 <i>net</i>	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	5 <i>net</i>	2.00	35	6.50	0.46	6.96
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J	1 <i>cut</i>	819.60	35	532.74	37.29	570.03
42200-T5B-N52	BEARING ASSYRR.HUB	1 ?	281.80	35	183.17	12.82	195.99
42100-T5A-J75	BEAM ASSYRR.AXLE	1 ?	893.20	35	580.58	40.64	621.22
52611-T5A-J12	DAMPER UNITRR.	1 ?	212.90	35	138.38	9.69	148.07
04631-TAS-300ZZ	PANEL SET,R.SIDE	1 <i>bt</i>	223.30	35	145.14	10.16	155.30
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE	1 <i>bt</i>	537.60	35	349.44	24.46	373.90
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR	1 <i>bt</i>	703.40	35	457.21	32.00	489.21
67825-T5A-003	TAPER.RR.DOOR SASH	1 <i>net</i>	15.40	35	10.01	0.70	10.71
72824-T5A-J01	SUB SEALR.RR.DOOR	1 ?	6.30	35	4.09	0.29	4.38
72825-T5A-013	SUB SEALR.RR.DOOR CENTER	1 ?	18.30	35	11.89	0.83	12.72
72826-T5A-003	SEALRR.DOOR LOWER	2 ?	3.20	35	4.16	0.29	4.45
71800-T5B-003ZF	GARNISH ASSYR.SIDE SILL	1 <i>cut</i>	363.60	35	236.34	16.54	252.88
72721-T5A-003	GARNISHR.RR.DOOR	1 ?	27.90	35	18.13	1.27	19.40
74551-T5B-000	COVERR.RR.FENDER	1 ?	21.10	35	13.71	0.96	14.67
74552-T5B-003	FENDER,R.RR.INNER	1 ?	77.50	35	50.37	3.53	53.90
91514-TF0-003	CLIPSIDE SILL GARNISH	4 <i>all</i>	5.10	35	13.26	0.93	14.19
Sum Item					3082.78	215.79	3,298.57

Survey By	<u>Taufik 97795749</u>	Total Amount	15,692.78	1,098.49	16,791.27
Date & Time	<u>13/3/18 @ 1220</u>	Total (Inclusive of GST),	<u>16,791.27</u>		
Excess	<u>\$500</u>				
Status	<u>Revent.</u>				
Signature	<u>Taufik</u> <i>9 days Resurvey before period. Sure @ lkhauto.com.</i>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 12/3/2018 7:50:46 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s)