

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 14 Mar 2018

Preliminary Advice

Vehicle No	: SLK9179J	Accident Date	: 10/03/2018
Make	: HONDA JAZZ	Policy No.	: A29070982QMY
Assignment Date	: 13/03/2018	Excess	: S\$500.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 9.00
Inspection At	: KAH MOTOR CO SDN BHD (ALEXANDRA) 255 ALEXANDRA ROAD SINGAPORE -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,692.78
Revised Amount	:S\$	10,008.11
Check Items (Estimated)	:S\$	2,904.48
Total	:S\$	12,912.59
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	53,997.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,003.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.