

ASS. REC. BY:

REF:

CS/MSH18004732/Tlvb

Special Instruction:

Supervisor:

Toufikhi

ASSIGNMENT (Office)

From (Person):

Eliza Hu

of

MSCH

Date/Time:

13/3/2018 10:22am

Estimated Cost:

Bill to:

 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 9179J

Insured:

at Workshop m/s

Kah Mutic

Tel:

9072 1769

of

255 Alexandra Rd

Policy No:

A29070982QMY

Claim No:

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

10/3/2018

(Client's Record)

CA REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13/3/2018 10:22am

Person Contacted:

Sin Hai

Vehicle:

 IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 9179J - X

14/3/18

Revert by merimen

14/3/18

Rece approved from Ming shao by merimen

14/3/18

Informed Sin Hai c/A ex \$500 by email

11/4/18

Final fig \$ 9626.87 (Reel 6086.12, 3915) confirmed by email

Survey Department Check List (Case Handler)

Reference No. : CS | MSG | 18004732 | Tivb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **)**: Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (_____ **)**: Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	✓			

Check By: VERON 11/4/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004732/T1vb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-03-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLK 9179J
Policy No.	A29070982QMY	Coverage (\$)	0.00
Claim No.		Excess (\$)	500.00
Assign From	MERIMEN (ELIZA HO)	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/03/2018	Inspection Date	13/03/2018
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--	--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018		13 Mar 2018 10:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG CHYE MING, ID: S6909225Z, Tel: +6596256514, Email: NOEMAIL								
Vehicle Reg. No.:	SLK9179J	Date of Loss:	10/03/2018 07:00 - :59						
Claim Type:	OD	Policy/Cover Note No.:	A29070982QMY (Comprehensive) Coverage: 06/02/2018 - 05/02/2019						
		Excess:	S\$500.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/03/2018]								
Driver/Custodian:	NG CHYE MING (48 / Male), NRIC: S6909225Z, Tel: +6596256514								
Adj Asg. Remarks:	REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SLK9179J (552171)**

OD

Mar 10 2018 7:00AM

[NG CHYE MING]

Kah Motor Co Sdn Bhd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 11/04/2018 09:34 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9626.87) - SLK9179J - Claim Handler: Eliza Ho Teng Boon

Approved:9626.87.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Eliza Ho Teng Boon	Date: 10 Apr 2018
--------------------------	-------------------

Preliminary Advice

Vehicle No	: SLK9179J	Accident Date	: 10/03/2018
Make	: HONDA JAZZ	Policy No.	: A29070982QMY
Assignment Date	: 13/03/2018	Excess	: S\$500.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 9.00
Inspection At	: KAH MOTOR CO SDN BHD (ALEXANDRA) 255 ALEXANDRA ROAD SINGAPORE -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,712.99	(incl.supplementary \$6.11)
Revised Amount	:S\$	9,626.87	(incl.supplementary \$6.11)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	9,626.87	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	53,997.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,003.00

Remarks

<input checked="" type="checkbox"/> (X)	The vehicle is economical for repair.
---	---------------------------------------

<input type="checkbox"/> ()	The above survey was conducted on a 'without prejudice' basis.
------------------------------	--

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 14 March 2018 2:57 PM
To: SUR; Ng Sin Hai (shng@kahmotor.onmicrosoft.com)
Subject: SLK 9179J-DOA: 10/3/2018 (MSIG OD)

Dear Sin Hai,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SLK 9179J (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLK9179J (552171)**
OD
Mar 10 2018 7:00AM
[NG CHYE MING]
Kah Motor Co Sdn Bhd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 14/03/2018 14:29 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10008.11) - SLK9179J - Claim Handler: Eliza Ho Teng Boon

Approved:10008.11:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Eliza Ho Teng Boon	
Date: 14 Mar 2018	
<u>Preliminary Advice</u>	

Vehicle No	: SLK9179J	Accident Date	: 10/03/2018
Make	: HONDA JAZZ	Policy No.	: A29070982QMY
Assignment Date	: 13/03/2018	Excess	: S\$500.00
Date of Inspection	: 13/03/2018	Est. Duration of Repair	: 9.00
Inspection At	: KAH MOTOR CO SDN BHD (ALEXANDRA) 255 ALEXANDRA ROAD SINGAPORE -		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,692.78
Revised Amount	:S\$	10,008.11
Check Items (Estimated)	:S\$	2,904.48
Total	:S\$	12,912.59

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	53,997.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,003.00

Remarks

The vehicle is economical for repair,

The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9225Z
Vehicle Details	
Vehicle No.:	SLK9179J
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B31190830
Chassis No.:	JHMGK5850HX201158
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,650.00
Original Registration Date:	06 Feb 2017
First Registration Date:	06 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$11,650.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Feb 2027
PARF Rebate Amount:	\$8,737.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$45,260.00
Total Rebate Amount:	\$53,997.00

The information contained herein is correct as at 14 Mar 2018

OK



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. A 29070982 QMY

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SLK9179J

2. Name of Policyholder
Ng Chye Ming

3. Effective Date of the Commencement of Insurance for the purposes of the Act
06/02/2018

4. Date of Expiry of Insurance
05/02/2019

5. Persons or Classes of Persons entitled to drive*

Ng Chye Ming

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S6909225Z**

Name:

NG CHYE MING

Birth Date: **19 Mar 1969**

Issue Date: **23 Feb 2004**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

26 Feb 1994

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms



17/428A

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 19:06
Date Of Accident	10/03/2018 07:30
Exact Location Of Accident	MACRITCHIE RESERVOIR CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK9179J
Insured/Policyholder	
Name Of Registered Owner	NG CHYE MING
NRIC No	S6909225Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96256514
Alternative Phone No	OFFICE-96256514

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29070982QMY
Cover Note Number	

Driver

Name of Driver	NG CHYE MING
NRIC No	S6909225Z
Date Of Birth	19/03/1969
Occupation	INDOOR
Date Of Driving Pass	26/02/1994
Driving Experience	24 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96256514
Fax Number	
Contact Number	OFFICE-96256514
EMail Address	NOEMAIL

Sketch Plan

Vehicle No _____

SKETCH PLAN

Annex B

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statements may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers") the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan





KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581
 Registration No : SLK9179J
 Chassis No : JHMGK5850HX201158
 Model : JAZZ 1.5VTIR CVT 17YM
 Owner's Name : NG CHYE MING
 Ins Policy No. :
 Date of Accident : 10/3/2018

Document No. : SQT18001069 Page 1
 Date : 12. Mar 2018
 Customer No. : WM003
 Svc Advisor : NG SIN HAI
 Engine No : L15B31190830
 Date | Time : 12. Mar 2018 7:17:36 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:A29070982QMY OWNER:NG CHYE MING ACC DATE:10/03/2018 SURVEYED BY: DATE:13/03/2018 AUTHORIZED ON : REF NO :						
BOSUN	SUNDRIES <i>New</i>	1	100.00	30 ✓	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓ 171	180.00	12.60	192.60
BOJSE	SEALANT FOR RHR FENDER	1	80.00	✓ ✓	80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓ 171	180.00	12.60	192.60
BMI02D	REMOVE & INSTALL RR SEATS	1	560.00	✓ 533	560.00	39.20	599.20
BG52R	REPLACE RR. R QTR GLASS.(N)	1	280.00	✓ 266	280.00	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	✓ ✓	80.00	5.60	85.60
BOMISC1	REMOVE AND REPLACE RHR WHEEL/RIM	1	50.00	✓ ✓	50.00	3.50	53.50
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. (N)	1	1900.00	1120? X	1900.00	133.00	2033.00
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00	✓ 533	560.00	39.20	599.20
BKFE22R	CUT OFF & RENEW RR R FENDER AND ALL DAMAGED PARTS <i>body</i>	1	5000.00	3360, 3192	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>Spnd.</i>	1	3000.00	2250, 2137.50	3000.00	210.00	3210.00
BOMISC1	REMOVE AND REPLACED RHS SPOILER	1	180.00	✓ 171	180.00	12.60	192.60
BOMISC1	RESET AND CALIBRATE SMART ENTRY SYSTEM	1	280.00	✓ 266	280.00	19.60	299.60
			Sum Labor		12430.00	870.10	13,300.10
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓ ✓	180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3638 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
 16 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581
 Registration No : SLK9179J
 Chassis No : JHMGK5850HX201158
 Model : JAZZ 1.5VTIR CVT 17YM
 Owner's Name : NG CHYE MING
 Ins Policy No. :
 Date of Accident : 10/3/2018

Document No. : SQT18001069 Page 2
 Date : 12. Mar 2018
 Customer No. : WM003
 Svc Advisor : NG SIN HAI
 Engine No : L15B31190830
 Date | Time : 12. Mar 2018 7:17:36 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04715-T5B-000ZZ	FACERR.BUMPER	1 pc	492.60	35	320.19	22.41	342.60
71593-T5A-000	SPACERR.RR.BUMPER	1 pc	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	5 pc	2.00	35	6.50	0.46	6.96
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J	1 pc	819.60	35	532.74	37.29	570.03
42200-T5B-N52	BEARING ASSYRR.HUB	1 pc	281.80	35	183.17	12.82	195.99
42100-T5A-J75	BEAM ASSYRR.AXLE	1 pc	893.20	35	580.58	40.64	621.22
52611-T5A-J12	DAMPER UNITRR.	1 pc	212.90	35	138.38	9.69	148.07
04631-TAS-300ZZ	PANEL SET,R.SIDE	1 pc	223.30	35	145.14	10.16	155.30
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE	1 pc	537.60	35	349.44	24.46	373.90
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR	1 pc	703.40	35	457.21	32.00	489.21
67825-T5A-003	TAPER.RR.DOOR SASH	1 pc	15.40	35	10.01	0.70	10.71
72824-T5A-J01	SUB SEALR.RR.DOOR	1 pc	6.30	35	4.09	0.29	4.38
72825-T5A-013	SUB SEALR.RR.DOOR CENTER	1 pc	18.30	35	11.89	0.83	12.72
72826-T5A-003	SEALRR.DOOR LOWER	2 pc	3.20	35	4.16	0.29	4.45
71800-T5B-003ZF	GARNISH ASSYR.SIDE SILL	1 pc	363.60	35	236.34	16.54	252.88
72721-T5A-003	GARNISHR.RR.DOOR	1 pc	27.90	35	18.13	1.27	19.40
74551-T5B-000	COVERR.RR.FENDER	1 pc	21.10	35	13.71	0.96	14.67
74552-T5B-003	FENDER,R.RR.INNER	1 pc	77.50	35	50.37	3.53	53.90
91514-TF0-003	CLIPSIDE SILL GARNISH	4 pc	5.10	35	13.26	0.93	14.19
Sum Item					3082.78	215.79	3,298.57

15,712.99

Survey By : Tanpin 97145749
 Date & Time : 13/3/18 @ 1220
 Excess : 9500
 Status : Revert.
 Signature : Tanpin # Not Authorised.

Handwritten signature and date: 15/3/18

Total Amount 15,692.78 1,098.49 16,791.27
 Total (Inclusive of GST) **16,791.27**

9 days Resurvey before paint. Sur to Likaand.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WM003 / MSIG INSURANCE
Chassis No: JHMGK5850HX201158
License No: SLK9179J
Mileage: 11173
Engine No: L15B31190830

Document No: SVO18014526
Printed By: SHNG
Order Date: 13. March 2018
Order Time: 12:42:07 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:A29070982QMY OWNER:NG CHYE MING ACC DATE:10/03/2018 SURVEYED BY:TAUFIHK DATE:13/03/2018 AUTHORIZED ON : REF NO : ADDITIONAL PART EXTERNAL LABOUR SALES - INS. EXCESS	-1	500.00		-500.00	-35.00	-535.00
54206					SUM EXCESS: -500.00	-35.00	-535.00
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	5	2.00	35	6.50	0.46	6.96
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J	1	819.60	35	532.74	37.29	570.03
04631-TA5-300ZZ	PANEL SET,R.SIDE	1	223.30	35	145.14	10.16	155.30
04636-T5B-300ZZ	PANEL SETR.RR.OUTSIDE	1	559.30	35	363.54	25.45	388.99
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR	1	703.40	35	457.21	32.00	489.21
67825-T5A-003	TAPER.RR.DOOR SASH	1	15.40	35	10.01	0.70	10.71
71800-T5B-003ZF	GARNISH ASSYR.SIDE SILL	1	363.60	35	236.34	16.54	252.88
91514-TF0-003	CLIPSIDE SILL GARNISH	1	5.10	35	3.31	0.23	3.54
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD	1	3.40	35	2.21	0.15	2.36
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD	1	3.60	35	2.34	0.16	2.50
91503-TD4-003	CLIP C,QUARTER WINDSHIELD	1	2.40	35	1.56	0.11	1.67
					SUM PARTS: 1,768.37	123.77	1,892.14
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0701 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	5	171.00	11.97	182.97
BOJSE	0701 SEALANT FOR RHR FENDER	1	80.00		80.00	5.60	85.60
BML02I	0701 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00	5	171.00	11.97	182.97
BMI02D	0701 REMOVE & INSTALL RR SEATS LININGS GARNISHES & ETC.(N)	1	560.00	5	532.00	37.24	569.24
BG52R	0701 REPLACE RR. R QTR GLASS.(N)	1	280.00	5	266.00	18.62	284.62
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BOMISC1	0701 REMOVE AND REPLACE RHR WHEEL/RIM	1	50.00		50.00	3.50	53.50
BKDR22R	0701 REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN RR R DR.(N)	1	560.00	5	532.00	37.24	569.24

} (CA)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WM003 / MSIG INSURANCE
Chassis No: JHM GK5850HX201158
License No: SLK9179J
Mileage: 11173
Engine No: L15B31190830

Document No: SVO18014526
Printed By: SHNG
Order Date: 13. March 2018
Order Time: 12:42:07 PM
Service Advisor: NG SIN HAI

BKFE22R	0671 CUT OFF & RENEW RR R FENDER AND ALL DAMAGED PARTS	1	3,360.00	5	3,192.00	223.44	3,415.44
BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,250.00	5	2,137.50	149.63	2,287.13
BOMISC1	1610 REMOVE AND REPLACED RHS SPOILER	1	180.00	5	171.00	11.97	182.97
BOMISC1	1610 RESET AND CALIBRATE SMART ENTRY SYSTEM	1	280.00	5	266.00	18.62	284.62
SUM LABOUR:					7,678.50	537.50	8,216.00
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
SUM EXT SERVICE:					180.00	12.60	192.60
TOTAL SGD					9,126.87	638.87	9,765.74
Total Payable (SGD)							9,765.74

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MSIG INSURANCE (SINGAPORE) PTE
16 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SLK9179J

Chassis No : JHMGK5850HX201158

Model : JAZZ 1.5VTIR CVT 17YM

Owner's Name : NG CHYE MING

Ins Policy No. :

Date of Accident :

Document No. : SQT18001243

Date : 23. Mar 2018

Customer No. : WM003

Svc Advisor :

Engine No : L15B31190830

Date | Time : 23. Mar 2018 3:45:06 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:A29070982QMY OWNER: ACC DATE: SURVEYED BY: DATE: AUTHORIZED ON : REF NO : SUPPLEMENTARY						
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD <i>Nee</i>	1	3.40	35	2.21	0.15	2.36
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD <i>Nee</i>	1	3.60	35	2.34	0.16	2.50
91503-TD4-003	CLIP C,QUARTER WINDSHIELD <i>Nee</i>	1	2.40	35	1.56	0.11	1.67
					Sum Item	6.11	0.42
							6.53

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 6.11 0.42 6.53

Total (Inclusive of GST) 6.53

Printed on 23/3/2018 3:47:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 11 April 2018 11:08 AM
To: 'Ng Sin Hai'; SUR
Subject: RE: Submission Pre-Invoice for vehicle SLK9179J

Dear Sin Hai,

Confirmed Cost of repair : S\$9626.87 before excess \$500 and GST

No of working days : 09 days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]
Sent: Monday, 9 April 2018 4:10 PM
To: SUR <sur@lkkauto.com>
Subject: FW: Submission Pre-Invoice for vehicle SLK9179J

Dear Veron,

Kindly assist.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



Visit our
Facebook page



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Ng Sin Hai
Sent: Friday, 23 March, 2018 4:19 PM
To: Taufikh@lkkauto.com
Subject: RE: Submission Pre-Invoice for vehicle SLK9179J

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$9,126.87 (before GST)
No of working days : 09 days.

We will proceed for closing after 1 week of submission to you.
Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018		13 Mar 2018 10:32 Edit Adj Rpt	S\$9,626.87 Edit Estimates	S\$9,626.87 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG CHYE MING , ID: S6909225Z, Tel: +6596256514, Email: NOEMAIL								
Vehicle Reg. No.:	SLK9179J	Date of Loss:	10/03/2018 07:00 - :59 [13 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 552171	Policy/Cover Note No.:	A29070982QMY (Comprehensive) Coverage: 06/02/2018 - 05/02/2019						
		Excess:	S\$500.00						
Repairer:	Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/04/2018]								
Driver/Custodian:	NG CHYE MING (48 / Male), NRIC: S6909225Z, Tel: +6596256514								
Adj Asg. Remarks:	REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (11/04/2018): Alert - Adj Mandate Approved (S\$9626.87) - SLK9179J - Claim Handler: Eliza Ho Te... MSIG_SG (14/03/2018): Alert - Adj Mandate Approved (S\$10008.11) - SLK9179J - Claim Handler: Eliza Ho T... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK9179J (552171)
OD
Mar 10 2018 7:00AM
[NG CHYE MING]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	12/03/18 19:15	Accident Statement		Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	14/03/18 13:41	Adjuster Immediate Advice		Load HTM						
2	10/04/18 11:36	Adjuster Immediate Advice		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	12/03/18 19:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
2	12/03/18 19:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
3	12/03/18 19:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
4	12/03/18 19:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
2	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
3	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
4	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
5	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
6	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
7	14/03/18 13:34	General View		Load JPG	<input checked="" type="checkbox"/>					
8	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
9	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
10	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
11	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
12	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
13	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
14	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
15	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
16	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
17	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
18	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
19	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
20	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
21	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
22	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
23	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
24	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
25	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
26	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					
27	14/03/18 13:35	General View		Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
29	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
30	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
31	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
32	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
33	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
34	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
35	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
36	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
37	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
38	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
39	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
40	14/03/18 13:35	General View	Load JPG	<input checked="" type="checkbox"/>
41	10/04/18 10:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	10/04/18 10:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	10/04/18 10:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	10/04/18 10:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	10/04/18 10:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	10/04/18 10:38	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/18 10:27	COE/PARF	Load PDF	
2	13/03/18 10:28	ESTIMATE + DRIVING LICENCE	Load PDF	
3	13/03/18 10:29	SIN HAI REQUEST FOR SURVEY	Load HTM	
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	12/03/18 19:15	Sketch Plan <small>[Linked Accident Report Documents]</small>	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 13:36	MARK ESTIMATE	Load PDF	
2	10/04/18 11:31	1ST MARK ESTIMATE	Load PDF	
3	10/04/18 11:31	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	12/03/18 19:15	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	12/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	12/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	12/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	12/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	12/03/18 19:15	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18004732/T1VBQ2

Date: 12/04/2018

REFERENCE

Insured/Claimant:	NG CHYE MING	Policy No:	A29070982QMY
Date of Loss:	10/03/2018	Nature of Claim:	OD
			Claim No: 552171

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9179J		
Make & Model:	HONDA JAZZ, 1.5 (A)	Engine No:	L15B31190830
Reg. Date:	06/02/2017 (Man. Year: 2016)	Chassis No:	JHMGK5850HX201158
Colour:	Blue	Odometer:	14858 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,202.99	1,798.37	1,404.62	43.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,510.00	7,828.50	4,681.50	37.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,712.99	9,626.87	6,086.12	38.73
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	15,212.99	9,126.87	6,086.12	40.01
+ GST 7.00/7.00% (S\$)	1,064.91	638.88	426.03	40.01
Nett Amount (S\$)	16,277.90	9,765.75	6,512.15	40.01

INSPECTION

Date of Assignment:	13/03/2018	
Date Inspected:	13/03/2018	Inspected At:
		Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD Singapore -
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts: 144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLK9179J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*FACERR.BUMPER	Repair	320.19 FS	*- FS
3	1		*SPACERR.RR.BUMPER	Necessary	7.47 FS	*7.47 FS
4	5		*CLIPBUMPER	Necessary	6.50 FS	*6.50 FS
5	1		*DISKALUMINIUM WHEEL 16X6J	Cut	532.74 FS	*532.74 FS
6	1		*BEARING ASSYRR.HUB	Serviceable	183.17 FS	*- FS
7	1		*BEAM ASSYRR.AXLE	Serviceable	580.58 FS	*- FS
8	1		*DAMPER UNITRR	Serviceable	138.38 FS	*- FS
9	1		*PANEL SET,R.SIDE	Bent	145.14 FS	*145.14 FS
10	1		*PANEL SET,R.RR.OUTSIDE	Bent	363.54 FS	*363.54 FS
11	1		*PANEL COMPR.RR.DOOR	Bent	457.21 FS	*457.21 FS
12	1		*TAPER.RR.DOOR SASH	Necessary	10.01 FS	*10.01 FS
13	1		*SUB SEALR.RR.DOOR	Serviceable	4.09 FS	*- FS
14	1		*SUB SEALR.RR.DOOR CENTER	Serviceable	11.89 FS	*- FS
15	2		*SEALRR.DOOR LOWER	Serviceable	4.16 FS	*- FS
16	1		*GARNISH ASSYR.SIDE SILL	Cut	236.34 FS	*236.34 FS
17	1		*GARNISHR.RR.DOOR	Serviceable	18.13 FS	*- FS
18	1		*COVERR.RR.FENDER	Serviceable	13.71 FS	*- FS
19	1		*FENDER,R.RR.INNER	Serviceable	50.37 FS	*- FS
20	1		*CLIPSIDE SILL GARNISH (4 PCS)	Necessary (1 PCS ONLY)	13.26 FS	*3.31 FS
21	1		*CLIP A ,QUARTER WINDSHIELD	Necessary	2.21 FS	*2.21 FS
22	1		*CLIP B ,QUARTER WINDSHIELD	Necessary	2.34 FS	*2.34 FS
23	1		*CLIP C ,QUARTER WINDSHIELD	Necessary	1.56 FS	*1.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,202.99	1,798.37
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS	New	180.00	171.00
2	SEALANT FOR RHR FENDER	New	80.00	80.00
3	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	180.00	171.00
4	REMOVE & INSTALL RR SEATS	New	560.00	532.00
5	REPLACE RR .R QTR GLASS	New	280.00	266.00
6	WINDSCREEN DAM KIT	New	80.00	80.00
7	REMOVE AND REPLACE RHR WHEEL/RIM	New	50.00	50.00
8	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS	New	1,900.00	0.00
9	REMOVE & TRANSFER ITEMS TO NEW RR R DR .ADJUST	New	560.00	532.00
10	CUT OFF & RENEW RR R FENDER AND ALL DAMAGED PARTS	New	5,000.00	3,192.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,000.00	2,137.50
12	REMOVE AND REPLACED RHS SPOILER	New	180.00	171.00
13	RESET AND CALIBRATE SMART ENTRY SYSTEM	New	280.00	266.00
14	WHEEL ALIGNMENT	New	180.00	180.00
Gross Labour Cost (S\$)			12,510.00	7,828.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >