



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer : MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No. : SQT18001243 Date : 23. Mar 2018 Customer No. : WM003 Svc Advisor : Engine No : L15B31190830 Date Time : 23. Mar 2018 3:45:06 PM Surveyor Name : Survey Date : Authorisation Date :	Page 1
Registration No : SLK9179J		
Chassis No : JHMGK5850HX201158		
Model : JAZZ 1.5VTIR CVT 17YM		
Owner's Name : NG CHYE MING		
Ins Policy No. :		
Date of Accident :		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO:A29070982QMY OWNER: ACC DATE: SURVEYED BY: DATE: AUTHORIZED ON : REF NO : SUPPLEMENTARY						
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD <i>Nee</i>	1	3.40	35	2.21	0.15	2.36
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD <i>Nee</i>	1	3.60	35	2.34	0.16	2.50
91503-TD4-003	CLIP C,QUARTER WINDSHIELD <i>Nee</i>	1	2.40	35	1.56	0.11	1.67
					Sum Item	6.11	0.42
							6.53

Survey By	_____						
Date & Time	_____				Total Amount	6.11	0.42
Excess	_____				Total (Inclusive of GST)		6.53
Status	_____						
Signature	_____						

Printed on 23/3/2018 3:47:30 PM
This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s)