

INS. CASE OWNER

CC 6/EQ1800 4735, KJ63

LKK
IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

12/21/18

Date / Time:

12/21/18

Registered in Merimen:

Pre-assign / CCU / FTE

GBE 6973C



Insured Vehicle No.

Name of Insured

STAR PEST CONTROL P/L

Insured Tel No.

HP:

Excess Sec II :\$5

D.O.A.:

2/2/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO: Driver Name / Age:

MUND AP12

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

0m1811000372

Policy No.:

0m1811000372-004509

Make / Model:

Nissan

Place of Accident:

Unit 115 A / 115 B

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

% Final? Yes / No

GBE 41699



INSRS:

WSP:

Tel:

Liability:

RMKS:

cheng
Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/21/18
ny

GBE 41699 - F
GBE 6973C - P
DID HIT STATIONARY TP
& A TAXI IN A TRAFFIC
JUNC. - NIL - 100%

@ 155 PM CALLED - NO ANSWER
21-4-18 @ 303 PM CALLED - NO ANSWER

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

NA

201 21-4-18

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

PRELIMINARY ADVICE

Date/Time:

12/21/18

Sent By:

DN

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

() days

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

5/11/18

Confirm with:

JUNE

Email

Call

Final Liability:

SS

100

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

SS

2,568.22

Loss of Rental (LOR):

SS

360

(560 x 6 days)

Loss of Use (LOU):

SS

360

(560 x 6 days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS

8.22

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

2,936.22

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,936.22

Name 1:

CHENG HOE HIOH PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

01 HIT STATIONARY TP.

2/11/18

00-81

blu

ASS. REC. BY:

REF:

EQ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

06 days

Res: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBC 41896

Yr Regn: 03.12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: _____

Ford Probe

c.c.

1248

Colour

N. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

95292

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ZFA223000

05635307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. _____

7

mm

Rear

R/Bal. _____

7

mm

L/Bal. _____

7

mm

L/Bal. _____

7

mm

D.O.A. _____

2/2/18

D.O.I. _____

12/3/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/3 Pk path to Carhome

L1 Pkg @ 24000 Carhome June 06X60

R (\$ 1092 + 10/31%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS - SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ118004735/Kjb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110		Date : 13-03-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 6973C	Veh. Inspected	GBC 4169G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/02/2018	Inspection Date	12/03/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/EQ118004735/Kjb3

Date: 13.03.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBC4169G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.03.2018 at the premises of M/s Cheng Hoe Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,030.00
Revised Estimate Amount	: S\$	2,790.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Cheng Hoe Motor Pte Ltd.

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBC 4169G
TP/EQ

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

Claim No: ES1890243
Estimate No: ES1890243/YISHUN
Date: 12 Mar 2018
Policy No: 17-MX002101-R03
Veh Reg No: GBC4169G
Make/Model: FIAT DOBLO 1.3MJTD
Chassis No: ZFA22300005635307
Engine No: 199A20002773784
Reg. Date: 26/03/2012

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 02/02/2018
TP Veh Reg No: GBE6973C

Not Noted
11 Sep @ ?
Survey After Point
6 days

Estimate Repair Cost to Vehicle No : GBC4169G

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Cost Plus				
1 REAR LH BUMPER SIDE PAD	150.00	1 PC <i>M/LA</i>	150.00	✓
2 REAR LH SIDE PANEL	580.00	1 PC <i>B</i>	580.00	✓
3 LH TAILLAMP	120.00	1 PC <i>CM</i>	120.00	✓
4 LH SLIDING DOOR GLASS	200.00	1 PC <i>LT</i>	200.00	✓
			1,050.00	
	Add 20%		210.00	1,260.00
Special Net				
5 LH SLIDING DOOR GLASS GUM	40.00	1 PC <i>me</i>	40.00	✓
				40.00
Labour				
6 REMOVE & REFIX LH SLIDING DOOR ASSY, TRACK ROLLER, LH TAILLAMP, REAR BUMP, TO CUT, WELD & RENEW REAR LH SIDE PANEL, KNOCK & REPAIR LH TAILLAMP PANEL, REAR LH FENDER INNER PANEL & REALIGN THE SAME	800.00	1 LA	800.00	<i>Foot</i>
7 REMOVE & REFIX LH SLIDING DOOR GLASS	80.00	1 LA	80.00	<i>600</i>
8 REMOVE & REFIX TOP ROOF LINING, SEAT, CARPET, ETC	120.00	1 LA	120.00	<i>100</i>
9 PUTTY & RESPRAY LH SLIDING DOOR, REAR LH SDIE PANEL, REAR BUMPER & REAR AFFECTED AREAS	700.00	1 LA	700.00	<i>800</i>
10 RUSTPROOFING	30.00	1 LA	30.00	✓
				1,730.00

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Total SS 3,030.00
Add GST @ 7% 212.10
Total Amount payable SS 3,242.10

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Bk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBC4169G
SUPP 1

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 02/02/2018
TP Veh Reg No: GBE6973C

Claim No: ES1890243
Estimate No: ES1890243/YISHUN
Date: 16 Mar 2018
Policy No: 17-MX002101-R03
Veh Reg No: GBC4169G
Make/Model: FIAT DOBLO 1.3MJTD
Chassis No: ZFA22300005635307
Engine No: 199A20002773784
Reg. Date: 26/03/2012

Estimate Repair Cost to Vehicle No : GBC4169G

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 LH TAILLAMP OUTER GARNISH	130.00	1 PC CM	130.00	—
2 LH TAILLAMP SIDE GARNISH	65.00	1 PC CM	65.00	—
			195.00	
	Add 20%		39.00	234.00
Total				S\$ 234.00
GST Amount				S\$ 16.38
Total Amount payable				S\$ 250.38

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 6820N

Vehicle Details

Vehicle No.: GBC4169G

Vehicle to be Exported: Yes

Intended De-registration
Date: 05 Feb 2018

Vehicle Make: FIAT

Vehicle Model: DOBLO 1.3MJTD

Primary Colour: Blue

Manufacturing Year: 2008

Engine No.: 199A20002773784

Chassis No.: ZFA22300005635307

Maximum Power Output: -

Open Market Value: \$20,134.00

Original Registration Date: 26 Mar 2012

First Registration Date: 26 Mar 2012

Transfer Count: 0

Actual ARF Paid: \$1,007.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Mar 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$50,009.00

COE Rebate Amount: \$20,689.00

Total Rebate Amount: \$20,689.00

The information contained herein is correct as at 05 Feb 2018

OK

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Saturday, 21 April 2018 1:59 PM
To: 'azmi@starpest.sg'
Subject: ACCIDENT INVOLVING GBE 6973C AND GBC 4169G ON 02/02/2018 ALONG AMK AVE 9/AVE 6

Our Ref: CC6/EQ18004735/Kjb3

STAR PEST CONTROL PTE LTD

Policy Holder

ATTENTION : Mr. Mohd Afiz and Insurance Policy person-in-charge

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 6973C AND GBC 4169G ON 02/02/2018 ALONG AMK AVE 9/AVE 6

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,


Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Your Ref :

THE MOTOR CLAIMS DEPT
EQ INSURANCE CO LTD

WITHOUT PREJUDICE

Singapore

40 LKK

Dear Sir / Madam

**T/ACCIDENT INVOLVING M/V GBC4169G & GBE6973C ON 02/02/2018
ALONG JUNCTION OF AMK AVE 6 & AVE 9.**

We are authorized by the owner of GBC4169G for his/her/their above claims.

As you are the insurer of GBE6973C, we therefore wish to seek your compensation.
Quantum of the claims as follow:-

COST OF REPAIR	: S\$	2568.00	(As recommended by Licensed Surveyor/ your appointed surveyor)
LOSS OF USE (6 x \$60/day)	: S\$	360.00	
HIRE OF VEHICLE DAYS	: S\$	—	
SURVEY FEE	: S\$	0.00	
LTA SEARCH	: S\$	8.00	
GIA SEARCH	: S\$	0.00	
OTHERS	: S\$	0.00	
	S\$	2936.00	

Copies of all the relevant documents (including a set of survey report/ photographs) are enclosed.

Please advise settlement within ten (10) days.

Thank you.

Yours Faithfully,



LETTER OF AUTHORISATION

Re: Motor Insurance Claim GBC4169G
in respect of the traffic accident on 02/02/2018
at/along Junction of Ang Mo Kio Ave 6 & Ave 9

I/We, Li Chuan Food Products Pte Ltd
NRIC 199306820N of 40 Woodlands Terrace S738456

owner of motor vehicle GBC4169G, insured by Tokio Marine Ins
Singapore Ltd under policy no. 17-MX002101-R03

hereby authorise **M/s CHENG HOE MOTOR PTE LTD** on Blk 1019 Yishun Industrial Park A #01-374 Singapore 768761, to act as my/our representative in my/our claim against the owner /driver of motor vehicle GBE6973C in respect of the above-mentioned accident.

I/We further authorise that any payment due to me/us from the aforesaid claim is to be directed to my/our abovenamed representative.

And I/We hereby indemnify my/our abovenamed representative against any claim and/or damage which may arise from any action taken on my/our behalf.

I/We affirm all the above by my/our signature below.

Signed : 

Date : 5/2/18

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

ORIGINAL

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 02/02/2018
TP Veh Reg No: GBE6973C

Final Repair Bill

Claim No: ES1890243
NO: PS1801215
Date: 19 Oct 2018
Policy No: 17-MX002101-R03
Veh Reg No: GBC4169G
Make/Model: FIAT DOBLO 1.3MJTD

Description

To Supply all replaced parts, all necessary and agreed labour &
miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity	List Price	Amount
	<u>SS</u>	<u>SS</u>
1 PC	S\$ 2,400.00	S\$ 2,400.00

Total	S\$ 2,400.00
Add GST @ 7%	168.00
Total Amount payable	S\$ 2,568.00

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

Enquire Vehicle & Owner Information (Vehicle No. GBE6973C As At 02 Feb 2018 / 20:50:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-GBC4169

Current Owner Details

Owner ID Type: Company

Owner ID: 200000913N

Owner Name: STAR PEST CONTROL PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House
No.: 25

Registered Street Name: MANDAI ESTATE

Registered Unit No.: # 01 - 06

Registered Building Name: INNOVATION PLACE

Registered Postal Code: 729930

Current Vehicle Details

Vehicle No.: GBE6973C

Make Description/Model: NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Insurance Company Name: EQ INSURANCE COMPANY LTD



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 09/11/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBE 6973C (Insd Veh)	Your Ref. No. : DM18HO00372
	GBC 4169G (TP Veh)	Our Ref. No. : CC6/EQI18004735/Kjb3q2
Date of Accident	2/2/2018	

Liability	100%	
Final Repair Cost	: \$ 2,568.00	
Loss of Use	: \$ 360.00	6 days
Rental (If any)	: \$	days
Others:	: \$ 8.00	
	: \$	
	2,936.00	
Final Settlement Sum	: \$ 2,936.00	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	CHENG HOE MOTOR PTE LTD	: \$ 2,936.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ18004735/Kjb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 09-11-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 6973C	Veh. Inspected	GBC 4169G	
Policy No.	DMCPHQ17-004509	Coverage (\$)	0.00	
Claim No.	DM18HO00372	Excess (\$)	0.00	
Assign From		Assign Date	12/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO (M)	c.c	1248	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	ZFA22300005635307	Colour	METALLIC BLUE	
Odometer	95292	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	185/65 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	185/65 R15	BRIDGESTONE	7 mm	
L/H Rear Tyre	185/65 R15	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2018	Inspection Date	12/03/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 4169G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LH BUMPER SIDE PAD (WCP)	DENTED / CUT	150.00	150.00
1	REAR LH SIDE PANEL (WCP)	BENT	580.00	580.00
1	LH TAILLAMP (WCP)	CRACKED	120.00	120.00
1	LH SLIDING DOOR GLASS (WCP)	CUT	200.00	200.00
1	LH TAILLAMP OUTER GARNISH (WCP) (ADDITIONAL)	CRACKED	130.00	130.00
1	LH TAILLAMP SIDE GARNISH (WCP) (ADDITIONAL)	CRACKED	65.00	65.00
	COST PLUS 20% (PARTS SUPPLIED BY WORKSHOP)		249.00	249.00
			1,494.00	1,494.00
	SPECIAL NETT ITEMS			
1	LH SLIDING DOOR GLASS GUM (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	LABOUR			
	REMOVE & REFIX LH SLIDING DOOR ASSY ,TRACK ROLLER ,LH TAILLAMP ,REAR BUMP ,TO CUT ,WELD & RENEW REAR LH SIDE PANEL ,KNOCK & REPAIR LH TAILLAMP PANEL ,REAR LH FENDER INNER PANEL & REALIGN THE SAME.		800.00	700.00
	REMOVE & REFIX LH SLIDING DOOR GLASS .		80.00	60.00
	REMOVE & REFIX TOP ROOF LINING,SEAT ,CARPET ,ETC .		120.00	100.00
	PUTTY & RESPRAY LH SLIDING DOOR ,REAR LH SIDE PANEL ,REAR BUMPER & REAR AFFECTED AREAS.		700.00	600.00
	RUSTPROOFING.		30.00	30.00
			1,730.00	1,490.00
	GRAND TOTAL		3,264.00	3,024.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00

Report Ref No. CC6/EQ118004735/Kjb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.