



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 BMW Z4 2.5 SPORTS COUPE (SKB7170E)

Date of Loss

8 March 2018

Time of Loss

14.20

Loss Description

REFER TO E-FILE REPORT

Comment

Workshop Details

Total Rebate Amount

52829

Nett Loss Amount

\$24,171.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/05/2018



Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKB7170E

Purchase Date
dd/mm/yyyy

Registration State
SINGAPORE

Registration Date *
24/06/2011

Mileage
38151

Age of Vehicle
6

CATEGORY Manufacturing Year

Driver Details

POLICY INFORMAT... 2011

CATEGORY Driver Name

ASSESSMENT INFO... 2011

FNOL INFORMATI... CHUN FONG PHONG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... BMW

ASSESSMENT INFO... B.M.W.

CATEGORY Model

POLICY INFORMAT... Z4 2.5 SPORTS COUPE

ASSESSMENT INFO... Z4 SDRIVE 23I 2.5L AT D/AB 2WD HID

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WBALM32050E494534

CATEGORY Date of Birth

FNOL INFORMATI... 1 April 1988

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 30

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI... 3

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 15577787N52B25AF

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... S8870101A

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 25 February 2015

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI... 1 January 2050

POST SURVEY INF... 

CATEGORY	Address
FNOL INFORMATI...	Singapore
POST SURVEY INF...	

CATEGORY	Address type
FNOL INFORMATI...	Personal Correspondence
POST SURVEY INF...	

CATEGORY	Gender
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Marital status
FNOL INFORMATI...	Unknown
POST SURVEY INF...	

CATEGORY	Identification #
FNOL INFORMATI...	S8870101A

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1600

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/35ZR19

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

255/30ZR19

Front left side

KUMHO5mm

Front right side

KUMHO5mm

Rear left side

KUMHO7mm

Rear right side

KUMHO7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT BUMPER			Cracked	980				980	Review
		2	1			FRONT BUMPER SIDE RETAINER LH			Damaged	38				38	Review
		3	1			FRONT BUMPER SIDE RETAINER RH			Serviceable	0	0	0	0	0	Deny
		4	10			FRONT BUMPER CLIP			Necessary	1.5				15	Review
		5	1			FRONT BUMPER REINFORCEMENT			Bent	610				610	Review
		6	1			FRONT FENDER LH			Repair	0	0	0	0	0	Deny
		7	1			FRONT FENDER COWLING			Cracked	90				90	Review
		8	15			FRONT FENDER COWLING CLIP			Serviceable	0	0	0	0	0	Deny
		9	1			HEADLAMP LH			Damaged	2280				2280	Review
		10	1			HEADLAMP NOZZLE LH			Cracked	105		0		105	Review
		11	1			HEADLAMP NOZZLE COVER LH			Damaged	30				30	Review
		12	1			HEADLAMP TOP PANEL LH			Repair	0	0	0	0	0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			FRONT BONNET			Bent	2000				2000	Review
		14	10			FRONT BONNET INSULATOR CLIP			Necessary	1.5				15	Review
		15	1			HEADLAMP LOWER BEAM LH			Damaged	220				220	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
		1		TO CHECK WIRING AND REFOCUS HEADLAMP	20	0	0	Reviewing		1
		2		TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	0	0	0	Deny		1
		3		TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD FRONT SUPPORT PANEL & HEADLAMP TOP PANEL. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	500	0	0	Reviewing		1
		4		TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT SUPPORT PANEL AND EFFECTED AREAS	500	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

RADIATOR
AIR
GUIDE
RIVET - 4
PC

Reviewing

6

(NECESSARY)
SUPP 1 -
16/03/2018



2

FRONT
FENDER
COWLING
LH - REAR
PORTION

Reviewing

90

(CRACKED)
SUPP 1 -
16/03/2018



3

FRONT
BUMPER
SENSOR

Reviewing

160

MISSING



4

DAYS OF
REPAIR : 4
DAYS

Reviewing



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$6,059.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,020.00	\$1,020.00
Spare Parts	\$6,383.00	\$6,383.00
Miscellaneous	\$256.00	\$256.00
Excess	-\$1,600.00	-\$1,600.00

Submit for Review