

ASS. REC. BY:

REF:

CS/SM018064745/Kvd3m

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Henry

of

SMO

Date/Time: 12/13/18 @ 3:53pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 6128 D

Insured:

FBM 1882Y

at Workshop m/s

Ah Lim Motor

Tel:

6483 1244

of

10, AMK Ind. Prk 2A #01-09

Policy No:

GA 081369/1

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 07/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

wup

H.O.D. Endorsement:

Date/Time:

10:42am @ 13/3/18

Person Contacted:

Zila

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate	
	SKH 6128 D - CV1 / VAL 17024351 / UV	D.O.A: 19/12/17
	FBM 1882Y - CS/SM018004544/Kvd3	D.O.A: 19/12/17
15/3/18	Email preli revised to Irene	
20/4/18	Kenneth confirmed: LS \$3600 (Red 4705, 569)	

ASS. REC. BY:

REF: *SMO1*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4-5 days

Res.: Yes or No

Lum Sum: _____

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

14/3 File pass to Cothorne

RECEIVED 2 9 APR 2010

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

20/4 - typst

Report Format :

TP

Lump Sum / I.B.I: (\$

3600/2

Veh No: *SKH 612PD*Yr Regn: *12, 12*Type: *M.Gar* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

*A Wagon*Make: *Ford**Mondeo*

c.c:

*1999*Colour: *M. Grey*

A/C: Insured / Std / Nil / NA

Sp. Reading: *119061*

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: *WFOGXG BBGCK 78900*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *225/45R17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. *4* mmR/Bal. *5* mmL/Bal. *4* mmL/Bal. *3* mmD.O.A. *7/3/18*D.O.I. *13/3/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or *None N/S*

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: *4*Resurvey No. of Trlp: *1*

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

250

Survey Department Check List (Case Handler)

Reference No.: CS/SMD 1800 4745 Kvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 20/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO18004745/Kvd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623			Date : 13-03-2018	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBM 1882Y	Veh. Inspected	SKH 6128D	
Policy No.	GA081369/1	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/03/2018	Inspection Date	13/03/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GA081369/1

Our ref: CS/SMO18004745/Kvd3

DATE: 15/3/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKH 6128D


We thank you for your instruction on 12/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/3/2018 at the premises of M/s AH LIM MOTOR CO and have the following to report:-

Workshop Estimate Amount	: S\$8,305.00
Revised Estimate Amount	: S\$3,037.50
"Check" Items Amount	: S\$4,313.75
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>
Sent: Wednesday, 14 March, 2018 2:26 PM
To: Zila - Ah Lim Motor Co (AMK)
Cc: assignments; Catherine Chong (LKK Auto)
Subject: RE: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y

WITHOUT PREJUDICE

Our ref : CMTD1801028

Dear Zila,

Liability is clear and appreciate you could finalize your repair cost and duration to repair with our appointed surveyor.

Best Regards,

Shawn Ngo

Claims Division

D: 6329 5202 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zila - Ah Lim Motor Co (AMK) [mailto:zila@ahlimmotor.com.sg]
Sent: Tuesday, March 13, 2018 4:01 PM
To: Ngo, Sau Wei Shawn
Cc: assignments; Catherine Chong (LKK Auto)
Subject: Re: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y

Hi Shawn,

Pls advise liability for this case.

Thanks.

Best Regards

Zila

Ah Lim Motor Company

10, Ang Mo Kio Ind Park 2A

#01-09 AMK Autopoint

Singapore 568047

Tel - 64831244 Fax - 64836170

From: [Henry, Irene James](#)

Sent: Monday, March 12, 2018 3:52 PM

To: [Zila - Ah Lim Motor Co \(AMK \)](#)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 March 2018 8:48 AM
To: 'Henry, Irene James'
Cc: 'Ngo, Sau Wei Shawn'; SUR
Subject: RE: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y
Attachments: SKH 6128D PRELI ADVISED.pdf

Dear Irene,

Enclosed preliminary revised of vehicle SKH 6128D
Date of survey: 13/3/2018
Number of days: 4-5 days

Some of the parts, pending for parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 13 March 2018 10:43 AM
To: 'Henry, Irene James' <irene.henry@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Monday, 12 March 2018 3:53 PM
To: Zila - Ah Lim Motor Co (AMK) <zila@ahlimmotor.com.sg>
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; assignments <assignments@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: RE: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y

WITHOUT PREJUDICE

Hi Zila,

We refer to the above matter.

Please be informed that Shawn Ngo is the handler for this matter.

We will be appointing LKK AUTO CONSULTANTS PT LTD to conduct the mentioned survey.

Aside to LKK AUTO,

Kindly assist to conduct motor survey of the mentioned.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zila - Ah Lim Motor Co (AMK) [<mailto:zila@ahlimmotor.com.sg>]

Sent: Monday, 12 March, 2018 11:12 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y

Hi Claims Dept,

Kindly arrange for survey.

Note: Owner will send vehicle Tue 13/03/2018 @ 1-4 pm.

Vehicle will be @ ALM AMK Autopoint workshop.

Best Regards

Zila

Ah Lim Motor Company

10, Ang Mo Kio Ind Park 2A

#01-09 AMK Autopoint

Singapore 568047

Tel - 64831244 Fax - 64836170

Catherine Chong (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Monday, 12 March, 2018 3:53 PM
To: Zila - Ah Lim Motor Co (AMK)
Cc: Ngo, Sau Wei Shawn; assignments; Catherine Chong (LKK Auto)
Subject: RE: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y
Attachments: 6128.pdf; 6128 - AXA.PDF

WITHOUT PREJUDICE

Hi Zila,

We refer to the above matter.

Please be informed that Shawn Ngo is the handler for this matter.

We will be appointing LKK AUTO CONSULTANTS PT LTD to conduct the mentioned survey.

Aside to LKK AUTO,

Kindly assist to conduct motor survey of the mentioned.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Zila - Ah Lim Motor Co (AMK) [mailto:zila@ahlimmotor.com.sg]

Sent: Monday, 12 March, 2018 11:12 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Henry, Irene James <irene.henry@sompo.com.sg>

Subject: TP / OUR CLIENT SKH6128D DOA: 07/03/2018 POLICY NO. GA081369/1 YOUR INSURED FBM1882Y

Hi Claims Dept,

Kindly arrange for survey.

Note: Owner will send vehicle Tue 13/03/2018 @ 1-4 pm.

Vehicle will be @ ALM AMK Autopoint workshop.

Best Regards

Zila

Ah Lim Motor Company

10, Ang Mo Kio Ind Park 2A

#01-09 AMK Autopoint

Singapore 568047

Tel - 64831244 Fax - 64836170

Register New Vehicle (Acknowledgement)**Vehicle Particulars**

Vehicle No.:	SKH6128D	Vehicle Scheme:	Normal
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	FORD	Vehicle Model:	MONDEO TITANIUM 2.0 AT 2WD 5DR WAGON
Chassis No.:	WF0GXXGBBGCK28900	Engine No.:	CK28900
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1999 cc	Power Rating:	-
Unladen Weight:	1588 kg	Maximum Laden Weight:	2380 kg
Primary Colour:	Brown	Secondary Colour:	-
First Registration Date:	28 Dec 2012	Original Registration Date:	28 Dec 2012
Manufacturing Year:	2012	Open Market Value:	\$23,211.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$11,605.00
No. of Transfers:	0		

Owner Particulars

Owner Name:	WONG HUNG-YIN BETINA CLAIRE
Owner ID Type:	Singapore NRIC
Owner ID:	S1828204F
Registered Address Type:	HDB / HUDC
Registered Block/House No.:	509
Registered Street Name:	SERANGOON NORTH AVENUE 4
Registered Unit No.:	# 05 - 366
Registered Building Name:	-
Registered Postal Code:	550509
COE No. / Expiry Date:	2013010103000572M / 27 Dec 2022
COE Bid Category:	B - Car (1601cc & above)
QP Paid:	\$93,501.00

Transaction Details

Business Transaction Ref. No.:	20121228093950530786
Business Transaction Date:	28 Dec 2012
Business Transaction Time:	09:39:50

Message

The above vehicle has been successfully registered.

Please note that \$107,458.00 will be deducted from your GIRO account.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/03/2018 15:35
Date Of Accident	07/03/2018 09:10
Exact Location Of Accident	CTE (TOWARDS TOWN)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH6128D
Insured/Policyholder	
Name Of Registered Owner	WONG HUNG-YIN BETINA CLAIRE
NRIC No	S1828204F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91444201
Alternative Phone No	OFFICE-97881053
Vehicle Particulars	
Manufacturer	FORD
Model	MONDEO TITANIUM 2.0 AT 2WD 5DR WAGON
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA081369/1
Cover Note Number	28/12/2017 - 27/12/2018
Driver	
Name of Driver	LIM CHOO TIONG HOWARD
NRIC No	S1695648A
Date Of Birth	07/10/1965
Occupation	INDOOR
Date Of Driving Pass	22/01/1990
Driving Experience	28 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97881053
Fax Number	
Contact Number	OTHERS-91444201
Email Address	HOWARD166@GMAIL.COM

Address	BLK 509 SERANGOON NORTH AVE 4 #05-366
Postcode	550509
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	JEFF
Phone Number	81884658
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM1882Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	SHAUN
NRIC/Passport Number	
Contact Number	93835148
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJH8297Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ROGER

NRIC/Passport Number

Contact Number

92337554

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 2/3/2018



Reporting Police Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 7/3/2018 Time: 09:10 Location: CTE (Towards Town)
 My Vehicle A: SKH6128D Vehicle B: SJH 8297Y Vehicle C: FBM 1882Y
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Motorcycle rear ended my car (SKH6128D) on 7/3/2018 @ 0910 hrs.

Vehicle A: SKH6128D

Vehicle B: SJH 8297Y (Roger: 9233 7554)

Vehicle C: FBM 1882Y (Shaun: 9383 5148)

Video clips provided: (Jeff @ 8188 4658) -> witness of the accident.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
 Email address :
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)(65) 6880 4740
customer.care@axa.com.sg

www.axa.com.sg

account number
04111

Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980 - Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	WONG HUNG-YIN BETINA CLAIRE	Certificate number	QA081369 / 1
Cover	Comprehensive	Chassis number	WFOGXXGBGCK28900
Plan name	For Her	Engine number	CK28900
NCD applicable	50%		
Vehicle registration number	SKH6128D		
Period of Insurance	from 28/12/2017 to 27/12/2018 (both dates inclusive)		
Finance loan company	OCBC BANK LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any Named Driver as stated in the Policy:
1. LIM CHOO TIONG HOWARD
(c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS Windscreen Excess

Not Applicable

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

Sketch Plan Pg. 4

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1695648A



NAMING
LIM CHOO TIONG HOWARD

RACE
CHINESE
Date of birth: 07-10-1965 Sex: M
Country of birth
SINGAPORE



97331032
o/c
for copy
1 per



Identity Card No. S1695648A



Date of issue
10-04-2012

Address:
APT BLK 509 SERANGOON NORTH AVENUE 4
#05-366
SINGAPORE 550509

4850512

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
22 Jan 1990

NP 428A





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WONG HUNG-YIN BETINA CLAIRE
 BLK 509 SERANGOON NORTH AVE 4
 #05-366
 SINGAPORE 550509
 TEL: 97881053
 ATTN: Motor Claim Department

Estimate No: MC0912926
 Date: 09 Mar 2018
 Policy No: GA081369/1
 Veh Reg No: SKH6128D
 Make/Model: FORD MONDEO
 TITANIUM 2.0

Your Ref No: SKH6128D
 Claim Type: Third Party
 Accident Date: 07/03/2018

Not Authorized
1-B1
Resurvey B4 parts
4-5 days

TP Vehicle: FBM1992Y

Estimate Repair Cost to Vehicle No :SKH6128D

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 TAILGATE		1 PC	B1 1,250.00	✓ 2 R
2 TAILGATE LOWER MOULDING		1 PC	B1 370.00	✓
3 TAILGATE EMBLEM (MONDEO)		1 PC	NEL 60.00	?
4 TAILGATE TITANIUM LOGO - CHECK PRICE		1 PC	NEL 0.0000	7 SS
5 TAILGATE ECO SYSTEM BADGE - CHECK PRICE		1 PC	NEL 0.0000	7 68
6 TAILGATE INNER LOCK		1 PC	R 125.00	X
7 TAILGATE RUBBER		1 PC	Sm 238.00	X
8 REAR BUMPER		1 PC	Bu 1,173.00	✓
9 REAR BUMPER SIDE RETAINERS LH - CHECK PRICE		1 PC	Sm 0.0000	X
10 REAR BUMPER SIDE BRACKET LH - CHECK PRICE		1 PC	R 0.0000	X
11 REAR BUMPER CTR BRACKET		1 PC	R 55.00	?
12 REAR BUMPER LOWER SPOILER (DUAL EXHAUST PIPE)		1 PC	SVL 220.00	?
13 REAR BUMPER REFLECTOR LH		1 PC	CM 45.00	✓
14 REAR BUMPER REINFORCEMENT		1 PC	R 530.00	?
15 REAR BUMPER PARKING SENSOR OUTER LH - CHECK PRICE		1 PC	Sm 0.0000	X
16 REAR BUMPER PARKING SENSOR HOLDER - CHECK PRICE		4 PC	Sm 0.0000	X
17 REAR BUMPER TOP CHROME PLATE		1 PC	NL 250.00	✓
18 REAR END PANEL OUTER - CHECK PRICE		1 PC	R 0.0000	?
19 REAR EXHAUST PIPE CHROME - CHECK PRICE		1 PC	NL 0.0000	✓ 600
20 REAR WINDSCREEN MOULDING WITH GLASS - CHECK PRICE		1 PC	NN 0.0000	?
			4,316.00	
			1,079.00	5,395.00
Special Nett				
21 INNER SEAL		1 PC	NH 20.00	?
22 WINDSCREEN SEALANT		1 PC	NN 40.00	?
				60.00
LABOUR				
23 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC		40.00 201
24 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1 PC	NH 150.00	?
25 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	NH 120.00	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WONG HUNG-YIN BETINA CLAIRE
BLK 509 SERANGOON NORTH AVE 4
#05-366
SINGAPORE 550509
TEL: 97881053
ATTN: Motor Claim Department

Estimate No: MC0912926
Date: 09 Mar 2018
Policy No: GA081369/1
Veh Reg No: SKH6128D
Make/Model: FORD MONDEO
TITANIUM 2.0

Your Ref No: SKH6128D
Claim Type: Third Party
Accident Date: 07/03/2018

Estimate Repair Cost to Vehicle No :SKH6128D

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
26 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		1 PC	NH 80.00	?
27 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC		120.00 600
28 TO RESET REVERSE SENSOR		1 PC	NH 180.00	?
29 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.		1 PC	NH 80.00	?
30 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.		1 PC		80.00 600
31 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC		1,000.00 ? 500
32 TO SPRAY TAILGATE,TAILGATE TRIM LOWER,REAR BUMPER.		1 PC		1,000.00 600
				2,850.00
				9208.75
Amount Before Excess				S\$ 8,305.00
Add GST @ 7%				581.35
Total Amount payable				S\$ 8,886.35

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED EIGHTY SIX AND CENTS THIRTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WONG HUNG-YIN BETINA CLAIRE
BLK 509 SERANGOON NORTH AVE 4
#05-366
SINGAPORE 550509

TEL: 97881053

ATTN: Motor Claim Department

Your Ref No: SKH6128D

Claim Type: Third Party

Accident Date: 07/03/2018

Estimate No: MC0912926

Date: 09 Mar 2018

Policy No: GA081369/1

Veh Reg No: SKH6128D

Make/Model: FORD MONDEO
TITANIUM 2.0

TP Vehicle: FBM1392Y

*Not Authorized
Resony B4pam
4-5 days*

Estimate Repair Cost to Vehicle No :SKH6128D

Description	U/Price	Quantity	Cost SS	Amount SS
SPARE PARTS				
1 TAILGATE	R	1 PC	1,250.00	X Repair
2 TAILGATE LOWER MOULDING	protech	1 PC	370.00	✓
3 TAILGATE EMBLEM (MONDEO)	nn	1 PC	60.00	✓ photo
4 TAILGATE TITANIUM LOGO - CHECK PRICE	nn	1 PC	0.0000	✓ photo
5 TAILGATE ECO SYSTEM BADGE - CHECK PRICE	nn	1 PC	0.0000	✓ photo
6 TAILGATE INNER-LOCK		1 PC	125.00	X
7 TAILGATE RUBBER		1 PC	238.00	X
8 REAR BUMPER		1 PC	1,173.00	✓
9 REAR BUMPER SIDE RETAINERS LH - CHECK PRICE		1 PC	0.0000	X
10 REAR BUMPER SIDE BRACKET LH - CHECK PRICE		1 PC	0.0000	X
11 REAR BUMPER CTR BRACKET	R	1 PC	55.00	7
12 REAR BUMPER LOWER SPOILER (DUAL EXHAUST PIPE)	nn	1 PC	220.00	7
13 REAR BUMPER REFLECTOR LH		1 PC	45.00	✓
14 REAR BUMPER REINFORCEMENT	R	1 PC	530.00	7
15 REAR BUMPER PARKING SENSOR OUTER LH - CHECK PRICE		1 PC	0.0000	X
16 REAR BUMPER PARKING SENSOR HOLDER - CHECK PRICE		4 PC	0.0000	X
17 REAR BUMPER TOP CHROME PLATE		1 PC	250.00	✓
18 REAR END PANEL OUTER - CHECK PRICE	R	1 PC	0.0000	X 600t
19 REAR EXHAUST PIPE CHROME - CHECK PRICE		1 PC	0.0000	✓
20 REAR WINDSCREEN MOULDING WITH GLASS - CHECK PRICE	nn	1 PC	0.0000	X
			4,316.00	
Add 25%			1,079.00	5,395.00
<i>Photo Taken By Simon Email photo to Ponce</i>				
Special Nett				
21 INNER SEAL		1 PC	20.00	X
22 WINDSCREEN SEALANT		1 PC	40.00	X
				60.00
LABOUR				
23 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	201
24 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1 PC	150.00	X
25 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	130.00	X





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WONG HUNG-YIN BETINA CLAIRE
BLK 509 SERANGOON NORTH AVE 4
#05-366
SINGAPORE 550509
TEL: 97881053
ATTN: Motor Claim Department

Estimate No: MC0912926
Date: 09 Mar 2018
Policy No: GA081369/1
Veh Reg No: SKH6128D
Make/Model: FORD MONDEO
TITANIUM 2.0

Your Ref No: SKH6128D
Claim Type: Third Party
Accident Date: 07/03/2018

Estimate Repair Cost to Vehicle No :SKH6128D

Description	U/Price	Quantity	Cost	Amount
			SS	SS
26 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	7	
27 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	120.00	601	
28 TO RESET REVERSE SENSOR.	1 PC	180.00	7	
29 TO SPRAY ANTI RUST COATING ON AFFECTED AREAS.	1 PC	80.00	7	
30 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	601	
31 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	3001	
32 TO SPRAY TAILGATE, TAILGATE TRIM LOWER, REAR BUMPER.	1 PC	1,000.00	6001	
				2,850.00

Amount Before Excess S\$ 8,305.00
Add GST @ 7% 581.35
Total Amount payable S\$ 8,886.35

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED EIGHTY SIX AND CENTS THIRTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : WONG HUNG-YIN BETINA CLAIRE
BLK 509 SERANGOON NORTH AVE 4
#05-366
SINGAPORE 550509
TEL: 97881053
ATTN:

Claim No: MC0912926
Ref No: MF0910991
Date: 04 Apr 2018
Policy No: GA081369/1
Veh Reg No: SKH6128D
Make/Model: FORD MONDEO
TITANIUM 2.0

Your Ref No: SKH6128D
Claim Type: Third Party
Accident Date: 07/03/2018

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SKH6128D

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 TAILGATE LOWER PROTECTOR		1 PC	370.00	
2 TAILGATE EMBLEM (MONDEO)		1 PC	60.00	
3 TAILGATE TITANIUM LOGO		1 PC	55.00	
4 TAILGATE ECO SYSTEM BADGE		1 PC	68.00	
5 REAR BUMPER		1 PC	1,173.00	
6 REAR BUMPER REFLECTOR LH		1 PC	45.00	
7 REAR BUMPER TOP CHROME PLATE		1 PC	250.00	
8 REAR EXHAUST PIPE CHROME (WITH SILENCER)		1 PC	600.00	
			2,621.00	
	Add 25%		655.25	3,276.25
LABOUR				
9 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
10 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	60.00	
11 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.		1 PC	60.00	
12 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	500.00	
13 TO SPRAY TAILGATE,TAILGATE TRIM LOWER,REAR BUMPER.		1 PC	600.00	
				1,240.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : WONG HUNG-YIN BETINA CLAIRE
BLK 509 SERANGOON NORTH AVE 4
#05-366
SINGAPORE 550509
TEL: 97881053
ATTN:

Claim No: MC0912926
Ref No: MF0910991
Date: 04 Apr 2018
Policy No: GA081369/1
Veh Reg No: SKH6128D
Make/Model: FORD MONDEO
TITANIUM 2.0

Your Ref No: SKH6128D
Claim Type: Third Party
Accident Date: 07/03/2018

Repair Cost to Vehicle No (For Finalization):SKH6128D

Total	S\$ 4,516.25
Lump Sum Less 20%	-903.25
Amount Before Excess	S\$ 3,613.00
Less Rounding	-13.00
Amount Before Excess	S\$ 3,600.00
Less Excess	S\$ 0.00
Amount Before GST	S\$ 3,600.00
Add GST @ 7%	252.00
Total Amount payable	S\$ 3,852.00

TOTAL: SINGAPORE DOLLAR THREE THOUSAND EIGHT HUNDRED FIFTY TWO ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 13/03/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004745/Kvd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 24-04-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 1882Y	Veh. Inspected	SKH 6128D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801028	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	FORD MONDEO (A)	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WF0GXXGBBGCK28900	Colour	METALLIC GREY
Odometer	119061	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	4 mm
L/H Front Tyre	225/45 R17	MICHELIN	4 mm
R/H Rear Tyre	225/45 R17	MICHELIN	5 mm
L/H Rear Tyre	225/45 R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/03/2018	Inspection Date	13/03/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 6128D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE (WCP)	TO REPAIR SEE LABOUR	1,250.00	-
1	TAILGATE LOWER PROTECTOR (WCP)	BENT	370.00	370.00
1	TAILGATE EMBLEM (MONDEO) (WCP)	NECESSARY	60.00	60.00
1	TAILGATE TITANIUM LOGO (WCP)	NECESSARY	55.00	55.00
1	TAILGATE ECO SYSTEM BADGE (WCP)	NECESSARY	68.00	68.00
1	TAILGATE INNER LOCK (WCP)	TO REPAIR SEE LABOUR	125.00	-
1	TAILGATE RUBBER (WCP)	SERVICEABLE	238.00	-
1	REAR BUMPER (WCP)	BUCKLED	1,173.00	1,173.00
1	REAR BUMPER SIDE RETAINERS LH (WCP)(NPA)	SERVICEABLE	-	-
1	REAR BUMPER SIDE BRACKET LH (WCP)(NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER CTR BRACKET (WCP)	TO REPAIR SEE LABOUR	55.00	-
1	REAR BUMPER LOWER SPOILER (DUAL EXHAUST PIPE) (WCP)	SERVICEABLE	220.00	-
1	REAR BUMPER REFLECTOR LH (WCP)	CRACKED	45.00	45.00
1	REAR BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	530.00	-
1	REAR BUMPER PARKING SENSOR OUTER LH (WCP) (NPA)	SERVICEABLE	-	-
4	REAR BUMPER PARKING SENSOR HOLDER (WCP)(NPA)	SERVICEABLE	-	-
1	REAR BUMPER TOP CHROME PLATE (WCP)	DENTED	250.00	250.00
1	REAR END PANEL OUTER (WCP)(NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR EXHAUST PIPE CHROME (WCP)	DENTED	600.00	600.00
1	REAR WINDSCREEN MOULDING WITH GLASS (WCP) (NPA)	NOT NECESSARY	-	-
	COST PLUS 25%		1,259.75	655.25
			6,298.75	3,276.25
<u>SPECIAL NETT ITEMS</u>				
1	INNER SEAL (SN)	NOT NECESSARY	20.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
			60.00	-

Report Ref No. CS/SMO18004745/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE AND REINSTALL/REPLACE REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	NOT NECESSARY	80.00	-
	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.		120.00	60.00
	TO RESET REVERSE SENSOR.	NOT NECESSARY	180.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.		80.00	60.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF TAILGATE, TAILGATE INNER LOCK, REAR BUMPER SIDE BRACKET LH, REAR BUMPER CTR BRACKET, REAR BUMPER REINFORCEMENT AND REAR END PANEL OUTER.		1,000.00	500.00
	TO SPRAY TAILGATE, TAILGATE TRIM LOWER, REAR BUMPER.		1,000.00	600.00
			2,850.00	1,240.00
	GRAND TOTAL		9,208.75	4,516.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00

Report Ref No. CS/SMO18004745/Kvd3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.