

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9275P

MAKE :

MODEL : HYUNDAI i40

CHINA

DATE 12/3/2018 11:32

DOA: 10.03.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover <i>Refit</i>			\$	1052.20
	Front Bumper Bracket Top (RH) <i>X 2</i>			\$ 22.40	
	Front Bumper Retainer Mounting <i>X 2</i>			\$ 9.20	
	Headlamp (RH) <i>Grind</i>			\$ 1,388.00	
	Front Fender (RH) <i>Ref</i>			\$ 619.00	
	Front Fender Shield (RH) <i>X 2</i>			\$ 169.80	
	Front Fender Retainer <i>X 2</i>			\$ 9.20	
	SUB TOTAL			\$ 2,779.90	
	LESS 20%			\$ 555.98	
	DISCOUNTED TOTAL			\$ 2,223.92	
	Front Fender Advertisement Logo (RH) <i>Ref</i>			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge			500	
	Panel Beating			\$ 500.00	
	Spray Painting Charge			\$ 500.00	360
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	20
	TOTAL LABOUR			\$ 1,100.00	
	ESTIMATE TOTAL			\$ 3,423.92	
<i>Kaka (UKK)</i> <i>12/3/18 1500hrs</i> <i>2 Days</i> <i>P/P</i> <i>Before Paint photo</i>					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Larry Ng

Acknowledged by Repairer
Signature:
Date: