

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2603Y

DATE 12/3/2018 11:26

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>x repair</i>			\$ 562.30
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp (LH) /			\$ 1,388.00
	Front Fender (LH) /			\$ 619.00
	Front Fender Shield (LH) X			\$ 169.80
	Front Windscreen Glass X			\$ 1,059.25
	Front Windscreen Moulding X			\$ 60.00
	Front Wheel Hub Cap (LH) /			\$ 150.70
	SUB TOTAL			\$ 4,033.65
	LESS 20%			\$ 806.73
	DISCOUNTED TOTAL			\$ 3,226.92
	Front Door Comfort Logo (LH) /			\$ 75.00 Nett
	Front Windscreen Sealant X			\$ 46.00 Nett
	Front ERP Sticker X			\$ 26.00 Nett
				\$ 147.00
	Labour Charge			300
	Panel Beating			\$ 500.00
	Spray Painting Charge			\$ 750.00 540
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Front Windscreen Glass			\$ 120.00 X
	Remove/Refix Cushion & Upholstery Front			\$ 90.00 X
	TOTAL LABOUR			\$ 1,560.00
	ESTIMATE TOTAL			\$ 4,933.92
<i>Kahin 16/11/18</i> <i>12/3/18 1435h</i> <i>3 Days</i> <i>P.P.</i> <i>Before Paint PHH</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Date: