

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018762
Kwok Sai Kuai

Page 1 of 2
Your ref. TP-SKN 319C AXA
Job No. 69310
Our ref. 18.03.20
Payment
Date 12/3/2018

Attn

Vehicle No SKK 2188R
Vehicle Model : Infiniti Q50
Accident on ... 11/3/2018

Not Authorized

Resurvey B4 paym

7 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear door LH	1,140.70	10.00 <i>R1</i>	1,026.63 ✓
1.00	Pc	Rear sport rim LH (Original-19")	1,799.20	10.00 <i>R1</i>	1,619.28 ✓
1.00	Pc	Rear fender LH	1,112.60	10.00 <i>R1</i>	1,001.34 ✓
Labour & Misc:					
1.00		To remove + refix side skirt LH + repair	80.00		80.00 } <i>12</i>
1.00		To dismantle + refix rear cushion assy + upholstery, etc	80.00		80.00 }
1.00		To check wheel alignment (computerised)	80.00		80.00 <i>601</i>
1.00		To renew sport rim + wheel balancing	30.00		30.00 ✓
1.00		To cut + weld, to knock dents on rear fender inner panel LH and renew of parts	700.00		700.00 <i>650</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018762
Kwok Sai Kuai

Page 2 of 2
Your ref. TP-SKN 319C AXA
Job No. 69310
Our ref 18.03.20
Payment
Date 12/3/2018

Attn

Vehicle No SKK 2188R
Vehicle Model : Infiniti Q50
Accident on ... 11/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (Pearl white / including side skirt, front door and rear bumper)	1,400.00		1,400.00

12006

Sub-Total 6,017.25
GST 7.00% 421.21
Total S\$ 6,438.46

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."