

ASS. REC. BY:

REF: CS/AGI18004754/Ktd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Albert Hong

of AGI

Date/Time: 13/3/18 @ 10:24am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 9151 Y

Insured:

SFD 1119 T

at Workshop m/s

Trans-Carb

Tel:

6287 6666

of

No 2 AMK Strt 63

Policy No:

Claim No:

C10001415

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/3/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:50am @ 12/3/18

Person Contacted: Jiong how

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SHD 9151 Y - X</u>
	<u>SFD 1119 T - NA / FCI 14010297/e1</u>
	<u>D.O.A: 01/06/14</u>

ASS. REC. BY:

REF:

AGZ/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 91514

Yr Regn: 09, 11.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet

Enr

c.c

1991

Colour

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

700506

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K21WA69RJBB 058026

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

195/65R15

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

9/3/18

D.O.I.

13/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/3

File pass to Customer

11 Ring 856001 (Red: 20869-63-78%)

RECEIVED 28 MAR 2018

Date/Time, File Pass to?

11/28/3 Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

450

Report Format :

Lump Sum / I.B.I. (\$

5600

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Tuesday, 13 March 2018 10:24 AM
To: assignments@lkkauto.com
Cc: 'SUR'
Subject: Appoint LKK to conduct TP survey; Our Ref: C10001415
Attachments: image001.wmz; img-312160123.pdf

Hi Team,

Please accept assignment and liaise with TP workshop.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg



Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: jionghow.ng <jionghow.ng@transcab.com.sg>
Sent: Tuesday, 13 March, 2018 9:47 AM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Cc: 'Candy Kong' <candy.kong@transcab.com.sg>
Subject: ARRANGE SURVEY FOR SHD9151Y

Hi all,

Please arrange survey for SHD9151Y

I have attached GIA and Estimate for your perusal

Thank you.

Regards,

Jiong How Ng



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AG118004754/Ktd3	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 13-03-2018	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFD 1119T	Veh. Inspected	SHD 9151Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001415	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	13/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/03/2018	Inspection Date	13/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/03/2018 16:38
 Date Of Accident 09/03/2018 15:30
 Exact Location Of Accident PIE SLIPROAD CTE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD9151Y
Insured/Policyholder
 Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
 Co Reg No 200303878K
 Email Address CLAIMS@TRANSCAB.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-62876666
Vehicle Particulars
 Manufacturer CHEVROLET
 Model EPICA-2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A)
 Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy YES
 Policy Number VPX/P1680520
 Cover Note Number
Driver
 Name of Driver WONG WENG CHEONG
 NRIC No S1159756D
 Date Of Birth 18/09/1955
 Occupation OUTDOOR
 Date Of Driving Pass 26/11/1973
 Driving Experience 44 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91142108
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address	9B YUAN CHING ROAD #01-20
Postcode	618644
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On the 09.03.2018 at about 1530hours, i was travelling straight along the left lane of PIE slip road towards CTE. When Vehicle in front of me are moving slowly and suddenly i felt an impact from the rear. after the accident, i alighted to check and realized that i engaged into a chain collision between Vehicle B(SFD1119T) and Vehicle C(SLM7634P)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFD1119T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEW KUAN SIONG
NRIC/Passport Number	S1607081E
Contact Number	97370373
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM7634P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	NG WEI SHAN
NRIC/Passport Number	S8228320Z
Contact Number	82888119
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	WONG WENG CHEONG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHD9151Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

A - SHD 9151Y		P1E slip road
B - SFD 11187		towards
C - SLM 7634P		CTE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to GNA report -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9151Y

Vehicle to be Exported: Yes

Intended De-registration Date: 12 Mar 2018

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR
TURBO

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: Z20S1443358K

Chassis No.: KL1LA69RJBB058026

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,178.00

Original Registration Date: 09 Sep 2011

First Registration Date: 09 Sep 2011

Transfer Count: 0

Actual ARF Paid: \$14,178.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Sep 2019

PARF Rebate Amount: \$9,215.00

Intended COE Rebate Details

COE Expiry Date:	08 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
QP Paid:	\$35,200.00
COE Rebate Amount:	\$6,555.00
Total Rebate Amount:	\$15,770.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-086**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9151Y -*Not Notified
11 Sep @ 5600*

Vehicle No.:

SHD9151Y - JHOW

Chassis No.:

KL1LA69RJB058026

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

09.03.2018

Third Party Insurer :

AUTO GENERAL

		PART		LIST
1	1	Rear Bumper	\$	B 1,202.00 —
2	1	Rear Bumper Beam	\$	B 239.94 —
3	1	Rear Bumper Centre Absorber	\$	CM 260.00 —
4	1	Rear Bumper Side Retainer RH	\$	SL 68.76 X
5	1	Rear Bumper Side Retainer LH	\$	DIS 68.76 ✓
6	1	Rear Bumper Reflectors RH	\$	SL 119.74 X
7	1	Rear Bumper Reflectors LH	\$	CM 119.74 ✓
8	1	Rear Bumper Tow Hook Cover	\$	SL 93.00 X
9	1	Rear Luggage Floor Panel	\$	R 973.00 X
10	1	Rear Luggage Floor Panel Insulator	\$	SL 63.50 X
11	1	Rear Luggage Floor Panel Trim Board	\$	SL 378.00 X
12	1	Rear End Panel Outer	\$	B 623.76 —
13	1	Rear End Panel Inner Trim	\$	DIS 263.84 —
14	1	Bootlid	\$	B 973.00 —
15	1	Bootlid inner trim board	\$	SL 400.00 X
16	1	Bootlid Weatherstrip	\$	DIS / CVT 344.28 50% SL
17	1	Bootlid Lock - Top	\$	DIS 466.56 —
18	1	Bootlid 'CHEVROLET' Badge	\$	SL 120.62 —
19	1	Bootlid Logo	\$	SL 138.84 —
20	1	Bootlid 'EPICA LT' Badge	\$	SL 119.84 —
21	1	Bootlid Reflector Centre	\$	SL 217.97 X
22	1	Bootlid Reflector RH	\$	SL 128.40 X
23	1	Bootlid Reflector LH	\$	CM 128.40 ✓
24	1	Bootlid Hinge RH	\$	R 120.00 X
25	1	Bootlid Hinge LH	\$	R 120.00 X
26	1	Rear Tail Lamp RH	\$	SL 479.30 X
27	1	Rear Tail Lamp Panel RH	\$	R 359.00 X
28	1	Rear Tail Lamp LH	\$	B 479.30 ✓
29	1	Rear Tail Lamp Panel LH	\$	R 359.00 X
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-086**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9151Y -

31	1	Rear Fender RH	\$	<i>R</i> 1,145.00 <i>X</i>
32	1	Rear Fender Inner Trim RH	\$	<i>Sm</i> 418.44 <i>X</i>
33	1	Rear Fender LH	\$	<i>R</i> 1,145.00 <i>X</i>
34	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 418.44 <i>X</i>

TOTAL	\$	13,665.43
10%	\$	1,366.54
	\$	12,298.89

Special Nett

1	1Set	Licence Plate With Holder	\$	<i>Sm</i> 60.00 <i>X</i>
2	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 <i>X</i>
3	1Set	Rear Bumper Parking Sensor	\$	<i>nd</i> 300.00 <i>✓</i>
4	1Set	Rear Bumper Fastener Clip	\$	<i>nc</i> 44.00 <i>✓</i>
5	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00 <i>X</i>
6	1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 <i>X</i>
7	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00 <i>X</i>
8	1	Rear Boot Sticker 'Trans-cab'	\$	<i>nc</i> 30.00 <i>✓</i>
9	1	Rear Boot Sticker '6555-3333'	\$	<i>nc</i> 30.00 <i>✓</i>
10	1	Rear Exhaust Mounting	\$	<i>Sm</i> 10.00 <i>X</i>
11	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00 <i>X</i>
12	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 <i>X</i>
13	1	Spare Tyre	\$	<i>Sm</i> 180.00 <i>X</i>
14	1	Spare Wheel Rim	\$	<i>Sm</i> 126.74 <i>X</i>

TOTAL	\$	1,090.74
--------------	-----------	-----------------

TOTAL PARTS	\$	13,389.63
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 5,400.00 *700*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *600*

Putty And Spray Painting Of The Affected
Portion.

\$ 5,600.00 *800*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9151Y -**AAD1803-086**

To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of end panel fittings and conduct water seepage test.	\$	170.00
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00 <i>601</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>~ 170.00</i> X
To transfer of boot fittings and conduct water seepage test.	\$	170.00 <i>601</i>
Towing fees	\$	<i>~ 120.00</i> X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>~ 170.00</i> X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>~ 380.00</i> X
To check steering geometry and computer wheel alignment	\$	<i>~ 220.00</i> X
	\$	13,080.00
TOTAL	\$	26,469.63

Repair Days~~20 Days~~*5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18004754/Ktd3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 28-03-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFD 1119T	Veh. Inspected	SHD 9151Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001415	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KL1LA69RJBB058026	Colour	WHITE / RED
Odometer	700506	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GREMAX	6 mm
L/H Front Tyre	195/65 R15	GREMAX	6 mm
R/H Rear Tyre	195/65 R15	GITI	9 mm
L/H Rear Tyre	195/65 R15	GITI	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/03/2018	Inspection Date	13/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9151Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	CRACKED	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	CRACKED	119.74	119.74
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	973.00	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	63.50	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	DISTORTED	263.84	263.84
1	BOOTLID	BENT	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID LOCK-TOP	DENTED	466.56	466.56
1	BOOTLID "CHEVROLET" BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID "EPICA LT" BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	CRACKED	128.40	128.40
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	120.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	120.00	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP LH	BROKEN	479.30	479.30
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-

Report Ref No. CS/AGI18004754/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,332.11	-520.46
			11,989.04	4,684.14
1	BOOTLID WEATHERSTRIP (50%)(SN)	DISTORTED / CUT	344.28	172.14
	LESS 10% DISCOUNT		-34.43	-
			309.85	172.14
<u>SPECIAL NETT ITEMS</u>				
1	SET LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	44.00	44.00
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,090.74	404.00
<u>LABOUR</u>				
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR LUGGAGE FLOOR PANEL,BOOTLID HINGE RH,BOOTLID HINGE LH,REAR TAIL LAMP PANEL RH,REAR TAIL LAMP PANEL LH,REAR EXHAUST BOX (MUFFLER A-EXH,RR),REAR FENDER RH AND REAR FENDER LH.		5,400.00	700.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00

Report Ref No. CS/AGI18004754/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,600.00	800.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST. }		170.00	60.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST. }		170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			13,080.00	1,760.00
GRAND TOTAL			26,469.63	7,020.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,600.00

Report Ref No. CS/AGI18004754/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.