



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1008 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065
Co. Reg. No. 08062400M GST Reg. No. 09-062400-M

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WSK/JW/SF-SJA9729Z
Policy No:	1000595688	Date of Loss:	02/03/2018
Vehicle Reg. No.:	SJA9729Z	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FOO SOO KONG	Contact No:	+6591090788
Driver:	FOO SOO KONG		
Make/Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Vehicle Reg. Date:	27/12/2007
Vehicle Colour:	RED		
Engine No:	1AZ5685988	Chassis No:	JTEGH23B700024792
Odometer:	138997 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO ATTACHED.		
Remarks:	VEHICLE NOT IN YET.		
Present Location:	SHU FATT AUTO WORKS (HQ)		

LKK 12/2/18

COST OF CLAIMS

	Amount
Parts	2,824.30
Miscellaneous Items	0.00
Labour	2,000.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	4,824.30
- Excess (S\$)	500.00
(S\$)	4,324.30
+ GST 7.00% (S\$)	302.70
Nett Amount (S\$)	4,627.00

This claim is handled by: **PATRICIA KOH**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 08 Mar 2018)**Parts:** M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Shu Fatt Auto Works/SJA9729Z/08/03/2018 13:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	0.00	0.00	*280.00 FBT
2	1		*Front bonnet lock	0.00	0.00	*50.00 FBT
3	2		*Front headlights	0.00	0.00	*420.00 F CRA
4	1		*Front grille	0.00	0.00	*190.00 F CRA
5	1		*Front grille emblem	0.00	0.00	*55.00 F ALA
6	1		*Front support panel	0.00	0.00	*380.00 F BT
7	1		*Front brace panel	0.00	0.00	*55.00 F BT
8	1		*Front bumper	0.00	0.00	*210.00 F DE
9	1		*Front bumper reinforcement	0.00	0.00	*120.00 F ? R
10	12		*Front bumper clips	0.00	0.00	*18.00 F ALA
11	1		*Front bumper foam	0.00	0.00	*60.00 F CRA
12	2		*Front bumper side retainers	0.00	0.00	*90.00 F X
13	1		*Front horn	0.00	0.00	*105.00 F X
14	1		*Front aircon condenser	0.00	0.00	*480.00 F BT
15	1		*Coolant	0	0.00	*15.00 FS
16	1		*Front number plate	0	0.00	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,573.00
+ Margin on L,N Items 10.00% (\$\$)	251.30
Total Parts (\$\$)	2,824.30

Shu Fatt Auto Works/SJA9729Z/08/03/2018 13:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt fender, left frt wheel house, rt frt fender, rt frt wheel house, rt frt fender, rt frt wheel house, frt lower membver, renew frt bonnet, frt support panel, frt lights, frt grille, frt bumper & assembly.	New	900.00 600
2	To respray damaged parts.	New	980.00 650
3	To remove, replace frt air con condenser, fill air con freon & assembly.	New	120.00 100
Gross Labour Cost (S\$)			2,000.00

Shu Fatt Auto Works/SJA9729Z/08/03/2018 13:13. Not valid without Reference section.
Generated using Merimeh e-Claims IEAS

< END OF ESTIMATES >

Issue
H# 90010068
15/3/18

6 days

P/P

13/03/18 @ 1145

EXCESS: 500

REVERT

Resurvey 64 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: