

## REPAIR DETAILS

### Reference

**Report Source:** MRM-SG      Version: 1.0 (Last Synchronised: 08 Mar 2018)  
**Vehicle:** M1-MPV      TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue: Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Shu Fatt Auto Works/SJA9729Z/08/03/2018 13:13  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| Lo.                                | Qty | Part No. | Particulars                  | %Disc | %Depr | Amount        |
|------------------------------------|-----|----------|------------------------------|-------|-------|---------------|
|                                    | 1   |          | *Front bonnet                | 0.00  | 0.00  | *280.00 FRA   |
|                                    | 1   |          | *Front bonnet lock           | 0.00  | 0.00  | *50.00 FRA    |
|                                    | 2   |          | *Front headlights            | 0.00  | 0.00  | *420.00 F CRA |
|                                    | 1   |          | *Front grille                | 0.00  | 0.00  | *190.00 F CRA |
|                                    | 1   |          | *Front grille emblem         | 0.00  | 0.00  | *55.00 F NE   |
|                                    | 1   |          | *Front support panel         | 0.00  | 0.00  | *380.00 FRA   |
|                                    | 1   |          | *Front brace panel           | 0.00  | 0.00  | *55.00 FRA    |
|                                    | 1   |          | *Front bumper                | 0.00  | 0.00  | *210.00 F DE  |
|                                    | 1   |          | *Front bumper reinforcement  | 0.00  | 0.00  | *120.00 F ?   |
|                                    | 12  |          | *Front bumper clips          | 0.00  | 0.00  | *18.00 F NE   |
|                                    | 1   |          | *Front bumper foam           | 0.00  | 0.00  | *60.00 F CRA  |
|                                    | 2   |          | *Front bumper side retainers | 0.00  | 0.00  | *90.00 F X    |
|                                    | 1   |          | *Front horn                  | 0.00  | 0.00  | *105.00 F X   |
|                                    | 1   |          | *Front aircon condenser      | 0.00  | 0.00  | *480.00 F     |
|                                    | 1   |          | *Coolant                     | 0     | 0.00  | *15.00 FS     |
|                                    | 1   |          | *Front number plate          | 0     | 0.00  | 35 *45.00 FS  |
| Sub Total (S\$)                    |     |          |                              |       |       | 2,573.00      |
| + Margin on L,N Items 10.00% (S\$) |     |          |                              |       |       | 251.30        |
| Total Parts (S\$)                  |     |          |                              |       |       | 2,824.30      |

Shu Fatt Auto Works/SJA9729Z/08/03/2018 13:13. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                       | Particulars                                                                                                                                                                                                                                                                               | Lab.Type | Amount                |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------------|
| <u>Labour Items</u>      |                                                                                                                                                                                                                                                                                           |          |                       |
| 1                        | To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt fender, left frt wheel house, rt frt fender, rt frt wheel house, rt frt fender, rt frt wheel house, frt lower member, renew frt bonnet, frt support panel, frt lights, frt grille, frt bumper & assembly. | New      | <del>900.00</del> 600 |
| 2                        | To respray damaged parts.                                                                                                                                                                                                                                                                 | New      | <del>980.00</del> 650 |
| 3                        | To remove, replace frt air con condenser, fill air con freon & assembly.                                                                                                                                                                                                                  | New      | <del>120.00</del> 100 |
| Gross Labour Cost (\$\$) |                                                                                                                                                                                                                                                                                           |          | 2,000.00              |

Shu Fatt Auto Works/SJA9729Z/08/03/2018 13:13. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Resue  
Hf 90010068

6 days

P/R

13/03/18 @ 1145

EXCESS: 500

REVERT.

Resurvey 64 paint

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: