

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Mar 2018)
Parts: M1-MPV TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Shu Fatt Auto Works/SJA9729Z/20/03/2018 14:46
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Radiator	0.00	0.00	*570.00 F
F=Franchise part.						
Sub Total (\$\$)						570.00
+ Margin on L,N Items 10.00% (\$\$)						57.00
Total Parts (\$\$)						627.00

Shu Fatt Auto Works/SJA9729Z/20/03/2018 14:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Parts: 2768.00
 +10%: 276.80
 Sub: 3044.80
 60.00
 3104.80
 Labour: 1450.00
 4554.80