

Wilson

CC 6 UR
AIG 1800

477r, A 103

LKK
IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

17/7/18

Date / Time

17/7/18

Registered in Meritmen:

17/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 8110U

Name of Insured:

UR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

17/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

U17M6

If NO, Driver Name / Age: AHMAD BIN CAPIK

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

Sjm 44074



INSRS:
WSP:
Tel:
Liability:
RMKS:

Modern



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

17/7/18
U17

19/13/18

Old came out from minor road (with stop line) & collided with TP who was on main road.
Sent letter to OI via email

13/9/18 - DV sent

13/9/18 - File pass to Shm Per to close

STAGE

DATE / PIC

Non-Reporting Itr (1st):		
Non-Reporting Itr (2nd):		
Non-Reporting Itr (Final):		
Notification Itr (if non-pickup):		
Call OI:	17/7/18	
After call Itr to OI:	(By email)	
Documentation Check List:	Handler	Typist
Notification Itr (if non-pickup)		
After call Itr to OI:		
Authorisation To Act:		
Release Voucher:		
Final Repair Bill:		
Car Rental Invoice:		
Towing Invoice:		
UTA / GIA:		
Medical Bill:		
PIR:		
Mandate/Reject Instruction:		
LOD:		
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed) BOLA S/N No.:

7

If NO or B 28, Ass. Lia:

Repair Cost:

SS

6473.50

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

420.00

(

days)

Loss of Income (LOI):

SS

(

days)

(LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/TA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

Total:

SS

6900.99

Global Sum SS:

6900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6900.00

Name 1:

Modern Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 9P
3) Survey fee: \$320 + \$20

COPY SENT
17/7/18

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

02/01/09.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJM4407Y - Yr Regn: 2009, JanType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Golf cc 1390Colour: White A/C: Insured / Std / NI / NASp. Reading: 148046 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZ2JKZ84034190Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 13/03/18Survey held at: Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

US \$ 6050 (keel of 252099/2997)

MV: 19K

PV: 11.6K

Nett: 7.4K

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18004772/Ab3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 13-03-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 8110U	Veh. Inspected	SJM 4407Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/03/2018	Inspection Date	13/03/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Xiao Tong

Quotation

DATE : 13.03.2018
VEH NO : SJM4407Y
MODEL : Volkswagen Golf
D O A : 13.03.2018
YR REF : SLE8110U

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJM4407Y (VOLKSWAGEN GOLF)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Front Bumper <i>Deformed</i>	1	1,048.30 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>LH Dmgd</i>	2	20.20 <i>35.10</i>
4	Front Bumper Protector - LH <i>cut</i>	1	36.90 ✓
5	Front Bumper Fog Lamp Cover - LH <i>missing</i>	1	158.90 ✓
6	Front Bumper Sponge <i>Deformed</i>	1	91.40 ✓
7	Front Bumper Reinforcement <i>Bent</i>	1	597.40 ✓
8	Front Grille <i>cracked</i>	1	316.90 ✓
9	Front Grille Logo <i>new</i>	1	68.90 ✓
10	Front Grille Clips <i>new</i>	1 set	15.00 ✓
11	Headlamp - LH <i>Cracked</i>	1	807.50 ✓
12	Headlamp Lower Bracket - LH <i>Cracked</i>	1	58.90 ✓
13	Bonnet <i>Deformed</i>	1	839.60 ✓
14	Bonnet Lock <i>not the</i>	1	78.90 ✓
15	Front Fender - LH <i>Distorted</i>	1	519.50 ✓
16	Front Fender Inner Shield - LH <i>Deformed</i>	1	198.40 ✓
17	Front Fender Inner Shield Clips - LH <i>new</i>	1 set	30.00 ✓
18	Front Fender Inner Bracket - LH <i>Bent</i>	1	32.90 ✓
19	Front Support Panel <i>cracked</i>	1	841.40 ✓
20	Air Duct <i>cracked</i>	1	68.00 ✓
21	Air Cleaner Box <i>Cracked</i>	1	392.10 ✓
			6,301.10
Less 10%			(630.11)
			\$ 5,670.99

6187.10
5877.14

S/NET ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SJM4407Y (VOLKSWAGEN GOLF)

1	Front Number Plate	<i>3 plate new</i>	1	\$	30.00 ^x
2	Front Number Plate Holder		1	\$	30.00 ^x
3	Radiator Coolant	<i>new</i>	1	\$	60.00 ⁴⁰
Total Parts				\$	5,790.99

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts		\$	1,400.00 ⁹⁰⁰
2	To putty & spray up paint works		\$	1,000.00 ⁶⁰⁰
3	To check wiring	<i>1650</i>	\$	50.00 ³⁰
4	To underseal		\$	150.00 ^x
5	To remove condenser, radiator & to re-gas		\$	180.00 ¹²⁰
Total Labour				\$ 2,780.00
Grand Total				\$ 8,570.99

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

*total: 756774
h/s: 6050*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6977J
Vehicle Details	
Vehicle No.:	SJM4407Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI 7 SPD A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	CAX071045
Chassis No.:	WVWZZZ1KZ8U034190
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,277.00
Original Registration Date:	02 Jan 2009
First Registration Date:	02 Jan 2009
Transfer Count:	2
Actual ARF Paid:	\$22,277.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jan 2019
PARF Rebate Amount:	\$11,138.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$6,200.00
COE Rebate Amount:	\$495.00
Total Rebate Amount:	\$11,633.00

The information contained herein is correct as at 14 Mar 2018

OK

Hsiao Tong (LKKAuto)

From: Meei Huey <meeihuey@modernautomotive.com.sg>
Sent: Thursday, 5 April 2018 3:41 PM
To: Hsiao Tong (LKKAuto)
Cc: Chin
Subject: TP Settlement SJM4407Y (AIG)
Attachments: LOD - SJM4407Y.PDF

Dear Hsiao Tong,

We refer to the above matter.

Kindly confirm settlement as follow :-

Repair Cost : \$6,473.50 (Incl GST)
LOU (7 days x \$100) : \$700.00
Search fee : \$7.49

Total: \$7,180.99

We enclosed herewith our LOD for your perusal.

Regards,

Mei

Modern Automotive Pte Ltd | MM Trading Enterprise
Blk 3023A Ubi Road 1 #01-61 S(408717)
Tel: 6744 4422 / 8121 3226
Fax: 6747 6720

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422/ 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SLE8110U

Our Ref : SJM4407Y

Date : 05.04.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SJM4407Y & SLE8110U ON 13.03.2018
ALONG JALAN ISHAK / LORONG MARICAN

We refer to the above matter.

We have been authorized by our client Mr Andrew Neale Weaver to make claim against your insured vehicle No. SLE8110U in respect of the above accident for the following :

Repair Cost	\$	6,473.50	(Incl GST)
Loss of use (\$100 x 7 days)	\$	700.00	
Search fee	\$	7.49	
Total :	\$	7,180.99	

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully


Modern Automotive Pte Ltd

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 12 April 2018 5:23 PM
To: 'Meei Huey'
Cc: Chin
Subject: RE: TP Settlement SJM4407Y (AIG) *LKK REF: CC6/LCR18004772/Apb3

Without Prejudice

Hi Mei,

We refer to your below email.

We propose settlement at a global sum of **\$6,840.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Meei Huey [mailto:meeihuey@modernautomotive.com.sg]
Sent: Thursday, 5 April 2018 3:41 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: Chin <chin@modernautomotive.com.sg>
Subject: TP Settlement SJM4407Y (AIG)

Dear Hsiao Tong,

We refer to the above matter.

Kindly confirm settlement as follow :-

Repair Cost : \$6,473.50 (Incl GST)

LOU (7 days x \$100) : \$700.00

Search fee : \$7.49

Total: \$7,180.99

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 12 April 2018 5:59 PM
To: Meei Huey
Cc: Chin
Subject: RE: TP Settlement SJM4407Y (AIG) *LKK REF: CC6/LCR18004772/Apb3
Attachments: DV_SJM 4407Y.pdf

Without Prejudice

Hi Mei,

We refer to the above matter.

We confirm settlement at a global sum of \$6,900.00(all-in).

Please duly sign the DV enclosed and return to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 12 April 2018 5:23 PM
To: Meei Huey <meeihuey@modernautomotive.com.sg>
Cc: Chin <chin@modernautomotive.com.sg>
Subject: RE: TP Settlement SJM4407Y (AIG) *LKK REF: CC6/LCR18004772/Apb3

Without Prejudice

Hi Mei,

We refer to your below email.

We propose settlement at a global sum of \$6,840.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 19 March 2018 4:50 PM
To: 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLE 8110U(AIG) & SJM 4407Y ON 13/03/2018

Your Ref: **SLE 8110U**
Our Ref: CC6/LCR18004772/Apb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLE 8110U(AIG) & SJM 4407Y ON 13/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SJM 4407Y against your insurance policy.

Based on the accident report and accident scenario, liability is down against us.
We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORIZATION

Date: 13/3/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SJM44074 / SLE81104

ON 13/3/18 ALONG Jalan Ishak / Lorong
Marican

This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully


Signature of Owner

Andrew Wee
Name / NRIC S7656977J

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,900.00 (Global Sum) for vehicle no. SJM 4407Y that was damaged pursuant to the accident which occurred on 13/03/2018 (date) along JALAN ISHAK / LORONG MARICAN involving vehicle no/s SLE 8110U.

This is pursuant to the inspection conducted on 13/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ANDREW NEALE WEAVER ("the third party claimant") of vehicle no. SJM 4407Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJM 4407Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 (day) of April (month) 2018 (year)



LUP

Signed by appointed surveyor



mtt

Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1#01-58/61 SINGAPORE 406717
TEL : 67474422 67454422 FAX : 67476720
GST REG NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department

Contact : 6415-3727 6419-3000

Tax Invoice : TP001170

Date : 05/04/2018
Vehicle Num. : SJM 4407Y
Make/Model : VOLKSWAGEN GOLF-2009
Chassis/Eng# :
Accident Date : 13/03/2018
Claim No. :
Reference :
Policy No. : 5085297173-01

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		6,050.00
		Labour Total S\$:		6,050.00

Total S\$:	6,050.00
GST @ 7% S\$:	423.50
Amount Due S\$:	6,473.50


MODERN AUTOMOTIVE PTE LTD

Thank you!



Minder Kaur has successfully logged out.

Your last login date and time was 13 Mar 2018, 15:37:36.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.Asset</u> <u>Type</u>	<u>Asset ID</u>	<u>Asset</u> <u>Owner</u> <u>ID</u>	<u>Transaction Type</u>	<u>Transaction</u> <u>Amount(S\$)</u>	<u>Log</u> <u>Date/Time</u>
1 Vehicle	SLE8110U-		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	13 Mar 2018 / 15:39:50

**Enquire Vehicle & Owner Information (Vehicle No. SLE8110U As At
13 Mar 2018 / 12:15:00)**

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MODERNAUTOMOTIVE(40)

Current Owner Details

Owner ID Type: Company
Owner ID: 201624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11 - 01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLE8110U
Make Description/Model: HONDA / VEZEL HYBRID 1.5X A
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018 Edit Reg		13 Mar 2018 00:00 Edit Adj Rpt	\$46,050.00 Edit Estimates	\$46,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	ANDREW NEALE WEAVER, ID: S76569773		
Vehicle Reg. No.:	SJM4407Y	Date of Loss:	13/03/2018 12:00 - :59 [110 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7595781428SG	Policy/Cover Note No.:	0999994806
Vehicle Reg. No. (Insured):	SLE8110U	Policy No. (Claimant):	5085297173-01
		Excess:	
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.






































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM4407Y (7595781428SG)
[SLE8110U]
TP
ANDREW NEALE WEAVER
Mar 13 2018 12:00PM
[LCRF Pte Ltd]
Modern Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit			
															3 per page		<input checked="" type="checkbox"/>	
Photos/Images																		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
2	11/04/18 01:36	Chassis Number												1	Load JPG	<input checked="" type="checkbox"/>		
3	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
4	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
5	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
6	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
7	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
8	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
9	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
10	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
11	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
12	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
13	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
14	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
15	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
16	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
17	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
18	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
19	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
20	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
21	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
22	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
23	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
24	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
25	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
26	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
27	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
28	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
29	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
30	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
31	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
32	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
33	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		
34	11/04/18 01:36	General View												1	Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/18 01:36	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/04/18 01:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/04/18 01:36	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 17:44	TP GIA REPORT	Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
			1		
2	11/04/18 11:28	TP ESTIMATE	2	Load PDF	
3	17/04/18 09:39	WORKSHOP INVOICE	3	Load PDF	
4	17/04/18 09:39	AUTHORISATION TO ACT FORM	4	Load PDF	
5	17/04/18 09:39	Release Voucher	5	Load PDF	
6	17/04/18 09:39	LTA SEARCH	6	Load PDF	
7	17/04/18 09:39	LETTER TO OI	7	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	14/03/18 14:21	OI GIA report	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLE8110U (Insd veh)	Model:	VOLKSWAGEN GOLF 1.4 (A)
	SJM4407Y (TP veh)		
Date of Accident:	13/03/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	9,508.06
Final Repair Cost	:	\$	6,900.00
Loss of Use	:	\$	7.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	6,900.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ___100___(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 6,900.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

17 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18004772/APB3Q2

Date: 17/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994806
Claimant Vehicle No : SJM4407Y **Insured Vehicle No :** SLE8110U
 Date of Loss: 13/03/2018 Nature of Claim: TP Claim No: 7595781428SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM4407Y**
 Make & Model: VOLKSWAGEN GOLF, 1.4 (A) Engine No: CAX071045
 Reg. Date: 02/01/2009 (Man. Year: 2008) Chassis No: WWZZZ1KZ8U034190
 Colour: White Odometer: 148046 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,106.04	5,917.74	188.30	3.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,650.00	1,130.00	40.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,886.04	7,567.74	1,318.30	14.84
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	8,886.04	6,050.00	2,836.04	31.92
+ GST 7.00/7.00% (S\$)	622.02	423.50	198.52	31.92
Nett Amount (S\$)	9,508.06	6,473.50	3,034.56	31.92
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,900.99		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 13/03/2018
 Date Inspected: 13/03/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,048.30 FL	*1,048.30 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER -LH & RH	N/S Damaged	70.20 FL	*35.10 FL
4	1		*FRONT BUMPER PROTECTOR -LH	Cut	36.90 FL	*36.90 FL
5	1		*FRONT BUMPER FOG LAMP COVER- LH	Missing	158.90 FL	*158.90 FL
6	1		*FRONT BUMPER SPONGE	Deformed	91.40 FL	*91.40 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	597.40 FL	*597.40 FL
8	1		*FRONT GRILLE	Cracked	316.90 FL	*316.90 FL
9	1		*FRONT GRILLE LOGO	Necessary	68.90 FL	*68.90 FL
10	1		*SET FRONT GRILLE CLIPS	Necessary	15.00 FL	*15.00 FL
11	1		*HEADLAMP -LH	Cracked	807.50 FL	*807.50 FL
12	1		*HEADLAMP LOWER BRACKET-LH	Cracked	58.90 FL	*58.90 FL
13	1		*BONNET	Dented	839.60 FL	*839.60 FL
14	1		*BONNET LOCK	Not Necessary	78.90 FL	*- FL
15	1		*FRONT FENDER -LH	Distorted	519.50 FL	*519.50 FL
16	1		*FRONT FENDER INNER SHIELD -LH	Deformed	198.40 FL	*198.40 FL
17	1		*SET FRONT FENDER INNER SHIELD CLIPS-LH	Necessary	30.00 FL	*30.00 FL
18	1		*FRONT FENDER INNER BRACKET -LH	Bent	32.90 FL	*32.90 FL
19	1		*FRONT SUPPORT PANEL	Cracked	841.40 FL	*841.40 FL
20	1		*AIR DUCT	Cracked	68.00 FL	*68.00 FL
21	1		*AIR CLEANER BOX	Cracked	392.10 FL	*392.10 FL
22	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
23	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
24	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	6,421.10	6,227.10
- List Item Discount on L Items 5.00/5.00% (S\$)		315.06	309.36
	Total Parts (S\$)	6,106.04	5,917.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	1,400.00	900.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE CONDENSER ,RADIATOR & TO RE-GAS	New	180.00	120.00
Gross Labour Cost (\$\$)			2,780.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >