

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18004775/Dvb

Special Instruction:

Surveyor:

Merimen

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSLH

Date/Time:

13032018 2.45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGA 9038U

Insured:

SKE 8917X

at Workshop m/s

BH Auto

Tel:

6559 8944

of

Blk 1 Sin ming Ind Est #01-115

Policy No:

27 310172SMP

Claim No:

550298

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

15.032018 @ 11am - 12pm

H.O.D. Endorsement:

Date/Time:

13032018 3.15pm

Person Contacted:

Jacelyn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGA 9038U - X

SKE 8917X - X

16/3/18

Send preli revised by merimen

10/04/18

checked with w/shop, vehicle still not send in for app

Surinder

Merimen

## ASSIGNMENT

CoE Nov 2020

From: Date: 15/8/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGA 9038U

at Workshop m/s BH Auto

of Blk 1 Sin Ming #01-115

Insured:

Policy No:

Claims No:

Sum Insured: Excess:


(Client's Record)

Make of Veh:

11am - 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGA 9038U Yr Regn: Dec 2005

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla Altis C.C. 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 357920 T/Radio: Insured / Std / NI / NA

Eng/No: 3224527312

C/No: MR0532EC107105593

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 170 R14

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton

Front

Rear

R/Bal. S' mm

R/Bal. S' mm

L/Bal. S' mm

L/Bal. S' mm

D.O.A. 10/03/2018

D.O.I. 15/08/2018

Survey held at BH Auto Sin Ming

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time          | Action / Instruction                                 |
|----------------------|------------------------------------------------------|
|                      | MSG SKE 8917X                                        |
|                      | MV MV 20K                                            |
|                      | LTA 15.3K                                            |
|                      | NIL 4.7K                                             |
| 16/04/18             | 1 moved 115 14001- with 4 dgs 7 7 (Red 2818.39, 675) |
| RECEIVED 16 APR 2018 |                                                      |

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

200

10

210

Date/Time, File Return to?

2) 6/4 - typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: merimen

Lump Sum / I.B.I: (\$ 1400/-)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                      |                 |                          |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-----------------|--------------------------|--|
| MSIG INSURANCE (SINGAPORE) PTE LTD                                                                                                     |                                                                                                      |                 | Ref : CS/MSG18004775/Dvb |  |
| 16 RAFFLES QUAY<br>#24-01 HONG LEONG BLDG SINGAPORE 048581                                                                             |                                                                                                      |                 | Date : 13-03-2018        |  |
|                                                                                                                                        |                                                                                                      |                 | Code : MSG               |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                      |                 |                          |  |
| Insured Veh.                                                                                                                           | SKE 8917X                                                                                            | Veh. Inspected  | SGA 9038U                |  |
| Policy No.                                                                                                                             | 27310172SMP                                                                                          | Coverage (\$)   | 0.00                     |  |
| Claim No.                                                                                                                              | 550298                                                                                               | Excess (\$)     | 0.00                     |  |
| Assign From                                                                                                                            | MERIMEN (CHRISTINA WONG)                                                                             | Assign Date     | 13/03/2018               |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                      |                 |                          |  |
| Make & Model                                                                                                                           |                                                                                                      | c.c             | 0                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                               | Year of Reg.    |                          |  |
| Chassis No.                                                                                                                            |                                                                                                      | Colour          |                          |  |
| Odometer                                                                                                                               | -                                                                                                    | Steering        |                          |  |
| Brakes                                                                                                                                 |                                                                                                      | Modification    |                          |  |
| General                                                                                                                                |                                                                                                      |                 |                          |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                      |                 |                          |  |
|                                                                                                                                        | Size                                                                                                 | Make            | Balance                  |  |
| R/H Front Tyre                                                                                                                         |                                                                                                      |                 | mm                       |  |
| L/H Front Tyre                                                                                                                         |                                                                                                      |                 | mm                       |  |
| R/H Rear Tyre                                                                                                                          |                                                                                                      |                 | mm                       |  |
| L/H Rear Tyre                                                                                                                          |                                                                                                      |                 | mm                       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                      |                 |                          |  |
|                                                                                                                                        |                                                                                                      |                 |                          |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                      |                 |                          |  |
| Accident Date                                                                                                                          | 10/03/2018                                                                                           | Inspection Date | 15/03/2018               |  |
| Survey held at                                                                                                                         | BH AUTO SERVICES PTE LTD<br>BLK 1 SIN MING INDUSTRIAL ESTATE<br>SECTOR C #01-115<br>SINGAPORE 575636 |                 |                          |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                      |                 |                          |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                      |                 |                          |  |

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 16 Mar 2018

**Preliminary Advice**

|                    |                                                                                                            |                         |              |
|--------------------|------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKE8917X                                                                                                 | Accident Date           | : 10/03/2018 |
| TP Vehicle No      | : SGA9038U                                                                                                 | Assignment Date         | : 13/03/2018 |
| Make               | : TOYOTA COROLLA                                                                                           | Est. Duration of Repair | : 4.00       |
| Date of Inspection | : 15/03/2018                                                                                               |                         |              |
| Inspection At      | : B H AUTO SERVICES PTE LTD (HQ)<br>BLK 1 SIN MING INDUSTRIAL ESTATE, SECTOR C #01-115<br>SINGAPORE 575636 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,513.67 |
| Revised Amount              | :S\$ | 1,780.43 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,780.43 |

Lump Sum Repair

:S\$

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**☐ The vehicle is economical/not economical for repair.☒ The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                               |
|------|-------------|---------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Main | 12 Mar 2018 |               | 13 Mar 2018<br>14:45<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

## CLAIM SUBFOLDER DETAILS

|                             |  |                                                                                                                    |                        |                                                                  |
|-----------------------------|--|--------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------|
| Insured:                    |  | ABDUL MAJID BIN ABDULLAH, ID: S0008242B, Tel: +6585184283, Email: NOEMAIL                                          |                        | [Created by insurer]                                             |
| Main Claimant:              |  | FLYCAR ENTERPRISE, Co. Reg. No.: 53347508B                                                                         |                        |                                                                  |
| Vehicle Reg. No.:           |  | SGA9038U                                                                                                           | Date of Loss:          | 10/03/2018 13:00 - :59                                           |
| Claim Type:                 |  | TP / 550298                                                                                                        | Policy/Cover Note No.: | 27310172SMP (Comprehensive)<br>Coverage: 13/04/2017 - 12/04/2018 |
| Vehicle Reg. No. (Insured): |  | SKE8917X                                                                                                           | Policy No. (Claimant): |                                                                  |
|                             |  |                                                                                                                    | Excess:                | S\$1,500.00                                                      |
| Repairer:                   |  | B H Auto Services Pte Ltd (HQ) BLK 1 SIN MING INDUSTRIAL ESTATE, SECTOR C #01-115, 575636 Sin Ming - Tel: 65598944 |                        |                                                                  |
| Handling Insurer:           |  | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]         |                        |                                                                  |
| Adjuster:                   |  | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/03/2018]                                 |                        |                                                                  |
| Driver/Custodian (Insured): |  | ABDUL MAJID BIN ABDULLAH (67 / Male), NRIC: S0008242B, Tel: +6585184283                                            |                        |                                                                  |
| Adj Asg. Remarks:           |  | VEHICLE NOT IN YET - PLEASE ALIAS WITH WORKSHOP WHEN TO SURVEY                                                     |                        |                                                                  |

## ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



Toyota Corolla Altis 1.6A (COE till 02/2022) \$30,500 \$7,790 /yr 09-Feb-2007 1,598 cc Sedan Available

Elegant Toyota Altis, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 11-Mar-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 01/2021) \$19,800 \$7,020 /yr 06-Jan-2006 1,598 cc 118,000 km Sedan Available

Up To 90% Loan! Flexible Repayment With In House Financing. Well Maintain, Immaculate Condition, Fuel Efficient And Reliable, In House Loan And Bank Loan Available, Trade In Are Welcome, Call Or Visit...

Motor Universe Credit Pte Ltd

Posted: 11-Mar-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla 1.6A (COE till 01/2020) \$19,899 \$10,590 /yr 28-Jan-2005 1,598 cc 130,000 km Sedan Available

Asking Low! Good Running Conditions After 13 Years. Smooth Engine/ Transmission. Average Mileage Done. Buy Back Car Body At \$1.5k Upon De-Registration. Do Not Missed! Buy With Trust And Confidence On...

Posted: 11-Mar-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 06/2021) \$23,899 \$7,260 /yr 26-Jun-2006 1,598 cc 128,000 km Sedan Available

\$3000 Down Payment. Low Mileage, Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained By Previous Owner, Clean And Neat Interior! B...

Posted: 11-Mar-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2021) \$22,800 \$7,780 /yr 15-Feb-2006 1,598 cc 147,000 km Sedan Available

See To Believe, Comes With "One Year In-House Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$485 Low Month...

Carway

Posted: 11-Mar-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2022) \$30,500 \$7,680 /yr 01-Mar-2007 1,598 cc Sedan Available

Elegant Silver, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available, Very Well Kept, Perfect Condition - \$2500 Drive Away.

Prime Motor & Leasing

Posted: 11-Mar-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla 1.6A (COE till 04/2021) \$20,800 \$6,700 /yr 19-Apr-2006 1,598 cc 94,300 km Sedan Available

Only 1 Owner, Low Depreciation Of \$6500+ Per Year Only, Drive Away With Minimum Down Payment. Low Mileage Done! Fully Maintained And Well Taken Care By Owner Since Day One, Excellent Condition, Elegan...

Posted: 10-Mar-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 04/2026) N.A 05-Apr-2006 1,598 cc Sedan SOLD

Cheapest In The Market! Beautiful Condition, Better Value Than Monthly Rent Car, Best Fuel Economy, Accident Free, Trade In Welcomed, Bank/In House Loan Available, Call Our Friendly Sales Consultant N...

Heritage Auto Enterprise Pte Ltd

Posted: 10-Mar-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 06/2021) \$20,600 \$6,250 /yr 29-Jun-2006 1,598 cc 196,000 km Sedan Available

Immaculate Condition And Well Maintained And Serviced Regularly With Most Wear And Tears New Paint Work And Michelin Tyre And New Sport Rim Full Leather Seat And Power Sliding Door Low Depreciation Po...

Posted: 10-Mar-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 01/2022) \$26,500 \$6,810 /yr 01-Feb-2007 1,598 cc 159,000 km Sedan Available

New 6 Months Road Tax, New Engine Mounting, Fully Serviced, Tip Top Condition, 100% No Repairs Needed, High Loans Available. Feel Free To Call For Enquires And Viewing Of Car.

Posted: 09-Mar-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 05/2026) \$48,800 \$5,950 /yr 24-May-2006 1,598 cc 115,918 km Sedan Available

Guaranteed Cheapest Deal! This Altis Is So Well Kept And Properly Serviced, It Drives Like Brand New! Pay The Lowest For This Japanese Work Hor Not Give You Any Headaches! Prev...

Car House Pte Ltd

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 7508B

### Vehicle Details

Vehicle No.: SGA9038U  
Vehicle to be Exported: No  
Intended De-registration Date: 12 Mar 2018  
Vehicle Make: TOYOTA  
Vehicle Model: COROLLA 1.6  
Primary Colour: Silver  
Manufacturing Year: 2005  
Engine No.: 3ZZ4527312  
Chassis No.: MR053ZEC107105593  
Maximum Power Output: 81.0 kW (108 bhp)  
Open Market Value: \$16,772.00  
Original Registration Date: 01 Dec 2005  
First Registration Date: 01 Dec 2005  
Transfer Count: 2  
Actual ARF Paid: \$18,450.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 30 Nov 2020  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 5  
PQP Paid: \$28,292.00  
COE Rebate Amount: \$15,371.00  
**Total Rebate Amount: \$15,371.00**

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2018



# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

## MSIG Insurance (Singapore) Pte Ltd

16 Raffles Quay

#24-01 Hong Leong Building

Singapore 048581

Tel: 6220 9644 Fax: 62257402

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

**ACCIDENT REPAIR ON: SGA9038U**

**MODEL : TOYOTA ALTIS 1.6**

**POLICY NO : 5084801342-01**

**CHASSIS NO : MR053ZEC107105593**

**YEAR OF MANUFACTURE : 2005**

**DATE / TIME OF ACCIDENT: 10/03/2018 Time: 1325Hrs at ALONG TAMPINES ST 45.**

**THIRD PARTY VEHICLE NO: SKE8917X**

Date: 13/03/2018

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

### Replacement Of Parts

| S/N                                          | Quantity | Unit Price | Condition   | Amount   |
|----------------------------------------------|----------|------------|-------------|----------|
|                                              |          | S\$        |             | S\$      |
| 1 Rear bumper <i>distorted</i>               | 1        | 376.80     | Torn        | 376.80 ✓ |
| 2 Rear bumper side retainer LH <i>src</i>    | 1        | 29.80      | Necessary   | 29.80 X  |
| 3 Rear bumper side retainer RH <i>src</i>    | 1        | 29.80      | Necessary   | 29.80 X  |
| 4 Rear bumper lower spoiler <i>distorted</i> | 1        | 357.10     | Cut         | 357.10 ✓ |
| 5 Rear bumper sensor LH <i>src</i>           | 1        | 208.01     | Malfunction | 208.01 X |
| 6 Rear bumper sensor RH <i>src</i>           | 1        | 208.01     | Malfunction | 208.01 X |
| 7 Rear bumper centre bracket LH <i>src</i>   | 1        | 44.80      | Bented      | 44.80 X  |
| 8 Rear bumper centre bracket RH <i>src</i>   | 1        | 44.80      | Bented      | 44.80 X  |
| 9 Rear end panel <i>71g</i>                  | 1        | 615.00     | Dented      | 615.00 X |
| 10 Rear end panel top garnish <i>src</i>     | 1        | 45.70      | Kinked      | 45.70 X  |

Sub-Total: 1,959.82

Less: 25% discount - 489.96

**Total Parts after 25% discount: 1,469.87**

*733.90*  
*550.42*

### Special Nett Items

|                                |    |       |             |                   |
|--------------------------------|----|-------|-------------|-------------------|
| 1 Anti-rust coating <i>12x</i> | 1  | 80.00 |             | 160.00 X          |
| 2 Rear bumper clips <i>huc</i> | 12 | 5.71  | <i>30/-</i> | 68.52 <i>30/-</i> |
|                                |    |       |             | 228.52            |

**Total Parts: 1,698.39**

### Labour Charges For Rear Portion

|                                                                                                                                              |  |  |               |                       |
|----------------------------------------------------------------------------------------------------------------------------------------------|--|--|---------------|-----------------------|
| 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. |  |  |               | 1,250.00 <i>600/-</i> |
| 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities             |  |  |               | 1,000.00 <i>500/-</i> |
| 3 Provide skill labour to disconnect and check electrical wiring                                                                             |  |  |               | 60.00 <i>huc</i>      |
| 4 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs                   |  |  |               | 150.00 <i>60/-</i>    |
| 5 Provide skill labour to remove and replace rear bumper sensors                                                                             |  |  | <i>1200/-</i> | 60.00 <i>40/-</i>     |
| <b>Total Labour:</b>                                                                                                                         |  |  |               | <b>2,520.00</b>       |

*1780.42*  
*415 1400/-*



|                       |                 |
|-----------------------|-----------------|
| Total Parts & Labour: | 4,218.39        |
| GST 7%                | 295.29          |
| Grand Total:          | <u>4,513.67</u> |

|                          |                |
|--------------------------|----------------|
| Estimate Repair Duration | <u>09 days</u> |
|--------------------------|----------------|

ACCIDENT VEHICLE OF : SGA9038U

Page : 2 of 2

**Remark:** Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Bryan  
 Company : LKK Auto  
 Date : 15/03/2018  
 Time : 1200hrs  
 Contact No : 97237799  
 Email : \_\_\_\_\_

Not Attached  
 4/5mm 4 dgs.  
 Photo after repair  
  
 LKK Auto  


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004775/DVBN2

Date: 16/04/2018

## REFERENCE

|                       |                                      |                      |             |
|-----------------------|--------------------------------------|----------------------|-------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | 27310172SMP |
| Claimant Vehicle No : | SGA9038U                             | Insured Vehicle No : | SKE8917X    |
| Date of Loss:         | 10/03/2018                           | Nature of Claim:     | TP          |
|                       |                                      | Claim No:            | 552098      |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SGA9038U                     | Engine No:  | 3ZZ4527312        |
| Make & Model:               | TOYOTA COROLLA, 1.6 (M)      | Chassis No: | MR053ZEC107105593 |
| Reg. Date:                  | 01/12/2005 (Man. Year: 2005) | Odometer:   | 357920 km         |
| Colour:                     | Silver                       |             |                   |
| Engine Capacity:            | 1598 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 185/70R14   | Rear Tyre Size:  | 185/70R14   |
| Front Left Side:  | Neuton 5 mm | Rear Left Side:  | Neuton 5 mm |
| Front Right Side: | Neuton 5 mm | Rear Right Side: | Neuton 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 1,538.38        | 580.42          | 957.96          | 62.27        |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 2,680.00        | 1,200.00        | 1,480.00        | 55.22        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>4,218.38</b> | <b>1,780.42</b> | <b>2,437.96</b> | <b>57.79</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>1,400.00</b> |                 |              |
| (S\$)                                    | 4,218.38        | 1,400.00        | 2,818.38        | 66.81        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>295.29</b>   | <b>98.00</b>    | <b>197.29</b>   | <b>66.81</b> |
| <b>Nett Amount (S\$)</b>                 | <b>4,513.67</b> | <b>1,498.00</b> | <b>3,015.67</b> | <b>66.81</b> |

## INSPECTION

|                             |                          |                                                                                                             |
|-----------------------------|--------------------------|-------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 13/03/2018               |                                                                                                             |
| Date Inspected:             | 15/03/2018 Inspected At: | B H Auto Services Pte Ltd (HQ)<br>BLK 1 SIN MING INDUSTRIAL<br>ESTATE, SECTOR C #01-115<br>Singapore 575636 |
| Estimated Period of Repair: | 4.0 days                 |                                                                                                             |

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 16 Apr 2018)                                                                                                                                |
| <b>Parts:</b> 143                                            | TOYOTA COROLLA 1.6 (M) (Catalogue:Merimen Singapore 1.0)                                                                                                                     |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SGA9038U) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition   | Repairer's | Amount     |
|-----|-----|----------|--------------------------------|-------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                   | Distorted   | 376.80 FL  | *376.80 FL |
| 2   | 1   |          | *REAR BUMPER SIDE RETAINER LH  | Serviceable | 29.80 FL   | *- FL      |
| 3   | 1   |          | *REAR BUMPER SIDE RETAINER RH  | Serviceable | 29.80 FL   | *- FL      |
| 4   | 1   |          | *REAR BUMPER LOWER SPOILER     | Distorted   | 357.10 FL  | *357.10 FL |
| 5   | 1   |          | *REAR BUMPER SENSOR LH         | Serviceable | 208.01 FL  | *- FL      |
| 6   | 1   |          | *REAR BUMPER SENSOR RH         | Serviceable | 208.01 FL  | *- FL      |
| 7   | 1   |          | *REAR BUMPER CENTRE BRACKET LH | Serviceable | 44.80 FL   | *- FL      |
| 8   | 1   |          | *REAR BUMPER CENTRE BRACKET RH | Serviceable | 44.80 FL   | *- FL      |
| 9   | 1   |          | *REAR END PANEL                | Repair      | 615.00 FL  | *- FL      |
| 10  | 1   |          | *REAR END PANEL TOP GARNISH    | Serviceable | 45.70 FL   | *- FL      |
| 11  | 12  |          | *REAR BUMPER CLIPS             | Necessary   | 68.52 FS   | *30.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                 |               |
|-----------------------------------------------------------|-----------------|---------------|
| <b>Sub Total (S\$)</b>                                    | <b>2,028.34</b> | <b>763.90</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | <b>489.96</b>   | <b>183.48</b> |
| <b>Total Parts (S\$)</b>                                  | <b>1,538.38</b> | <b>580.42</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                                                             | Lab.Type | Repairer's | Amount   |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                                                                                                                         |          |            |          |
| 1                       | ANTI-RUST COATING                                                                                                                       | New      | 160.00     | -        |
| 2                       | PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS | New      | 1,250.00   | 600.00   |
| 3                       | PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES          | New      | 1,000.00   | 500.00   |
| 4                       | PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING                                                                          | New      | 60.00      | -        |
| 5                       | REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM GARNISH,ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS                     | New      | 150.00     | 60.00    |
| 6                       | PROVIDE SKILL LABOUR TO REMOVE AND REPLACE REAR BUMPER SENSORS                                                                          | New      | 60.00      | 40.00    |
| Gross Labour Cost (S\$) |                                                                                                                                         |          | 2,680.00   | 1,200.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;