

ACC. REC. BY:

REF:

(9/MSG18004777/Tgbn2)

Special Instruction:

SUNAJAY

ASSIGNMENT (Office)

Meriman

From (Person):

Christina Wang

of

MSCH

Date/Time: 13/03/2018 2:48pm

Estimated Cost:

Bill to:

OD / HD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 6676E

Insured:

SFU 8217H

at Workshop m/s

Mova Automotive

Tel:

of

Blk 1008 Bukit Merah Lane 3 #01-04

Policy No:

277202320MX

Claim No:

552096

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10.03.2018

CA / REV / REP. / REV 24 HRS WP

15 Fan Yang Rd

H.O.D. Endorsement:

Date/Time:

13/03/2018 3:14pm

Person Contacted:

April

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKS 6676 E - CCB / ATG16017540 / Khc392

DA: 180916

SFU 8217H - x

14/3/18@4:27pm REVISD to Christina Wang via Meriman.

19/3/18@3:50pm confirmed with Alan CS 8430, 5 days by email.

(Red @ 3682.75, 46%)

Tanpin

REF:

MSM.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS6676E Yr Regn: 2013 Dec.
 Type: (3) M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Vellfire C.O. 2362
 Colour: Black A/C Insured / Std / Nil / NA
 Sp Reading: 86248 T-Radio Insured / Std / Nil / NA
 Eng No: _____
 G No: ANH 208298087
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / Shim / STD A/Rim or
 Tyre Size: F: 225/55R18
 R: 225/55R18
 (BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R.Bal: 6 mm L.Bal: 6 mm
 D.O.A. _____ D.O.I. 13/3/18 6pm.
 Survey held at: Mara Far Young
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

- No before paint photo upload 20/3 [Signature]

RECEIVED 24 AUG 2018

Date/Time: File Pass to T

24/8 Tanpin

Date/Time: File Return to T

2

Report Format:

Lump Sum / I.B. / S

MER-TP

4300

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp. \$
☐ Interview \$
☐ Techn. Insp. \$
☐ Weekend \$

Survey Fee

Transportation

US-490 \$

Photos

Other

Total

200
10

210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18004777/T1qb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 13-03-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFU 8217H	Veh. Inspected	SKS 6676E	
Policy No.	27720232QMX	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/03/2018	Inspection Date	13/03/2018	
Survey held at	15 FAN YONG ROAD			
Repairer	MOVA AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 14 Mar 2018

Preliminary Advice

Insured Vehicle No	: SFU8217H	Accident Date	: 10/03/2018
TP Vehicle No	: SKS6676E	Assignment Date	: 13/03/2018
Make	: TOYOTA VELLFIRE	Est. Duration of Repair	: 5.00
Date of Inspection	: 13/03/2018		
Inspection At	: MOVA AUTOMOTIVE PTE LTD (HQ) BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08/94 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,982.75
Revised Amount	:S\$	5,838.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,838.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018		13 Mar 2018 14:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YUEN CHUN ON, ID: S7013222B		
Main Claimant:	MOVA AUTOMOTIVE PTE LTD, Co. Reg. No.: 198904033G		
Vehicle Reg. No.:	SKS6676E	Date of Loss:	10/03/2018 13:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	27720232QMX Coverage: 16/05/2017 - 15/05/2018
Vehicle Reg. No. (Insured):	SFU8217H	Policy No. (Claimant):	
		Excess:	
Repairer:	Mova Automotive Pte Ltd (HQ) Block 1008 Bukit Merah Lane 3 #01-04/06/08/94, 159722 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/03/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Alan Chng <tuckmeng@mov.com.sg>
Sent: Monday, 19 March 2018 3:50 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: finalization for veh no:SKS6676E ***LKK REF:CS/MSG18004777/T1qb

Dear Shiau Chan,

Confirm thanks!

Best Regards
Alan Chng
Claims Estimator
Mova Automotive Pte Ltd
H/P 9686 9276
Office No:6262 3377
Fax No:6264 3151

-----Original Message-----

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Monday, 19 March 2018 3:10 PM
To: Alan Chng; Shu Pei (LKKAUTO); Taufikh (LKKAUTO)
Cc: Admin A; SUR
Subject: RE: finalization for veh no:SKS6676E ***LKK REF:CS/MSG18004777/T1qb

Dear Alan,

Offer Lump Sum \$4,300.00 before GST and 5 repair days.
Kindly confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya
Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@mov.com.sg]
Sent: Monday, 19 March 2018 3:03 PM
To: Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Taufikh (LKKAUTO)
<Taufikh@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: finalization for veh no:SKS6676E ***LKK REF:CS/MSG18004777/T1qb

Dear All,

Please refer the attach after paint photos FYI.
Thanks!

Best Regards

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4033G

Vehicle Details

Vehicle No.:	SK\$6676E
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.4Z G-EDITION A
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	2AZG249146
Chassis No.:	ANH208298087
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$40,850.00
Original Registration Date:	09 Dec 2013
First Registration Date:	09 Dec 2013
Transfer Count:	3
Actual ARF Paid:	\$49,190.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2023
PARF Rebate Amount:	\$36,892.00

Intended COE Rebate Details

COE Expiry Date:	08 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$87,910.00
COE Rebate Amount:	\$50,444.00
Total Rebate Amount:	\$87,336.00

The information contained herein is correct as at 12 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 10:32
Date Of Accident	10/03/2018 13:10
Exact Location Of Accident	SLE TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS6676E
Insured/Policyholder	
Name Of Registered Owner	MOVA AUTOMOTIVE PTE LTD
Co Reg No	198904033G
Email Address	BONG@MOVA.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62723892

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE 2.4Z G-EDITION A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017V0096246VPFR002
Cover Note Number	

Driver

Name of Driver	THONG WEN JIE, JASPER
NRIC No	S9003957A
Date Of Birth	01/02/1990
Occupation	INDOOR
Date Of Driving Pass	18/03/2014
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96230012
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	35 AMBER GARDENS #07-10
Postcode	439966
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFU8217H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YUEN CHAN ON
NRIC/Passport Number	S7013222B
Contact Number	96641150
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 10/3/18 @ 13.10pm I was driving along the
 towards CTE in front CAR stop and I stop?
 Suddenly Veh. B hit on my rear position

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO
 SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY
 FOR MORE INFORMATION.

Please State:

() Claim Own Policy ☒ Claim Third Party () Claim OD/TP at other workshop () Reporting only

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
 Time

X

Driver's Signature (if driver is not the policyholder) / Date
 & Time



Witnessed by Reporting Centre
 Personnel



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

12/03/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- SKS6676E

Veh Model :- TOYOTA VELLFIRE

Estimate# :- CK417190

Claim # :-

ACC. Date :- 10/03/18

Terms :- C.O.D Days

Remarks :-

Alan 9869276

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	989.00 <i>de</i>	989.00
2.	REAR TOWING COVER LH	1 PC	45.00 <i>de</i>	45.00
3.	REAR BUMPER REFLECTOR LAMP LH	1 PC	130.00 <i>ad</i>	130.00
4.	REAR PARKING SENSOR HOLDER	3 PC	30.00 <i>ne</i>	90.00
5.	REAR PARKING SENSOR	1 PC	313.00 <i>de</i>	313.00
6.	REAR BUMPER SIDE RETAINER LH	1 PC	90.00 <i>ne</i>	90.00
7.	REAR BUMPER TOP COVER LH	1 PC	230.00 <i>Ry</i>	230.00
8.	REAR BUMPER CLIPS	10 PC	5.00 <i>ne</i>	50.00
9.	TAILGATE	1 PC	2,980.00 <i>de</i>	2,980.00
10.	TAILGATE (VELLFIRE) EMBLEM	1 PC	160.00 <i>ne</i>	160.00
11.	TAILGATE LOGO	1 PC	55.00 <i>ne</i>	55.00
12.	REAR WINDSCREEN MOULDING	1 PC	230.00 <i>ne</i>	230.00
13.	TAILGATE INNER TRIM	1 PC	680.00 <i>xm</i>	680.00
14.	END PANEL ASSY	1 PC	789.00 <i>Ry</i>	789.00
LIST TOTAL S\$				7,457.00
25% DISCOUNT S\$				-1,864.25
				5,592.75
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN GLASS SEALANT	1 PC	40.00 <i>ne</i>	40.00
SPECIAL NET TOTAL S\$				40.00
LABOUR :				
TO REMOVE & INSTALL REAR WINDSCREEN				120.00
TO REMOVE & INSTALL REAR PARKING SENSOR				60.00
TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE				100.00
TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET & RTC IN ORDER TO CUT OFF PANEL				250.00
TO CUT OFF END PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGEDS PARTS				700.00
TO APPLY BODY JOINT SEALANT ON CUTTING AREAS				40.00
TO APPLY RUST PROOF ON AFFECTED AREAS				80.00
TO SPRAY PAINT ON REPLACED, REPAIRED ARAES				800.00
TO REPROGRAMMING ON REAR PARKING SENSOR AFTER REPAIR				200.00
LABOUR TOTAL S\$				2,350.00



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

12/03/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 131041

Veh # :- SKS6676E

Veh Model :- TOYOTA VELLFIRE

Estimate# :- CK417190

Claim # :-

ACC. Date :- 10/03/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

7,982.75

GST @ 7 %

558.79

AMOUNT DUE S\$

8,541.54

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
- WP
13/3/18 @ 6pm
Resurvey before (after) paint
5 days.
sun @ lkkauto.com 14/3/18

\$4350 Selang



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/05/06/94
Singapore 159722

Tel: (65) 6272 3882
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

12/03/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1

Veh # :- SKS6676E

Veh Model :- TOYOTA VELLFIRE

Estimate# :- CK417190

Claim # :-

ACC. Date :- 10/03/18

Terms :- C.O.D Days

Remarks :-

Alan 9869276

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	989.00 <i>de</i>	989.00
2.	REAR TOWING COVER LH	1 PC	45.00 <i>de</i>	45.00
3.	REAR BUMPER REFLECTOR LAMP LH	1 PC	130.00 <i>cut</i>	130.00
4.	REAR PARKING SENSOR HOLDER	3 PC	30.00 <i>rev</i>	90.00
5.	REAR PARKING SENSOR	1 PC	313.00 <i>dis</i>	939.00
6.	REAR BUMPER SIDE RETAINER LH	1 PC	90.00 <i>re</i>	90.00
7.	REAR BUMPER TOP COVER LH	1 PC	230.00 <i>re</i>	230.00
8.	REAR BUMPER CLIPS	10 PC	5.00 <i>no</i>	50.00
9.	TAILGATE	1 PC	2,980.00 <i>hb</i>	2,980.00
10.	TAILGATE (VELLFIRE) EMBLEM	1 PC	160.00 <i>re</i>	160.00
11.	TAILGATE LOGO	1 PC	55.00 <i>re</i>	55.00
12.	REAR WINDSCREEN MOULDING	1 PC	230.00 <i>re</i>	230.00
13.	TAILGATE INNER TRIM	1 PC	680.00 <i>x</i>	680.00
14.	END PANEL ASSY	1 PC	789.00 <i>re</i>	789.00
	LIST TOTAL S\$			7,457.00
	25% DISCOUNT S\$			-1,864.25
				5,592.75
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN GLASS SEALANT	1 PC	40.00 <i>re</i>	40.00
	SPECIAL NET TOTAL S\$			40.00
LABOUR :				
	TO REMOVE & INSTALL REAR WINDSCREEN			120.00
	TO REMOVE & INSTALL REAR PARKING SENSOR			60.00
	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE			100.00
	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET & RTC IN ORDER TO CUT OFF PANEL			250.00
	TO CUT OFF END PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGEDS PARTS			700.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS			40.00
	TO APPLY RUST PROOF ON AFFECTED AREAS			80.00
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS			800.00
	TO REPROGRAMMING ON REAR PARKING SENSOR AFTER REPAIR			200.00
	LABOUR TOTAL S\$			2,350.00

P-5132

-258

P-3849



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088664-2

Estimate

12/03/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 131041

Veh # :- SKS6676E

Veh Model :- TOYOTA VELLFIRE

Estimate# :- CK417190

Claim # :-

ACC. Date :- 10/03/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts SS
-----	-------------	-----	---------	------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

7,982.75

GST @ 7 %

558.79

AMOUNT DUE S\$

8,541.54

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

P-3849

SIN-40

LC-1520

5409

-20665

4327.20

Taughtin 97445749

-wp

13/3/18 @ 6pm

Resuming before/after point

5 days

sun @ mva.com

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004777/T1QBN2

Date: 27/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27720232QMX
Claimant Vehicle No :	SKS6676E	Insured Vehicle No :	SFU8217H
Date of Loss:	10/03/2018	Nature of Claim:	TP
		Claim No:	552096

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS6676E	Engine No:	2AZG249146
Make & Model:	TOYOTA VELLFIRE, 2.4 Z G-Edition (A)	Chassis No:	ANH208298087
Reg. Date:	09/12/2013 (Man. Year: 2013)	Odometer:	86248 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,632.75	3,889.00	1,743.75	30.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,520.00	830.00	35.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,982.75	5,409.00	2,573.75	32.24
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	7,982.75	4,300.00	3,682.75	46.13
+ GST 7.00/7.00% (S\$)	558.79	301.00	257.79	46.13
Nett Amount (S\$)	8,541.54	4,601.00	3,940.54	46.13

INSPECTION

Date of Assignment: 13/03/2018

Date Inspected: 13/03/2018 Inspected At:

15 Fan Yong Road
 Repairer: Mova Automotive Pte Ltd (HQ)
 Block 1008 Bukit Merah Lane 3 #01-04/06/08/94
 Singapore 159722

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2018)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 Z G-Edition (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS6676E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	989.00 FL	*989.00 FL
2	1		*REAR TOWING COVER LH	Deformed	45.00 FL	*45.00 FL
3	1		*REAR BUMPER REFLECTOR LAMP LH	Cut	130.00 FL	*130.00 FL
4	3		*REAR PARKING SENSOR HOLDER	Necessary	90.00 FL	*90.00 FL
5	1		*REAR PARKING SENSOR	Distorted (1 Ps only)	939.00 FL	*313.00 FL
			(3 Pcs)			
6	1		*REAR BUMPER SIDE RETAINER LH	Necessary	90.00 FL	*90.00 FL
7	1		*REAR BUMPER TOP COVER LH	Repair	230.00 FL	*- FL
8	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
9	1		*TAILGATE	Bent	2,980.00 FL	*2,980.00 FL
10	1		*TAILGATE (VELLFIRE) EMBLEM	Necessary	160.00 FL	*160.00 FL
11	1		*TAILGATE LOGO	Necessary	55.00 FL	*55.00 FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	230.00 FL	*230.00 FL
13	1		*TAILGATE INNER TRIM	Not Necessary	680.00 FL	*- FL
14	1		*END PANEL ASSY	Repair	789.00 FL	*- FL
15	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,497.00	5,172.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,864.25	1,283.00
Total Parts (S\$)	5,632.75	3,889.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00	120.00
2	TO REMOVE & INSTALL REAR PARKING SENSOR	New	60.00	30.00
3	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	100.00	60.00
4	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES,CARPET & RTC IN ORDER TO CUT OFF PANEL	New	250.00	80.00
5	TO CUT OFF END PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGEDS PARTS	New	700.00	500.00
6	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	40.00	-
7	TO APPLY RUST PROOF ON AFFECTED AREAS	New	80.00	30.00
8	TO SPRAY PAINT ON REPLACED,REPAIRED AREAS	New	800.00	600.00
9	TO REPROGRAMMING ON REAR PARKING SENSOR AFTER REPAIR	New	200.00	100.00
Gross Labour Cost (S\$)			2,350.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >