

INS. CASE OWNER: ANBA CC3 / III1800 4776, R, W37 LKK: IDAC:

Surveyor: KARUL DOI: 02104118 Date / Time: 12/7/18 Registered in Merimen: 12/7/18

Pre-assign / CCU / FTE:



Insured Vehicle No.: SHA 5987K
Name of Insured: CTL
Insured Tel No.: _____ HP: _____
Excess Sec II :SS _____ D.O.A: 12/7/18
Is driver the owner? (YES / NO) Nature of Accident: _____
If NO, Driver Name / Age: MUNASIB BIN RASO
Driver Tel No.: _____ (V/L: YES / NO)

Claim No.: NOT18030391
Policy No.: ML0M0045
Make / Model: HYUNDAI
Place of Accident: SUP RP FROM BADOEN RO TWO
W37 & CIA PAYAH
OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No

SKV 4480N



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time		STAGE	DATE / PIC
<u>14/7/18</u>	<u>SKV 4480N - V</u>	Non-Reporting ltr (1st):	
<u>14/7/18</u>	<u>CTL</u>	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
<u>19/08/18</u>	<u>FILE SUBMITTED. OLD REPAIR-ENDED TP.</u>	Call OE:	<u>UC</u>
	<u>SEEK LIABILITY WARRANT.</u>	After call ltr to OE:	
<u>22/08/18</u>	<u>IN KUALA LUMPUR</u>	Documentation Check List: Handler	Typist
	<u>BUAH LUMUT CURE</u>	Notification ltr (if non-pickup)	
	<u>MINISTER</u>	After call ltr to OE:	
<u>18/01/19</u>	<u>ORIGINAL TP LOD IN</u>	Authorisation To Act:	
	<u>TP REPORT FOR WARRANTS APPROVAL</u>	Release Voucher:	
<u>29/01/19</u>	<u>REPORT DONE</u>	Final Repair Bill:	
	<u>SEEK WARRANTS APPROVAL TO B BY HARMON.</u>	Car Rental Invoice:	
<u>15/02/19</u>	<u>TP DO AT THE REPAIR PHOTOS</u>	Towing Invoice:	
	<u>ALL APPROVED WARRANTS.</u>	LTA / GIA:	
	<u>CONFIRMED AMOUNT SHAW AS LOD</u>	Medical Bill:	
	<u>ALL DOCS IN ORDER.</u>	PIR:	
	<u>TO CLOSE.</u>	Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		Confirm by: _____	
Repair Cost: <u>R/P</u>	SS <u>2,136.40</u> (3 days) Reduction: <u>59</u> %	Email ☐ Call ☐	
FINAL SETTLEMENT Date/Time: <u>13/08/19</u> Confirm with: <u>CHEONG</u>		Email ☐ Call ☐	
Final Liability: % <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>27</u>	If NO or B 28, Ass. Lia: _____	
Repair Cost: <u>W/600</u>	SS <u>2,285.95</u>	<u>OLD REPAIR-ENDED TP</u>	
Loss of Rental (LOR):	SS _____ (_____ days)	<u>COPY SENT</u>	
Loss of Use (LOU):	SS <u>300.00</u> (100 x 3 days)		
Loss of Income (LOI):	SS _____ (5 x days)		
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search:	SS _____	1) Claim status: <u>Normal/Reject/Private Settle</u>	
Medical:	SS _____	2) Report Format: _____	
Disbursement:	SS _____ (e.g. Tow/Independent)	3) Survey fee: <u>\$ 350.00</u>	
Legal Cost:	SS _____		
Total:	SS <u>2,585.95</u> Global Sum SS: _____		
FINAL PAYMENT Date/Time: _____ Confirm with: _____		Email ☐ Call ☐	
Payee 1:	SS <u>2,585.95</u> Name 1: <u>PERFORMANCE MOTORS LIMITED</u>		
Payee 2: (Strike if N.A.)	SS _____ Name 2: _____		
Payee 3: (Strike if N.A.)	SS _____ Name 3: _____		

Form

REF: III

h

88210

ASSIGNMENT

From: Date: 02042018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKV 4480A
at Workshop m/s Performana
of 303 Alexandra Rd

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKV 4480A Yr Regn: 2011 / July

Type: M.Co / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318I C.C 1995

Colour: BLACK A/C Insured / Std / NI / NA

Sp.Reading: 092910 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W04PF72060FG90241

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 12/03/18 D.O.I. 02/04/18

Survey held at: PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$2,136.40
C/P: \$3,080.05 (59%)

Date/Time: File Pass to?

☐ : Prel. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

Transportation:

1)

Add Fee: ☐ Site Insp (\$

\$ + P.P. \$

Report Format :

☐ Interview (\$

Phone

Lump Sum / I.B.I. (\$

☐ Tech. Invs (\$

Other

☐ Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC3/III18004778/hb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 13-03-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5981K	Veh. Inspected	SKV 4480A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/03/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740133PM GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190123 (AfterSales)
Fax: 64747770

281, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel: 63190886 (AfterSales)
Fax: 63448773

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

13 MAR 2018

Estimate No. : b1 46213
Date Estimated : 13/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Soh Eng
19 Jalan Sedap

Singapore 438275

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

DESCRIPTION

To replace rear bumper assembly and all attachments
cause by accident

VALUE
850 ~~1,700.00~~

Painting on rear bumper upper assembly

934 ~~1,038.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~170.00~~

Sundries

to ? 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER SET MOUNTING PARTS
RR BUMPER CARRIER
RR BUMPER CTR GUIDE
RR BUMPER CTR BOTTOM GUIDE
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER INSERT (M)
RR BUMPER COVER (M)
PDC HOLDER OUTSIDE LH
PDC HOLDER OUTSIDE RH
PDC HOLDER INSIDE LEFT
PDC HOLDER INSIDE RIGHT
RR BUMPER (M)
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
1	33.15	33.15
1	424.25	424.25
1	31.60	31.60
1	61.20	61.20
1	57.05	57.05
1	57.05	57.05
1	158.45	158.45
1	79.70	79.70
1	12.45	12.45
1	12.75	12.75
1	12.80	12.80
1	13.10	13.10
1	1,247.70	1,247.70
4	5.05	20.20

Total Parts : 2,221.45

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197403359K GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747773

389, Kampong Arang Road
East Coast Centre
Singapore 436185
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190318 (AfterSales)
63190331/332 (Motorcard)
64796481 (AfterSales)
64796424 (Motorcard)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46213
Date Estimated : 13/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured Losses / Direct Settlement

Reg. No. _____ Date: 02/04/18 @ 1400

Quoted By: Rfme

Quoted To: 9006068

Quoted For: _____

Quoted By: _____

Quoted To: _____

Quoted For: _____

3 days

Labour 1	:	2,995.00
Parts	:	2,221.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	365.15
Grand Total	:	5,581.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

5.216.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 167401559W, GST Reg. No. M3-0030081-3



FINAL REPORT

Estimate No. : b1 46213
Date Estimated : 13/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Ng Soh Eng
19 Jalan Sedap

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 438275

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the rear bumper include replacment of damaged parts and knocking out dents caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	40.00		40.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER INSERT (M)	162.40	1.00		162.40

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	162.40
Total Labour & Parts :	2,136.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,136.40
GST @7%:	149.55
Grand Total :	2,285.95

Print Received Message

This mail is associated with :

***SKV4480A (MCT18030391)**
[SHA5981K]
TP
NG SOH ENG
Mar 12 2018 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 13/03/2019 15:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2585.95) - SKV4480A - Claim Handler: Zuhaidah Bte Samsuri

Approved:2585.95.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg No. L97401559W GST Reg. No M2-0020081-X



332, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747772

280, Karpong Arang Road
East Coast Centre
Singapore 438180
Tel: 63180988 (AfterSales)
Fax: 63469773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63150528 (AfterSales)
63150533/330 (MotorRAD)
Fax: 64798601 (AfterSales)
64798624 (MotorRAD)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

1255761

13 MAR 2018

Estimate No. : b1 46213
Date Estimated : 13/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Soh Eng
19 Jalan Sedap

Singapore 438275

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

DESCRIPTION

To replace rear bumper assembly and all attachments
cause by accident

850 ~~1,700.00~~

Painting on rear bumper upper assembly

934 ~~1,038.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~177.00~~

Sundries

? 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER SET MOUNTING PARTS
RR BUMPER CARRIER
RR BUMPER CTR GUIDE
RR BUMPER CTR BOTTOM GUIDE
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER INSERT (M)
RR BUMPER COVER (M)
PDC HOLDER OUTSIDE LH
PDC HOLDER OUTSIDE RH
PDC HOLDER INSIDE LEFT
PDC HOLDER INSIDE RIGHT
RR BUMPER (M)
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
1	33.15	? 33.15
1	424.25	? 424.25
1	31.60	? 31.60
1	61.20	? 61.20
1	57.05	? 57.05
1	57.05	? 57.05
1	158.45	? 158.45
1	79.70	? 79.70
1	12.45	? 12.45
1	12.75	? 12.75
1	12.80	? 12.80
1	13.10	? 13.10
1	1,247.70	R 1,247.70
4	5.05	? 20.20

Total Parts : 2,221.45

103, Alexandra Road
Time Darty Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770260, Kembangan Arang Road
East Coast Centre
Singapore 438186
Tel: 63190888 (AfterSales)
Fax: 63669770118, Alexandra Road
Time Darty Business Centre
Singapore 159944
Tel: 63190328 (AfterSales)
63190333/538 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46213
Date Estimated : 13/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Online OD / 3rd Party / Uninsured / Insured (Third Party)

Reg No. _____

Amount: 02/04/18 @ 1400

Signature: Rfme

Amount: 90000068

3 days

Labour 1	:	2,995.00
Parts	:	2,221.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	365.15
Grand Total	:	5,581.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



(vic)

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref :

Our Ref :

Date :

Subject :

08 January 2019

ACCIDENT INVOLVING VEHICLES SKV4480A & SHA5981K ON 12.03.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	2285.95
Loss of use	:	S\$	300.00 (S\$100.00 x 3 days)
Total	:	S\$	2585.95

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SKV 4480A & SHA 5981K ON 12/3/18

I, Ng Soh Eng owner of Vehicle Registration No. SKV 4480A
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:

Name: TAN JINWEN MARK (Date)

NRIC No.: S86157049

In the presence of:

PERFORMANCE MOTORS LIMITED

303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63190111 (AfterSales)

Name: _____ (Date)

NRIC No.: _____



INDIA
INTERNATIONAL
INSURANCE
CORPORATION LTD

INDIA INTERNATIONAL INSURANCE PTE LTD

100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: WCT18030391
Claimant Ref: SKV 4480A

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,285.95 (repair cost), S\$ 600.00 (loss of use/rental), S\$ — (search fee), vehicle no. SKV 4480A that was damaged pursuant to the accident which occurred on 12/05/2018 (date) at BRADDELL ROAD (location) involving vehicle no. SHASBIK (insured vehicle). This is pursuant to the inspection conducted on 02/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NA SOH ENG ("the third party claimant") of vehicle no. SKV 4480A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKV 4480A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,285.95 PERFORMANCE MOTORS LIMITED

Dated this 13 day of 03 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

363 ALEXANDRA ROAD

SINGAPORE 159941

Nationality:

Occupation:

WITNESS:

Signature:



HOR

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

19907198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408033

Nationality:

Occupation:

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref:
Claimant Ref:

We/I, Performance Motors Ltd (workshop*) hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$22,500 (repair cost), S\$300 (loss of use/rental), S\$ (search fee), vehicle no. S4V4500 that was damaged pursuant to the accident which occurred on 12-3-18 (date) at Brouhela Rd to Tanjong Pagar (location) involving vehicle no. S4S566 (insured vehicle). This is pursuant to the inspection conducted on _____ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Ng Suk Eng ("the third party claimant") of vehicle no. S4V4500 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to S4V4500 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ _____ to _____.

Dated this _____ day of _____ 20____

CLAIMANT:

Signature: _____

Signed by "the workshop" (with chop)

Name: _____

PERFORMANCE MOTORS LIMITED

NRIC: _____

303 Alexandra Road

Address: _____

Singapore Darty Performance Centre

Singapore 159941

TEL: 63190100 (Sales)

63190111 (After-sales)

Nationality: _____

Occupation: _____

WITNESS:

Signature: _____

Signed by appointed Surveyor

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

240, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190529 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796501 (AfterSales)
64796524 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1255767
Date IN : 02/04/2018
Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 1
Invoice Number : 2050666 / WSB
Invoice Date : 07/01/2019
Payment Terms : 30 Days From Invoice
Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mdm Ng Soh Eng
19 Jalan Sedap

Singapore 438275

- INVOICE TO - 219

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318I/4 (A)	92910

--- LABOUR 1 ---

To make good the rear bumper including replacement of damaged parts and knock out dented area caused by the accident.

To respray rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 12.03.2018. 3RD PARTY CAR : SHA5981K.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON 02.04.2018 AT 2PM. AUTHORISED REPAIR BY MS VIC ALPEH FROM LKK AUTO ON 22.03.2018 VIA EMAIL.

PROPOSE LOSS OF USE = \$100X3. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

Total Labour 1: 1,974.00

--- PARTS ---

RR BUMPER INSERT (M)

Qty	Retail Price	NETT
1	162.40	162.40
Total Parts :		162.40

Labour Charges : 1,934.00
Parts Charges : 162.40
Lubricant/Misc : 40.00

Total Labour & Parts Charges : S\$ 2,136.40
Less Insurance Excess : S\$ 0.00
Invoice Total Amount Exclude GST : S\$ 2,136.40
GST @ 7% : S\$ 149.55
Invoice Total Amount Include GST : S\$ 2,285.95

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 2,285.95

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2018 Edit Reg		02 Apr 2018 00:00 Edit Adj Rpt	S\$2,136.40 Edit Estimates	S\$2,136.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	NG SOH ENG , ID: S1298821D								
Vehicle Reg. No.:	SKV4480A	Date of Loss:	12/03/2018 15:00 - :59 [79 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18030391	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA5981K	Policy No. (Claimant):	VA1/GA148914						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (13/03/2019): Alert - Adj Mandate Approved (S\$2585.95) - SKV4480A - Claim Handler: Zuhaidah Bt... - III_SG (29/01/2019): Alert - Adj Mandate Maintained - SKV4480A - Claim Handler: Zuhaidah Bte Samsuri - III_SG (19/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SKV4480A - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV4480A (MCT18030391)
[SHA5981K]
TP
NG SOH ENG
Mar 12 2018 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/12/18 14:11	Odometer Reading	1	Load JPG	
2	21/12/18 14:11	Chassis Number	1	Load JPG	
3	21/12/18 14:11	General View	1	Load JPG	
4	21/12/18 14:11	General View	1	Load JPG	
5	21/12/18 14:11	General View	1	Load JPG	
6	21/12/18 14:11	General View	1	Load JPG	
7	21/12/18 14:11	General View	1	Load JPG	
8	21/12/18 14:11	General View	1	Load JPG	
9	21/12/18 14:11	General View	1	Load JPG	
10	21/12/18 14:11	General View	1	Load JPG	
11	21/12/18 14:11	General View	1	Load JPG	
12	21/12/18 14:11	General View	1	Load JPG	
13	21/12/18 14:11	General View	1	Load JPG	
14	21/12/18 14:11	General View	1	Load JPG	
15	21/12/18 14:11	General View	1	Load JPG	
16	21/12/18 14:11	General View	1	Load JPG	
17	21/12/18 14:11	General View	1	Load JPG	
18	21/12/18 14:11	Reinspection Photo	1	Load JPG	
19	21/12/18 14:11	Reinspection Photo	1	Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/03/18 18:11	TP ESTIMATE	1	Load PDF	
2	13/03/18 18:11	TP GIA REPORT	1	Load PDF	
3	03/04/18 18:49	TP ESTIMATE- MARKED	1	Load PDF	
4	21/01/19 13:52	WORKSHOP INVOICE	1	Load PDF	
5	21/01/19 13:52	LOD	1	Load PDF	
6	15/03/19 16:02	AUTHORISATION TO ACT FORM	1	Load PDF	
7	15/03/19 16:02	DISCHARGE VOUCHER	1	Load PDF	

No

Finalized On

India International Insurance Pte Ltd (HQ)

No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	14/03/18 08:40	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18004778/R1HB3Q2

Date: 15/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SKV4480A

Insured Vehicle No: SHA5981K

Date of Loss: 12/03/2018

Nature of Claim: TP

Claim No: MCT18030391

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV4480A

Make & Model: BMW 318, 2.0 CIA Coupe (A)

Reg. Date: 28/07/2011 (Man. Year: 2011)

Colour: Black

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: B413I944N46B20BZ

Chassis No: WBAPF72060FG90241

Odometer: 92910 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,305.40	202.40	2,103.00	91.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,220.40	2,136.40	3,084.00	59.08
+ GST 7.00/7.00% (S\$)	365.43	149.55	215.88	59.08
Nett Amount (S\$)	5,585.83	2,285.95	3,299.88	59.08
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,585.95		

INSPECTION

Date of Assignment: 02/04/2018

Date Inspected: 02/04/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts: M1-COUPE	BMW 318 2.0 CIA Coupe (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKV4480A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
2	1		*REAR BUMPER SET MOUNTING PARTS	Not Necessary	33.15 FS	*- FS
3	1		*RR BUMPER CARRIER	Not Necessary	424.25 FS	*- FS
4	1		*RR BUMPER CTR GUIDE	Not Necessary	31.60 FS	*- FS
5	1		*RR BUMPER CTR BOTTOM GUIDE	Not Necessary	61.20 FS	*- FS
6	1		*RR BUMPER LH GUIDE	Not Necessary	57.05 FS	*- FS
7	1		*RR BUMPER RH GUIDE	Not Necessary	57.05 FS	*- FS
8	1		*RR BUMPER INSERT (M)	Deformed	162.40 FS	*162.40 FS
9	1		*RR BUMPER COVER (M)	Not Necessary	79.70 FS	*- FS
10	1		*PDC HOLDER OUTSIDE LH	Not Necessary	12.45 FS	*- FS
11	1		*PDC HOLDER OUTSIDE RH	Not Necessary	12.75 FS	*- FS
12	1		*PDC HOLDER INSIDE LEFT	Not Necessary	12.80 FS	*- FS
13	1		*PDC HOLDER INSIDE RIGHT	Not Necessary	13.10 FS	*- FS
14	1		*RR BUMPER (M)	Repair	1,247.70 FS	*- FS
15	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
				Total Parts (S\$)	2,305.40	202.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ASSEMBLY AND ALL ATTACHMENTS CAUSE BY ACCIDENT	New	1,700.00	850.00
2	PAINTING ON REAR BUMPER UPPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >