

22/03/2012

ASS. REC. BY:

REF: CS/MSH18004779/Kpbm2 Special Instruction:

Supervisor:

Kenneth

ASSIGNMENT (Office)

From (Person): Christina Wong of MSH Date/Time: 13/03/2018 256pm

Estimated Cost: Bill to:

OD-TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 9932K Insured: SKQ 9127P

at Workshop m/s Trans - (ab) Auto Tel:

of No. 2 AMK St 63

Policy No: 34047659AT2 Claim No: 552036

Sum Insured: Excess:

Make of Veh: D.O.A. 09/03/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp' H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 9932K - CS / 101/501924 / Kpbm2 DA: 13/12/15
	SKQ 9127P - X
14/3/18 @ 4.33pm	revised to Christina Wong via Messenger.

ASS. REC. BY:

REF: MSG-1

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 9832KYr Regn: 06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Perodua Lotusc.c. 1995Colour: White

A/C: Insured / Std / Nil / NA

Sp. Reading: 364348

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: VIFIABEBAUC 277845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim orTyre Size: Long Long 215/60R16R: 15114BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 7 mmL/Bal. 9 mmL/Bal. 7 mmD.O.A. 9/3/18D.O.I. 13/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/3

File pass to Customer

L1 Bump & 81000 (Add to 37567.07, 8210)

RECEIVED 15 MAR 2018

Date/Time, File Pass to?

☐

: Prell. Report

1) 14/3 11:00 AM

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

Report Format: MPR-TPLump Sum / I.B.I. (\$ 8100)

TOTAL

350




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004779/Kqb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 13-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 9127P	Veh. Inspected	SHD 9932K	
Policy No.	29047659AT2	Coverage (\$)	0.00	
Claim No.	552036	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/03/2018	Inspection Date	13/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018		13 Mar 2018 14:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	YEW KWEE ENG, ID: S0871227A, Tel: +6597548393	[Created by insurer]	
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9932K	Date of Loss:	09/03/2018 14:00 - :59
Claim Type:	TP / 552036	Policy/Cover Note No.:	29047659AT2 (Comprehensive) Coverage: 05/01/2018 - 04/01/2019
Vehicle Reg. No. (Insured):	SKQ9127P	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/03/2018]		
Driver/Custodian (Insured):	IVAN CHUA MIN LIP (), NRIC: S7836676A, Tel: +6591829307		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View All

Search Tasks

Create New Task

Complete

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 14 Mar 2018

Preliminary Advice

Insured Vehicle No	: SKQ9127P	Accident Date	: 09/03/2018
TP Vehicle No	: SHD9932K	Assignment Date	: 13/03/2018
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 5.00
Date of Inspection	: 13/03/2018		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD (ANG MO KIO) 2, ANG MO KIO STREET 63 SINGAPORE 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,667.07
Revised Amount	:S\$	10,098.51
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,098.51
Lump Sum Repair	:S\$	8,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9932K
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001216
Chassis No.:	VF1ABL15AUC277845
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$30,309.00
Total Rebate Amount:	\$39,682.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2018 15:53
Date Of Accident	09/03/2018 15:10
Exact Location Of Accident	ANG MO KIO AVE 3 SLIP ROAD TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9932K
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	ONG HO BENG
NRIC No	S1456568Z
Date Of Birth	09/10/1960
Occupation	OUTDOOR
Date Of Driving Pass	05/03/1979
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96409754
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 254 BISHAN ST 22 #07-452
Postcode	570254
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On the 09.03.2018 at about 1508hours, i was travelling straight along the right lane of Ang Mo Kio Avenue 3 sliproad towards CTE. When Vehicle in front of me suddenly made a stop and so i followed suit. Moment later while stationary, i felt an impact from the rear. i alighted to check and realized that Vehicle B(SKQ9127P) had hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ9127P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	IVAN CHUA
NRIC/Passport Number	S7836676A
Contact Number	91829307

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

A - SHD 99321C
 B - SKQ 9127P

Ang Mo Kio Ave 3
 Slip road towards
 CTE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to FID report -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9932K -**AAD1803-084***Not Notified**11 Sep 8 8100*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9932K - JHOW

VF1ABL15AUC277845

RENAULT

LATITUDE

09.03.2018

MSIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i>	1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Re</i>	768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Re</i>	113.47	✓
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Sh</i>	135.97	X
5	1	BUMEP R RETAINER RH REAR	\$	<i>Sh</i>	44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>Sh</i>	43.61	X
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Sh</i>	135.97	X
8	1	BUMEP R RETAINER LH REAR	\$	<i>Sh</i>	44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sh</i>	43.61	X
10	1	BUMPER BEAM REAR	\$	<i>Re</i>	777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Re</i>	225.95	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Re</i>	225.95	X
13	1	BOOT REAR	\$	<i>Re</i>	2,872.68	✓
14	1	BOOT FINISHER	\$	<i>Sh</i>	470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>Sh</i>	323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sh</i>	493.35	X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sh</i>	493.35	X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Re</i>	225.36	✓
19	1	BOOT BADGE	\$	<i>Re</i>	225.36	✓
20	1	BOOT STRUT LH	\$	<i>Sh</i>	276.08	}
21	1	BOOT STRUT RH	\$	<i>Sh</i>	276.08	
22	1	BOOT HINGE LH	\$	<i>Re</i>	367.84	
23	1	BOOT HINGE RH	\$	<i>Re</i>	367.84	
24	1	BOOT INNER TRIM	\$	<i>Sh</i>	586.45	
25	1	BOOT SWITCH	\$	<i>Sh</i>	168.13	
26	1	BOOT LOCK	\$	<i>Re</i>	202.67	
27	1	BOOT LOCK CATCH	\$	<i>Re</i>	74.40	
28	2	LICENCE PLATE LAMP	\$	<i>Sh</i>	50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sh</i>	221.81	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sh</i>	671.45	}
31	1	FENDER PANEL REAR LH	\$	<i>Re</i>	3,299.13	
32	1	WHEELARCH REAR LH	\$	<i>Sh</i>	543.47	
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Re</i>	671.45	
34	1	FENDER PANEL REAR RH	\$	<i>Re</i>	3,299.13	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-084**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9932K -

35	1	WHEELARCH REAR RH	\$	<i>Sn</i>	543.47	X
36	1	TAILLAMP RH	\$	<i>Sn</i>	552.55	X
37	1	TAILLAMP PANEL RH	\$	<i>R</i>	986.70	X
38	1	TAILLAMP LH	\$	<i>Mjcm</i>	552.55	✓
39	1	TAILLAMP PANEL LH	\$	<i>R</i>	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	<i>Bu</i>	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>nd</i>	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	X
44	1	EXHAUST REAR	\$	<i>R</i>	7,489.05	X
45	1	EXHAUST CAP REAR	\$	<i>R</i>	230.49	X

TOTAL	\$	35,868.94	<i>92</i>
10%	\$	3,586.89	
	\$	32,282.05	

Specical Nett

1	1SET	PARKING AID	\$	<i>Shan</i>	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	<i>na</i>	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	<i>na</i>	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i>	35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	X
19	1	TAILLAMP CLIP RH	\$	<i>na</i>	5.00	X
20	1	TAILLAMP CLIP LH	\$	<i>na</i>	5.00	✓
21	2	REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	X
22	1	WINDSCREEN MOULDING	\$	<i>na</i>	100.00	X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i>	385.00	X
25	1	SPARE TYRE	\$	<i>Sn</i>	330.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9932K -**AAD1803-084**

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	~ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	~ 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
Towing Fees	\$	120.00	~ 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X

Repair Days by Reparer

Signature:

Date:

TOTAL \$ 11,160.00**Over All Total \$ 45,667.07****15 Days****5 days**

05

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004779/KQBN2

Date: 15/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29047659AT2
Claimant Vehicle No :	SHD9932K	Insured Vehicle No :	SKQ9127P
Date of Loss:	09/03/2018	Nature of Claim:	TP
		Claim No:	552036

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9932K	Engine No:	M9R8839C001216
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC277845
Reg. Date:	05/06/2014 (Man. Year: 2014)	Odometer:	564348 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Linglong 9 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Linglong 9 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,507.05	8,598.51	25,908.54	75.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,160.00	1,500.00	9,660.00	86.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,667.05	10,098.51	35,568.54	77.89
Approved Total (Overridden) (S\$)		8,100.00		
(S\$)	45,667.05	8,100.00	37,567.05	82.26
+ GST 7.00/7.00% (S\$)	3,196.69	567.00	2,629.69	82.26
Nett Amount (S\$)	48,863.74	8,667.00	40,196.74	82.26

INSPECTION

Date of Assignment:	13/03/2018	
Date Inspected:	13/03/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2018)
Parts: 143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD9932K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1	*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1	*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
31	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
32	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
33	1	*FENDER PANEL INNER TRIM REAR RH	Repair	671.45 FL	*- FL
34	1	*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
35	1	*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
36	1	*TAILLAMP RH	Serviceable	552.55 FL	*- FL
37	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1	*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL
39	1	*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
40	1	*OUTER PANEL REAR (END PANEL)	Buckled	1,471.77 FL	*1,471.77 FL
41	1	*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
42	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
43	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
44	1	*EXHAUST REAR	Repair	7,489.05 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
46	1	*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
47	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
48	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
49	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
50	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
51	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
52	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
53	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
54	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
55	1	*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
56	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
57	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
58	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
59	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
60	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
61	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
62	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
63	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
64	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
65	1	*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
66	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
68	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
69	1	*SPARE TRYE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
70	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,093.94	9,450.57
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,586.89	852.06
Total Parts (\$\$)	34,507.05	8,598.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	660.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST }	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TOWING FEES	New	120.00	-
13	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (S\$)			11,160.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >