

INS. CASE OWNER:

Ming Yao

cc 6, AIG 1800 4780, G w039

LKK:
IDAC

XGA

ASSIGNMENT

Surveyor:

DOI:

12/13/18

Date / Time:

12/13/18

Registered in Merimen:

12/13/18

Pre-assign / CCU / FTE

SK2000D



Insured Vehicle No.:

Claim No.:

520 947793456

Name of Insured:

CHOW STEW YING

Policy No.:

1500085379

Insured Tel No.:

HP:

98183338

Make / Model:

M-BENZ C200

Excess Sec II :SS

D.O.A.:

7/13/18

Place of Accident:

WPP Serangoon Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

CB7001E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Bedok Motor Engineering Pte Ltd



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/14

CB7001E - X

SK2000D - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

23/4/18

Need to get video from TP.

23/4/18

Receive vide from TP. Send to AIG.

called CB confirm accident details. inform TP. claim. inform we receive TP video agree to settle. then send out

RECEIVED 07 AUG 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

SS

400.00

Loss of Rental (LOR):

SS

440.00

(

days) X

220.00

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

12.84

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

852.84

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

852.84

Name 1:

Bedok Motor Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
8/8/18

Signature

Xnl

REF:

AG

ASSIGNMENT

From:

Date:

14.08.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

CB 7001 E

at Workshop n/s

Bedok Motor

of

30 Defu Lane 9

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

2.82 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

31/7/18 confirm 2.8.2 \$400.00 with 2 working days.

(Rd) = \$3398.74
89.1.1

Veh No:

CB7001 E

Yr Regn:

11 Sep 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yutong ZK6100H

cc.

6693

Colour

Green/white

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LZYTBTD 67 B1012 946

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

11R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

AU FINE

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14-03-18

Survey held at

w/s

12pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS) \$

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18004780/Gwa3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-03-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SK 2000D	Veh. Inspected	CB 7001E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/03/2018	Inspection Date	14/03/2018
Survey held at	BEDOK TRANSPORT PTE LTD 30/32 DEFU LANE 9 SINGAPORE 539270		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Estimate To Repair CB7001E YUTONG ZK6100H

Chassis No : LZYTBD67B1012946

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear wheel rim hub cap right ✓ <i>cut</i>	\$ 455.49
2	1pc	Rear wheel rim right X <i>NN</i>	\$ 654.22
			\$ 1,109.71
			Less 10%
			\$ 110.97
			\$ 998.74
<u>SPECIAL NETT ITEAMS</u>			
3	1pc	Rear wheel tyre right X <i>Y NN</i>	\$ 480.00
4	1set	Rear wheel mudflaps X <i>Y NN</i>	\$ 120.00
			\$ 600.00
<u>LABOUR & MISC CHARGE</u>			
1		Labour to make good repair to right wheel mudguard and rear body side panel.	\$ 600.00
2		To putty and spray painting of the affected areas with two tone colours.	\$ 1,500.00
			\$ 2,100.00
			Total
			\$ 3,698.74

2 Days

~~Long term repair~~ P/P

After repair photos

GuoQiang - 82880282

GuoQiang@lkkauto.com

14/3/18

100 (SN)

~~100~~

~~20~~

300

400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Estimate To Repair CB7001E YUTONG ZK6100H

Chassis No :LZYTBD67B1012946

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear wheel rim hub cap right ✓ <i>cut</i>	\$ 455.49
2	1pc	Rear wheel rim right X <i>NN</i>	\$ 654.22
			\$ 1,109.71
			Less 10%
			\$ 110.97
			\$ 998.74
<u>SPECIAL NETT ITEAMS</u>			
3	1pc	Rear wheel tyre right X	\$ 480.00
4	1set	Rear wheel mudflaps X	\$ 120.00
			\$ 600.00
<u>LABOUR & MISC CHARGE</u>			
1		Labour to make good repair to right wheel mudguard and rear body side panel.	\$ 600.00 <i>400</i>
2		To putty and spray painting of the affected areas with two tone colours.	\$ 1,500.00 <i>600</i>
			\$ 2,100.00
			Total
			\$ 3,698.74

2 Days .

less sum repair .

After repair photos .

GuoQiang - 82880282

GuoQiang@lkkauto.com

14/3/18 .

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Our Ref CB 7001 E
Your Ref SK 2000 D

Date 30/7/2018

Claims Department - Executive In charge

WITHOUT PREJUDICE

Dear Sir / Madam,

ACCIDENT INVOLVING CB 7001 E & SK 2000 D on 7/3/18 17.25 p.m

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf :-

- O Original survey report / _____ copies of photographs _____
- O Original Tax-Invoice number BME -1-A 10036 O Original rental invoice number JTS -1807006
- O SAS / AS & IS / police report O Police result
- O Certificate Of Insurance _____ O Vehicle search result
- O _____ O _____

* Survey under insurance instruction / Independent surveyor / No survey.

- a) Cost of repair (inclusive GST)
- b) Survey fees / Photographs as per request
- c) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees
- d) ~~Loss of hire / use / rental / earnings~~ / rental fees
- e) Scene photographs
- f) Administrative charges to negotiate settlement
(Waive if 100% offer made within acknowledge timeframe)

\$ 400.00

\$ —

\$ 12.8K

\$ 560.00

\$ —

\$ —

g) _____

\$ 972.84

\$ —

Total

*Driver's Injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to " Bedok Motor Engineering Pte Ltd " within 28 days.

Your Faithfully,
Email : workshop@bedoktransport.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18004780/Gwa3

24 April 2018

Chow Siew Ying
101 Bukit Teresa Road
Singapore 099742

Dear Sir/Madam,

ACCIDENT INVOLVING SK 2000D AND CB 7001E ON 07/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To : BEDOK MOTOR ENGINEERING PTE LTD

From : OWNER OF VEHICLE NUMBER

CB 7001E

ACCIDENT INVOLVING

CB 7001E & SK 2000D.

ALONG / AT

Opp Serangoon Road.

ON

7/3/18

I / We hereby authorize you to act on my / our behalf in pursuance of my / our claim for losses arising out of the above accident.

This letter serves as the 'AUTHORITY TO ACT'

I / We also hereby authorize all agreed settlement payment be made in favour to BEDOK MOTOR ENGINEERING PTE LTD.

Bedok

Transport.

Pte Ltd.

Name

NRIC / Co Reg No.

200311654W

Address

30 Petir Lane 9 Singapore

Contact

62843032

Date

3/8/18

Signature

Owner's / Hirer's signature / RTP
(Company's stamp if applicable)



RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, BEDOK MOTOR ENGINEERING PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANT'S PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 400.00 (repair cost), S\$ 440.00 (loss of rental/use), S\$ 12.84 (disbursement), for vehicle no. CB 7001E that was damaged pursuant to the accident which occurred on 07/03/2018 (date) along UPPER SERANGOON RD (location) involving vehicle no/s SK 2100D.

This is pursuant to the inspection conducted on 14/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner BEDOK TRANSPORT PTE LTD (the third party claimant") of vehicle no. CB 7001E make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to CB 7001E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 8 (day) of 8 (month) 2018 (year)



X6Q

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

INVOICE

INVOICE BME-I-A10036
DATE 30-Jul-2018
TERM -

Services Rendered to :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building, 78 Shenton Way
#08-16
Singapore 079120

No.	DESCRIPTION	AMOUNT
1	Bus No : CB7001E Lump Sum Repair	\$ 400.00
Total :		\$ 400.00

for **BEDOK MOTOR ENGINEERING PTE LTD**



Authorised Signature

ALL CHEQUES MUST BE CROSSED
AND MADE PAYABLE TO :
BEDOK MOTOR ENGINEERING PTE LTD

Motor Vehicle Rental Agreement

Hirer Name :	Bedok Transport Pte Ltd.		
Address :	30. Dalm Lane 9, Singapore		
Phone :	539270		
Vehicle Reg No:	62848032		
Make :	CS 7001 E		
Model :	Yutong 2K 660H		
Date out :	15/3/18	Time :	9:00 a.m.
Due in:	16/3/18	Time :	5:30 p.m.
Rental period :	2 days.		
Deposit :			
Charges :	unit price :	Period :	Amount :
Daily :	\$280	2	\$560
Weekly :			
Monthly :			
Extra hours :			
Fuel :			
Collision Damage Waiver :			
Sub-Total :			
GST 7 %			
Total :	\$280	2	\$560

PART 2**Conditions of Hire**

Hirer must have recent driving experience and hold the vocational licence
 Hirer is responsible for all damages arising from a single vehicle accident
 Motor vehicle is to be returned with substantially the same amount of fuel
 All rental rates, fees & charges are subject to change without notice
 The hirer is totally responsible for all loss of, or damage to the motor vehicle
 (including loss of use) cost of the vehicle, legal expenses, towing and recovery
 charges and insurance excess of \$1,500 (including offence and fine)
 Hirer must check and top-up Engine Oil and water every day.

NOTE: If there is to be any extension of the period of hire beyond that stated on the rental agreement, the Company must be notified and it must agree to such extension in writing, otherwise the Vehicle will be immediately reported to the police as stolen.

Signed by: -



JIN TAO BUS SERVICE

Signed by: -



Name :

金 淘 巴 士 服 务
JIN TAO BUS SERVICE

Block 123A Rivervale Drive #05-133

Singapore 541123

Tel : 6385 7453 HP: 9238 8380

Date : 30-Jul-2018

Invoice : **JTS-1807006**

BEDOK MOTOR ENGINEERING PTE LTD

No. 30 & 32 Defu Lane 9

Singapore 539270

<u>(ref: Accident Veh - CB7001E)</u>	<u>No of days</u>	<u>Per day</u>	<u>Amount</u>
Being Rental of one bus (Reg No. CB6747T)			
Date : 2018 MAR : 15, 16	2	\$ 280.00	\$ 560.00

(Singapore Dollars : Five Hundred & Sixty Only)	\$ 560.00
---	-----------

(This is a computer generated document and does not require a signature)

*With the Compliments
of*

KURU & CO
Advocates & Solicitors
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

URGENT	
	for your comments and instructions
	for your approval and return
	for your necessary action
	for your signature and return
	for your onward transmission
	for your attention / perusal
	for your information and file
	by way of service

Date : 08.03.18

To : Bedok Motor Engineering Pte Ltd / BY FAX: 6287 0633

Please let us have the payment for the LTA search fees:

<u>Our ref</u>	<u>Yr Client Vehicle No.</u>	<u>3RD Party Vehicle No.</u>	<u>Search Date</u>	<u>Amount</u>
L.18.MISC2.1616	CB 7001E	SK 2000D	07.03.18	\$12.84
				----- \$12.84 -----

Regards,
Kuru & Co

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Mar 2018 Edit Reg		14 Mar 2018 00:00 Edit Adj Rpt	S\$400.00 Edit Estimates	S\$400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS Insured: CHOW SIEW YING, ID: S01024142 Main Claimant: BEDOK TRANSPORT PTE LTD, Co. Reg. No.: 200311654W Vehicle Reg. No.: CB7001E Claim Type: TP / 5209477934SG Vehicle Reg. No. (Insured): SK2000D Date of Loss: 07/03/2018 17:00 - :59 [65 Months and 24 Days From LTA Reg Date (Man Yr)] Policy/Cover Note No.: 1700085519 (Comprehensive) Coverage: 15/12/2017 - 14/12/2018 Policy No. (Claimant): D17MTSCBU000314 Excess: Repairer: Bedok Motor Engineering Pte Ltd (HQ) 30 Defu Lane 9, 539270 Defu Lane - Tel: 62843032 Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/03/2018] View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED There are no mail for this case.																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*CB7001E (5209477934SG)
[SK2000D]
TP
BEDOK TRANSPORT PTE LTD
Mar 7 2018 5:00PM
[CHOW SIEW YING]
Bedok Motor Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View In Browser

1 per page ☐

☒

Letters/Correspondences			Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1	Edit
1	(Draft)	Third Party Express Settlement - Payment Breakdown		

1 per page ☐

☒

Assessment Reports			Thumbnail	Print
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1	Load HTM
1	14/03/18 13:22	Accident Statement From: OD - Reg. No: SK2000D, Claimant: CHOW SIEW YING		

3 per page ☐

☒

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load JPG
1	30/07/18 09:47	General View	1	Load JPG
2	30/07/18 09:47	General View	1	Load JPG
3	30/07/18 09:47	General View	1	Load JPG
4	30/07/18 09:47	General View	1	Load JPG
5	30/07/18 09:47	General View	1	Load JPG
6	30/07/18 09:47	General View	1	Load JPG
7	30/07/18 09:47	General View	1	Load JPG
8	30/07/18 09:47	General View	1	Load JPG
9	30/07/18 09:47	General View	1	Load JPG
10	30/07/18 09:47	General View	1	Load JPG
11	30/07/18 09:47	General View	1	Load JPG
12	30/07/18 09:47	General View	1	Load JPG
13	30/07/18 09:47	General View	1	Load JPG
14	30/07/18 09:47	General View	1	Load JPG
15	30/07/18 09:47	General View	1	Load JPG
16	30/07/18 09:47	General View	1	Load JPG
17	30/07/18 09:47	General View	1	Load JPG
18	30/07/18 09:47	General View	1	Load JPG
19	30/07/18 09:47	General View	1	Load JPG
20	30/07/18 09:47	General View	1	Load JPG
21	30/07/18 09:47	General View	1	Load JPG
22	30/07/18 09:47	General View	1	Load JPG
23	30/07/18 09:47	General View	1	Load JPG
24	30/07/18 09:47	General View	1	Load JPG
25	30/07/18 09:47	General View	1	Load JPG

1 per page ☐

☒

Documentation			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF
1	13/03/18 18:40	TP ESTIMATE	1	Load PDF
2	13/03/18 18:40	TP GIA REPORT	1	Load PDF
3	09/04/18 22:42	TP ESTIMATE - MARKED		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	16/08/18 09:12	AUTHORISATION TO ACT FORM		Load PDF
5	16/08/18 09:12	LETTER TO OI		Load PDF
6	16/08/18 09:12	LTA SEARCH		Load PDF
7	16/08/18 09:12	Release Voucher		Load PDF
8	16/08/18 09:12	RENTAL RECEIPT		Load PDF
9	16/08/18 09:12	WORKSHOP INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SK2000D (Insd veh)	Model:	YUTONG ZK6100H 6.7 D (M)
	CB7001E (TP veh)		
Date of Accident:	07/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,698.74
Final Repair Cost	:	\$	400.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	440.00 2 days
LTA / GIA Search Fee	:	\$	12.84
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	852.84

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Bedok Motor Engineering Pte Ltd	:	\$ 852.84
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

16 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18004780/GWA3Q2

Date: 16/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700085519
 Claimant Vehicle No: CB7001E Insured Vehicle No: SK2000D
 Date of Loss: 07/03/2018 Nature of Claim: TP Claim No: 5209477934SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: CB7001E Engine No: ISBE425022002305
 Make & Model: YUTONG ZK6100H, 6.7 D (M) Chassis No: LZYTBTD67B1012946
 Reg. Date: 11/09/2012 (Man. Year: 2011) Odometer: 0 km
 Colour: White/Green
 Engine Capacity: 6693 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5
 Front Left Side: AUFINE 6 mm Rear Left Side: AUFINE 6 mm
 Front Right Side: AUFINE 6 mm Rear Right Side: AUFINE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,598.74	100.00	1,498.74	93.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	300.00	1,800.00	85.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,698.74	400.00	3,298.74	89.19
+ Car Rental (2.0 x S\$220.00/day) (S\$)		440.00		
+ Doc/Search Fee (S\$)		12.84		
Nett Liability (S\$)		852.84		

INSPECTION

Date of Assignment: 14/03/2018
 Date Inspected: 14/03/2018 Inspected At: Bedok Motor Engineering Pte Ltd (HQ)
 30 Defu Lane 9
 Singapore 539270
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL RIM HUB CAP RIGHT	Cut	409.94 FS	*100.00 FS
2	1		*REAR WHEEL RIM RIGHT	Not Necessary	654.22 FL	*- FL
3	1		*REAR WHEEL TYRE RIGHT	Not Necessary	480.00 FS	*- FS
4	1		*SET REAR WHEEL MUDFLAPS	Not Necessary	120.00 FS	*- FS
					Sub Total (\$\$)	1,664.16 100.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	65.42 0.00
					Total Parts (\$\$)	1,598.74 100.00

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO MAKE GOOD REPAIR TO RIGHT WHEEL MUDGUARD AND REAR BODY SIDE PANEL	New	600.00	100.00
2	TO PUTTY AND SPRAY PAINTING OF THE AFFECTED AREAS WITH TWO TONE COLOURS	New	1,500.00	200.00
Gross Labour Cost (S\$)			2,100.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >