

NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

Date: 13th March 2018

Quotation: SKS 8953 S BMW X1

S\$

1 Pc. Rear lid	1,742.16	PA✓
1 Pc. Rear lid 'BMW' logo	80.90	m✓
1 Pc. Rear lid lock	268.56	X
1 Pc. Rear lid rubber	289.65	m✓
1 Pc. Rear bumper top	1,086.49	DB✓
1 Pc. Rear bumper bottom	476.42	DB✓
1 Pc. Rear bumper beam	419.51	?
1 Pc. Rear bumper reinforcement	541.25	?
1 Set Rear bumper clips	50.00	m✓
2 Pcs Rear bumper side retainers @ 70.95	RHm/141.90	2H-X
2 Pcs Rear bumper reflectors @ 50.20	100.40	?
2 Pcs Rear bumper tow cover @ 49.55	cul/RH 99.10	2H-X
3Pcs 1 Pc Reverse sensor @ 398.50	1,594.00	m✓
1 Pc. Rear end panel	1,791.46	B?.
1 Pc. Rear end panel inner trim	216.18	?
1 Pc. Rear exhaust silencer box	1,631.61	X
	10,529.59	
	Less 10%	1,052.96
	c/fd	9,476.63

NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

S\$

b/fd

9,476.63

Special Net Items:-

	60
1 Pc. Rear lid windscreen sealant	150.00 70
1 Pc. Rear end panel sealant	100.00 60?
1 Set Rear no. plate & casing	60.00 X

Labour Charges:-

① To check wiring	50.00 30?
② To do computerised resetting	180.00 80
③ To remove & refix rear windscreen	300.00 120
④ To remove & transfer rear lid inner components	200.00 80
⑤ To remove & refix inner upholstery	280.00 100
⑥ To do rustproofing	160.00 80
⑦ To remove & renew rear exhaust silencer box	250.00 X
⑧ Panel beating	1,200.00 500
⑨ Spray painting	1,500.00 750

Total: 13,906.63

RASUL

HP 90010068

5 days

4/5

14/03/18 @ 1640

Done after repair

NGIAK MOTOR WORKS

MAILING ADDRESS: BLK 6, GHIM MOH ROAD #10-194

SINGAPORE 270006

H/P: 9850 2253

Reg. No. 207300/00C

SKS 8953 S BMW XI

Supplementary

1	Pc	Rear buzzer monty crank	S\$ 136.85 ✓
		Less 10%	13.69
			<u>123.16</u>

for recovery by Bnp

2 KK Ant

8

15/03/2018