



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Yeo Ing Ann (Yang Ying'An)  Blk 111 Clementi Street 13 #02-38 Singapore 120111  Contact No Mobile: 91054417	Cust No/Name	/Mr Yeo Ing Ann (Yang Ying'An)
	Reg No/Reg Date	SLV5654Y / 03/01/201
	Date In/Mileage	/ 0
	Chassis No	KNAFJ411MJ5756469
	Engine No	G4FGHH688572
	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	12/03/2018/ 21:28		465 / Tay Jian Ye	24756
Description of Goods / Services				Qty	Unit Price Disc% Amount
E PNT88000					1650.00
TO REPAIR REAR BUMPER, REAR RH FENDER					840
E PNT98000					1200.00
PAINT WORK SPRAY REAR BUMPER, REAR RH FENDER					20
A 54900099					50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					200.00
A 10028901					
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					
A WHEELALIGNMENTBP					120.00
To Conduct Computerize Full Wheel Alignment					30
M SUNDRY					60.00
TO TRANSFER REAR RH TYRE TO NEW RIM AND BALANCING					800
M SUNDRY					480.00
TO SUPPLY SSW021 RIM REAR RH					40
M SUNDRY					80.00
TO APPLY ANTI COROSSION ON AFFECTED PORTION					20
M SUNDRY					50.00
SUNDRIES					


SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Rasul-Hp 90010018



15/03/15 @ 1145

3-4 days

Ready after repair

Confirm &amp; accepted by

Nett 3,950.00  
7% GST on 3950.00 276.50  
Total Payable 4,226.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.