

ASS. REC. BY:

REF: CS/C7L18004787 / Uqbn2 Special Instruction:

Supervisor:

ASSIGNMENT (Office) ✓

From (Person): Chung Boon Sen of C7L Date/Time: 13032018 1:19pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 5802A Insured: SJR 8441U

at Workshop m/s Hock Wah Tel: 6441 5655

of Blk 301 Bedok Ind Park E #01-2008

Policy No: DMPCSN3050521700 Claim No: SNM18DD1311C02.

Sum Insured: Excess:

Make of Veh: D.O.A. 11-03-2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 13032018 3:41pm Person Contacted: Markis Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGT 5802A - CC6 / ALG17019656 / Uua3g2
	SJR 8441U - x



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004787/Uqb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 8441U	Veh. Inspected	SGG 5802A
Policy No.	DMPCSN3050521700	Coverage (\$)	0.00
Claim No.	SNM18D01311C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/03/2018	Inspection Date
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2018		13 Mar 2018 13:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS
[Created by insurer]

Insured:	NORADILAH BINTE ANDUL KARIM		
Main Claimant:	M & N SERVICES, Co. Reg. No.: 53349777M		
Vehicle Reg. No.:	SGG5802A	Date of Loss:	11/03/2018 18:00 - :59
Claim Type:	TP / SNM18D01311C02	Policy/Cover Note No.:	DMPCSN3050521700
Vehicle Reg. No. (Insured):	SJR8441U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2018]		
Adj Asg. Remarks:	DEAR MARCUS, PLEASE CONDUCT THIRD PARTY SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 9777M

Vehicle Details

Vehicle No.: SGG5802A

Vehicle to be Exported: Yes

Intended De-registration Date: 20 Mar 2018

Vehicle Make: TOYOTA

Vehicle Model: WISH 1.8 A

Primary Colour: Blue

Manufacturing Year: 2006

Engine No.: 1ZZ2551620

Chassis No.: ZNE100303094

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$23,035.00

Original Registration Date: 17 May 2006

First Registration Date: 17 May 2006

Transfer Count: 5

Actual ARF Paid: \$25,339.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 May 2021

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$23,024.00

COE Rebate Amount: \$14,524.00

Total Rebate Amount: \$14,524.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Mar 2018

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53349777M
M&N SERVICES
NO

SINGAPORE
TEL: FAX:
PH: 96431797
ATTN:

*Not found
2/5 # 2550/c
4-8 27
the photo attached
20/3/18*

ESTIMATE BILL

Number : EB00004766
Date : 13/3/2018
Case No : AD00009609
Vehicle No : SGG5802A
Chassis : ZNE100303094
Year of Mfr : 2006
Policy No : 5085875668
Model : TOYOTA WISH 1.8 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR BOOTLID <i>So 500</i>	1.0	987.80	25	740.85
2	REAR BOOTLID EMBLEM LOGO <i>Rec</i>	1.0	77.36	25	58.02
3	REAR BOOTLID CHROME <i>11</i>	1.0	241.31	25	180.98
4	REAR LAMP LH <i>11</i>	1.0	489.20	25	366.90
5	REAR LAMP RH <i>11</i>	1.0	489.20	25	366.90
6	REAR END PANEL <i>2</i>	1.0	886.76	25	665.07
7	REAR END PANEL TOP GARNISH <i>11</i>	1.0	192.31	25	144.23
8	REAR BUMPER <i>D.S</i>	1.0	678.90	25	509.18
9	REAR BUMPER SIDE RETAINER LH <i>Ref</i>	1.0	75.12	25	56.34
10	REAR BUMPER SIDE RETAINER RH <i>Ref</i>	1.0	75.12	25	56.34
11	REAR BUMPER BRACKET LH <i>11</i>	1.0	95.80	25	71.85
12	REAR BUMPER BRACKET RH <i>11</i>	1.0	95.80	25	71.85
List Price - Parts Sub Total					3,288.51
13	REAR NUMBER PLATE <i>Ref</i>	1.0	30.00	0	30.00
14	REAR NUMBER PLATE HOLDER <i>Ref</i>	1.0	30.00	0	30.00
15	REAR BUMPER REVERSE SENSOR <i>Ref</i>	1.0	280.00	0	280.00
16	REAR BUMPER REVERSE SENSOR <i>Ref</i>	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					620.00
Parts Total					3,908.51
17	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
18	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
19	ANTI-RUST COATING	1.0	250.00	0	250.00
20	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
21	WIRING	1.0	80.00	0	80.00
Labour 1 Sub Total					2,680.00
SINGAPORE DOLLARS - SEVEN THOUSAND FORTY-NINE AND CENTS					0.00
SEVENTY-ONE ONLY					0.00
Less Excess					0.00
SUBTOTAL					6,588.51
GST 7.00%					461.20
TOTAL					7,049.71

Date of accident : 11/03/2018 06:15 PM. Place : ALONG PIE TOWARDS TPE(SLE)

E. & O. E.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18004787/UQBN2

Date: 16/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3050521700
Claimant Vehicle No :	SGG5802A	Insured Vehicle No :	SJR8441U
Date of Loss:	11/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01311C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG5802A	Engine No:	1ZZ2551620
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100303094
Reg. Date:	17/05/2006 (Man. Year: 2006)	Odometer:	188579 km
Colour:	Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,908.51	1,660.72	2,247.79	57.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,530.00	1,150.00	42.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,588.51	3,190.72	3,397.79	51.57
Approved Total (Overridden) (\$\$)		2,550.00		
(\$\$)	6,588.51	2,550.00	4,038.51	61.30
+ GST 7.00/7.00% (\$\$)	461.20	178.50	282.70	61.30
Nett Amount (\$\$)	7,049.71	2,728.50	4,321.21	61.30

INSPECTION

Date of Assignment:	13/03/2018	
Date Inspected:	20/03/2018 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGG5802A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Badly Dented	987.80 FL	*987.80 FL
2	1		*REAR BOOTLID EMBLEM LOGO	Necessary	77.36 FL	*77.36 FL
3	1		*REAR BOOTLID CHROME	Not Necessary	241.31 FL	*- FL
4	1		*REAR LAMP LH	Not Necessary	489.20 FL	*- FL
5	1		*REAR LAMP RH	Not Necessary	489.20 FL	*- FL
6	1		*REAR END PANEL	Repair	886.76 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	192.31 FL	*- FL
8	1		*REAR BUMPER	Distorted	678.90 FL	*678.90 FL
9	1		*REAR BUMPER SIDE RETAINER LH	Bent	75.12 FL	*75.12 FL
10	1		*REAR BUMPER SIDE RETAINER RH	Bent	75.12 FL	*75.12 FL
11	1		*REAR BUMPER BRACKET LH	Not Necessary	95.80 FL	*- FL
12	1		*REAR BUMPER BRACKET RH	Not Necessary	95.80 FL	*- FL
13	1		*REAR NUMBER PLATE }	Bent	30.00 FS	*40.00 FS
14	1		*REAR NUMBER PLATE HOLDER }	Bent	30.00 FS	*- FS
15	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	1		*REAR BUMPER REVERSE SENSOR	Repeated	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,004.68	2,134.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,096.17	473.58
Total Parts (\$\$)	3,908.51	1,660.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,200.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	800.00
3	ANTI-RUST COATING	New	250.00	60.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
5	WIRING	New	80.00	20.00
Gross Labour Cost (S\$)			2,680.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >