

10
IS CASE OWNER:

CC6, A1618004792, Aka39

LKK:
IDAC:

Surveyor:

ADRIAN

DOI:

12/13/18

Date / Time:

12/13/18

Registered in Merimen:

12/13/18

Pre-assign / CCU / FTE

STY 7088 B



Insured Vehicle No.:

Name of Insured:

SHEA CHRISTOPHER DAVID MICHAEL

Insured Tel No.:

HP:

83285330

Excess Sec II :SS

D.O.A.:

12/05/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

22X663188856

Policy No.:

2100373600

Make / Model:

Jaguar XF

Place of Accident:

Sector of Shiboo St & Havelock Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKX 3712C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Leang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

15/12

24:00

SKX 3712C 116/142/77345 Tel: 116/142/77345
116/142/77345 / 116/142/77345 ; 116/142/77345
116/142/77345 / 116/142/77345 ; 116/142/77345

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 03 JUL 2018

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

6,200

VIDEO

Loss of Rental (LOR):

S\$

500

(\$100 x 5 days)

Loss of Use (LOU):

S\$

500

(\$100 x 5 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

S\$

745

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow / Independent)

Legal Cost:

S\$

-

Total:

S\$

6,707.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6,707.45

Name 1:

LEANG AUTOMOTIVE

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

COPY SENT
3/1/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18004792/Aka3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 13-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 7088B	Veh. Inspected	SKX 3712C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/03/2018	Inspection Date	12/03/2018	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TPAIG
Zaini

SKX3712C

Date

No.

Taylor Vixy
ZWR800145760

£

Front Bumper Deformed	1892.70 ✓ 1580
Front Bumper Clips m	50.30
Front Bumper Side Holder x 02 LH Rdyd	92.5 x 2 = 185 92.50
Front Bumper Sponge Not New	142.30 X
Front Bumper Reinforcement Not New	488.90 X
Front Bumper Fog Lamp LH cracked.	487.90 ✓ 365
Front Bumper Fog Lamp Cover LH behind	92.90 ✓
Front Bumper Lower Grille Deformed	97.80 ✓
Front Grille	597.90 X
Front Grille Logo.	576.80 X
Front Grille Clips	10 X
Headlamp LH cracked	2893.90 ✓
Headlamp Panel LH Best	327.40 ✓
Front LH Fender Dented	558.90 ✓
Front LH Fender Bracket Best	78.90 ✓
Front LH Fender Inner Shield	279.80 X
Front LH Fender Inner Shield clips	30 X
Front LH Wheel Rebr. At	880 (SW) 500 (SW)
Front LH Tyre Not New	320 (SW) X
Front LH Lower Arm Best	579.80 ✓
Front LH Knuckle Arm Best	448.90 ✓
Front LH Lower Arm Shock Absorber Best	598.90 ✓
Front LH Wheel Hub clw Bearing. Rdyd	197.90 ✓
Steering Rack and Pinion Not New	3709.80 X

7942.80
5957.10

S-N: 500





Auto
Consultants
Pte Ltd

51 UBI AVE, L, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG/8004792/Aka3

19 MARCH 2018

SHEA CHRISTOPHER DAVID MICHAEL
9 EBER GARDENS
SINGAPORE 239760

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 7088B AND SKX 3712C ON 12.03.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,



Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Date:

12/03/2018

To: M/s Leang Automotive
No. 1 Kaki Bukit Avenue 6
#01-68
Singapore 417883

LETTER OF AUTHORITY & INDEMNITY

I/We CASSIA VALET SERVICES NRIC No/ Co Registration No. S3324641A of (address) BLK 298A COMPASSVALE Street #06-076 (S) 541298 the registered owner (or his/her/their/agent) of motor vehicle registration no. 8KX3712C hereby authorise M/s Leang Automotive ("the Repairer") to commence repairs to my/our vehicle and to forward the claim for inter alia the costs of repairs to the owner/insured of the Third Party responsible for the said accident on (date) 12-3-2018 involving motor vehicle nos SJY 7088B along Sailor St Towards Haylock Road. I further authorise M/s Leang Automotive to sign and execute all documents in my name including but not limited to the Discharge Voucher in connection with the claim against the Third Party

However, if the third party rejects liability for whatever reasons and/or if the claim is reverted to my/our insurers and my/our insurers do not settle the repair costs and disbursements under my/our own insurance policy, I/we will be fully responsible for the repair costs and disbursements.

I also agree that if I do not fully co-operate in the Third Party claim, I will be responsible for any losses incurred by my Repairer.

My/our vehicle is repaired by the Repairer on my/our own free will and without any threat, inducement and/or promise.

In the event that the Repairer is compelled to enforce this undertaking, I/we agree that I/we shall pay for the legal costs incurred by the Repairer on a solicitor and client full indemnity basis.


Signature/ Co. Stamp



RELEASE VOUCHER**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, LEANG AUTOMOTIVE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,200.00 (Repair Cost), 500.00 (Loss of Use) S\$7.45 (Disbursement) for vehicle no. SKX 3712C that was damaged pursuant to the accident which occurred on 12/03/2018 (date) along SAIBOO ST. TOWARDS HAVELOCK ROAD (location) involving vehicle no/s SJY 7088B. This is pursuant to the inspection conducted on 12/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CASSIA VALET SERVICES ("the third party claimant") of vehicle no. SKX 3712C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKX 3712C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3 (day) of 7 (month) 2018 (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

LEANG AUTOMOTIVE

No. 1134

Auto Bay @ Kaki Bukit 1 Kaki Bukit Ave 6 #01-68 Singapore 417883
Tel: 6909 3048 Fax: 6909 3046

M/s AIIG ASIA PACIFIC INSURANCE P/L

Vehicle No: SKX3712C

Vehicle Model: VOXY HYBRID

Date: 11-4-2018

[illegible]

Authorised Signature

[illegible]

12-03-2018 10:37 FROM- Arasan Law Chambers

RECEIVED 19/03/2015 01:15
68353352

T-477 P0001/0002 F-419

Enquire Vehicle & Owner Information (Vehicle No, SJY7088B As At 12 Mar 2018 / 08:48:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No: .

Current Owner Details

Owner ID Type: Foreign Identification Number

Owner ID: G5977127U

Owner Name: SHEA CHRISTOPHER DAVID MICHAEL

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No: 113

Registered Street Name: ARTHUR ROAD

Registered Unit No: -

Registered Building Name: -

Registered Postal Code: 439824

Current Vehicle Details

Vehicle No: SJY7088B

Make Description/Model: JAGUAR /XF 3.0 V6 PREMIUM LUXURY AT ABS D/AB HID

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Irs Auth'd	Status
Main	13 Mar 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	\$56,200.00 Edit Estimates	\$56,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured: **SHEA CHRISTOPHER DAVID MICHAEL**, ID: G5977127U

Main Claimant: **CASSIA VALET SERVICES**, Co. Reg. No.: 53224641A

Vehicle Reg. No.: SKX3712C	Date of Loss: 12/03/2018 08:00 - :59 [27 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / 2256631888SG	Policy/Cover Note No.: 2100373600
Vehicle Reg. No. (Insured): SJY7088B	Policy No. (Claimant): 5076232253-02
Excess:	

Repairer: **Leang Automotive - Kaki Bukit (HQ)** AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000 ... [Handled by **Lee, Ming-Yao**] MingYao.Lee@aig.com

Claimant's Insurer: **NTUC Income Insurance Co-operative Ltd (HQ)** - Tel:

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 22/03/2018]**

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX3712C (2256631888SG)
[SJY7088B]

TP



















































CASSIA VALET SERVICES

Mar 12 2018 8:00AM



[SHEA CHRISTOPHER DAVID MICHAEL]

Leang Automotive - Kaki Bukit

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports				
			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/03/18 11:01	Accident Statement <small>From: SC - Reg. No: SJY7088B, Claimant: SHEA CHRISTOPHER DAVID MICHAEL</small>		Load HTM
Photos/Images				
			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/04/18 13:40	General View		Load JPG
2	11/04/18 13:40	Chassis Number		Load JPG
3	11/04/18 13:40	General View		Load JPG
4	11/04/18 13:40	General View		Load JPG
5	11/04/18 13:40	General View		Load JPG
6	11/04/18 13:40	General View		Load JPG
7	11/04/18 13:40	General View		Load JPG
8	11/04/18 13:40	General View		Load JPG
9	11/04/18 13:40	General View		Load JPG
10	11/04/18 13:40	General View		Load JPG
11	11/04/18 13:40	General View		Load JPG
12	11/04/18 13:40	General View		Load JPG
13	11/04/18 13:40	General View		Load JPG
14	11/04/18 13:40	General View		Load JPG
15	11/04/18 13:40	General View		Load JPG
16	11/04/18 13:40	General View		Load JPG
17	11/04/18 13:40	General View		Load JPG
18	11/04/18 13:40	General View		Load JPG
19	11/04/18 13:40	General View		Load JPG
20	11/04/18 13:40	General View		Load JPG
21	11/04/18 13:40	General View		Load JPG
22	11/04/18 13:40	General View		Load JPG
23	11/04/18 13:40	General View		Load JPG
24	11/04/18 13:41	Reinspection Photo		Load JPG
25	11/04/18 13:41	Reinspection Photo		Load JPG
26	11/04/18 13:41	Reinspection Photo		Load JPG
27	11/04/18 13:41	Reinspection Photo		Load JPG
28	11/04/18 13:41	Reinspection Photo		Load JPG
29	11/04/18 13:41	Reinspection Photo		Load JPG
30	11/04/18 13:41	Reinspection Photo		Load JPG

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	11/04/18 13:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 10:45	TP GIA REPORT	 Load PDF	
2	05/07/18 09:40	WORKSHOP INVOICE	 Load PDF	
3	05/07/18 09:40	AUTHORISATION TO ACT FORM	 Load PDF	
4	05/07/18 09:40	Release Voucher	 Load PDF	
5	05/07/18 09:40	LTA SEARCH	 Load PDF	
6	05/07/18 09:40	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY7088B (Insd veh)	Model:	TOYOTA VOXY HYBRID V 1.8
	SKX3712C (TP veh)		(A)
Date of Accident:	12/03/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	17,806.40	
Final Repair Cost	:	\$	6,200.00	
Loss of Use	:	\$	500.00	5.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.45	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	6,707.45	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)	
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability ____ 100 ____ (%)
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Leang Automotive	:	\$ 6,707.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Jul
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18004792/AJA3Q2

Date: 05/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100373600
Claimant Vehicle No : SKX3712C **Insured Vehicle No :** SJY7088B
 Date of Loss: 12/03/2018 Nature of Claim: TP Claim No: 2256631888SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX3712C**
 Make & Model: TOYOTA VOXY HYBRID V, 1.8 (A) Engine No: 2ZR6548442
 Reg. Date: 08/12/2015 (Man. Year: 2015) Chassis No: ZWR800145760
 Colour: White Odometer: 182904 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,506.40	6,457.10	9,049.30	58.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,330.00	970.00	42.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,806.40	7,787.10	10,019.30	56.27
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	17,806.40	6,200.00	11,606.40	65.18
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,707.45		

INSPECTION

Date of Assignment: 12/03/2018
 Date Inspected: 12/03/2018 Inspected At: Leang Automotive - Kaki Bukit (HQ)
 AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT
 AVE 6 #01-68
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,892.70 F	*1,580.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER	N/S Damaged	185.00 F	*92.50 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	142.30 F	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	488.90 F	*- FL
6	1		*FRONT BUMPER FOG LAMP LH	Cracked	487.90 F	*365.00 FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Deformed	92.90 F	*92.90 FL
8	1		*FRONT BUMPER LOWER GRILLE	Deformed	97.80 F	*97.80 FL
9	1		*FRONT GRILLE	Not Necessary	597.90 F	*- FL
10	1		*FRONT GRILLE LOGO	Not Necessary	576.80 F	*- FL
11	1		*FRONT GRILLE CLIPS	Not Necessary	10.00 F	*- FL
12	1		*HEADLAMP LH	Cracked	2,893.90 F	*2,893.90 FL
13	1		*HEADLAMP PANEL LH	Bent	327.40 F	*327.40 FL
14	1		*FRONT LH FENDER	Dented	558.90 F	*558.90 FL
15	1		*FRONT LH FENDER BRACKET	Bent	78.90 F	*78.90 FL
16	1		*FRONT LH FENDER INNER SHIELD	Not Necessary	279.80 F	*- FL
17	1		*FRONT LH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 F	*- FL
18	1		*FRONT LH WHEEL RIM	Cut	880.00 FS	*500.00 FS
19	1		*FRONT LH TYRE	Not Necessary	300.00 FS	*- FS
20	1		*FRONT LH LOWER ARM	Bent	579.80 F	*579.80 FL
21	1		*FRONT LH KNUCKLE ARM	Bent	448.90 F	*448.90 FL
22	1		*FRONT LH SHOCK ABSORBER	Bent	598.90 F	*598.90 FL
23	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	197.90 F	*197.90 FL
24	1		*STEERING RACK AND PINION	Not Necessary	3,709.80 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,506.40	8,442.80
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,985.70
Total Parts (S\$)	15,506.40	6,457.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE FRONT UNDERCARRIAGE	New	350.00	220.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$\$)			2,300.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >