

Co Peg No : 1977014696

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
MR NORRUDIN BIN JALALUDDIN	Cust No/Name	/MR NORRUDIN BIN JALALUDI		
PIK NORRODIN BIN SALALODDIN	Reg No/Reg Date	SGE2094G / 31/03/201		
BLK 701 CHOA CHU KANG ST 53	Date In/Mileage	/ 0		
#02-18 SINGAPORE 680701	Chassis No	MMBSTA13AHH004301		
	Engine No	3A92UDS0355		
Contact No Mobile: 92707305	Make/Model	MIT/17MY ATTRAGE 1.2 CVT		
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK		

Account No Terms Date/1	ime Printed CSE	Operator		WIP No		
CSM00041 Cash 09/03	/2018/ 13:52 TLC	442 / CocoLu		22575		
Desc	ription of Goods / Serv	rices	Qty U	Init Price	Disc%	Amount
E PNT88000 TO RENEW FRT FENDER RH, SIDE SILL RH E PNT98000 TO SPRAY PAINT FOR FRT SIDE SILL RH E PNT88000 TO REMOVE & INSTALL DOO B WHEELALIGNMENT TO CONDUCT COMPUTERIZE M SUNDRY TO TRANSFER NEW RIM TO A 54900099 TO CHECK WIRING & ELECT A 54900099 TO CONDUCT DIAGNOSTIC CO A 54900099 TO RENEW FRT UNDER CARR M SUNDRY Sundry M FENDER, FR RH M SHIELD, FR WHEELHOUSE, RH M PANEL ASSY, FR DOOR, RH M TAPE, FR DOOR SASH, RH M GARNISH, FR PILLAR, RH M WHEEL, DISC M HUB ASSY, FR WHEEL M SNAP RING, FR WHEEL HUB M BEARING, FR WHEEL HUB	BUMPER, FRT FENDER F R TRIMS AND GLASS TO Full Wheel Alignment TYRE RICAL SYSTEM HECK FOR THE CAR SYSTAGE	Taylin 974957	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	939.00 28.00 28.00 743.00 203.00 8.00 119.00	00.00 00.00 00.00 00.00 00.00 00.00 00.00	1/60 1650.00 1/260 2100.00 240 300.00 120.00 200.00 200.00 200.00 20.00 458.00 97.00 458.00 97.00 4458.00 743.00 743.00 743.00 78.00 719.00
Conf rm Wackepted by tanto no the Repar • To res • To de. • Parts; • Third parts and. • No illegrance			7% GST on	Net 7613.0 al Payabl	00	7,613.00 532.93 8,145.93

Validaty of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has estarted and needed for repairs or rep acement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.