



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS ADAMDAM  471B FERVALE STREET 03-103 FERVALE RIVERGROVE SINGAPORE 792471  Contact No Mobile: 81898208 22/02/	Cust No/Name	/MS ADAMDAM
	Reg No/Reg Date	SLC9724C / 31/05/201
	Date In/Mileage	22/02/2018/ 41956
	Chassis No	KNAFZ411MG5580435
	Engine No	G4FGFH609750
	Make/Model	KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim	D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/03/2018/ 13:34	TLT	465 / Tay Jian Ye	23458			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR REAR BUMPER								550.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER								420.00
E PNT88000 TO RENEW FRT BUMPER , HOOD, (FRT SUPPORT PANEL ?????CHECK????)								1100.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER , HOOD,								840.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								20.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								200.00
M SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION								60.00
M SUNDRY SUNDRIES								20.00
X BRACKET-FR BUMPER SIDE MTG,LH					1.00	12.00	00.00	12.00
X BRACKET-FR BUMPER SIDE MTG,RH					1.00	12.00	00.00	12.00
X ABSORBER-FRONT BUMPER ENERGY					1.00	97.00	00.00	97.00
X COVER-FR BUMPER					1.00	728.00	00.00	728.00
X GRILLE ASSY-RADIATOR					1.00	322.00	00.00	322.00
X LAMP ASSY-HEAD,LH					1.00	1870.00	00.00	1870.00
X LAMP ASSY-HEAD,RH					1.00	1870.00	00.00	1870.00
X PANEL ASSY-HOOD					1.00	1408.00	00.00	1408.00
X LOGO ASSY-KIA SUB					1.00	51.00	00.00	51.00

Confirm & accepted by

	Nett	9,580.00
7% GST on	9580.00	670.60
Total Payable		10,250.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**MITSUBISHI**  
**MOTORS**

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MR NORRUDIN BIN JALALUDDIN  BLK 701 CHOA CHU KANG ST 53 #02-18 SINGAPORE 680701  <b>Contact No Mobile: 92707305</b>	Cust No/Name	/MR NORRUDIN BIN JALALUDDIN
	Reg No/Reg Date	SGE2094G / 31/03/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH004301
	Engine No	3A92UDS0355
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	09/03/2018/ 13:52	TLC	442 / CocoLu	22575			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 TO RENEW FRT FENDER RH, FRT DOOR RH, REPAIR FRT BUMPER, SIDE SILL RH								1650.00
E PNT98000 TO SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, FRT DOOR RH SIDE SILL RH								2100.00
E PNT88000 TO REMOVE & INSTALL DOOR TRIMS AND GLASS TO FACILITATE REPAIR								300.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY TO TRANSFER NEW RIM TO TYRE								30.00
A 54900099 TO CHECK WIRING & ELECTRICAL SYSTEM								20.00
A 54900099 TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								200.00
A 54900099 TO RENEW FRT UNDER CARRIAGE								550.00
M SUNDRY Sundry								20.00
M	FENDER,FR RH				1.00	458.00	00.00	458.00
M	SHIELD,FR WHEELHOUSE,RH				1.00	97.00	00.00	97.00
M	PANEL ASSY,FR DOOR,RH				1.00	939.00	00.00	939.00
M	TAPE,FR DOOR SASH,RH				1.00	28.00	00.00	28.00
M	GARNISH,FR PILLAR,RH				1.00	28.00	00.00	28.00
M	WHEEL,DISC				1.00	743.00	00.00	743.00
M	HUB ASSY,FR WHEEL				1.00	203.00	00.00	203.00
M	SNAP RING,FR WHEEL HUB				1.00	8.00	00.00	8.00
M	BEARING,FR WHEEL HUB				1.00	119.00	00.00	119.00

Confirm &amp; accepted by

	Nett	7,613.00
7% GST on	7613.00	532.91
<b>Total Payable</b>		<b>8,145.91</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.