ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N GST Reg. No.: 201113667N.

Vehicle Insured : SFK1113Y Accident Date : 10-Mar-2018 No.: 05749

Date: 13-Mar-2018

Our Ref : 218052 (AUTO & GEN) / CHAN

PAGE: 1

KOH LENG NGUANG 7 BRIGHT HILL DRIVE #07-02 Singapore 579599

Not Northands

ESTIMATED COST OF REPAIR FOR M/BENZ E200 CGI SBX900C

```
Rear bumper fascia
                                                              By 1,764.00 —
   1 pc Rear bumper lower spoiler
   3 pcs Rear bumper lower bracket
                                                 @ S$ 17.00 CM 51.00 -
  1 pc Rear bumper reinforcement
2 pcs Rear bumper reinforcement
1 pc Rear bumper parking sensor Shor @ S$297.00
1 pc Rear parking sensor wire
1 pc Rear bumper centre moulding
2 pcs Rear bumper side moulding @ S$141.00
                                                                写 869.00 —
                                                                1,188.00 47
suc 169.00
                                                               Del 189.00
                                                 @ S$141.00 Ma 282.00
  2 pcs Rear bumper side retainer Msag @ S$ 40.00
                                                                     80.00 LT
                                                              R 2,983.00 X
    pc Boot lid
    рс
         Boot lid "E200" emblem
                                                                na 82.00
         Boot lid "CGI" emblem
    pc
                                                                Ma 82.00
         Rear end panel
    pc
                                                              31,352.00 -
138.00 7
  1 pc
        Rear end panel top garnish
  1 pc
                                                           M CAA 387.00 w
        Rear spare tyre panel
 1 pc Rear exhaust silencer box
                                                             2, 148.00 7th
  1 pc
         Rear exhaust chrome pipe
                                                                  227.00
 2 pcs Taillamp
                                                @ S$715.00 1,430.00
                      MI TURY Olson
 1 pc Rear n/s under cover
                                                             · CM 488.00
                                        Mg cm @ $1268.00
 2 pcs Headlamp
1 pc Front bumper fascia
1 pc Front bumper sponge
2 pcs Front bumper side sponge
1 pc Front bumper tow cover
2 pcs Front bumper lower chrome
1 pc Front bumper no plate garnie
                                                               2,536.00
                                                                               T
                                                            Bur 1,585.00
                                                             CM 117.00 2
                                               @ S$ 58.00 fm 116.00
                                                                    86.00
                                                @ S$ 91.00 Na 182.00 L
        Front bumper no.plate garnish
                                                              DU 196.00
 2 pcs Front bumper inner parts(side) @ S$ 75.00 f 150.00 \not 	imes
 1 pc Front bumper inner parts(ctr)
                                                                    79.00
```

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...