

ASS. REC. BY:

REF: CS/FCI/18004799/Ktd3/12

Special Instruction:

Surveyor:

CWS

From (Person):

May chuan

of

FCI

Date/Time:

13/3/18 @ 4:34pm

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV CS

To Inspect Vehicle No:

SJX 541K

Insured:

SHC 1070E

at Workshop m/s

K Kim Hin Auto

Tel:

64527018

of

160 Sin Ming Drive #02-20

Policy No:

Claim No:

D18001649MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/2/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

4:48pm @ 13/3/18

Person Contacted:

shumem

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJX 541K -x

SHC 1070E - CS/FCI 1800 3892 / M/tb

D.O.A: 23/2/18

23/3-9:12am revert email preli 1

19/6 82033.76 Cashmere (Red: 816.64; 23%)

REF: FCL

## ASSIGNMENT

From: Date: 21-03-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJX 541K

at Workshop m/s: K Kim Hin

of 160 9m Ming Drive #02-18

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

22/3 File pass to Catherine

Veh No: PTX 541K Yr Regn: 05 10

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante C.C. 1591

Colour: M. Brown A/C: Insured / Std / NI / NA

Sp. Reading: 86276 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM1HD41BMA4992683

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Ydco 185/65R15

R: Kenda

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / Yokohama or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 23/2/18

Survey held at

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 21/3/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

UPC

RECEIVED 2:0 JUN 2018

Date/Time. File Pass to?



Preli. Report

1) Jdb Typist



Final Report

Date/Time. File Return to?

2)

Days Of Repair: 4 2

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 2033.76

110

50

50+50

19

279



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004799/Ktd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-03-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SHC 1070E      | Veh. Inspected | SJX 541K   |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | D18001649MFSH  | Excess (\$)    | 0.00       |
| Assign From  | CWS (MAY CHUA) | Assign Date    | 14/03/2018 |

## 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

## 5. General Information

|                |                              |                 |  |
|----------------|------------------------------|-----------------|--|
| Accident Date  | 23/02/2018                   | Inspection Date |  |
| Survey held at | 160 SIN MING DRIVE #02-20    |                 |  |
| Repairer       | K KIM HIN AUTOMOTIVE PTE LTD |                 |  |

## 5a. Remarks

|                                                                                                                                        |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--|



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001649MFSH

Date: 23/3/2018

Our Ref: CS/FCI18004799/Ktd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SJX 541K.**

Please be informed that we had conducted the inspection of the abovementioned vehicle 21/3/2018 at the premises of M/s K Kim Him Auto and have the following to report: -

|                          |                         |
|--------------------------|-------------------------|
| Workshop Estimate Amount | : S\$ <u>2,850.40</u>   |
| Revised Estimate Amount  | : S\$ <u>1,941.84</u>   |
| "Check" Items Amount     | : S\$ <u>485.12</u>     |
| Market Value             | : S\$ <u>-</u>          |
| LTA Reimbursement Value  | : S\$ <u>          </u> |
| Nett Value               | : S\$ <u>          </u> |

**Description of Damage:**

The vehicle sustained damages  
at the rear n/s.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Kenneth  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                             |                              |
|--------------------|-------------------------------------------------------------|------------------------------|
| Date               | 26-02-2018                                                  | Our Ref No. D18001649MFSH    |
| Accident Date      | 23-02-2018                                                  | Claim Type. Third Party      |
| Insured Vehicle    | SHC1070E                                                    | Third Party Vehicle. SJX541K |
| Survey Location    | 160 Sin Ming Drive #02-20SIN MING AUTOCITY                  |                              |
| Contact Person.    | SHUMAN                                                      |                              |
| Contact No.        | 64527018/ 96222116                                          | Fax No. 64583895             |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                              |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                              |
| Contact Person     | NA                                                          | Fax No. 68416315             |
| Contact Number.    | NA                                                          |                              |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                         |                         |
|-------------------|-------------------------|-------------------------|
| Cc : Workshop     | K. KIM HIN AUTO PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                      | TP Solicitor Fax No. NA |
| Officer Incharge  | MAY CHUA                |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235360)



PRI Documents



Close



## PRI Header Details

|                   |                                                      |                                   |                                                                                                                                    |                      |               |
|-------------------|------------------------------------------------------|-----------------------------------|------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------|
| Claim No          | D18001649MFSH                                        | Policy No                         | D-18088936MFSH                                                                                                                     | Claimant S.No & Name | 1 & K. KIM HI |
| Workshop Name     | K. KIM HIN AUTO PTE LTD<br>(Contact Person : SHUMAN) | Survey Location & Contact Details | 160 Sin Ming Drive #02-20SIN MING AUTOCITY<br>Mobile: 96222116 , Phone: 64527018 , Fax: 6458389!<br>EmailId: ADMIN1@KKIMHIN.COM.SG |                      |               |
| Our Surveyor      | LKK AUTO CONSULTANTS PTE LTD                         | Instructions To Surveyor          | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM                                                                                      |                      |               |
| Insured Name      | COMFORT TRANSPORTATION PTE LTD                       | Insured Vehicle No                | SHC1070E                                                                                                                           | TP Vehicle No        | SJX541K       |
| PRI Recieved Date | 13-03-2018 03:11:25 PM                               | Surveyor Appointed Date           | 13-03-2018 04:33:36 PM                                                                                                             | Surveyor Accept Date | 13-03-2018 0  |

## Survey Report Upload

|                             |  |                      |            |                         |                                            |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|
| Surveyor Inspection Date *: |  | Surveyor Report Date | 13-03-2018 | Upload Survey Report *: | <input type="button" value="Choose File"/> |
|-----------------------------|--|----------------------|------------|-------------------------|--------------------------------------------|

## Vehicle Particulars

|           |                                                 |                |                                                  |         |                                          |
|-----------|-------------------------------------------------|----------------|--------------------------------------------------|---------|------------------------------------------|
| Make      | <input type="text" value="Please Select Make"/> | Model          | <input type="text" value="Please Select Model"/> | Year    | <input type="text" value="Select Year"/> |
| Chasis No | <input type="text"/>                            | Engine No      | <input type="text"/>                             | Mileage | <input type="text"/>                     |
| Color     | <input type="text"/>                            | Cubic Capacity | <input type="text"/>                             |         |                                          |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Friday, 23 March 2018 9:12 AM  
**To:** Admin-D (LKKAUTO); 'Claim Workflow System'; assignments  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18001649MFSH/1  
**Attachments:** PRELI ADVISED SJX 541K.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJX 541K**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 13 March 2018 4:50 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18001649MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 13 March 2018 4:33 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001649MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team

## Enquire PARF/COE Rebate for Registered Vehicle

|                                          |                                |
|------------------------------------------|--------------------------------|
| Vehicle Owner Particulars                |                                |
| Owner ID Type:                           | Singapore NRIC                 |
| Owner ID:                                | 2937H                          |
| Vehicle Details                          |                                |
| Vehicle No.:                             | SJX541K                        |
| Vehicle to be Exported:                  | No                             |
| Intended De-registration Date:           | 16 Mar 2018                    |
| Vehicle Make:                            | HYUNDAI                        |
| Vehicle Model:                           | AVANTE 1.6 AT ABS D/AB 2WD 4DR |
| Primary Colour:                          | Red                            |
| Manufacturing Year:                      | 2010                           |
| Engine No.:                              | G4FCAU825552                   |
| Chassis No.:                             | KMH DU41BMAU992683             |
| Maximum Power Output:                    | 89.7 kW (120 bhp)              |
| Open Market Value:                       | \$11,282.00                    |
| Original Registration Date:              | 12 May 2010                    |
| First Registration Date:                 | 12 May 2010                    |
| Transfer Count:                          | 0                              |
| Actual ARF Paid:                         | \$11,282.00                    |
| OPC Cash Rebate Details                  |                                |
| OPC Cash Rebate Eligibility:             | No                             |
| OPC Cash Rebate Eligibility Expiry Date: | -                              |
| OPC Cash Rebate Amount:                  | -                              |
| Intended PARF Rebate Details             |                                |
| PARF Eligibility:                        | Yes                            |
| PARF Eligibility Expiry Date:            | 11 May 2020                    |
| PARF Rebate Amount:                      | \$6,769.00                     |
| Intended COE Rebate Details              |                                |
| COE Expiry Date:                         | 11 May 2020                    |
| COE Category:                            | A - Car (1600cc & below)       |
| COE Period(Years):                       | 10                             |
| QP Paid:                                 | \$9,102.00                     |

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

No. : 29626

Vehicle Insured : SHC 1070 E  
Accident Date : 23-Feb-2018

Date : 14-Mar-2018

Our Ref : 180148 (FIRST) / SHUMAN

PAGE : 1

MOHAMED RASHID BIN ABDUL KARIM (MR)  
Singapore

*Not Notified  
After 8? 82033-76  
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR HYUNDAI AVANTE 1.6 AT ABS (2010) SJX541K

|        |                                           |        |             |        |    |
|--------|-------------------------------------------|--------|-------------|--------|----|
| 1 pc   | n/s taillamp assy                         |        |             | 288.40 | X  |
| 1 pc   | n/s bootlid lamp                          |        |             | 163.60 | X  |
| 1 pc   | bootlid "AVANTE" emblem                   |        |             | 13.50  | —  |
| 1 pc   | bootlid logo                              |        |             | 23.30  | —  |
| 1 pc   | rear bumper                               |        |             | 489.10 | —  |
| 10 pcs | rear bumper clips                         |        |             | 20.00  | —  |
| 2 pcs  | rear bumper top bracket                   | MUM    | @ S\$ 24.00 | 48.00  | 2+ |
| 1 pc   | rear bumper reinforcement                 |        |             | 270.00 | ✓  |
| 2 pcs  | rear bumper reinforcement bracket (lh/rh) | lit An | @ S\$ 67.30 | 134.60 | X  |

1,450.50

Less 20% : -290.10

1,160.40

1 pc reverse sensor

Shan 220.00 20052 sn

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

550.00 4001

To focus taillamps. To check rear  
wiring and lighting operation.

50.00 201

To remove and refit rear upholstery  
trimming, roof lining, seats,  
speaker board in order to  
facilitate repairing works

m 120.00 X

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

Con't Page 2 ...



CO. REG. NO: 199402370D  
GST NO: M2-0123250-3

AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 1070 E  
Our Ref : 180148

Page : 2  
No. : 29626

To putty and respray on affected  
portions.

600/

|         |              |
|---------|--------------|
|         | 750.00       |
|         | -----        |
| Total : | S\$ 2,850.40 |
|         | =====        |
|         | 2938.40      |

Singapore Dollars Two Thousand Eight Hundred  
and Fifty and Cents Forty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

**K. Kim Hin**CO. REG. NO: 199402370D  
GST NO: M2-0123250-3**AUTO PTE LTD****金興(龔)汽車私人有限公司**160 Sin Ming Drive, #02-20,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sgVehicle Insured : SHC 1070 E  
Accident Date : 23-Feb-2018

Date : 21-Mar-2018

Our Ref : 180148 (AIG ASIA)

MR MOHAMED RASHID BIN ABDUL KARIM  
Singapore**SUPPLEMENTARY ESTIMATE FOR HYUNDAI AVANTE 1.6 SJX 541K**

1 pc Rear Bumper Inner Sponge

CMT \$ 110.00 ✓

|            |           |
|------------|-----------|
|            | \$ 110.00 |
| Less 20 %: | - 22.00   |
| Total:     | \$ 88.00  |

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                              |                             |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                              | Ref : CS/FCI18004799/Ktd3n2 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                              | Date : 21-06-2018           |  |  |
|                                                                                                                                                                                        |                              | Code : FCI2                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                              |                             |                                                                                     |  |
| Insured Veh.                                                                                                                                                                           | SHC 1070E                    | Veh. Inspected              | SJX 541K                                                                            |  |
| Policy No.                                                                                                                                                                             | D-18088936MFSH               | Coverage (\$)               | 0.00                                                                                |  |
| Claim No.                                                                                                                                                                              | D18001649MFSH                | Excess (\$)                 | 0.00                                                                                |  |
| Assign From                                                                                                                                                                            | MAY CHUA                     | Assign Date                 | 13/03/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                              |                             |                                                                                     |  |
| Make & Model                                                                                                                                                                           | HYUNDAI AVANTE (A)           | c.c                         | 1591                                                                                |  |
| Engine No.                                                                                                                                                                             | HIDDEN                       | Year of Reg.                | 2010                                                                                |  |
| Chassis No.                                                                                                                                                                            | KMH DU41BMAU992683           | Colour                      | METALLIC BROWN                                                                      |  |
| Odometer                                                                                                                                                                               | 86276                        | Steering                    | IN ORDER                                                                            |  |
| Brakes                                                                                                                                                                                 | IN ORDER                     | Modification                | STANDARD ALLOY RIM                                                                  |  |
| General                                                                                                                                                                                | GOOD                         |                             |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                              |                             |                                                                                     |  |
|                                                                                                                                                                                        | Size                         | Make                        | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                                                                         | 185/65 R15                   | YOKOHAMA                    | 7 mm                                                                                |  |
| L/H Front Tyre                                                                                                                                                                         | 185/65 R15                   | YOKOHAMA                    | 7 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                                                                          | 185/65 R15                   | KENDA                       | 9 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                                                                          | 185/65 R15                   | KENDA                       | 9 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                                                                       |                              |                             |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                         |                              |                             |                                                                                     |  |
| <b>5. General Information</b>                                                                                                                                                          |                              |                             |                                                                                     |  |
| Accident Date                                                                                                                                                                          | 23/02/2018                   | Inspection Date             | 21/03/2018                                                                          |  |
| Survey held at                                                                                                                                                                         | 160 SIN MING DRIVE #02-20    |                             |                                                                                     |  |
| Repairer                                                                                                                                                                               | K KIM HIN AUTOMOTIVE PTE LTD |                             |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                                                                     |                              |                             |                                                                                     |  |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                              |                             |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                              |                             |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                              | 4 Working Days              |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 541K

| Qty                                | Description of Parts                                                                                                                                            | Condition                           | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                                                                                                                                                 |                                     |                           |                   |
| 1                                  | N/S TAILLAMP ASSY                                                                                                                                               | SERVICEABLE                         | 288.40                    | -                 |
| 1                                  | N/S BOOTLID LAMP                                                                                                                                                | SERVICEABLE                         | 163.60                    | -                 |
| 1                                  | BOOTLID "AVANTE" EMBLEM                                                                                                                                         | NECESSARY                           | 13.50                     | 13.50             |
| 1                                  | BOOTLID LOGO                                                                                                                                                    | NECESSARY                           | 23.30                     | 23.30             |
| 1                                  | REAR BUMPER                                                                                                                                                     | CRACKED                             | 489.10                    | 489.10            |
| 10                                 | REAR BUMPER CLIPS @\$2.00                                                                                                                                       | NECESSARY                           | 20.00                     | 20.00             |
| 2                                  | REAR BUMPER TOP BRACKET @\$24.00                                                                                                                                | N/S CRACKED                         | 48.00                     | 24.00             |
| 1                                  | REAR BUMPER REINFORCEMENT                                                                                                                                       | CRACKED                             | 270.00                    | 270.00            |
| 2                                  | REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$67.30                                                                                                              | N/S BENT / O/S TO REPAIR SEE LABOUR | 134.60                    | 67.30             |
| 1                                  | REAR BUMPER INNER SPONGE (ADDITIONAL)                                                                                                                           | CRACKED                             | 110.00                    | 110.00            |
|                                    | LESS 20% DISCOUNT                                                                                                                                               |                                     | -312.10                   | -203.44           |
|                                    |                                                                                                                                                                 |                                     | 1,248.40                  | 813.76            |
| <b>SPECIAL NETT ITEMS</b>          |                                                                                                                                                                 |                                     |                           |                   |
| 1                                  | REVERSE SENSOR (SN)                                                                                                                                             | SHORTED                             | 220.00                    | 200.00            |
|                                    |                                                                                                                                                                 |                                     | 220.00                    | 200.00            |
| <b>LABOUR</b>                      |                                                                                                                                                                 |                                     |                           |                   |
|                                    | TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF O/S REAR BUMPER REINFORCEMENT BRACKET. |                                     | 550.00                    | 400.00            |
|                                    | TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION.                                                                                                 |                                     | 50.00                     | 20.00             |
|                                    | TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING,ROOF LINING,SEATS,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.                                            | NOT NECESSARY                       | 120.00                    | -                 |
|                                    | TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.                                                                                                                      |                                     | 750.00                    | 600.00            |
|                                    |                                                                                                                                                                 |                                     | 1,470.00                  | 1,020.00          |
| <b>GRAND TOTAL</b>                 |                                                                                                                                                                 |                                     | <b>2,938.40</b>           | <b>2,033.76</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                                                                                 |                                     |                           | <b>2,033.76</b>   |

Report Ref No. CS/FCI18004799/Ktd3n2



Report Ref No. CS/FCI18004799/Ktd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.