

ASS. REC. BY:

REF:

CS/MSG18004804/Uqbm2

Special Instruction:

SAV. FOR:

manus

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

15032018 843am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 2813Y

Insured:

SLH 3677T

at Workshop m/s

Jim Auto

Tel:

of

14 Defu Lane 10 #01-410 / 412

Policy No:

80443777 DMV

Claim No:

550084

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

12032018

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 2813Y - CC6 / AL714021045 / Kwms30
	SLH 3677T - X
19/3/18 @ 5.05pm	revised to Christina Wong via Meinmen.

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

5

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

L/Bal.

mm

D.O.A.

12/3/18

L/Bal.

mm

D.O.I.

12/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27952983 Dep 15k. Next Me.

huger 1912.45, huger lower 1873.75 sensor 300.38 Chrom 814.05
Exhaust cost price 8980workshop won p/p repair agree reduce 5% on total cost
confirmed Repair sum \$ 7700 with Jones.*Note new parts replacement.
(led \$ 9229.11, 56%)

✓ 11/4

Date/Time, File Pass to?



Preli. Report

1) 10/4/18



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

300

10

Photos

Others

TOTAL

310

Report Format:

MEP-7P

Lump Sum / I.B.I. (\$

7700