

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0309/2018/GW
Date	:	10-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tsai Shang Liang Lex
Address	:	23 Soo Chow Way Singapore 575321
Telephone	:	HP +65 97266708
Type of Claim	:	Own Damage Claijms
Policy No.	:	2100446158-08
Vehicle No	:	SJD 5485 L
Model Code	:	Audi A6 1.8 TFSI ULTRA S
Model / Year	:	Dec-15
Engine No	:	CYG 010295
Chassis No	:	WAUZZZ4G2GN102256
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	8-Mar-18
Place of Accident	:	Thomson rd at PIE exit- infront of 376 Thomson Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJD 5485 L.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy, with parking aid.	S/N \$ 480.00 ✓	
2	To remove and renew front bumper, radiator grille, bonnet, lhs headlight assy, reinstall all parts removed.	\$ 2,100.00 500	
3	To respray front bumper, bonnet.	\$ 1,800.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,572.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJD 5485 L.

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	\$ 2,425.00	X
2	FRONT BUMPER LOWER GRILLE <i>3 men</i>	\$ 574.00	X
3	FRONT BUMPER LOCKING CLIP	\$ 62.00	✓
4	FRONT BUMPER TRIM <i>3 men</i>	\$ 260.00	X
5	FRONT BUMPER FIXING PARTS	\$ 43.00	X
6	RADIATOR GRILLE <i>6x</i>	\$ 1,697.00	✓
7	BONNET <i>Regis</i>	\$ 4,771.00	X
8	BONNET ATTACHMENT PARTS <i>3 men</i>	\$ 153.00	X
9	LED HEADLIGHT-LH	\$ 10,934.00	✓
10	FRONT CAR PLATE NO. <i>at</i>	S/N \$ 25.00	✓
11	SUNDRIES	\$ 200.00	?
TOTAL SPARE PARTS		: \$ 21,144.00	
TOTAL LABOUR CHARGES		: \$ 4,572.00	
GRAND TOTAL		: \$ 25,716.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Hj*
Surveyed Date : *12/03/18.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorized Repair, 04hrs*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant