

ASS. REC. BY:

REF:

TMI/ C03/TMU8004809/Kabnz

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.:

Yes or No

Lum Sum:

13.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

14/3

File pass to Catherine

3034.57 (Ref to 27675.35, 88%)

SHD 392C - C03/ACH10002827/Delgt

SKM 6360Y - X

DA: 03022010

14/3/18 @ 2.47pm Envt GHA report to estimate to Shirey.

RECEIVED 15 MAR 2018

Date/Time, File Pass to?

11/15/3 Invt

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

MER-TP

3034.57

250

10

260

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 14 March 2018 2:47 PM  
**To:** Too Joon Hwa  
**Cc:** Priscilla Tan; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 09/03/2018 , SHD 392C (TP Vehicle), SKM 6360Y (OI Vehicle)  
**Attachments:** SHD392C EST.pdf, SHD392C GIA.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle **SHD 392C** M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 13/03/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD392C
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003124
Chassis No.:	VF1ABL15AUC283251
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	29 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$34,137.00
<b>Total Rebate Amount:</b>	<b>\$49,135.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Mar 2018

OK

## Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SLN9459K	08 Mar 2018 / 19:35:00	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
FW6440G	09 Mar 2018 / 15:22:00	NTUC INCOME INS CO-OP LTD
SKM6360Y	09 Mar 2018 / 09:15:00	TOKIO MARINE INSURANCE SINGAPORE LTD
SKU787Y	09 Mar 2018 / 07:35:00	NTUC INCOME INS CO-OP LTD
SKQ9127P	09 Mar 2018 / 15:08:00	MSIG INSURANCE (SINGAPORE) PTE LTD

[Print](#)[OK](#)[Save as PDF](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/03/2018 11:24
Date Of Accident	09/03/2018 09:15
Exact Location Of Accident	PIE TOWARDS JURONG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD392C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TNG CHYE LEONG
NRIC No	S1706084H
Date Of Birth	13/08/1965
Occupation	OUTDOOR
Date Of Driving Pass	01/05/1987
Driving Experience	30 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81115702
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 40 SIMS DRIVE #03-215
Postcode	380040
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SANTHA KUMAR V R GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 09.03.2018 at about 0915hours, I was travelling straight on the extreme right lane along PIE towards Jurong when Vehicle in front of me made a stop so I follow suit. Suddenly I felt an impact. Vehicle B (SKM6360Y) overtake my taxi and hit onto my taxi's left rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM6360Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YAP LAY HUAT
NRIC/Passport Number	S7900867B
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:--

\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

plz see attach G.A. Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHD392C - TOKIO**

AAD1803-079

*Not Authored*  
*Resurvey B4 pain* **B3034.57**

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD392C - CANDY**  
**VF1ABL15AUC283251**  
**RENAULT**  
**LATITUDE**  
**09.03.2018**  
**TOKIO**

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Per</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Ad/lt</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
5	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99
6	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
7	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
8	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99
9	1	ROCKER PANEL OUTER LH	\$	<i>7</i> 987.49
10	1	FENDER PANEL REAR LH	\$	<i>7</i> 3,299.13
11	1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45
12	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
13	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
14	1	TAILLAMP PANEL LH	\$	<i>7</i> 986.70
15	1	DOOR PANEL REAR LH	\$	<i>7</i> 2,844.66
16	1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82
17	1	DOOR HINGE UPPER LH	\$	<i>7</i> 274.50
18	1	DOOR HINGE LOWER LH	\$	<i>7</i> 300.55
19	1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96
20	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49
21	1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52
22	1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89
23	1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22
24	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60
25	1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10
26	1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Sn</i> 410.66
27	1	DOOR SEAL REAR LH	\$	<i>Sn</i> 162.02
28	1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Sn</i> 334.69
29	1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82
30	1	DOOR PANEL FRT LH	\$	<i>7</i> 2,844.66

TOTAL	\$	17,913.25
10%	\$	1,791.32
	\$	16,121.92

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1803-079

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD392C - TOKIO

**Special Nett**

1	1SET	PARKING AID	\$	Shaw 700.00	✓
2	1SET	REAR BUMPER CLIP	\$	nn 66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn 33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn 10.00	X
5	1SET	BUMEPR RETAINER LH CLIP RR	\$	nn 20.00	X
6	1SET	BUMPER LOWER REAR RIVET	\$	nn 22.00	X
7	1SET	BUMPER LOWER REAR CLIP	\$	nn 66.00	✓
8	1	TAILLAMP CLIP LH	\$	nn 5.00	} X
9	1SET	WHEELARCH CLIP RR LH	\$	nn 66.00	
10	2	REAR WINDSCREEN SELANT	\$	nn 80.00	
11	1	WINDSCREEN MOULDING	\$	nn 100.00	
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	
13	1	CAP HUB LH RR	\$	nn 35.00	
14	1	RIM LH RR	\$	nn 385.00	
15	1	TYRE LH RR	\$	nn 330.00	
16	1	DOOR STICKER "Trans-cab"	\$	nn 80.00	
17	1	DOOR STICKER "Classic"	\$	nn 30.00	
18	1	DOOR STICKER "6555-3333"	\$	nn 80.00	

<b>TOTAL</b>	<b>\$</b>	<b>2,208.00</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>18,329.92</b>

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	601
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD392C - TOKIO**

Towing Fees	\$	<i>~ 120.00</i> X
To check steering geometry and computer wheel alignment	\$	<i>~ 220.00</i> X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>~ 170.00</i> X
To transfer of tire, rim and on wheel balancing.	\$	<i>~ 170.00</i> X

<b>TOTAL</b>	<b>\$</b>	<b>7,330.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>25,659.92</b>

**(PARTS BY PARTS)****Repair Days**~~10 Days~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification was allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18004809/KQBN2

Date: 16/03/2018

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU010047
Claimant Vehicle No :	SHD392C	Insured Vehicle No :	SKM6360Y
Date of Loss:	09/03/2018	Nature of Claim:	TP
		Claim No:	M1801300

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD392C	Engine No:	M9R8839C003124
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283251
Reg. Date:	30/09/2016 (Man. Year: 2015)	Odometer:	150660 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/65R16	Rear Tyre Size:	215/65R16
Front Left Side:	Falken 4 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,329.92	2,554.57	15,775.35	86.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,330.00	480.00	6,850.00	93.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>25,659.92</b>	<b>3,034.57</b>	<b>22,625.35</b>	<b>88.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,796.19</b>	<b>212.42</b>	<b>1,583.77</b>	<b>88.17</b>
<b>Nett Amount (S\$)</b>	<b>27,456.11</b>	<b>3,246.99</b>	<b>24,209.12</b>	<b>88.17</b>

## INSPECTION

Date of Assignment: 14/03/2018

Date Inspected: 13/03/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2018)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD392C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
9	1		*ROCKER PANEL OUTER LH	Repair	987.49 FL	*- FL
10	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
11	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
12	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
13	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
14	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
15	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
16	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
17	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
18	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
19	1		*DOOR GRAB HANDLE REAR LH	Serviceable	210.96 FL	*- FL
20	1		*DOOR HANDLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
21	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
22	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
23	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
24	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
25	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
26	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
27	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL
28	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*- FL
29	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
30	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
31	1		*SET PARKING AID	Shorted	700.00 FS	*700.00 FS
32	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
33	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
34	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
35	1		*SET BUMPER RETAINER LH CLIP RR	Not Necessary	20.00 FS	*- FS
36	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
37	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
38	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
39	1		*SET WHEELARCH CLIP RR LH	Not Necessary	66.00 FS	*- FS
40	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
42	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
43	1		*CAP HUB LH RR	Serviceable	35.00 FS	*- FS
44	1		*RIM LH RR	Serviceable	385.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*TYRE LH RR	Serviceable	330.00 FS	*-FS
46	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
47	1		*DOOR STICKER CLASSIC	Not Necessary	30.00 FS	*-FS
48	1		*DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*-FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>20,121.25</b>	<b>2,742.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>1,791.33</b>	<b>187.73</b>
<b>Total Parts (S\$)</b>	<b>18,329.92</b>	<b>2,554.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
4	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	200.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
8	TOWING FEES	New	120.00	-
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
10	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
11	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
Gross Labour Cost (\$\$)			<b>7,330.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >