ASS. REC. BY:	(3/TP18004S11/KVbn2
Kenneth	ASSIGNMENT
From: Date:	1760
Estimated Cost:	Veh No: 5/40 38B Yr Regn: 06,16
OD TP) WS I TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lorry / Faxi / Prime Mover /
To Inspect Vehicle No:	Truck / Traffer or
	Make: Mangelt Cotitude ac 1895
at Workshop m/s Trans Cob	Colour Mhhite IBd AC: Insured / Std / NI / NA
Insured:	Sp.Reading /38636 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: VIFIABLISAUC. 282705
200 T. (3-0000)	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: MILI'S/Rim / STD A/Rim or
	Tyre Size: F: 215/61216
(Policy Condition)	R:
Remark: The veh had commenced its N/S C	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO or GT
Bal. or Market Value:	Front
IDAC Accident Rport: Consistent? : Yes or No	BRM G
GIA / PR Seen: Consistent?: Yes or No	UBal, S mm R/Bal. mm
Est. Repairs: 02 days Res.: Yes or No	D.O.A. 8 /3 /18 D.O.I. 13 /2 /1 10
Lum Sum: / 1/2 % 3 Val.: Yes or No	Survey held at D.O.I. 13/3/18
CA / REV / REP. / 24 HRS	
Vehicle: IN / O	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	I Body Structure affected due to collision.
Q 12 GOT MAN	
9HD 38B - 05/10/3011113/	16.07, 9590) (NO RES)
- 21W 340 - (8 / HE13011143 / 0	1902 DOA: 15000013
	15/3/2018
DESERVED LOW	10.0049
KERFIAER LA R	10.0 F0.10
Date/Time, File Pass to?	
Prell. Report	Days Of Repair:
1) : Final Report Coto/Time, File Return to?	Resurvey No. of Trip:
w tall or a v	Transportation: [7]
7 15 3 - tapiet Add Fee	9: Site Insp (\$)_s-RS_SI
Paned Famul	: Interview (S) Protos \\2
Report Format:	Tech Invs (\$) Others 80
Lump Sum / I.B.I: (S 1300-30 1	Weekend (\$
	IOTAL CAT



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

THE .		Affiliated to Federation Internation	onale Des Ex	perts En Automol	oile
TRA	NS-CAB AUTO SI	ERVICES PTE LTD	Ref : C	CS/TP18004811/	Kvb
NO.2 ANG MO KIO STREET 63SINGAPORE 569111			Date: 1	14-03-2018 FP378	
1.		Policy Particulars	:- THIRD I	PARTY CLAIM	
	Insured Veh.		Veh. Ins	pected	SHD 38B
	Policy No.		Coverag	e (\$)	0.00
	Claim No.		Excess ((\$)	0.00
	Assign From		Assign D	Date	13/03/2018
2.		Vehicle Parti	culars & C	Condition	Transfer and the second
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of F	Reg.	
	Chassis No.		Colour		
	Odometer	Early 11 = 11	Steering		
	Brakes		Modifica	ition	
	General				
3.		Conditi	ions of Tyr	res	
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.		Description	on of Dam	ages	
5.	27 P. 1942 SAME	Conse	l Informati	ion	
	Accident Date	08/03/2018	Inspection	Wilder Committee of the	13/03/2018
	Survey held at	TRANS-CAB AUTO SERVICES		on Date	10/00/2010
	Carrey field at	NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	PARTY COM	Ri	emarks		The Administration of the
	A)THE INSPECTION	ON WAS CONDUCTED ON A"WIT	HOUT PRE	JUDICE" BASIS	D REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD38B
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002942
Chassis No.:	VF1ABL15AUC282705
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	09 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$29,000.00
Total Rebate Amount:	\$43,998.00
Message	

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2018

OK

MTC518032689 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE & TIME: 09/03/2018 10:22 SUBMITTED BY: No Jiong How

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date Of Report

09/03/2018 10:22

Date Of Accident

08/03/2018 22:30

Exact Location Of Accident

PIE TOWARDS CHANGI NEAR BKE

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD38B

Insured/Policyholder

Name Of Registered Owner

TRANS-CAB SERVICES PTE LTD

Co Reg No

200303878K

Email Address

CLAIMS@TRANSCAB.COM.SG

Mobile Phone No

Alternative Phone No.

OFFICE-62876666

Vehicle Particulars

Manufacturer

RENAULT

Model

LATITUDE-2.0 DCI AUTO D/AB 4DR (A)

Exact Purpose for which vehicle was being used at

time of accident

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

AXA INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY

Fleet Policy

YES

Policy Number

VPX/P1680520

Cover Note Number

PEH LOO ENG

Name of Driver NRIC No

S0117721D

Date Of Birth

16/08/1946

Occupation

OUTDOOR

Date Of Driving Pass

Driving Experience

24/11/1973 44 YEARS AND 3 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-84204269

Fax Number

Contact Number

EMail Address

NOEMAIL

Page 1 of 16

Address

BLK 38B BENDEMMER ROAD

#05-830

Postcode

332038

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - RELIEF

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

VY4453 (MOTORCYCLE)

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: KEN TAN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

GEYLANG NEIGHBOURHOOD POLICE CENTRE

ROAD: 132 PAYA LEBAR ROAD, POSTCODE: 409014, COUNTRY:

SINGAPORE

Police Station Address Police Station Contact

TEL NO: 1800-8486999 - FAX NO: 68486799

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT: T/20180309/2002

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO BIG

Was there any audio recorded?

NO

Details of Witness 1

Name

GBA9559S

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

VY4453

Vehicle Make/Model/Colour

Page 2 of 16

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

MOTORCYCLIST Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

VY4453

Were seat belts worn?

NO

Was this injured conveyed to hospital by

ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver s not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

rch Plan			
			11111111111
			D-210383
			P - VY1453
		+++++	
			DIE JOHANDS
	TO PILL TIT		Charei near 8/5
	8		
	TYTHHHH	11111	
		11	
SCRIBE CIRCUMSTANCE	OF THE ACCIDENT		
	-place refor	to also	react -
	- Proje resor	an price	18677
			4-17
		St	
			2 The second of
atti e			
	_		
			(a
DECLARATION			
DECLARATION //We declare the foregoing p	articulars are true in every respect.		3 A ×
DECLARATION /We declare the foregoing p	articulars are true in every respect.		W
DECLARATION /We declare the foregoing p	articulars are true in every respect.		y
/We declare the foregoing p	John John Marie		Reporting Centre Dersonnel's Signature
DECLARATION I/We declare the foregoing p Policyholder's Signature Date & Time:	articulars are true in every respect. Driver's Signature (if driver is not the policyh	older)	Reporting Centre Dersonnel's Signature Name: NRIC/FIN No.:

QUARSIC SketcMhanForm_V3





Police Station Of Origin: Geylang N.P.C 132 Paya Lebar Road SINGAPORE 409014 Tel No: 1800-8486999 3 of 3 Report No. T/20180309/2002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Ro G / Sgt 2 GNOH JUN XIAI	/	Signature Of Informant:
Signature Of Interprete Not applicable	er;	Date/Time: 09/03/2018 00:24
Officer In Charge Of C TP / AEIT / SSI 2 SITIMARSITA E Contact No.: 6547621	BINTE BOHARI	Classification Of Case:
Authentication Stamp	SINGAPORE POLICE FORCE	

SIGNATURE





Yes

1 of 3

Police Station Of Origin; Geylang N.P.C 132 Paya Lebar Road SINGAPORE 409014 Tel No: 1800-8486999

Type of Collision: Between Moving Vehicles - Head To Rear

Report No. T/20180309/2002

	Report M	: ACCIDENT lade:	Vide Re	Vide Report No.:			Station Diary No.: 9
		ulars	120000	4. T. W. S. T.		物源特性的	
nforman Name of PEH LOC	Informant:	II dis constant services	APT BI 332038	LK 38B BEN	IDEMEER I	ROAD #05-	830 SINGAPORE
ID Type /	ID No.: / S01177	21D	Contac Home/	Office:		Mobile: 8	4204269
Nationalit		ŒN	Email:				
Sex: Male	Age:	Date of Birth: 16/08/1946	Driver	of Informant:		Institution	n / School Name:
Race: Chinese			Langu			mstitution	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:				Expiry:	
				(080 <u>5</u> 1) 510.4	850 8 1 481 Tu	15 16 25 16 1	中国 医中毒性 基础
	Informatio	on of the Accident	Lance of the land	Drink	Date/Ti	me of	Type of Locatio Straight Road
Type of Acciden	t:	Foreign Vehicle		Drive: No	08/03/2	018 22:30	Olidigin
Transportation of the second	toad 1 LAND EXF	PRESSWAY					
PIE TO		HANGI NEAR BK	Road	Road Surface:			Road Speed Limit:
Clear	35.00			ic Control:			Traffic Volume: Moderate
One W			Not	Controlled			Anyone conveyed by ambulance:

	ehicle Involve	Make	Model	Color	Condition No of Passen
hicle No:	CADE THE	111000			1
ID38B	Car				0
/4453	Motorcycle				0

	A TOTAL OF THE STATE OF THE STA
Details of Person Involved	19天文·公司,1955年,1956年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年,1957年
Any Pedestrian Involved: NO	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



2 of 3

Report No. T/20180309/2002

Police Station Of Origin: Geylang N.P.C

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

CONTINUATION OF REPORT

Driver 411	the state of the same of the s	中国的现代社会的自然的	aprimed.	10.15.16	CHICAGO CONTRACTOR AND CANCOLO
Name	PEH LOO ENG		ID No.		S0117721D
Related Vehicle	SHD38B (Car)		Contac	ct No.	84204269
Hospital/Clinic	NIL		Class Driving Licence Expiry	e &	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Disc		NIL	1
No. of Days gran	ted Medical Leave NIL	Degree of	f Injury	NIL	Commence of the Land of
Passenger 5	八山经验证明 经公公公司 由这	(在1),加拿大	The second	100	0011000011
Name	KEN TAN		ID No.	i.	S8110060H
Related Vehicle	SHD38B (Car)		Conta	ct No.	84960284
			Class of Driving Licence & Expiry Date		Class: NIL
Hospital/Clinic	NIL		Drivin Licen	g ce &	Date of Expiry: NIL
Hospital/Clinic		Date Disc	Drivin Licend Expiry charge	g ce & / Date NIL	Date of Expiry: NIL

Brief Details.

On the above mentioned date time and place, I was driving my vehicle bearing registration number SHD38B along PIE towards Changi near to BKE when I met with an accident. I was driving my vehicle along the second lane.

Out of a sudden, I felt an impact from the back of my vehicle. I then realised another motorcycle bearing registration number VY4453 had collided onto the left corner and left side of my vehicle. I do not know how it happened.

The police and ambulance came to my scene. The motorcyclist was conveyed to hospital for treatment.

The van behind the motorcyclist managed to stop in time to prevent hitting the motorcyclist.

The van driver then informed me that the motorcyclist wanted to overtake me and accidentally hit onto the rear of my vehicle. The van driver informed me that he has camera footage in his vehicle and is willing to be a witness. I do not have the details of the van driver. The van registration plate number is GBA9559S.

I wish to further inform that I have a passenger in my vehicle however he was not injured.

6 Mo Klo Norm 51 Ang Mo Klo Ave 3 Singapore 565784 *e: 4849999



Traffic Police Department Charge Office 10 Ubi Avenue 3 Singapore 408865

AMENDMENT

P 168 No. ccident Date/Time : 08/03/2018 @ 123040 Address : Bix 388 380 380 380 405 - 830 ccident Date/Time : 08/03/2018 @ 123040 Address : Bix 388 380 380 380 405 - 830 SHPTYS NRIC No : S01177219 Tel No : 94204249 Date : 08/03/8 Address : Bix 388 380 380 380 380 SHPTYS NRIC No : S01177219 Tel No : 94204249 Date : 08/03/8 Address : Bix 388 380 380 380 380 SHPTYS NRIC No : S01177219 Date : 08/03/8 Address : Bix 388 380 380 380 SHPTYS NRIC No : S01177219 Date : 08/03/8 Address : Bix 388 380 380 380 SHPTYS NRIC No : S01177219 Date : 08/03/8 Address : Bix 388 380 380 SHPTYS NRIC No : S01177219 Date : 08/03/8 Address : Bix 388 380 380 SHPTYS NRIC No : S01177219 Date : 08/03/8 Address : Bix 388 380 380 SHPTYS NRIC No : S01177219 Date : 08/03/8 Address : Bix 388 380 380 SHPTYS NRIC No : S01177219 Tel No : 943048 Date : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 Tel No : 943048 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 Tel No : 943048 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 Tel No : 943048 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 Tel No : 943048 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 OR : 08/03/8 Address : Bix 388 380 SHPTYS NRIC No : S01177219 OR : 08/03/8 Address : Bix 388 380 OR : 08/03/8 Address : Bix 388 380 OR : 08/03/8 Address : Bix 388 380 OR : 08/03/8 Address : Bix 388 OR : 08/03/8 Address : Bix 388 OR : 08/03/8 Address		AMENI	MENT	Peh Las Eng
P 168 No. ccident Date/Time : 08/03/2018 @ 1230kr Address : 611 388 Rendemeer fload #05-830 chicle(s) Involved : SHD38 8 VY 4453 NRIC No : S0117-210 Tel No : Y4204219 Date : 41318. Dear Sir / Madam Accident involving one taxi and one forthe one on 9/3/18 at 220 hours long PIE + 2266, Changi new BIE on 9/3/18 at 220 hours With reference to the above, I have on 4/3/18 (date) 0024 hours (time) make a colice report at Gyrlay Nfc (Police Station/NPP/NPC) On 9/3/18 (date), 1005 hours (time) at Ray no No New Arch Nfc On 9/3/18 (date), 1005 hours (time) at Ray no No New Arch Nfc		. T/20180309/2002	Name	
ehicle(s) Involved: SHP388 VY4453 NRIC No: S0117219 Tel No: Q4204269 Date: Accident involving But fax: and one forthe near-bit. Accident involving PIE 10064; Changi near BIE With reference to the above, I have on 413/18 (date) 6024 hours (time) make a colice report at With reference to the above, I have on 413/18 (date) 6024 hours (time) make a colice report at NP 168 - T/2018 2012 2002 On 413/18 (date), 1105 hours (time) at Any no 1610 Minch NPC On 413/18 (date), 1105 hours (time) at Any no 1610 Minch NPC			Address	: Bix 388 sendemeer food #05-850
Pie + sward, change near give on \$13/18 at \$2.270 hours (time) and \$13/18 (date), \$10.5 hours (time) at \$1.00 for the above report;	ceident Date/Time	THE RESERVE AND PARTY OF THE PA		
Dear Sir / Madam Accident involving Box taxi and one foreign motorbial. Accident involving Box taxi and one foreign motorbial. Accident involving Box taxi and one foreign motorbial. On PIE toward, Changi new BUE On PISITS ON	ehicle(s) involved	*	NRIC No	
Date Date Date Accident involving But taxi and one forth motorbid. Accident involving But taxi and one forth motorbid. Accident involving But taxi and one forth motorbid. On glaing at 2270 hours With reference to the above, I have on glaing (date) 6024 hours (time) make a colice report at Gramp Mfc (Police Station/NPP/NPC) On glaing (date), 1105 hours (time) at Reg no Ho March Mfc On glaing (date), 1105 hours (time) at Reg no Ho March Mfc		-	Tel No	
With reference to the above, I have on 413/19 (date) 6024 hours (time) make a colice report at 641649 Nfc (Police Station/NPP/NPC) In NP 168 - T/2019 030112 002 On 9/1/18 (date), 1005 hours (time) at Ray no 160 NP240 NFC			Date	: 9/3/18.
	With reference police report at On 9/3//3	e to the above, I have on Geyling Nfc (date), 1105 hour	s (time) at	(date) 1024 hours (time) make a (Police Station/NPP/NPC) Any no No Narth Nrc nts to the above report;
	Yours Faithfully,			
Yours Faithfully,	(Signature)			
	(*)	FOR	FFICIAL U	SE
(Signature)	If a police	officer recorded these r	imenaments, j	nease complete are re-
(Signature) FOR OFFICIAL USE If a police officer recorded these amendments, please complete the following.	Name / Rank No			
(Signature) FOR OFFICIAL USE If a police officer recorded these amendments, please complete the following. Name / Rank No : Virga cheek bit. Lig		9/2/:9	The second second second	
FOR OFFICIAL USE If a police officer recorded these amendments, please complete the following. Name / Rank No: 9/3/4 8 105/6				
FOR OFFICIAL USE If a police officer recorded these amendments, please complete the following. Name / Rank No: Virst cheek bit. Lig Place and Time Place Pl	Station Dairy No	S END WO NOW		SE 000 12
FOR OFFICIAL USE If a police officer recorded these amendments, please complete the following. Name / Rank No : Virgo chee 66. big	Signature	51 Ang Mg Kio A Singapore 5597	VA	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD38B -

Not Northertel \$1302.30

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD38B - JHOW

VF1ABL15AUC283315

RENAULT

LATITUDE

08.03.2018

MALAYSIAN

PART	LIST

1	1	BUMPER COVER REAR	\$	7 1,108.46
2	1	BUMPER LOWER REAR	5	Jh 768.84
3	1	BUMPER BRACKET CTR REAR	S	∫h 113.47
4	1	BUMEPR BRACKET SIDE LH REAR	S	J ₂ 135.97
5	1	BUMEPR RETAINER LH REAR	S	JL 44.99
6	1	BUMPER REFLECTOR LH	\$	Ju 43.61
7	1	BUMEPR BRACKET SIDE RH REAR	s	135.97
8	1	BUMEPR RETAINER RH REAR	\$	1 _{44.99}
9	1	ROCKER PANEL OUTER LH	\$	M 987.49
10	1	FENDER PANEL REAR LH	\$	M 3,299.13
11	1	WHEELARCH REAR LH	\$	Jy 543.47J
12	1	TAILLAMP LH	\$	cns 552.55
13	1	TAILLAMP PANEL	\$	N 986.70
14	1	DOOR PANEL REAR LH	S	N 2,844.66
15	1	DOOR GUIDE REAR LH	S	July 176.82
16	1	DOOR HINGE UPPER LH	\$	17 274.50
17	1	DOOR HINGE LOWER LH	\$	M 300.55
18	1	DOOR CHECK REAR LH	\$	Sh 203.06
19	1	DOOR GRAB HANDLE REAR LH	S	$\int \omega 210.96 \rangle \chi$
20	1	DOOR HANDLE OUTER REAR LH	\$	5h 126.49
21	1	DOOR HANDLE CAP REAR LH	\$	Su 35.52
22	1	DOOR HANDLE SEAL REAR LH	\$	Sh 7.89
23	1	DOOR HANDLE COVER REAR LH	S	Ju 13.22
24	1	DOOR HANDLE MODULE REAR LH	\$	√ 133.60
25	1	DOOR FINISHER REAR LH	\$	In 423.10
26	1	DOOR WHEATHESTRIP REAR LH	\$	In 410.66
27	1	DOOR SEAL REAR LH	\$	Sin 162.02
28	1	DOOR WAIST SEAL OUTER REAR LH	\$	5∟ 334.69
29	1	DOOR MOULDING REAR LH	\$	J ~ 176.82
30	1	DOOR PANEL FRT LH	S	A 2,844.66

TOTAL	\$	17,444.86
TOTAL \$	1,744.49	
,	\$	15,700.37

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330 CO/GST REG NO. 201019626G

SHD38B -

Specical Nett

			-	In 700 00
1	1SET		\$	700.00 X 700.00 X
2	1SET	REAR BUMPER CLIP	\$	66.00 X
3	1SET	BUMPER BRACKET CTR CLIP	\$	ルル 33.00 X
4	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00 X
5	1SET	BUMEPR RETAINER LH CLIP RR	\$	ペス 20.00 ×
6	1SET	BUMPER LOWER REAR RIVET	\$	~~ 22.00 〈
7	1SET	BUMPER LOWER REAR CLIP	\$	12 66.00 X
8	1	TAILLAMP CLIP LH	\$	na 5.00
9	1SET	WHEELARCH CLIP RR LH	\$	nn 66.00 x
10	2	REAR WINDSCREEN SELANT	\$	ルル 80.00)
11	1	WINDSCREEN MOULDING	\$	~~ 100.00 /
12	1	REAR WINDSCREEN INNER SPONGE SEAL	S	100.00 X
13	1	CAP HUB LH RR	\$	35.00
14		RIM LH RR	\$	385.00
15		TYRE LH RR	\$	Jan 330.00
16		DOOR STICKER "Trans-cab"	S	nn 80.00
17		DOOR STICKER "Classic"	S	un 30.00
18		DOOR STICKER "6555-3333"	\$	ner 80.00 6052-
				ANT POTAMAN.
		TOTAL	\$	2,208.00
		TOTAL TOTAL PARTS	2000	2,208.00 17,908.37
		TOTAL PARTS	2000	
			\$	17,908.37
		TOTAL PARTS	2000	
		Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 4401
		TOTAL PARTS Putty And Spray Painting Of The Affected	\$	17,908.37
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor.	\$ \$ \$	3,000.00 4401 N~ 170.00 X
		Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 4401
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas.	\$ \$ \$	3,000.00 4401 N~ 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening	\$ \$ \$	3,000.00 4401 N~ 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal	\$ \$ \$	3,000.00 4401 NA 170.00 X NA 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening	\$ \$ \$	3,000.00 4401 N~ 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$ \$ \$	3,000.00 4401 NA 170.00 X NA 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To transfer of bootlid fittings, attachments and	\$ \$ \$	3,000.00 4401 NA 170.00 X NA 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$ \$ \$ \$	3,000.00 4801 NN 170.00 X NN 170.00 X 2,800.00 3001 NN 170.00 X
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To transfer of bootlid fittings, attachments and perform water seepage test.	\$ \$ \$ \$	3,000.00 4801 NA 170.00 X NA 170.00 X 2,800.00 3001
		Putty And Spray Painting Of The Affected Portion. To reinstall rear bumper parking sensor. To Rust-Proofing Of The Affected Areas. Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To transfer of bootlid fittings, attachments and	\$ \$ \$ \$	3,000.00 4801 NN 170.00 X NN 170.00 X 2,800.00 3001 NN 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330 CO/GST REG NO. 201019626G

SHD38B -

TOTAL Over All Total	and the same of th	7,710.00 25,618.37
To transfer of tire, rim and on wheel balancing.	\$	~~ 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	S	~~ _{170.00} X
To check steering geometry and computer wheel alignment	\$	Nr 220.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	S	ル~ 170.00 ×
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	12 380.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" history
- No illingal modification(strip allowed)
- Supplementary nem(s) must be resurveyed and is subject to final approval from Inserance Company

Acknowledged by Repairer



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	Internationale Des	Experts En	Automobile
--------------------------	--------------------	------------	------------

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP18004811/Kvbn2

IO.2 ANG MO KIO ST	REET 63SINGAPORE 5691	Date: 10 00 2010	
		Code: TP378	
	Policy Particula	rs :- THIRD PARTY CLAI	
Insured Veh.		Veh. Inspected	SHD 38B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018
2.	Vehicle Pa	rticulars & Condition	
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC282705	Colour	METALLIC WHITE / RED
Odometer	186638	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm
4.	Descri	iption of Damages	Later Sand State
	USTAINED DAMAGES AT THE	N/S REAR BODY.	
DAMAGES SEE	DETAILS.		
5.		eral Information	
Accident Date	08/03/2018	Inspection Date	13/03/2018
Survey held at		CES PTE LTD	
	NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.		Remarks	
ANTHE INSPECT	TION WAS CONDUCTED ON A NCE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA S, WE HAVE NOT AUTHOR	ISED REPAIRS.
5b.		nate Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	2 Working Da	ays



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 38B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
- 1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	
	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	
	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13) D
1	WHEELARCH REAR LH	SERVICEABLE	543.47	
1	TAILLAMP LH	CRACKED	552.55	552.55
	TAILLAMP PANEL	TO REPAIR SEE LABOUR	986.70	0
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	8
4	DOOR GUIDE REAR LH	SERVICEABLE	176.82	2
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	5
	DOOR CHECK REAR LH	SERVICEABLE	203.00	3
	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	3
- 3	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	9
- 8	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.5	2
3	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	9
	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.2	2
	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.6	0
	1 FOOR FINISHER REAR LH	SERVICEABLE	423.1	0
	1 DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.6	6
1 20	1 DOOR SEAL REAR LH	SERVICEABLE	162.0	2
	1 DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.6	9
111 8	1 DOOR MOULDING REAR LH	SERVICEABLE	176.8	2

Report Ref No. CS/TP18004811/Kvbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	IDOOR FANEL FREE LITE	TO REPAIR SEE LABOUR	2,844.66	
	LESS 10% DISCOUNT	D IDOUT	-1,744.49	-55.25
	LESS 10% DISCOUNT		15,700.37	497.30
	SPECIAL NETT ITEMS			
-1		SERVICEABLE	700.00	12
	4 (CONTROL OF CONTROL	NOT NECESSARY	66.00	
	The state of the s	NOT NECESSARY	33.00	
		NOT NECESSARY	10.00	
		NOT NECESSARY	20.00	
	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	10-
	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
	SET WHEELARCH CLIP RR LH (SN)	NOT NECESSARY	66.00	
	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	15.
7/19	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	
	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	
	CAP HUB LH RR (SN)	SERVICEABLE	35.00	
	RIM LH RR (SN)	SERVICEABLE	385.00)
	TYRE LH RR (SN)	SERVICEABLE	330.00	
	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	
	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	
	1 DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			2,208.00	65.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.0	D
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.0	53 ST-00 COMP.
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR, ROCKER PANEL OUTER LH, FENDER PANEL REAR LH, TAILLAMP PANEL, DOOR PANEL REAR LH, DOOR HINGE UPPER LH, DOOR HINGE LOWER LH AND DOOR PANEL FRT LH.		2,800.0	0 300.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.0	0

Report Ref No. CS/TP18004811/Kvbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

1,302.30

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	2
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	1.5
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	
			7,710.00	740.00
_	GRAND TOTAL		25,618.37	1,302.30

RECOMMENDED COST OF REPAIRS

Report Ref No. CS/TP18004811/Kvbn2

KONG SENG CHEONG

Licensed Appraiser