

Pass

REF:

NS/INC18004820/Rivber

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: RD 6198P

Policy No. 5085730780-01 16092017

Claims No. MT/1785728-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHC 4718B

Yr Regn:

2014 / 86P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS

c.c 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

287404

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

3TDKN364405751157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

11/03/18

D.O.A.

13/03/18

Survey held at

SMR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/3/18 LS \$700 confirmed by email (Ref 2013.10, 7610)

03/18/2016

NTUC

RD 6198P

RECEIVED-25 MAR 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/3- typist

Report Format :

TP

Lump Sum / I.B.I: (\$

700k

Days Of Repair:

2

Resurvey No. of Trip:

-

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

160

35

195

Survey Department Check List (Case Handler)

Reference No. : NS/INC/800 4822/ R/VB
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 21/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004822/R1vb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 14-03-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	RD 6198P	Veh. Inspected	SHC 4718B
Policy No.	5085730780-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	11/03/2018	Inspection Date	13/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0985728-002	SMRT TAXIS PTE LTD	SHC 4718B	RD 6198P	11/03/2018	\$ 2,913.10	\$ 700.00
2	MT/0984526-002	SMRT TAXIS PTE LTD	SHB 1384E	FBF 4924C	28/02/2018	\$ 1,821.60	\$ 624.15

Claim received from LKK Auto

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5085730780-01	HDT SINGAPORE TAXI PTE. LTD.	201609494H	GFT	Comprehensive	RD6198P	RD6198P	16/09/2017	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4718B
Vehicle to be Exported:	No
Intended De-registration Date:	15 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1431515
Chassis No.:	JTDKN36U405751157
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	24 Sep 2014
First Registration Date:	24 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$28,661.00
Total Rebate Amount:	\$34,727.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 12:50
Date Of Accident	11/03/2018 21:55
Exact Location Of Accident	KLANG LANE (HILTON GARDEN INN)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4718B
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	LIM PENG HWA
NRIC No	S1353316D
Date Of Birth	06/08/1959
Occupation	OUTDOOR
Date Of Driving Pass	27/08/1981
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 12-1520
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5
 Passenger 1 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 3 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 4 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG THE DRIVEWAY OF HILTON GARDEN INN (KLANG LANE) AS I WAS ALIGHTING MY PASSENGERS. SUDDENLY A VEHICLE RD6198P WHICH WAS IN FRONT OF MY TAXI WHICH ALSO ALIGHTED PASSENGERS, STARTED TO REVERSE AND HIT ONTO THE FRONT LEFT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number RD6198P
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

KANG

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

Greater love has no man than to lay down his life for his friends.
John 15:13

✱



82
12-03-18

Mr Kang-
HP: 9832 5679
RD 6198P
BYD
Acc: 9.55pm
Date: 11/3/2018

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature:
Date & Time:

Sm 12/3/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

12/3/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 1

Greater love has no man than to lay down his life for his friends.
John 15:13

*



12-03-18

Mr. Kang
HP: 9832 5679
RD 6198P
BYD
Acc: 9:55pm
Date: 11/3/2018

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

12/3/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

12/3/2018


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 12-3-18
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 12/3/2018
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

G119

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4718B
Ref. No : TAX/03/18/2056
Reg. Date : 24/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LIM PENG HWA
Type of Accident : OTHERS
Date / Time of Accident : 11/03/2018 09:55:00 PM
Accident Reported Date / Time : 12/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095002
Special Instruction to ARC, if any :
RD6198P / NTC / Resurvey after repair
Prepared Date : 12/03/2018 01:01:33 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405751157

Mileage :


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 738.00	0.00
Total Material Charges	: 877.44	1,064.10
Other Charges	: 140.00	0.00
TOTAL	: 2,093.44	0.00
Lum Sum Total	: 2,100.00	0.00
No. of Repair Days	: 3.00	0.00 2 days - L/S
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 12/03/2018 04:06:39 PM	01/01/1900 12:00:00 AM


13/03/18
@1410
15/3/18

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/03/2018 04:02:09 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 X
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	140.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>DE</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.33	Repair	Replace <i>Repair</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>?</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>?</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace <i>?</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								1,039.50	1,272.83	
TOTAL MATERIALS(Discounted)							877.44	1,064.10		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

15-3-18/10:56
15-3-18/14:56

SMRT Accident Vehicle Repair Estimates

13-3-18/14:56

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4718B
Ref. No : TAX/03/18/2056
Reg. Date : 24/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LIM PENG HWA
Type of Accident : OTHERS
Date / Time of Accident : 11/03/2018 09:55:00 PM
Accident Reported Date / Time : 12/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Rasul
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095002
Special Instruction to ARC, if any :

RD6198P - NTUC IDAC 45

Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL
/ HP : 9001 0068, email: rasul@lkkauto.com

LUMPSUM REPAIR

Prepared Date : 12/03/2018 01:01:33 PM



Recording Camera

☐ ☒

Radio Antenna


☐ ☒

1st witness

Date 13-3-18

2nd witness

Date 15/3/18



Vehicle to Wega Date In: 14/3	Towing:
Time In: 11:30	Driver: TMT
Wega Job No: 0310192	
Vehicle sent to SMRT Date In: 15-3-2018	Towing:
Time In: 1-25	Driver:
Received by (SMRT):	

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405751157

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	200.00
Total Spray Painting Charges	: 738.00	300.00
Total Material Charges	: 628.61	361.50
Other Charges	: 140.00	-161.50
TOTAL	: 1,844.61 2913.10	700.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sign Off Date	: 12/03/2018 04:06:39 PM	13/03/2018 02:56:32 PM

F

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/03/2018 04:02:09 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0493

Invoice No :

Quotation Date : 20/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	200.00
Total Labour	338.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100.00
Total Spray Painting & Panel Beating	738.00	300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO WASH AND VACUUM	60.00	40.00
Lump Sum Adjustment by Surveyor	0.00	-201.50
Total Other Costs	140.00	-161.50

2913.10

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT DE	1	482.00	25.00	361.50	Replace	Replace	No <input checked="" type="checkbox"/>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	100.00	0.00	Repair	Repair	No <input checked="" type="checkbox"/>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Check	No <input checked="" type="checkbox"/>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Check	No <input checked="" type="checkbox"/>
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Check	No <input checked="" type="checkbox"/>
52116-47040		6505516	BUMPER SUPPORT F/LH	0	76.40	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
TOTAL MATERIALS							982.20	361.50		
TOTAL MATERIALS(Discounted)							628.61	361.50		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 361.50 \\
 + 200.00 \\
 + 340.00 \\
 \hline
 901.50 \\
 - 20\% \\
 \hline
 721.20 \\
 \text{L/S \$700/-}
 \end{array}$$

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 21 March 2018 2:08 PM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Cc: SUR; CS A Team; 'Leong Chee kwong'
Subject: RE: SHC4718B

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 21 March 2018 11:52 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAUTO)
Cc: SUR; CS A Team; 'Leong Chee kwong'
Subject: RE: SHC4718B

Dear Poh Suan,

Confirmed amount of \$700 @ 2 working days under lump sum repair.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 20 March 2018 6:04 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; 'Leong Chee kwong' <cheekwongwega@gmail.com>
Subject: SHC4718B

Hi Rasul,

Attached herewith the repair estimate of SHC 4718B having Case No: TAX/03/18/2056.

There is no change to the approved amount of \$700 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Tuesday, 20 March 2018 3:59 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 21 March 2018 11:52 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; Rasul (LKKAUTO)
Cc: SUR; CS A Team; 'Leong Chee kwong'
Subject: RE: SHC4718B

Dear Poh Suan,

Confirmed amount of \$700 @ 2 working days under lump sum repair.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 20 March 2018 6:04 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; 'Leong Chee kwong' <cheekwongwega@gmail.com>
Subject: SHC4718B

Hi Rasul,

Attached herewith the repair estimate of SHC 4718B having Case No: TAX/03/18/2056.

There is no change to the approved amount of \$700 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Tuesday, 20 March 2018 3:59 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6



National Assessment Centre Services


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004822/R1vbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 28-03-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	RD 6198P	Veh. Inspected	SHC 4718B	
Policy No.	5085730780-01	Coverage (\$)	0.00	
Claim No.	MT/0985728-002	Excess (\$)	0.00	
Assign From		Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U405751157	Colour	MAROON	
Odometer	287404	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	5 mm	
L/H Front Tyre	195/65 R15	FALKEN	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/03/2018	Inspection Date	13/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4718B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER GRILLE SUB-ASSY, LOWER	TO REPAIR	311.10	-
			1,697.10	361.50
LABOUR				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		418.00	200.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		738.00	300.00
	TO WASH AND VACUUM.		60.00	40.00
			1,216.00	540.00
GRAND TOTAL			2,913.10	901.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				700.00

Report Ref No. NS/INC18004822/R1vbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.