

REF:

NS/INC18004824/Svb2

Surveyor:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time / Action / Instruction

91C 11155 - NS/INC171113155 / 30/3/2013

DOF: 09/07/13

THX/03/15/2013

27/3/18 Sebastian Confirmed LS \$2150 (Red 7401.10, 7710)

SHD 2745E

RECEIVED 1 APR 2013

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 4/4 - typst

Report Format:

Lump Sum / I.B.I. (\$

TP

2150f

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$1

Phone

Others

TOTAL

160

35

195

Veh No:

SHC 40759

Yr Regn:

30/10/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius.

cc 1798

Colour

Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading

558822

T/Radio: Insured / Std / NI / NI

Eng/No:

C/No:

JTDKN 3C4005199763

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

m

L/Bal.

6

mm

L/Bal.

6

m

D.O.A.

7/5/18

D.O.I.

12/3/18

Survey held at

SHD

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Survey Department Check List (Case Handler)

Reference No. : **NS INC 1804824 Svb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **4/4/18**
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004824/Svb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 14-03-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 2745E	Veh. Inspected	SHC 4075Y
Policy No.	5068045737-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 27 March 2018 3:57 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHC4075Y

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Tuesday, 27 March 2018 10:35 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team
Subject: RE: SHC4075Y

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi
Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 26 March 2018 2:34 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: SHC4075Y

Hi Sebastian,

Attached herewith the repair estimate of SHC 4075Y having Case No: TAX/03/18/2047.

There is no change to the approved amount of \$2,150 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 26 March 2018 1:59 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

TP Claims against NTUC Income: Follow-Through Survey

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative repair cost
1	MT/0985649-002	SMRT TAXIS PTE LTD	SHB 5685K	SHD 2900Z	9/3/2018	\$16,906.80	\$6,560.24
2	NOT OI	SMRT BUSES LTD	SMB 345R	SJZ 4060U	3/3/2018	\$6,580.60	\$2,400.00
3	MT/0986413-002	SMRT TAXIS PTE LTD	SHB 5115P	GV 4199K	15/3/2018	\$5,679.73	\$2,200.00
4	MT/0986530-002	SMRT TAXIS PTE LTD	SHC 4705M	SIK 565K	18/3/2018	\$3,114.88	\$700.00
5	MT/0985664-002	SMRT TAXIS PTE LTD	SHC 4075Y	SHD 2745E	9/3/2018	\$9,551.10	\$2,150.00
6	MT/0984993-002	SMRT TAXIS PTE LTD	SHB 1968X	SKA 9766D	6/3/2018	\$7,649.50	\$1,925.94
7	MT/0988280-002	SMRT TAXIS PTE LTD	SHB 1169K	SJR 3086U	12/3/2018	\$7,887.10	\$2,350.00

Claim received from LKK Auto

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5068045737-03	PRIME CAR RENTAL & TAXI SERVICES PTE. LTD.	199606293Z	GFT	Third Party, Fire & Theft	SHD2745E	SHD2745E	09/10/2017	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHC4075Y

Vehicle to be Exported: No

Intended De-registration Date: 14 Mar 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2013

Engine No.: 2ZR1317277

Chassis No.: JTDKN36U005699963

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$33,120.00

Original Registration Date: 30 Oct 2013

First Registration Date: 30 Oct 2013

Transfer Count: 0

Actual ARF Paid: \$8,368.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Oct 2021

PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$27,777.00
Total Rebate Amount:	\$34,053.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2018 09:46
Date Of Accident	09/03/2018 23:00
Exact Location Of Accident	YISHUN AVE 6 SLIP ROAD TO YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4075Y
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	SALIM BIN SALLEH
NRIC No	S1791936I
Date Of Birth	28/06/1967
Occupation	OUTDOOR
Date Of Driving Pass	26/06/2012
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

103

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - RELIEF

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD OF YISHUN AVE 6 WITH A PASSENGER ON BOARD TO LOOK OUT FOR THE ONCOMING TRAFFIC ON YISHUN AVE 1 WHEN THE PRIME TAXI SHD2745E FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHD2745D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

LIM BOON HWEE

NRIC/Passport Number

S1627045H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

du 12/3/16
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4075Y
 Ref. No : TAX/03/18/2047
 Reg. Date : 30/10/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : SALIM BIN SALLEH
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 09/03/2018 11:00:00 PM
 Accident Reported Date / Time : 10/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094967
 Special Instruction to ARC, if any :
 TOWED \$40 / SHD2745E (PRIME) - NTUC (IDAC)
 Prepared Date : 10/03/2018 10:10:56 AM



Sebastian
 12/3/18 -
 - Lump Sum Repair
 - Question Mark Item
 Photo
 - Photo After Paint


 12/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U00-5699963

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,314.00	0.00
Total Material Charges	: 3,747.90	3,747.90
Other Charges	: 1,265.00	0.00
TOTAL	: 7,340.90	0.00
Lum Sum Total	: 7,350.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sign Off Date	: 10/03/2018 10:51:24 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/03/2018 10:51:24 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,314.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,265.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>✓ CRK</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No <i>✓ BT</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No ?
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No <i>✓ BT</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ?
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>X</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No <i>X</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>X</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>✓ CRK</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ?
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓ NEC</i>
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No ?
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ?
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No <i>R</i>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No <i>X</i>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No <i>X</i>
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No <i>X</i>
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No <i>X</i>
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No <i>X</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>✓ NEC</i>
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No <i>X</i>
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace	No ?
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No ?
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No <i>R</i>
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>✓ NEC</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>✓ NEC</i>
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace	No <i>X</i>
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No <i>X</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No ?
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace	No ?
TOTAL MATERIALS							4,684.93	4,684.87		
TOTAL MATERIALS(Discounted)							3,747.90	3,747.90		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									




SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4075Y
Ref. No : TAX/03/18/2047
Reg. Date : 30/10/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : SALIM BIN SALLEH
Type of Accident : HEAD TO REAR
Date / Time of Accident : 09/03/2018 11:00:00 PM
Accident Reported Date / Time : 10/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No Yes
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094967
Special Instruction to ARC, if any :

TOWED \$40 / SHD2745E (PRIME) - NTUC (IDAC)
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121
LUMP SUM REPAIR

Prepared Date : 10/03/2018 10:10:56 AM



17:10 15-3-18 page

Recording Camera



Radio Antenna




1st witness

Date 12-3-18

2nd witness

Date 15-3-18



558822

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

15-3-2018

Vehicle Return Time:

11:40

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U00-5699963

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	600.00
Total Spray Painting Charges	: 1,314.00	700.00
Total Material Charges	: 1,288.95	1,153.94
Other Charges	: 1,185.00	-303.94
TOTAL	: 4,801.95 9551.10	2,150.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	5.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 10/03/2018 10:51:24 AM	12/03/2018 02:38:15 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/03/2018 10:51:24 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0523

Invoice No :

Quotation Date : 22/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	600.00 /
Total Labour	1,014.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
Total Spray Painting & Panel Beating	1,314.00	700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 / nrc
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-558.94 255
Total Other Costs	1,185.00	-303.94

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No ✓ CRK
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ✓ BT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No X NW
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No ✓ BT
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No ✓ DWG
76088-47020		6505617	BUMPER LIP COVER RR/LH	0	72.20	25.00	0.00	Replace	Not given	No X NW
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.58	Replace	Replace S	No ✓ Defect
76891-47020		6505619	BUMPER LIP REAR	0	228.90	25.00	0.00	Replace	Not given	No X NW
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ✓ CRK
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No X NW
			PIXEL STICKER	2	60.00 120	0.00	120.00	Replace	Replace	No ✓ NEC
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Check	No X NW
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X NW
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No R
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No X
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No X
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	0	29.40	25.00	0.00	Replace	Not given	No X NW
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓ NEC
67881-47022			TAILGATE DOOR WEATHER STRIP	0	353.40	25.00	0.00	Replace	Not given	No X NW
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.03	Replace	Check	No X
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Replace S	No ✓ CRK
61604-47090			FENDER RR/RH	1	766.80	100.00	0.00	Replace	Repair	No R
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓ NEC
62710-47130			QUARTER GLASS RR/RH	0	846.50	25.00	0.00	Replace	Not given	No X NW
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X

580790

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.68	Replace	Check	No <input checked="" type="checkbox"/>
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.98	Replace	Check	No <input checked="" type="checkbox"/>
TOTAL MATERIALS							2,014.00	1,153.94		
TOTAL MATERIALS(Discounted)							1,288.95	1,153.94		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

+ 1153.93 /
 + 600.00 /
 + 955.00 /

2708.93 /
 - 20%

2167.14 /

4 s \$ 2150/- /

Sebastian
 27/3/18

**National Assessment Centre Services**


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004824/Svbn2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 09-04-2018	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 2745E	Veh. Inspected	SHC 4075Y
Policy No.	5068045737-03	Coverage (\$)	0.00
Claim No.	MT/0985664-002	Excess (\$)	0.00
Assign From		Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U005699963	Colour	MAROON
Odometer	558822	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4075Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	CRACKED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY,RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER LIP COVER RR/RH (DISC 25%)	DEFORMED	118.10	88.58
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CRACKED	94.80	71.10
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	TAIL LAMP BRACKET,RH (DISC 25%)	CRACKED	30.70	23.03
1	SOLAR FILM (SN)	NECESSARY	125.00	125.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	ARM SUB-ASSY,RR BUMPER LH	NOT NECESSARY	139.60	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	END PANEL	NOT NECESSARY	602.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAIL GATE DOOR GLASS MOULDING,LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING,RH	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	MOULDING BACK WINDOW LOWER NO.1	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	TAIL LAMP BRACKET,LH	NOT NECESSARY	30.70	-
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	BUMPER SEAL,RR LH	NOT NECESSARY	88.90	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	TAILGATE ASY	TO REPAIR	1,007.90	-

Report Ref No. NS/INC18004824/Svbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER RR/RH <u>LABOUR</u> THATCHAM STANDARD REPAIR TIME ON BODY WORKS. THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR. TO REPLACE SUNDRY PARTS. TO WASH AND VACUUM.	TO REPAIR	766.80	
			6,163.10	1,278.95
			1,814.00	710.00
		NOT NECESSARY	1,414.00	700.00
			100.00	20.00
			60.00	-
GRAND TOTAL			9,551.10	2,708.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,150.00

Report Ref No. NS/INC18004824/Svbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.