

REF:

NS/2NC18004816/Svbez

Surveyor

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAG Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time | Action / Instruction

SHB 5185K - 103/CTI 5015973 / Kug32-1

27/3/18 Sebastian confirmed \$ 6560.24 (Red 10,346.56, 6190)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

4/4 typist

Report Format:

Lump Sum / I.B.I. (\$

TP

6560.24

6560.24

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear

R/Bal.

L/Bal.

D.O.I.

The UIC / Chassis frame / Body Structure affected due to collision

Days Of Repair: to

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech. Insp (\$

Weekend (\$

Survey Fee:

Transportation:

S+RS \$

Phone

Others

TOTAL

RECEIVED 1 APR 2018

160

39

199

Survey Department Check List (Case Handler)

Reference No. : NS INC 1800 4826 SV0
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 4/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004826/Svb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 14-03-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 2900Z	Veh. Inspected	SHB 5685K
Policy No.	5068045737-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative repair cost
1	MT/0985649-002	SMRT TAXIS PTE LTD	SHB 5685K	SHD 2900Z	9/3/2018	\$16,906.80	\$6,560.24
2	NOT OI	SMRT BUSES LTD	SMB 345R	SJZ 4060U	3/3/2018	\$6,580.60	\$2,400.00
3	MT/0986413-002	SMRT TAXIS PTE LTD	SHB 5115P	GV 4199K	15/3/2018	\$5,679.73	\$2,200.00
4	MT/0986530-002	SMRT TAXIS PTE LTD	SHC 4705M	SJK 565K	18/3/2018	\$3,114.88	\$700.00
5	MT/0985664-002	SMRT TAXIS PTE LTD	SHC 4075Y	SHD 2745E	9/3/2018	\$9,551.10	\$2,150.00
6	MT/0984993-002	SMRT TAXIS PTE LTD	SHB 1968X	SKA 9766D	6/3/2018	\$7,649.50	\$1,925.94
7	MT/0988280-002	SMRT TAXIS PTE LTD	SHB 1169K	SJR 3086U	12/3/2018	\$7,887.10	\$2,350.00

Claim received from LKK Auto

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5068045737-03	PRIME CAR RENTAL & TAXI SERVICES PTE. LTD.	199606293Z	GFT	Third Party, Fire & Theft	SHD2900Z	SHD2900Z	09/10/2017	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5685K
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS110364
Chassis No.:	JTDKB3FU603575779
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2025

PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$32,371.00
Total Rebate Amount:	\$36,121.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2018 10:43
Date Of Accident	09/03/2018 16:50
Exact Location Of Accident	ECP TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5685K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	N MOHANASUNDERN
NRIC No	S1258458Z
Date Of Birth	23/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	25/11/1985
Driving Experience	32 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

448

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - RELIEF

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1 NAME: : UNKNOWN

GENDER: : MALE

Passenger 2 NAME: : UNKNOWN

GENDER: : FEMALE

Passenger 3 NAME: : UNKNOWN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG ECP AT THE RIGHT MOST LANE WITH THREE PASSENGERS ON BOARD WHEN THE FRONT VEHICLE SJW2755C BRAKE AND STOPPED. I APPLIED MY BRAKE AND WAS ABLE TO STOP IN TIME. HOWEVER, THE TAXI SHD2900Z FROM BEHIND FAILED TO STOP AND COLLIDED ONTO THE REAR PORTION OF MY TAXI. THE GREAT IMPACT CAUSE MY TAXI TO SURGE FORWARD AND HIT ONTO THE REAR OF THE VEHICLE SJW2755C.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE TOO LARGE

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD2900Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

KAREN KOH

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJW2755C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MOHD SAKBAN

NRIC/Passport Number

S1114464J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

SKETCH PLAN

↑ ↑ ↑

C

A

B

C - SJW 2755C

A - SHB 5685K

B - SHD 2900Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

NTHC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5685K
 Ref. No : TAX/03/18/2048
 Reg. Date : 30/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : N MOHANA SUNDERN
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 09/03/2018 04:50:00 PM
 Accident Reported Date / Time : 10/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 09/03/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094969
 Special Instruction to ARC, if any :
 TOWED \$90 / SHD2900Z
 Prepared Date : 10/03/2018 11:10:55 AM



Sebastian
12/3/18.

- Part by part repair.
- Question Mark Item
- Photo
- Photo Before Paint

Signature
15/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603575779

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	0.00
Total Spray Painting Charges	: 2,430.00	0.00
Total Material Charges	: 8,697.65	8,697.65
Other Charges	: 1,316.00	0.00
TOTAL	: 14,302.65	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 11.00	0.00
Prepared / Adjusted By	:	6 days
Arc / Surveyor Sign Off Date	: 10/03/2018 01:43:52 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/03/2018 01:43:52 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	0.00 600
TO REPAIR FRONT PORTION	676.00	0.00 200
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 X
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00 X
TO RESPRAY REAR FENDER RH	378.00	0.00 X
TO REPSRAY FRONT BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	2,430.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	126.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,316.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No <i>R</i>
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No <i>✓N3C</i>
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace	No <i>X</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No <i>?</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>?</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>✓N3C</i>
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No <i>?</i>
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No <i>?</i>
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No <i>?</i>
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No <i>?</i>
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace	No <i>?</i>
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No <i>?</i> <i>Defory</i>
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No <i>✓Defory</i>
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No <i>?</i>
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.72	Replace	Replace	No <i>?</i>
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No <i>R</i>
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No <i>✓CAR</i>
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No <i>?</i>
6932147010			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.00	18.97	Replace	Replace	No <i>X</i>
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace	No <i>X</i>
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace	No <i>X</i>
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No <i>X</i>
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace	No <i>X</i>
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace	No <i>X</i>
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No <i>X</i>
6472147050C0			TAILGATE BOARD, COVER	1	24.10	25.00	18.07	Replace	Replace	No <i>X</i>
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No <i>✓N3C</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓Nec	No
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓Nec	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓Nec	No
	COMMON		STICKER DECAL 65558888	1	21.60	0.00	21.60	Replace	Replace ✓Nec	No
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No ?
5835047010			REINFORCEMENT ASSY, REAR FLOOR END PANEL , RH & LH	2	56.70	25.00	85.05	Replace	Replace	No ?
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ?
6160247160			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace	No X
6101847010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	25.00	209.40	Replace	Replace R	No ✗
6160147150			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	25.00	618.60	Replace	Replace	No ?
6101747010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	25.00	209.40	Replace	Replace R	No ✗
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace	No ?
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace	No ?
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No R
5211647050			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace	No ?
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace	No ✓OF
5311247240			GRILLE, RADIATOR	1	165.00	25.00	123.75	Replace	Replace	No ?
5211447190			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Replace	No ?
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No ✓BT
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No ✓ckk
5310147080			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace	No ?
7531047060			EMBLEM ASSY FRONT	1	87.10	25.00	65.32	Replace	Replace	No ✓Nec
5202147110			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.32	Replace	Replace	No ?
5261147140			ABSORBER, FR BUMPER	1	70.30	25.00	52.72	Replace	Replace	No ?
5210347010			EXTENSION SUB-ASSY, LH	1	116.30	25.00	87.22	Replace	Replace	No ?
5210247020			EXTENSION SUB-ASSY, RH	1	116.30	25.00	87.22	Replace	Replace	No ?
5213247010			REINFORCEMENT FRONT LOWER	1	238.50	25.00	178.87	Replace	Replace	No ?

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5261847090			ABSORBER, FR BUMPER LOWER	1	117.00	25.00	87.75	Replace	Replace	No
TOTAL MATERIALS							8,610.01	8,609.90		
TOTAL MATERIALS(Discounted)							8,697.65	8,697.65		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

19-3-18 / 10:34

14-3-18 / 14:34

12-3-18 / 14:34

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5685K
 Ref. No : TAX/03/18/2048
 Reg. Date : 30/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : N MOHANA SUNDERN
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 09/03/2018 04:50:00 PM
 Accident Reported Date / Time : 10/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 09/03/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094969
 Special Instruction to ARC, if any :

TOWED \$90 / SHD2900Z NTUC P/P

BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianyeang @lkkauto.com HP:90036121

Prepared Date : 10/03/2018 11:10:55 AM



Recording Camera

Radio Antenna

1st witness

2nd witness

Date 12-3-18

54996 km

Supplementary
 & Refer to the Supplementary part later

QC 21/3/18 14:16 Reject

Filler for bumper L1 dent

22/3/18 10:32 PM

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 21/3/18

Vehicle Return Time: 1030

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603575779

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	1,000.00
Total Spray Painting Charges	: 2,790.00	1,400.00
Total Material Charges	: 7,151.41	3,925.01
Other Charges	: 1,190.00	310.00
TOTAL	: 12,990.41 16,906.80	6,635.01
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 11.00	10.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 10/03/2018 01:43:52 PM	12/03/2018 02:34:59 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/03/2018 01:43:52 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0567

Invoice No :

Quotation Date : 24/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	800.00 /
TO REPAIR FRONT PORTION	676.00	200.00 /
Total Labour	1,859.00	1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY PANEL SIDE ROOF LH	180.00	100.00 /
TO RESPRAY PANEL SIDE ROOF RH	180.00	100.00 /
Total Spray Painting & Panel Beating	2,790.00	1,400.00 /

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00 /
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	120.00 /
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,190.00	310.00 /

16906.80

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.93	Replace	Replace	No ✓
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50 15	25.00	11.25	Replace	Replace	No ✓
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.93	Replace	Replace	No ✓
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No ✓
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓
			PIXEL STICKER	2	60.00 120	0.00	120.00	Replace	Replace	No ✓
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80 7.6	25.00	5.70	Replace	Check	No X
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80 7.6	25.00	5.70	Replace	Check	No X
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80 7.6	25.00	5.70	Replace	Check	No X
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00 22	25.00	16.50	Replace	Check	No X
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Check	No X
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.73	Replace	Replace	No ✓
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No ✓
5246147010			PAD, RR BUMPER, CTR	3	2.20 6.6	25.00	4.95	Replace	Check	No X
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.73	Replace	Check	No X
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace	No ✓
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No ✓
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Check	No X
6932147010			TAIL GATE LOCK COVER, BACK DOOR	0	25.30	25.00	0.00	Replace	Not given	No X
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	0	24.90	25.00	0.00	Replace	Not given	No X
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	0	360.70	25.00	0.00	Replace	Not given	No X
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.28	Replace	Replace	No ✓
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.78	Replace	Replace	No ✓
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	25.00	20.93	Replace	Replace	No ✓
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ✓
6472147050C0			TAILGATE BOARD, COVER	0	24.10	25.00	0.00	Replace	Not given	No X
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No ✓

4990.10

2883.35

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ✓
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No ✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Check	No X
5835047010			REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH	2	56.70 113.40	25.00	85.05	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
6160247160			PANEL SUB-ASSY, FENDER REAR LH	0	824.80	25.00	0.00	Replace	Not given	No X
6101847010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	279.20	100.00	0.00	Replace	Repair	No R
6160147150			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	25.00	618.60	Replace	Check	No X
6101747010			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	279.20	100.00	0.00	Replace	Repair	No R
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Check	No X
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Check	No X
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.63	Replace	Replace	No ✓
5211647050			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.73	Replace	Check	No X
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.67	Replace	Replace	No ✓
5311247240			GRILLE, RADIATOR	1	165.00	25.00	123.75	Replace	Check	No X
5211447190			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Replace	No X
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No ✓
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No ✓
5310147080			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace	No ✓
7531047060			EMBLEM ASSY FRONT	1	87.10	25.00	65.32	Replace	Replace	No ✓
5202147110			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.33	Replace	Check	No X
5261147140			ABSORBER, FR BUMPER	1	70.30	25.00	52.73	Replace	Replace	No ✓
5210347010			EXTENSION SUB-ASSY, LH	1	116.30	25.00	87.23	Replace	Check	No X
5210247020			EXTENSION SUB-ASSY, RH	1	116.30	25.00	87.23	Replace	Check	No X
5213247010			REINFORCEMENT FRONT LOWER	1	238.50	25.00	178.88	Replace	Check	No X
5261847090			ABSORBER, FR BUMPER LOWER	1	117.00	25.00	87.75	Replace	Check	No X

96689

6077.70

TOTAL MATERIALS	7,151.44	3,925.01
TOTAL MATERIALS(Discounted)	7,151.41	3,925.01

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

3850.24
1000.00
+ 1710.00

6560.24

Sebastian.
21/3/18.

3925.01
+ 1000.00
+ 1710.00

6635.01

Remark: Bracket, FR Bumper No Photo Given.

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 27 March 2018 6:29 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB5685K

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Tuesday, 27 March 2018 10:35 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team
Subject: RE: SHB5685K

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi
Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 26 March 2018 2:27 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5685K

Hi Sebastian,

Attached herewith the repair estimate of SHB 5685K having Case No: TAX/03/18/2048.

There is no change to the approved amount of \$6,635.01 @ 10 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 26 March 2018 2:00 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham describe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004826/Svbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 11-04-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 2900Z	Veh. Inspected	SHB 5685K
Policy No.	5068045737-03	Coverage (\$)	0.00
Claim No.	MT/0985649-002	Excess (\$)	0.00
Assign From		Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603575779	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/03/2018	Inspection Date	12/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5685K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	TORN	423.90	317.93
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	FILLER, RR BUMPER, LH (DISC 25%)	CRACKED	119.90	89.93
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.73
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	CRACKED	14.80	11.10
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	BENT	929.60	697.20
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	CRACKED	891.20	668.40
1	TAIL GATE MOULDING GLASS, BACK DOOR (DISC 25%)	NECESSARY	29.70	22.28
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	19.70	14.78
1	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE (DISC 25%)	NECESSARY	27.90	20.93
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	COVER, FR BUMPER (DISC 25%)	TORN	495.50	371.63
1	SUPPORT, FR BUMPER RH (DISC 25%)	DENTED	76.90	57.67
1	GRILLE SUB-ASSY (DISC 25%)	CRACKED	335.60	251.70
1	EMBLEM ASSY FRONT (DISC 25%)	NECESSARY	87.10	65.32
1	ABSORBER, FR BUMPER (DISC 25%)	CRACKED	70.30	52.73
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	NUMBER PLATE (SN)	BENT	35.00	35.00
1	NUMBER PLATE FRAME (SN)	CRACKED	25.00	25.00
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80	NOT NECESSARY	7.60	-

Report Ref No. NS/INC18004826/Svbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	SEAL, RR BUMPER, LH	NOT NECESSARY	85.20	-
3	PAD, RR BUMPER, CTR @\$2.20	NOT NECESSARY	6.60	-
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	234.30	-
1	TAIL GATE LOCK ASSY, BACK DOOR	NOT NECESSARY	452.10	-
1	TAIL GATE LOCK COVER, BACK DOOR	NOT NECESSARY	25.30	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	NOT NECESSARY	24.90	-
1	TAIL GATE WEATHERSTRIP, BACK DOOR	NOT NECESSARY	360.70	-
1	TAILGATE BOARD, COVER	NOT NECESSARY	24.10	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	NOT NECESSARY	629.80	-
2	REINFORCEMENT ASSY, REAR FLOOR END PANEL, RH & LH @\$56.70	NOT NECESSARY	113.40	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	PANEL SUB-ASSY, FENDER REAR LH	NOT NECESSARY	824.80	-
1	PANEL SUB-ASSY, FENDER REAR RH	NOT NECESSARY	824.80	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	WIRE, LUGGAGE ROOM	NOT NECESSARY	143.50	-
1	SUPPORT, FR BUMPER LH	NOT NECESSARY	82.30	-
1	GRILLE, RADIATOR	NOT NECESSARY	165.00	-
1	BRACKET, FR BUMPER	NOT NECESSARY	99.80	-
1	REINFORCEMENT FRONT UPPER	NOT NECESSARY	691.10	-
1	EXTENSION SUB-ASSY, LH	NOT NECESSARY	116.30	-
1	EXTENSION SUB-ASSY, RH	NOT NECESSARY	116.30	-
1	REINFORCEMENT FRONT LOWER	NOT NECESSARY	238.50	-
1	ABSORBER, FR BUMPER LOWER	NOT NECESSARY	117.00	-
1	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	TO REPAIR	279.20	-
1	MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	TO REPAIR	279.20	-
			11,067.80	3,850.24
LABOUR				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			2,689.00	1,280.00

Report Ref No. NS/INC18004826/Svbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		2,990.00	1,430.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			5,839.00	2,710.00
GRAND TOTAL			16,906.80	6,560.24
RECOMMENDED COST OF REPAIRS (CONFIRMED)				6,560.24

Report Ref No. NS/INC18004826/Svbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.