

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3592
Date Estimated : 13/03/2018
Prepared By : Wong Guo Xiang

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Abel Yap Tien Hock (Ye Tianfu)
27 Anchorvale Crescent
#05-33

singapore 544657

- ACCOUNT - 2000
CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGC408J	WF0EXXWPCEGL54643	05/09/2017	Mon 2.0 5Dr	8

DESCRIPTION	VALUE
SUNDRIES	30 150.00
TO REPLACE/REPAIR FRT LHS FENDER, FRT LHS DOOR	1200 1,800.00
RESpray FRT LHS FENDER, FRT LHS DOOR, LHS DOOR MIRROR	1200 1,800.00
WIRING CONNECTION & CHECK (NETT)	✓ 150.00
TRANSFER FRT LHS DOOR MECHANISM (NETT)	✓ 300.00
WHEEL ALIGNMENT	✓ 600.00
TUFF KOTE @ \$60 PER PANEL	120 180.00
SEALANT FOR FRT LHS DOOR @ \$90 PER PANEL	✓ 90.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC CHECK INCLUDING CLEAR FAULT CODE (NETT)	✓ 600.00

Total Labour 1: 5,670.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
DS73F16006DD	FENDER ASSY - FRONT, LH	1	587.00	10.00	bt ✓ 528.30
DS73A16115EE	LHF MUDSHEILD <ED>	1	213.00	10.00	? 191.70
ES73F20899BB	MOULDING DOOR OUTSIDE LHF PILLAR	1	151.00	10.00	nee ✓ 135.90
59B8					
DS73F237A05C	LHF DR SEALING PLASTIC FOIL	1	102.00	10.00	nee ✓ 91.80
A					
DS73F201A19A	MOULDING LHF DOOR - BLACK	1	140.00	10.00	? 126.00
B3JA6					
DS7317E715MB	MIRROR ASSY, LH, PRIMED	1	963.00	10.00	? 866.70
XWAA					
DS73F20125DF	DOOR ASSY - LHF	1	1,922.00	10.00	bt ✓ 1,729.80
Total Parts :					3,670.20

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 3592
Date Estimated : 13/03/2018
Prepared By : Wong Guo Xiang

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGC408J	WF0EXXWPCEGL54643	05/09/2017	Mon 2.0 5Dr	8

Tanjin 97495749
15/3/18 @ 1130
- WP'
Resurvey before paint
sure lkkauto.com
tanjin@lkkauto.com
4 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Service Officer

Contact

Labour 1	:	5,670.00
Parts	:	3,670.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	653.81
Grand Total	:	9,994.01

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.