

SJE : _____
Date of Survey : _____
Contacts : _____

Vehicle Nos : SLB 9827U
Model : Subaru Forester
Year : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear boot <i>Dented</i>	1	\$ 1,292.00	\$ 1,292.00
2	Rear boot emblem - Subaru	1	\$ 55.60	\$ 55.60
3	Rear boot emblem - Forester	1	\$ 59.40	\$ 59.40
4	Rear boot logo	1	\$ 84.20	\$ 84.20
5	Rear boot lock	1	\$ 196.00	\$ 196.00
6	Rear boot w/strip	1	\$ 166.90	\$ 166.90
7	Rear boot hinge L+R	2	\$ 67.00	\$ 134.00
8	Rear boot damper L+R	2	\$ 98.00	\$ 196.00
9	Rear boot inner trim	1	\$ 342.00	\$ 342.00
10	Rear boot inner trim clip	10	\$ 5.50	\$ 55.00
11	Rear boot w/s glass moulding	1	\$ 117.00	\$ 117.00
12	Rear bumper	1	\$ 763.00	\$ 763.00
13	Rear bumper retainer L+R	2	\$ 34.00	\$ 68.00
14	Rear bumper bracket L+R	2	\$ 47.00	\$ 94.00
15	Rear bumper towing cap	1	\$ 45.00	\$ 45.00
16	Rear bumper reinforcement	1	\$ 389.00	\$ 389.00
17	Rear bumper sponge	1	\$ 176.00	\$ 176.00
18	Rear bumper clip	10	\$ 5.50	\$ 55.00
19	Rear bumper reflector L+R	2	\$ 48.00	\$ 96.00
20	Tail lamp L+R	2	\$ 562.00	\$ 1,124.00
21	Tail lamp panel L+R	2	\$ 214.00	\$ 428.00
22	Tail lamp clip L+R	4	\$ 5.50	\$ 22.00
23	Tail lamp lower bracket L+R	2	\$ 47.00	\$ 94.00
24	Rear end panel	1	\$ 553.00	\$ 553.00
25	Rear end panel top garnish	1	\$ 192.00	\$ 192.00
26	Rear end panel top garnish clip	2	\$ 5.50	\$ 11.00
27	Spare wheel panel	1	\$ 697.00	\$ 697.00
28	Spare wheel panel side foam L+R	2	\$ 174.00	\$ 348.00
29	Rear exhaust pipe L+R	2	\$ 972.00	\$ 1,944.00
30	Rear exhaust pipe chrome L+R	2	\$ 181.00	\$ 362.00
31	Rear exhaust pipe mounting	1	\$ 34.00	\$ 34.00
32	Rear signal RH	1	\$ 32.00	\$ 32.00
33	Rear exhaust pipe heat seal	2	\$ 96.00	\$ 192.00

34 Spare Wheel Panel Centre Foam *torn* 265.60

4948.50
3958.8

Parts Sub Total : \$ 10,417.10
Discount 20% : \$ 2,083.42
PARTS TOTAL : \$ 8,333.68

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Reverse sensor	1	\$ 280.00	\$ 280.00
2	Rear boot w/s glass sealant	1	\$ 100.00	\$ 100.00
3	Rear end panel sealant	1	\$ 100.00	\$ 100.00
4	Spare wheel panel sealant	1	\$ 100.00	\$ 100.00
5	Spare wheel panel insulator	1	\$ 150.00	\$ 150.00
6	Rear number plate	1	\$ 50.00	\$ 50.00
7	Reverse camera	1	\$ 400.00	\$ 400.00

8	Rear bumper spoiler <i>not in</i>	1	\$ 1,800.00	\$ 1,800.00	<i>1800</i>
9	Rear bumper chrome "forester" <i>Bent</i>	1	\$ 500.00	\$ 500.00	<i>380</i>
10	Rear spare wheel floor board <i>Not in</i>	1	\$ 600.00	\$ 600.00	<i>7</i>
				SPECIAL NETT TOTAL :	\$ 4,080.00

Nos.	LABOUR	SS
1	To panel beat, weld, cut, adjust, knock	\$ 1,800.00
2	To putty and respray accident affected area	\$ 2,000.00
3	To rust proof accident affected area	\$ 120.00
4	To R & R rear boot mechanism.	\$ 140.00
5	To R & R rear luggage compartment, rear seat, garnish and attachment parts.	\$ 200.00
6	To R & R reverse sensor and check function.	\$ 100.00
67	To R & R rear exhaust pipe system.	\$ 180.00
LABOUR TOTAL :		\$ 4,540.00

8 To R & R rear camera.

Adrian Lim
1/s 14/03/18

06 days.

PARTS TOTAL :	\$ 8,333.68
SPECIAL NETT TOTAL :	\$ 4,080.00
LABOUR TOTAL :	\$ 4,540.00
TOTAL :	\$ 16,953.68
Deduct 20% :	\$ 3,390.74
GRAND TOTAL :	\$ 13,562.94

total: 6938.80
1/s: 5550.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: