

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

GST No : 200600989k

FWD

Motorcar Claim Department

Attn Claim Officer

Tel 67275700

Estimate Repair

Date : 18/3/2018

*Not Attached
Running After Pain*

Accident Involving SJP258Z & SJL9590Y On 11/03/2018 At Johor

Item	Descriptions	Amount
1	Rear Bumper REPAIR	
2	Rear Left Fender REPAIR	

Total For Parts \$ -

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 300.00	<i>1201</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 450.00	<i>2501</i>
3	Cavity Preservation On All Affected Areas		
		\$ 750.00	

Total For Parts & Labour \$ 750.00

Ready Auto Care Pte Ltd

Nikki - 6481 2863

No Of Days For Repair *20 Days*
1 day



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: