

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 46201** Page No. :
Date Estimated : 12/03/2018
Prepared By : Kevin Leong Wai Kit

REPAIR FOR -
Gui Wee Fong Quiner
56 Kew Avenue

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 466340

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLE6615T	5F01686	28/07/2016	X1 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the RH roof frame, rear spoiler for boot lid include replacement of damaged parts and knocking out dents caused by the accident	2125.00		2,125.00	
To spray paint RH roof frame and rear spoiler for boot lid	806.00		806.00	
To replace front windscreen glass include conduct water leak test.	649.00		649.00	
To supply and install IU unit bracket.	31.00		31.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
3M S/F PLATINUM FFRONT WINDSCREEN	308.41	1.00		308.41
RH ROOF RAILS ALUMINIUM SATINATED	465.60	1.00		465.60
BUMP STOP	3.25	10.00		32.50
COVER WINDSHIELD TOP	34.10	1.00		34.10
FRT WINDSCREEN RAIN SENSOR (RLSBS)	686.40	1.00		686.40
RH DRIP MOULDING	66.15	1.00		66.15
# FRT RH DOOR SIDE GLASS WINDOW *	247.20	1.00		247.20
FRT RH DOOR COLUMN B COVER	74.05	1.00		74.05
FRT RH DOOR WINDOW FRAME COVER (ALU)	74.90	1.00		74.90
# FRT RH DOOR WINDOW GUIDE *	108.15	1.00		108.15
# REAR RH DOOR WINDOW GUIDE *	127.85	1.00		127.85
REAR RH DOOR COLUMN B COVER	48.15	1.00		48.15
RR RH DOOR WINDOW FRAME COVER (ALU)	59.75	1.00		59.75
REAR RH SIDE WINDOW FIXED (ALU)	310.05	1.00		310.05
# RR RH SIDE DOOR WINDOW FIXED *	146.05	1.00		146.05
# SENSOR RAIN/LIGHT/SOLAR/CONDENSATIO * (DG) CLEANER R1 (100ML)	372.55	1.00		372.55
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85

SUPPLEMENTARY ITEMS

Total Labour :	3,691.00
Total Parts :	3,476.66
Total Labour & Parts :	7,167.66
Deduction for Excess :	
Total Repair Costs less Excess:	7,167.66
GST @7%:	501.74
Grand Total :	7,669.40