

Vale on

CC 4, Asm 1800.4836, R19

24723

ASSIGNMENT

Surveyor:

Rasul

DOI:

10/04/18

Date / Time

13/3/2018

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLV 7893K

Name of Insured:

TOP LA HUA

Insured Tel No.:

HP: 92239438

Excess Sec II :S\$

D.O.A:

12/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

58m00Amo

Policy No.:

GA314097

Make / Model:

T. WUH 1-8(A)

Place of Accident:

P16

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLP 38424



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sugmtee



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

15/3/18

SLP 38424 - X

SLV 7893K - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7 THIN By Email 16/4

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18/4/18

5/11/19

20/8/19

Called OI no response.

RAC LOR send TP (Pending LOR).

Pending mandate approval.

08-01-20 TO SPEED UP SETTLEMENT AS AMT OF CLAIM IS NOT MUCH.

off 4165.32 (Pending acceptance)

2nd reminder to TP

TP send off, R1 off max 4165.32 (Pending acceptance)

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 5/11/19 / 9:59am

Confirm with:

Confirm by: Rasul

Repair Cost:

P1P

S\$ 1376.88

(2 days)

Reduction:

\$1424.11

%

51

Email

Call

FINAL SETTLEMENT

Date/Time: 20/3/2020

Confirm with:

Janice

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

Repair Cost:

(WIPST)

S\$ 1473.32

Loss of Rental (LOR):

S\$

(1 days)

Loss of Use (LOU):

S\$ 180.00

(5.00 x 3 days)

Loss of Income (LOI):

S\$

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost

S\$

Total:

S\$

1659.32

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

1659.32

Name 1:

Eng An Tee motor & Panel Service Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 24/5/2020



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18004836/ua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 14-03-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLV 7893K	Veh. Inspected	SLP 3842R	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00AMO	Excess (\$)	0.00	
Assign From		Assign Date	14/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/03/2018	Inspection Date		
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Surinder *Ram*

REF:

48361 Pina3 (C) 61807

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: *SLP 3842R*
at Workshop mis *SNH AH TEG*
of *BLK 3, Pioneer ROUTH*
Insured *ASM / TP*
Policy No. _____
Claims No. _____
Sum Insured _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *94k*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *2* days Res: Yes or No
Lum Sum: *1-3-1* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLP 3842R* Yr Regn: *2017 Jun*
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: *TOYOTA COROLLA MTIS 1.6 c.c 1598*
Colour: *Grey* A/C: Insured / Std / NI / NA
Sp. Reading: *20336* T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: *MROS 3REH 104558378*

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: *215/45R17*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: *6* mm R/Bal: *6* mm
L/Bal: *6* mm L/Bal: *6* mm
D.O.A. *12/03/18* D.O.I. *10/04/18*

Survey held at *SNH AH TEG*

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$1276.13

(Red = \$1424.11 / 51%)

* 2 repair days + 1 PRS = 3 days.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ Site Insp (\$

Transportation:

| S + RS \$

| Photos

| Others

Report Format :

Lump Sum / I.B.I. (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

= TOTAL

Cecilia

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003718

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01

AXA Tower (S) 068811

ATTENTION:

CONTACT: -

FAX NO: 68804838

DATE: 09/04/2018
ACCIDENT DATE: 09/04/2018 12/2/2018
VEHICLE NO: SLP3842R
CHASSIS/ENG.NO:
VEHICLE MODEL: TOYOTA COROLLA
CLAIM NO:
POLICY NO:
REMARK: 3842 AXA TP AGAINST SLV7893K

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

**** LIST PRICE ****

1	1	PC	REAR BUMPER	561.45	25	421.09	421.09
2	1	PC	REAR BUMPER SIDE RETAINER	132.25	25	99.19	198.38
3	1	PC	REAR BUMPER SPONGE	182.10	25	136.57	136.57

SUB-TOTAL: 756.04

470.68 \$619.47

**** SPECIAL NETT PRICE ****

1	1	PC	REAR BUMPER REVERSE SENSOR	180.00		180.00	180.00
---	---	----	----------------------------	--------	--	--------	--------

SUB-TOTAL: 180.00

\$180

**** WORK LABOUR ****

TO CHECK WIRING

TO APPLY ANTI RUST COATING

TO KNOCK REAR END PANEL, WELD, REMOVE & REPLACE ABOVE PARTS

TO PUTTY & RESPRAY PAINTING ON RR BUMPER, REAR END PANEL

AND AFFECTED AREAS

30.00 30.00

100.00 X 100.00

550.00 200 550.00

600.00 200 600.00

0.00 0.00

SUB-TOTAL: 1,280.00

\$430

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Supplementary

① Rear boot lock - \$385 X 283.75

② Rear bumper reinforcement \$345.64 (296.75)

SUB-TOTAL: S\$ 2,216.04

ADD 7% GST: S\$ 155.12

GRAND TOTAL: S\$ 2,371.16

\$2801.04

JOYCE

PAGE: 1

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457
Tel: 6268 6183 (4 Lines) Fax: 6268 1429

ATTN: THE MOTOR CLAIMS DEPT
AXA INSURANCE SINGAPORE PTE LTD
143 CECIL STREET
#01-01
GB BUILDING
SINGAPORE 069542

Our Ref:
Date : 9/4/2018

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No.	SLP3842R	Model / Year	TOYOTA COROLLA ALTIS
Date of Accident	09-Apr-18	Policy No.	
Type of Claim	TP AXA	Prepared By	SHARON
Survey By		Chassis No.	

S/NO	Description	Qty	Unit Price	Amount
1	REAR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 395.00	\$ 395.00
2	REAR BOOT LID LOCK <i>X ansur</i>	1	\$ 385.00	\$ 385.00
				\$ 780.00
		LESS 25%		\$ 195.00
				<u>\$ 585.00</u>

395
25%
98.75
296.25

This is a computer printout no signature is required.

P - 470.68
S/L - 180.00
L - 430.00
Suppl - 296.25
T - 1376.93
2 days

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003718

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01

AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE : 09/04/2018
ACCIDENT DATE : 09/04/2018
VEHICLE NO : SLP3842R
CHASSIS/ENG.NO :
VEHICLE MODEL : TOYOTA COROLLA
CLAIM NO :
POLICY NO :
REMARK : 3842 AXA TP AGAINST
SLV7893K

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	561.45	25	421.09 <i>DE</i>	421.09
2	<i>1pc</i>	PC	REAR BUMPER SIDE RETAINER	132.25	25	99.19 <i>me</i>	198.38
3	1	PC	REAR BUMPER SPONGE	182.10	25	136.57 <i>?</i>	136.57
SUB-TOTAL:							756.04
** SPECIAL NETT PRICE **							
1	1	PC	REAR BUMPER REVERSE SENSOR	180.00		180.00 <i>?</i>	180.00
SUB-TOTAL							180.00
** WORK LABOUR **							
TO CHECK WIRING						30.00 <i>/</i>	30.00
TO APPLY ANTI RUST COATING						100.00 <i>X</i>	100.00
TO KNOCK REAR END PANEL, WELD, REMOVE & REPLACE ABOVE PARTS						550.00 <i>200</i>	550.00
TO PUTTY & RESPRAY PAINTING ON RR BUMPER, REAR END PANEL						600.00 <i>200</i>	600.00
AND AFFECTED AREAS						0.00	0.00
SUB-TOTAL							1,280.00
<i>Ram</i> <i>Hp 90010064</i> <i>2 days</i> <i>P/P</i> <i>10/04/18 P1345</i> <i>Rasy by paint</i>				LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____			
JOYCE				SUB-TOTAL : S\$ 2,216.04			
				ADD 7% GST. S\$ 155.12			
				GRAND TOTAL : S\$ 2,371.16			

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00AMO
Our ref: CC4/ASM18004836/R1ua3

Date: 13.04.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLP 3842R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.04.2018 at the premises of M/s Sng Ah Tee Motor & Panel Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,216.04
Revised Estimate Amount	: S\$	1,049.47
"Check" Items Amount	: S\$	316.57
Total (Including Check Items)	: S\$	1,366.04

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8180D

Vehicle Details

Vehicle No.: SLP3842R
Vehicle to be Exported: No
Intended De-registration Date: 31 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 CVT
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: 1ZRY333452
Chassis No.: MR053REH104558378
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$19,990.00
Original Registration Date: 01 Jun 2017
First Registration Date: 01 Jun 2017
Transfer Count: 0
Actual ARF Paid: \$19,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 31 May 2027
PARF Rebate Amount: \$14,992.00

Intended COE Rebate Details

COE Expiry Date: 31 May 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$49,430.00
COE Rebate Amount: \$45,310.00
Total Rebate Amount: \$60,302.00

The information contained herein is correct as at 13 Mar 2018

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/08/2019

Survey Details:

Date of loss	12-Mar-18
Date of appointment	13-Mar-18
Date of survey	10-Apr-18
Location of survey	SNG AH TEE MOTOR & PANEL SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLP 3842R
Make and Model	TOYOTA COROLLA ALTIS
Date of registration	1/6/2017
Excess	
Market Value	\$94,000
Parf Rebate	\$60,300
Nett Loss	\$33,700

Repair details:

Initial Estimate	\$ 2,801.04
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 946.93
Check items (estimate)	\$ -
Labour	\$ 430.00
Total	\$ 1,376.93
Lump Sum(if applicable)	-

Number of days for repair	2
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

02 RECOMMENDED REPAIR DAYS + 1 PRS = 3DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost (W/GST)	\$ 1,473.32	W/GST
Loss of use (6days x \$50)	\$ 180.00	3days x \$60
Loss of rental	-	
Loss of income	-	
LTA search fees	\$ 2.00	
Others	-	
Proposed Total	\$ 1,655.32	\$ -



<MANDATE IA> - S8M00AM0 {ACCIDENT INVOLVING SLV 7893K (OI) & SLP 3842R (TP) ON 12/03/2018 }

Type

🔔 Question

Message

LIABILITY: 100% BOLA S27: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1655.32 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED INTO SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INVOICE. SO003880

AXA INSURANCE PTE LTD

8 Shenton Way #24-01

AXA Tower (S) 068811

ATTENTION:

CONTACT: -

FAX NO: 68804838

DATE : 20/07/2019
ACCIDENT DATE : 12/03/2018
VEHICLE NO : SLP3842R
CHASSIS/ENG.NO : MR053REH104558378
VEHICLE MODEL : TOYOTA COROLLA
CLAIM NO : CC4/ASM18004836/ua3
POLICY NO : SURVEY BY LKK
REMARK : 3842 AXA TP AGAINST
SLV7893K

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	561.45	25	421.09	421.09
2	1	PC	REAR BUMPER SIDE RETAINER	66.12	25	49.59	49.59
3	1	PC	REAR BUMPER REINFORCEMENT	395.00	25	296.25	296.25
SUB-TOTAL:							766.93
** SPECIAL NETT PRICE **							
1	1	PC	REAR BUMPER REVERSE SENSOR	180.00		180.00	180.00
SUB-TOTAL							180.00
** WORK LABOUR **							
			TO CHECK WIRING			30.00	30.00
			TO KNOCK REAR END PANEL, WELD, REMOVE & REPLACE ABOVE PARTS			200.00	200.00
			TO PUTTY & RESPRAY PAINTING ON RR BUMPER, REAR END PANEL			0.00	0.00
			AND AFFECTED AREAS			200.00	200.00
SUB-TOTAL							430.00

JANICE

PAGE: 1 of 1

SUB-TOTAL : S\$ 1,376.93

ADD 7% GST. S\$ 96.39

GRAND TOTAL : S\$ 1,473.32

ON BEHALF OF SNG AH TEE MOTOR & PANEL SERVICE PTE LTD E & O.E



Re:<MANDATE IA> - S8M00AM0 {ACCIDENT INVOLVING SLV 7893K (OI) & SLP 3842R (TP) ON 12/03/2018 }

Type

🔗 Question

Message

Hi Pls proceed, tks-VO

Reply

Cecilia Chong (LKK Auto)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 8 August 2019 2:20 PM
To: Janice Chang; Cecilia Chong (LKK Auto)
Cc: Admin A; CS A Team
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE SLP3842R AND YOUR INSURED SLV7893K ON 12/03/2018 *** LKK REF: CC4/ASM18004836/R1ga3
Attachments: SLP3842R.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Cecilia,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Chang <janice@sngahtee.com>
Sent: Wednesday, 24 July, 2019 9:49 AM
To: Admin A <admin-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE SLP3842R AND YOUR INSURED SLV7893K ON 12/03/2018 ***
LKK REF: CC4/ASM18004836/ua3
Importance: High

Hi Oi,

We refer to the above and have finalized with your surveyor.
Here is our LOD.

Quantum is as per below:-

COR = \$1,473.32

LOU= \$240.00 (\$80.00 x 3days)

SEARCH FEE = \$2.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004836/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:VALE OH

Date : 30-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 7893K ✓	Veh. Inspected	SLP 3842R ✓
Policy No.	GA314097 ✓	Coverage (\$)	0.00
Claim No.	S8M00AMO ✓	Excess (\$)	0.00
Assign From		Assign Date	13/03/2018 ✓

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598 ✓
Engine No.	HIDDEN ✓	Year of Reg.	2017 ✓
Chassis No.	MR053REH104558378	Colour	GREY ✓
Odometer	20336 ✓	Steering	IN ORDER ✓
Brakes	IN ORDER ✓	Modification	SPORTS RIM ✓
General	FAIR ✓		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17 ✓	MICHELIN ✓	6 mm ✓
L/H Front Tyre	215/45 R17 ✓	MICHELIN ✓	6 mm ✓
R/H Rear Tyre	215/45 R17 ✓	MICHELIN ✓	6 mm ✓
L/H Rear Tyre	215/45 R17 ✓	MICHELIN ✓	6 mm ✓

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. ✓
--

5. General Information

Accident Date	12/03/2018 ✓	Inspection Date	10/04/2018 ✓
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457. ✓		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. ✓
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days ✓
-------------------------------------	------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 3842R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	561.45	561.45
2	REAR BUMPER SIDE RETAINER (CONSISTENT)	NECESSARY	132.25	66.12
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	182.10	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT) (ADDITIONAL)	BENT	395.00	395.00
1	REAR BOOT LID LOCK (CONSISTENT) (ADDITIONAL)	SERVICEABLE	385.00	-
	LESS 25% DISCOUNT		-413.95	-255.64
			1,241.85	766.93
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	180.00	180.00
			180.00	180.00
<u>LABOUR</u>				
	TO CHECK WIRING .		30.00	30.00
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	100.00	-
	TO KNOCK REAR END PANEL,WELD ,REMOVE & REPLACE ABOVE PARTS.		550.00	200.00
	TO PUTTY & RESPRAY PAINTING ON RR BUMPER ,REAR END PANEL AND AFFECTED AREAS.		600.00	200.00
			1,280.00	430.00
GRAND TOTAL			2,701.85	1,376.93
RECOMMENDED COST OF REPAIRS				1,376.93

Report Ref No. CC4/ASM18004836/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SIM000AMQ
Reference	CC4/ASM18004836/R1ga3a2 
Loss Date	12 March 2018
Report Date	13 Mar 2018 12:56:21 PM
Request Date	12 July 2018
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Vehicle Information	
Incident Vehicle Registration #	SLP3842R
Make	TMVD TOYOTA
Model	COROLLA ALTIS-1.6 CVT (A)
Service Address	
...	
Primary Contact/Insured	
TOK LAI HUAT (ZHILUO LAIFA) BLK 469, CHOA CHU KANG AVENUE 3, #03-107, 680469, Singapore	
DOCUMENT@AXA.COM.SG	
Claim Handler	
OH Vale 6568004897 vale.oh@axa.com.sg	

Actions

Next StepWait for Approve Invoice

ADD Invoice

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPDATED
 LKKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE (UNLOADED)
 LKXInquisition (3).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LKXAdjustment1a.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 GJA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	31 March 2020
 LEO AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 MANDATE IA DD 20082019.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 PAIRF COE REBATE.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 TP EST LIST MARKED.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 LKX RESURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 LKX SURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 LKXInquisition Photo.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	18 April 2018
 Preliminary Advice.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	13 April 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LUX AUTO CONSULTANT'S PTE LTD (TP)	13 April 2018
 GIA REPORT OF SLV78Y3K (TP).PDF	Reports & Statement	GIA Report	KADRI Muteen	13 March 2018
 GIA REPORT OF SLV78Y3K (INSO).PDF	Reports & Statement	GIA Report	KADRI Muteen	13 March 2018
 EMAIL.jpg	Letters and Correspondence	Workshop	KADRI Muteen	13 March 2018