

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003718

AXA INSURANCE PTE LTD

8 Shenton Way #B1-01

AXA Tower (S) 068811

ATTENTION :

CONTACT : -

FAX NO: 68804838

DATE 09/04/2018
ACCIDENT DATE : 09/04/2018
VEHICLE NO : SLP3842R
CHASSIS/ENG.NO :
VEHICLE MODEL : TOYOTA COROLLA
CLAIM NO :
POLICY NO :
REMARK 3842 AXA TP AGAINST
SLV7893K

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	561.45	25	421.09 DE ✓	421.09
2	1	PC	REAR BUMPER SIDE RETAINER	132.25	25	99.19 me ✓	198.38
3	1	PC	REAR BUMPER SPONGE	182.10	25	136.57 ?	136.57
SUB-TOTAL:							756.04

** SPECIAL NETT PRICE **							
1	1	PC	REAR BUMPER REVERSE SENSOR	180.00		180.00 ?	180.00
SUB-TOTAL							180.00

** WORK LABOUR **			
TO CHECK WIRING	30.00	✓	30.00
TO APPLY ANTI RUST COATING	100.00	X	100.00
TO KNOCK REAR END PANEL, WELD, REMOVE & REPLACE ABOVE PARTS	550.00	200	550.00
TO PUTTY & RESPRAY PAINTING ON RR BUMPER ,REAR END PANEL	600.00	200	600.00
AND AFFECTED AREAS	0.00		0.00
SUB-TOTAL			1,280.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

JOYCE

PAGE: 1

SUB-TOTAL : S\$ 2,216.04

ADD 7% GST. S\$ 155.12

GRAND TOTAL : S\$ 2,371.16